

12/03/2002

ASS. REC. BY:

REF: CS/MSA19012661/TIVF302

Special Instruction:

Surveyor: Tanfikh

ASSIGNMENT (Office)

From (Person): Jocelyn Ng Shin Bun of MS19

Date/Time: 17.7.19 12.59 p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: XE 1548 U

Insured:

at Workshop m/s Tan chong Industrial

Tel: 97 879034

of 23 Jalan Buroh

Policy No: 29120984

Claim No: 599987

Sum Insured:

Excess: \$750.00

Make of Veh:

(Client's Record)

D.O.A 6.7.19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 18.7.19 10.04 a.m

Person Contacted:

Alfred

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

XE 1548U NA/CT117015689/K4 DOA = 12/8/17

19/7/19

Revert via merimen

19/7/19

Recd approved \$917.63 from Jocelyn by merimen

19/7/19

Informed Alfred c/A ex \$750 by email

16/8/19

Final fig \$10,332.54 (Recd 630, 670) confirmed by email



**...CLAIM SUBFOLDER...(New Assignment)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Jul 2019 12:28		17 Jul 2019 16:59 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	CWT PTE LIMITED, Co. Reg. No.: 197000498M	
Vehicle Reg. No.:	XE1548U	Date of Loss: 06/07/2019 10:00 - :59 [39 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 599987	29120984 (Comprehensive) Coverage: 01/04/2019 - 31/03/2020
	Excess:	S\$750.00
Repairer:	Tan Chong Industrial Machinery Pte Ltd (Jalan Buroh) 23 Jalan Buroh, 619479 Boon Lay - Tel: 66622287	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jocelyn Ng Shin Bun]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 18/07/2019]	
Driver/Custodian:	KAMARON BIN BASIRON (44 / Male), NRIC: S7441873B, Tel: +6598434267 Email: NOEMAIL	
Adj Asg. Remarks:	Car in. Survey & revert. Please contact us ASAP if you cannot attend this assignment.	

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		

ALL ASSOCIATED TASKS										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

## View Received Message

This mail is associated with :

**\*XE1548U (599987)**

OD

Jul 6 2019 10:00AM

[CWT PTE LIMITED]

Tan Chong Industrial Machinery Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** MSIG Insurance (Singapore) Pte. Ltd. (MSIG\_SG), sent on 15/08/2019 16:51 PM.

**To** LKK\_HQ

**Subject** Alert - Adj Mandate Approved (S\$10332.55) - XE1548U - Claim Handler: Jocelyn Ng Shin Bun

Approved:10332.55:a if c

### DOCUMENTS SUMMARY

There are no documents.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
-----	--	-------	---

Attn:	Jocelyn Ng Shin Bun	Date:	14 Aug 2019
-------	---------------------	-------	-------------

**Preliminary Advice**

Vehicle No	: XE1548U	Accident Date	: 06/07/2019
Make	: UD TRUCKS ESCOT V	Policy No.	: 29120984
Assignment Date	: 17/07/2019	Excess	: S\$750.00
Date of Inspection	: 18/07/2019	Est. Duration of Repair	: 7.00
Inspection At	: TAN CHONG INDUSTRIAL MACHINERY PTE LTD (JALAN BUROH) 23 JALAN BUROH SINGAPORE 619479		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,962.54	(incl.supplementary \$1114.91)
Revised Amount	:S\$	10,332.55	(incl.supplementary \$1114.91)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	10,332.55	
Lump Sum Repair	:S\$		

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	103,000.00
COE / PARF Rebate	:S\$	3,093.00
Salvage Value	:S\$	
Margin for Repair	:S\$	99,907.00

**Remarks**

( X ) The vehicle is economical for repair.

( ) The above survey was conducted on a 'without prejudice' basis.

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Friday, 19 July 2019 2:29 PM  
**To:** 'Alfred Lee'; SUR  
**Subject:** XE 1548U-DOA: 6/7/2019 (MSIG OD)

Dear Alfred,

As instructed by our client , please proceed to repair the **insured vehicle XE 1548R (Excess \$750/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## View Received Message

This mail is associated with :

**\*XE1548U (599987)**

OD

Jul 6 2019 10:00AM

[CWT PTE LIMITED]

Tan Chong Industrial Machinery Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** MSIG Insurance (Singapore) Pte. Ltd. (MSIG\_SG), sent on 19/07/2019 14:22 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$9217.63) - XE1548U - Claim Handler: Jocelyn Ng Shin Bun

Approved:9217.63:a if c

### DOCUMENTS SUMMARY

There are no documents.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jocelyn Ng Shin Bun

Date: 19 Jul 2019

**Preliminary Advice**

Vehicle No	: XE1548U	Accident Date	: 06/07/2019
Make	: UD TRUCKS ESCOT V	Policy No.	: 29120984
Assignment Date	: 17/07/2019	Excess	: S\$750.00
Date of Inspection	: 18/07/2019	Est. Duration of Repair	: 7.00
Inspection At	: TAN CHONG INDUSTRIAL MACHINERY PTE LTD (JALAN BUROH) 23 JALAN BUROH SINGAPORE 619479		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,847.63
Revised Amount	:S\$	9,217.63
Check Items (Estimated)	:S\$	0.00
Total	:S\$	9,217.63

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	103,000.00
COE / PARF Rebate	:S\$	3,093.00
Salvage Value	:S\$	
Margin for Repair	:S\$	99,907.00

**Remarks**

( X ) The vehicle is economical for repair.

( ) The above survey was conducted on a 'without prejudice' basis.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	498M
Vehicle Details	
Vehicle No.:	XE1548U
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Jul 2019
Vehicle Make:	UD TRUCKS
Vehicle Model:	GKB5ELDHNT ESCOT V
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	GH11734344
Chassis No.:	JNCM1F1AXGU005597
Maximum Power Output:	-
Open Market Value:	\$78,459.00
Original Registration Date:	23 Mar 2016
First Registration Date:	23 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$3,923.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	22 Mar 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$4,635.00
COE Rebate Amount:	\$3,093.00
Total Rebate Amount:	\$3,093.00

The information contained herein is correct as at 19 Jul 2019

OK

IC,DL,CI Pg. 1



MSIG

MSIG Insurance (Singapore) Pte. Ltd.  
 4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807  
 Tel: +65 6827 7888, Fax: +65 6827 7800  
 Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

197 000 498M  
 tel. 6262 6888

## Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)  
 THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)  
 THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)  
 (REPUBLIC OF SINGAPORE)  
 THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)  
 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.2.301

COMMERCIAL VEHICLE - FLEET

Goods Carrying Vehicle - Sch II

Comprehensive

Certificate No. B 29120984 MKF

Excess: SGD750

1. Index Mark and Registration Number of Vehicle

XE1548U

2. Name of Policyholder

CWT Pte. Limited

3. Effective Date of the Commencement of Insurance for the purposes of the Act

01/04/2019

4. Date of Expiry of Insurance

31/03/2020

5. Persons or Classes of Persons entitled to drive\*

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

\* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use\*

Use in connection with the Policyholder's business.  
 Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business.  
 Use for social domestic and pleasure purposes.

The Policy does not cover

- (1) Use for racing pace-making reliability trial or speed-testing.
- (2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.
- (3) Use for the carriage of passengers for hire or reward.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.  
 Approved Insurers

for Chief Executive Officer

ELYM201904011421

Page 2 of 8

MSAT19092553 / Sng Ah Tee Motor & Panel Service Pte Ltd - Pioneer  
 ENTRY DATE & TIME: 15/07/2019 17:22  
 SUBMITTED BY: Janice Chang Siew Yin

**Your NCD will be affected due to late reporting**  
**Actual e-Filing Submission Date & Time: 15/07/2019 17:44**

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	15/07/2019 17:22
Date Of Accident	06/07/2019 10:00
Exact Location Of Accident	WEST COAST HIGHWAY
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	XE1548U
Insured/Policyholder	
Name Of Registered Owner	CWT PTE LIMITED
Co Reg No	197000498M
Email Address	LAWRENCE@INTLIMITED.COM
Mobile Phone No	
Alternative Phone No	OFFICE-62626888
Vehicle Particulars	
Manufacturer	UD TRUCKS
Model	GKB5ELDHNT ESCOT V
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B29120984MKF
Cover Note Number	
Driver	
Name of Driver	KAMARON BIN BASIRON
NRIC No	S7441873B
Date Of Birth	12/12/1974
Occupation	OUTDOOR
Date Of Driving Pass	08/04/2008
Driving Experience	11 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98434267
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Page 1 of 1

Address BLK 129B CANBERRA ST #02-604  
 Postcode 752129  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident CHAIN COLLISION  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 3  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XD2103T  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category COMMERCIAL VEHICLE  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number XE2430T

Page 5 of 8

Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category COMMERCIAL VEHICLE  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

## Sketch Plan Pg. 1

## SKETCH PLAN

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:




Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Sketch Plan Pg. 2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along West Coast Highway toward city, traffic was heavy. I was occupied with a 40 foot loaded container and on lane 3.

Suddenly, the vehicle in front of me did a E-brake, I tried but could not stop in time and hit into it. No damage to 3rd party vehicle but my vehicle front portion badly damaged. No one was injured.

<input checked="" type="checkbox"/>	Driver's Name	Tan Chong
<input checked="" type="checkbox"/>	Driver's NRIC/Fin No.	B 29120984 MCF
<input checked="" type="checkbox"/>	Driver's License No.	MS166(C)
<input checked="" type="checkbox"/>	Driver's Vehicle No.	XE1548U

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/Fin No.:

LKK Auto Consultants hence notify the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• No illegal modification(s) is allowed  
• Any item(s) must be resurveyed and subject to final approval from Insurance Company

From ALFRED LEE

Date

17-Jun-19

To MSIG INSURANCE (SINGAPORE) PTE LTD

Our ref

AL/1548-010/0719

Attn MOTOR CLAIM DEPT

Tel

68277880

Fax

62257402

VEH NO : XE1548U

Model :

GKB5LDHNT

Chassis : JNCM1F1AXGU005597

Eng No :

GH11734344

1. The above vehicle was inspected by TCIM and append here under is the estimated repair cost :

Claim type: OWN DAMAGE

Description	Qty	Unit Price	Amount
LH BUMPER ASSY	1	\$ 497.28	NETT \$ 497.28 <i>bt</i>
BUMPER REINFORCEMENT	1	\$ 834.72	NETT \$ 834.72 <i>bt</i>
LH STEP BUMPER	1	\$ 65.00	NETT \$ 65.00 <i>mis</i>
LH BUMPER SIDE	1	\$ 48.50	NETT \$ 48.50 <i>mis</i>
LH HEADLAMP ASSY	1	\$ 1,392.64	NETT \$ 1,392.64 <i>one</i>
LH FOG LAMP ASSY	1	\$ 252.19	NETT \$ 252.19 <i>one</i>
LH SIGNAL LAMP ASSY	1	\$ 44.40	NETT \$ 44.40 <i>one</i>
BUMPER GRILLE (LH INNER)	1	\$ 88.80	25% \$ 66.60 <i>m.v</i>
BUMPER GRILER (LH OUTER)	1	\$ 82.80	25% \$ 62.10 <i>aa</i>
LH CORNER PANEL	1	\$ 185.00	NETT \$ 185.00 <i>aa</i>
FRONT PANEL ASSY	1	\$ 820.51	NETT \$ 820.51 <i>bt</i>
UD EMBLEM	1	\$ 128.00	NETT \$ 128.00 <i>ne</i>
PANEL LOCK ASSY	1	\$ 195.55	25% \$ 146.66 <i>bt</i>
LH PANEL HINGE	1	\$ 39.96	NETT \$ 39.96 <i>one</i>
PANEL GRILLE	1	\$ 452.88	NETT \$ 452.88 <i>one</i>
LOWER GRILLE	1	\$ 399.60	NETT \$ 399.60 <i>mi</i>
LH AIR BELLOW ASSY	1	\$ 408.48	NETT \$ 408.48 <i>one</i>
AIR FITTING JOINT	1	\$ 25.66	NETT \$ 25.66 <i>dis</i>
LH CABIN ABSORBER	1	\$ 108.34	NETT \$ 108.34 <i>bt</i>
AIRCON UNI PIPE	1	\$ 245.00	25% \$ 183.75 <i>del</i>
AIRCON GAS AND OIL	1	\$ 60.00	NETT \$ 60.00 <i>res</i>
WINDSCREEN WASHER TANK	1	\$ 195.36	NETT \$ 195.36 <i>de</i>

Estimated parts cost \$ 6,417.63

#### Labour cost

To putty/primer application and spray painting including touch-up affected areas with polyurethane paint.

\$ 550.00 *400.*

TO REPLACE RH DOOR ASSY.  
TO PANEL BEAT AND PUTTY FOR RH SIDE PANEL.  
TO REMOVE CABIN UPHOSTER TO FACILIATE PANEL BEATING OF REAR PANEL ASSY.

\$ 2,880.00 *2400.*  
(6 DAYS)

Estimated labour cost \$ 3,430.00

EST. LABOUR & PARTS COST 10,965.54 \$ 9,847.63

1. All prices quoted are subjected to 7% GST. The above quotation is based on initial visual inspection only.

Thank you and regards

ALFRED LEE  
Marketing Executive  
Service Department  
alfred\_lee@tanhong.com

DID : 6703 8755  
HP: 97879034

Tanpik 97495749  
18/7/19 231 Spw Not Authorise, Revert  
\$750 Ex: to be advise  
surc lkkanto.com.  
Part by Part  
Resurvey before paint  
7 days.



TAN CHONG INDUSTRIAL MACHINERY PTE LTD  
23 JALAN BUROH  
SINGAPORE 619479  
TEL:6703 8755 FAX:62665862

From ALFRED LEE Date 07-Aug-19  
To MSIG INSURANCE (SINGAPORE) PTE LTD Our ref AL/1548-010/0719  
Attn MOTOR CLAIM DEPT Tel 68277880  
Fax 62257402

VEH NO : XE1548U Model : GKB5LDHNT  
Chassis : JNCM1F1AXGU005597 Eng No : GH11734344

1. We are pleased to finalise the repair cost as follows.

Claim type: OWN DAMAGE

Description	Qty	Unit Price	Amount
LH BUMPER ASSY	1	\$ 497.28	NETT \$ 497.28
BUMPER REINFORCEMENT	1	\$ 834.72	NETT \$ 834.72
LH STEP BUMPER	1	\$ 65.00	NETT \$ 65.00
LH BUMPER SIDE	1	\$ 48.50	NETT \$ 48.50
LH HEADLAMP ASSY	1	\$ 1,392.64	NETT \$ 1,392.64
LH FOG LAMP ASSY	1	\$ 252.19	NETT \$ 252.19
LH SIGNAL LAMP ASSY	1	\$ 44.40	NETT \$ 44.40
BUMPER GRILLE (LH INNER)	1	\$ 88.80	25% \$ 66.60
BUMPER GRILER (LH OUTER)	1	\$ 82.80	25% \$ 62.10
LH CORNER PANEL	1	\$ 185.00	NETT \$ 185.00
FRONT PANEL ASSY	1	\$ 820.51	NETT \$ 820.51
UD EMBLEM	1	\$ 128.00	NETT \$ 128.00
PANEL LOCK ASSY	1	\$ 195.55	25% \$ 146.66
LH PANEL HINGE	1	\$ 39.96	NETT \$ 39.96
PANEL GRILLE	1	\$ 452.88	NETT \$ 452.88
LOWER GRILLE	1	\$ 399.60	NETT \$ 399.60
LH AIR BELLOW ASSY	1	\$ 408.48	NETT \$ 408.48
AIR FITTING JOINT	1	\$ 25.66	NETT \$ 25.66
LH CABIN ABSORBER	1	\$ 108.34	NETT \$ 108.34
AIRCON UNI PIPE	1	\$ 245.00	25% \$ 183.75
AIRCON GAS AND OIL	1	\$ 60.00	NETT \$ 60.00
WINDSCREEN WASHER TANK	1	\$ 195.36	NETT \$ 195.36

Estimated parts cost \$ 6,417.63

Labour cost

To putty/primer application and spray painting including touch-up affected areas with polyurethane paint. } \$ 400.00

TO REPLACE RH DOOR ASSY.  
TO PANEL BEAT AND PUTTY FOR RH SIDE PANEL.  
TO REMOVE CABIN UPHOSTER TO FACILIATE PANEL BEATING OF REAR PANEL ASSY. } \$ 2,400.00

Estimated labour cost \$ 2,800.00

SUPPLEMENTRY PARTS

Description	Qty	Unit Price	discount	Amount
LH CABIN MOUNTING BRACKET	1	\$ 846.55	25%	\$ 634.91
TO REPLACE ABOVE MENTION ITEMS. TO JACK CABIN REMOVE CABIN LINK TO FACILIATE REPLACMENT OF MOUNTING BRACKET ASSY. TO JACK AND ALIGN BACK CABIN.				\$ 480.00

Supplementary parts and labour \$ 1,114.91

**EST. LABOUR & PARTS COST**

**\$ 10,332.55**

Less excess \$750.00 **\$ 9,582.55**

1. All prices quoted are subjected to 7% GST

Thank you and regards

ALFRED LEE  
Marketing Executive  
Service Department  
alfred\_lee@tanchong.com

DID : 6703 8755  
HP: 97879034



## Veron Chen (LKKAUTO)

---

**From:** Alfred Lee <alfred\_lee@tanchong.com>  
**Sent:** Friday, 16 August 2019 11:45 AM  
**To:** Veron Chen (LKKAUTO); SUR  
**Subject:** Re: XE 1548U-DOA: 6/7/2019 (MSIG OD)

Dear Ms Veron,

Sorry for the error, Confirmed repair cost at \$10332.54 (before excess).

Regards,

*Alfred Lee*  
*Tan Chong Industrial Machinery Pte Ltd*  
*DID : 6703 8755*  
*FAX : 6266 5862*

---

**From:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Sent:** Friday, 16 August 2019 11:01 AM  
**To:** Alfred Lee <alfred\_lee@tanchong.com>; SUR <sur@lkkauto.com>  
**Subject:** RE: XE 1548U-DOA: 6/7/2019 (MSIG OD)

Dear Alfred,

Final amount **\$10,332.54** instead \$10,332.55 @ 7 working days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Alfred Lee <alfred\_lee@tanchong.com>  
**Sent:** Wednesday, 7 August 2019 1:24 PM  
**To:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>  
**Subject:** Re: XE 1548U-DOA: 6/7/2019 (MSIG OD)

Dear Ms Veron,

Kindly refer to the attached. By the way, Mr Rasul have taken the supplementary photos during the resurvey also.

Regards,

*Alfred Lee*  
*Tan Chong Industrial Machinery Pte Ltd*  
*DID : 6703 8755*

FAX: 6266 5862

---

**From:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Sent:** Wednesday, 7 August 2019 11:33 AM  
**To:** Alfred Lee <alfred\_lee@tanchong.com>; SUR <sur@lkkauto.com>  
**Subject:** FW: XE 1548U-DOA: 6/7/2019 (MSIG OD)

Dear Alfred,

Please provides supplementary photos.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Alfred Lee <alfred\_lee@tanchong.com>  
**Sent:** Wednesday, 7 August 2019 10:51 AM  
**To:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** Re: XE 1548U-DOA: 6/7/2019 (MSIG OD)

Dear Ms Veron,

Kindly refer to the attached for the finalise repair cost for XE1548U.

Regards,

*Alfred Lee*  
*Tan Chong Industrial Machinery Pte Ltd*  
*DID : 6703 8755*  
*FAX : 6266 5862*

---

**From:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Sent:** Wednesday, 31 July 2019 4:32 PM  
**To:** Alfred Lee <alfred\_lee@tanchong.com>  
**Subject:** RE: XE 1548U-DOA: 6/7/2019 (MSIG OD)

Dear Alfred,

Kindly advise vehicle status.

**If vehicle has been repaired, please finalize with us.**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Veron Chen (LKKAuto)

**Sent:** Friday, 19 July 2019 2:29 PM

**To:** 'Alfred Lee' <alfred\_lee@tanchong.com>; SUR <sur@lkkauto.com>

**Subject:** XE 1548U-DOA: 6/7/2019 (MSIG OD)

Dear Alfred,

As instructed by our client , please proceed to repair the **insured vehicle XE 1548R (Excess \$750/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**Veron Chen (LKKAUTO)**

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Friday, 16 August 2019 11:01 AM  
**To:** Alfred Lee; SUR  
**Subject:** RE: XE 1548U-DOA: 6/7/2019 (MSIG OD)

Dear Alfred,

Final amount **\$10,332.54** instead \$10,332.55 @ 7 working days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Alfred Lee <alfred\_lee@tanchong.com>  
**Sent:** Wednesday, 7 August 2019 1:24 PM  
**To:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>  
**Subject:** Re: XE 1548U-DOA: 6/7/2019 (MSIG OD)

Dear Ms Veron,

Kindly refer to the attached. By the way, Mr Rasul have taken the supplementary photos during the resurvey also.

Regards,

*Alfred Lee*

*Tan Chong Industrial Machinery Pte Ltd*

*DID : 6703 8755*

*FAX : 6266 5862*

---

**From:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Sent:** Wednesday, 7 August 2019 11:33 AM  
**To:** Alfred Lee <alfred\_lee@tanchong.com>; SUR <sur@lkkauto.com>  
**Subject:** FW: XE 1548U-DOA: 6/7/2019 (MSIG OD)

Dear Alfred,

Please provides supplementary photos.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Alfred Lee <alfred\_lee@tanchong.com>

**Sent:** Wednesday, 7 August 2019 10:51 AM

**To:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>

**Cc:** SUR <sur@lkkauto.com>

**Subject:** Re: XE 1548U-DOA: 6/7/2019 (MSIG OD)

Dear Ms Veron,

Kindly refer to the attached for the finalise repair cost for XE1548U.

Regards,

*Alfred Lee*

*Tan Chong Industrial Machinery Pte Ltd*

*DID : 6703 8755*

*FAX : 6266 5862*

---

**From:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>

**Sent:** Wednesday, 31 July 2019 4:32 PM

**To:** Alfred Lee <alfred\_lee@tanchong.com>

**Subject:** RE: XE 1548U-DOA: 6/7/2019 (MSIG OD)

Dear Alfred,

Kindly advise vehicle status.

**If vehicle has been repaired, please finalize with us.**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Veron Chen (LKKAuto)

**Sent:** Friday, 19 July 2019 2:29 PM

**To:** 'Alfred Lee' <alfred\_lee@tanchong.com>; SUR <sur@lkkauto.com>

**Subject:** XE 1548U-DOA: 6/7/2019 (MSIG OD)

Dear Alfred,

As instructed by our client , please proceed to repair the **insured vehicle XE 1548R (Excess \$750/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Jul 2019 12:28		17 Jul 2019 16:59 <a href="#">Edit Adj Rpt</a>	<b>S\$10,332.54</b> <a href="#">Edit Estimates</a>	<b>S\$10,332.54</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

















































  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	CWT PTE LIMITED, Co. Reg. No.: 197000498M								
Vehicle Reg. No.:	XE1548U	Date of Loss:	06/07/2019 10:00 - :59 [39 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 599987	Policy/Cover Note No.:	29120984 (Comprehensive) Coverage: 01/04/2019 - 31/03/2020						
		Excess:	S\$750.00						
Repairer:	Tan Chong Industrial Machinery Pte Ltd (Jalan Buroh) 23 Jalan Buroh, 619479 Boon Lay - Tel: 6265 3666 / 6703 8766								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jocelyn Ng Shin Bun]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 16/08/2019]								
Driver/Custodian:	KAMARON BIN BASIRON (44 / Male) , NRIC: S7441873B, Tel: +6598434267 Email: NOEMAIL								
Adj Asg. Remarks:	Car in. Survey & revert. Please contact us ASAP if you cannot attend this assignment.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>MSIG_SG (15/08/2019): Alert - Adj Mandate Approved (S\$10332.55) - XE1548U - Claim Handler: Jocelyn Ng ...</li> <li>MSIG_SG (19/07/2019): Alert - Adj Mandate Approved (S\$9217.63) - XE1548U - Claim Handler: Jocelyn Ng S...</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*XE1548U (599987)  
OD  
Jul 6 2019 10:00AM  
[CWT PTE LIMITED]  
Tan Chong Industrial Machinery Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	19/07/19 12:19	Adjuster Immediate Advice						Load HTM		
2	14/08/19 09:02	Adjuster Immediate Advice						Load HTM		
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
2	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
3	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
4	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
5	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
6	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
7	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
8	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
9	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
10	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
11	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
12	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
13	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
14	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
15	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
16	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
17	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
18	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
19	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
20	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
21	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
22	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
23	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
24	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
25	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
26	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
27	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
28	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
29	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
30	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
31	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
32	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
33	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	
34	19/07/19 12:13	General View						Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
35	19/07/19 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
36	19/07/19 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
37	19/07/19 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
38	19/07/19 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
39	19/07/19 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
40	19/07/19 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
41	19/07/19 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
42	19/07/19 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
43	19/07/19 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
44	19/07/19 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
45	19/07/19 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
46	19/07/19 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
47	19/07/19 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
48	19/07/19 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
49	19/07/19 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
50	19/07/19 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
51	19/07/19 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
52	19/07/19 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
53	19/07/19 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
54	19/07/19 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
55	19/07/19 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
56	19/07/19 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
57	19/07/19 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
58	07/08/19 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	07/08/19 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	07/08/19 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	07/08/19 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	07/08/19 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	07/08/19 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	07/08/19 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	07/08/19 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	07/08/19 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	07/08/19 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	07/08/19 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	07/08/19 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	07/08/19 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	07/08/19 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	07/08/19 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	07/08/19 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	07/08/19 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	07/08/19 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	07/08/19 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	07/08/19 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	07/08/19 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	07/08/19 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	07/08/19 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	07/08/19 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	07/08/19 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	17/07/19 12:29	PARF COE		Load PDF	
2	17/07/19 12:29	Transfer Fee Details		Load PDF	
3	17/07/19 12:31	Email from Tan Chong (Alfred Lee) - to arrange survey		Load PDF	
4	17/07/19 12:31	Estimate Repair Cost + GIA Report		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/07/19 12:22	MARK ESTIMATE		Load PDF	
2	14/08/19 08:57	SUPPLEMENTARY		Load PDF	

## Linked Accident Report Documents

				View	View in Browser
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	15/07/19 17:43	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	15/07/19 17:43	Sketch Plan		Load TIF	
2	15/07/19 17:43	IC,DL,CI		Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, #21-01 SGX Centre 2  
Singapore 068807

Our File No: CS/MSG19012661/T1VF3E2

Date: 03/09/2019

### REFERENCE

Insured/Claimant:	CWT PTE LIMITED	Policy No:	29120984	
Date of Loss:	06/07/2019	Nature of Claim:	OD	Claim No: 599987

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>XE1548U</b>		
Make & Model:	UD TRUCKS ESCOT V, 10.8 D GKB5ELDHNT (M)	Engine No:	GH11734344
Reg. Date:	23/03/2016 (Man. Year: 2016)	Chassis No:	JNCM1F1AXGU005597
Colour:	Green	Odometer:	144219 km
Engine Capacity:	10837 cc		
Market Value/New Car Price:	S\$103,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5 (D)
Front Left Side:	Kratos 8 mm	Rear Left Side:	Kratos 8/8 mm
Front Right Side:	Kratos 8 mm	Rear Right Side:	Kratos 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,052.54	7,052.54	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,910.00	3,280.00	630.00	16.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,962.54</b>	<b>10,332.54</b>	<b>630.00</b>	<b>5.75</b>
<b>- Excess (S\$)</b>	<b>750.00</b>	<b>750.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>10,212.54</b>	<b>9,582.54</b>	<b>630.00</b>	<b>6.17</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>714.88</b>	<b>670.78</b>	<b>44.10</b>	<b>6.17</b>
<b>Nett Amount (S\$)</b>	<b>10,927.42</b>	<b>10,253.32</b>	<b>674.10</b>	<b>6.17</b>

### INSPECTION

Date of Assignment:	17/07/2019	
Date Inspected:	18/07/2019 Inspected At:	Tan Chong Industrial Machinery Pte Ltd (Jalan Buroh) 23 Jalan Buroh Singapore 619479
Estimated Period of Repair:	7.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 03 Sep 2019)	
<b>Parts:</b>	N/A	UD TRUCKS ESCOT V 10.8 D GKB5ELDHNT (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for XE1548U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH BUMPER ASSY	Bent	497.28 FS	*497.28 FS
2	1		*BUMPER REINFORCEMENT	Bent	834.72 FS	*834.72 FS
3	1		*LH STEP BUMPER	Missing	65.00 FS	*65.00 FS
4	1		*LH BUMPER SIDE	Missing	48.50 FS	*48.50 FS
5	1		*LH HEADLAMP ASSY	Cracked	1,392.64 FS	*1,392.64 FS
6	1		*LH FOG LAMP ASSY	Cracked	252.19 FS	*252.19 FS
7	1		*LH SIGNAL LAMP ASSY	Cracked	44.40 FS	*44.40 FS
8	1		*BUMPER GRILLE (LH INNER)	Missing	66.60 FS	*66.60 FS
9	1		*BUMPER GRILER (LH OUTER)	Cracked	62.10 FS	*62.10 FS
10	1		*LH CORNER PANEL	Cracked	185.00 FS	*185.00 FS
11	1		*FRONT PANEL ASSY	Bent	820.51 FS	*820.51 FS
12	1		*UD EMBLEM	Necessary	128.00 FS	*128.00 FS
13	1		*PANEL LOCK ASSY	Bent	146.66 FS	*146.66 FS
14	1		*LH PANEL HINGE	Cracked	39.96 FS	*39.96 FS
15	1		*PANEL GRILLE	Cracked	452.88 FS	*452.88 FS
16	1		*LOWER GRILLE	Missing	399.60 FS	*399.60 FS
17	1		*LH AIR BELLOW ASSY	Cracked	408.48 FS	*408.48 FS
18	1		*AIR FITTING JOINT	Distorted	25.66 FS	*25.66 FS
19	1		*LH CABIN ABSORBER	Bent	108.34 FS	*108.34 FS
20	1		*AIRCON UNI PIPE	Dented	183.75 FS	*183.75 FS
21	1		*AIRCON GAS AND OIL	Necessary	60.00 FS	*60.00 FS
22	1		*WINDSCREEN WASHER TANK	Deformed	195.36 FS	*195.36 FS
23	1		*LH CABIN MOUNTING BRACKET	Bent	634.91 FS	*634.91 FS
<b>Total Parts (S\$)</b>					<b>7,052.54</b>	<b>7,052.54</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PUTTY / PRIMER APPLICATION AND SPRAY PAINTING INCLUDING TOUCH-UP AFFECTED AREAS WITH POLYURETHANE PAINT	New	550.00	400.00
2	TO REPLACE RH DOOR ASSY. TO PANEL BEAT AND PUTTY FOR RH SIDE PANEL. TO REMOVE CABIN UPHOSTER TO FACILITATE PANEL BEATING OF REAR PANEL ASSY	New	2,880.00	2,400.00
3	TO REPLACE ABOVE MENTION ITEMS. TO JACK CABIN REMOVE CABIN LINK TO FACILITATE REPLACEMENT OF MOUNTING BRACKET ASSY. TO JACK AND ALIGN BACK CABIN	New	480.00	480.00
Gross Labour Cost (S\$)			3,910.00	3,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >