

INSURANCE

INS CASE OWNER:

CC 4 / AIG1901 2665, Gebb

LKK

IDAC

Surveyor:

SGQ

DOI:

ASSIGNMENT

18/3/19

Date / Time:

18/3/19

Registered in Merimen:

18/3/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SCM 2665

Name of Insured:

Lai Sing Kiew

Insured Tel No.:

HP:

Excess Sec II : \$5

D.O.A.:

10/3/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT:

YES

NO

TP GIA REPORT:

YES

NO

Insured Liability:

%

Final ? Yes / No

8PM 39



INSRS:

WSP:

Tel:

Liability:

RMKS:

SAWPU



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

8PM 39 - 1

SCM 2665 - 1

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

25.03.19

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup):

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: SGQ

Repair Cost:

P/P \$5 604.00

(1 days) Reduction:

27 %

Email

Call

FINAL SETTLEMENT

Date/Time: 18/3/19

Confirm with YEE DOO

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

N/A

If NO or B 28, Ass. Lia:

Repair Cost:

\$5 604.00

OID REVERSED TTT TP

Loss of Rental (LOR):

\$5 -

(1 days)

Loss of Use (LOU):

\$5 90.00

(5 30 x 3 days)

Loss of Income (LOI):

\$5 -

(5 x 3 days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

\$5 2.00

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow/ Independent)

Legal Cost

\$5 -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$320

Total:

\$5 696.00

Global Sum \$5:

FINAL PAYMENT

Date/Time: 18/3/19

Confirm with: YEE DOO

Email

Call

Payee 1:

\$5 696.00

Name 1:

SAWPU MOBILE PTE LTD

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

Surveyor: G8

ASSIGNMENT (Office)

From (Person): Chen Lu Ying of AIG Date/Time: 17.7.19 10:55am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: JFM 39 Insured: SCM 262G

at Workshop m/s Sanfu Motor Tel: 90613299

of 1 Kaki Bukit Ave 6 #02-43

Policy No: Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A. 10.7.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 17.7.19 10:55am Person Contacted: Lilian H.O.D. Endorsement:

Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	JFM 39 X
	SCM 262G CS/AXA/2023173/Gm 2 DCA=25/11/12
22/7/19	@ 12:17pm Lilian said they want do direct settlement

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: Sanfu Motor
 at Workshop m/s
 of

Insured

Policy No.

Claims No.

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: \$5500

IDAC Accident Rpt.: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: JFM 39Yr Regn: 20 Re-16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha NmaxC.C. 155Colour: Grey

A/C Insured / Std / NI / NA

Sp. Reading: _____

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: P MY9935106 000 5350Gen. Cond: Good / Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110/80-14
 R: 140/70-14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or TIM SUN

Front

Rear

R/Bal. 5 mmR/Bal. 5 mm

L/Bal. _____ mm

L/Bal. _____ mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

P/P: 604 (200) 9 228 21/1

Date/Time. File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time. File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$ + RS. \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)



ASSESSMENT FOR REPAIR : JFM 39

YAMAHA NMAX

COE EXPIRY :

Lump Sum / Part by Part

Qty	Description	Repairer's Estimate
1	Front fender - <i>Cut</i>	60.00 /
1	Mole side cover 1 - <i>Cut</i>	40.00 /
1	Board Footrest - <i>Cut</i>	30.00 /
1	Side Cover X <i>NN</i>	40.00 X
1	Body Cowling = <i>Cut</i>	60.00 /
1	Panel X <i>NN</i>	32.00 X
1	Mole side Cover 2 - <i>Cut</i>	40.00 /
		<u>302.00</u>

Special Nett Items

230
10% 207

0.00

Total Parts 302.00

Labour Charges

1	Towing	0.00
2		0.00
3		0.00
4	Workmanship to renew damage parts	<u>200.00</u>
		<u>200.00</u>

Total Parts & Labours Concluded 502.00

1-2 Days

Lumpsum repair

After repair photos

GnoRiang - 8288 0282

17/7/19

SANFU MOTOR PTE LTD

Company Reg No.: 2006124876

1 Kaki Bukit Ave 6, #02-43, AutoBay@Kaki Bukit, Singapore 417883

Direct Line: 9061 3299 Tel: (65) 6744 7753 Fax: (65) 6744 6010

Email: sanfumotor0243@gmail.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

604

Singapore 417883

ASSESSMENT FOR REPAIR : JFM 39

YAMAHA NMAX

COE EXPIRY : 12 SEP 2021

Supplementary Parts

Qty	Description	Repairer's Estimate
1	lower front panel / Lt	30.00
1	Hellamp / RAC.	300
		30.00

⑥

⑦

330

Gino Ri +

29/7/19.

560



ASSESSMENT FOR REPAIR : JFM 39

YAMAHA NMAX

COE EXPIRY :

Lump Sum / Part by Part

Qty	Description	Repairer's
		Estimate
1	Front fender / <i>cut</i>	60.00
1	Mole side cover 1 / <i>cut</i>	40.00
1	Board Footrest / <i>cut</i>	30.00
1	Side Cover / <i>cut</i>	40.00
1	Body Cowling = ?	60.00
1	Panel ?	32.00
1	Mole side Cover 2 / <i>cut</i>	40.00
		<u>302.00</u>

Special Nett Items

0.00

Total Parts 302.00

Labour Charges

1	Towing	0.00
2		0.00
3		0.00
4	Workmanship to renew damage parts	200.00
		<u>200.00</u> 100

Total Parts & Labours Concluded 502.00

1-2 Days.

Lumpsum repair.

After repair photos.

Gno@iang - 82880282

17/7/19

SANFU MOTOR PTE LTD

Company Reg No.: 200612487G

1 Kaki Bukit Ave 6, #02-43, AutoBay@Kaki Bukit, Singapore 417883

Direct Line: 9061 3299 Tel: (65) 6744 7753 Fax: (65) 6744 6010

Email: sanfumotor0243@gmail.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

0JFZ0E1C

INV 001453

No. Pendaftaran : JFM39
No. 10 : 890927025033
Nama Pemunya Berdaftar : LIEW WEI WING
Alamat : 17, JALAN PERMATANG 22 TAMAN DESA JAYA,
81100 JOHOR BAHRU JOHOR

No. Chasis/No. Enjin : PWY0351000005350 / 03E4E-0237654
Buatan/Nama Model : YAMAHA / YAMAHA NMAX
Keupayaan Enjin : 155
Bahan Bakar : PETROL
Status Asal : PEMASANGAN TEMPATAN
Kelas Kegunaan : MOTOSIKAL
Jenis Badan/Tahun Dibuat : MOTOSIKAL / 2016
Tarikh Pendaftaran : 20/12/2016
B. D. M/B. G. K/BTM : -
Syarat Pendaftaran 1 : -
Syarat Pendaftaran 2 : -
Syarat Pendaftaran 3 : -

ACCIDENT INVOLVING OUR INSURED VEHICLE JFM39 AND SCM262G ON 10/07/2019

From: Chin, Lee-Ying
To: assignments, Admin A
Cc: Fong, Andy-EY
Sent: 7/17/2019 10:55:24 AM

Attachments: [INSURANCE.pdf](#) [SINGAPORE POLICE REPORT.pdf](#) [WhatsApp Image 2019-07-12 at 12.51.17 PM.jpeg](#) [WhatsApp Image 2019-07-12 at 12.51.27 PM.jpeg](#) [LOGCARD.pdf](#) [WhatsApp](#)

Hi LKK,

Kindly assist to survey, bike in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-15 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

From: Lilian Chia [<mailto:sanfumotor0243@gmail.com>]

Sent: Friday, July 12, 2019 2:03 PM

To: AIG SGP, Claims-Survey

Cc: info@sanfumotor.com.sg; anna

Subject: [EXTERNAL] ACCIDENT INVOLVING OUR INSURED VEHICLE JFM39 AND SCM262G ON 10/07/2019

This message is from an external sender; be cautious with links and attachments.

Dear Sir,

Need to help my client make a claim, would like to know if you can arrange a **PRE-REPAIR INSPECTION** for the above bike.

I have attach the following document for your inform.

-Singapore Police Report

-Nric, Insurance

-photo and video

Hope to hear from from soon. Thank you

You may reach me at 9061 3299 (Lilian Chia)

--

Thank You

Lilian Chia | Direct line +65 9061 3299

[SANFU MOTOR PTE LTD](#)

1 Kaki Bukit Ave 6, #02-43, Autobay@Kaki Bukit, Singapore 417883

Tel: (65) 6744 7753 | Fax: (65) 6744 6010 | Co. Reg. No. 200612487G

Business Hours: Mon-Fri: 9am to 7pm | Sat: 9am to 6pm | Sun & Public Holidays Closed

Veh In - XGQ.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Thursday, 25 July 2019 4:06 PM
To: sanfumotor0243@gmail.com
Subject: ACCIDENT INVOLVING JFM 39 & SCM 262G ON 10/07/2019
Attachments: OI SKETCH PLAN.pdf

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Your Ref: JFM 39
Our Ref: CC4/AIG19012665/Geb3

Dear Sirs,

ACCIDENT INVOLVING JFM 39 & SCM 262G ON 10/07/2019

We refer to the above matter.

Please be informed that liability is unclear for this matter. Our insured driver reported that your client rear ended our insured vehicle. Enclosed herewith in this email is a copy of our insured's accident report for your perusal.

We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, we would like to request a copy of video footage/witness statement/scene photos(if any) in order for us to look into the matter.

We shall revert upon hearing from you.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To : AIG Asia Pacific Insurance Pte. Ltd.
Attn : MdNoor, Norsiah

Your Ref : 5598092275SG
Our Ref : CC4/AIG19012665/GEB3
Date : 09 Oct 2019

"WITHOUT PREJUDICE"**ACCIDENT INVOLVING SCM262G & JFM39 ON 10/07/2019**

Refer to the above accident.

The accident occurred when insured reversed and hit third party vehicle (refer to CCTV). We have clarified with the OI on the nature of the accident and he/she is aware that his/her NCD would be affected.

On behalf of AIG Asia Pacific Insurance Pte. Ltd., we have **successfully / not successfully** carried out **TP Express Settlement** between your insured (vehicle no. SCM262G) and third party claimant (vehicle no. JFM39).

Summary of offer made to workshop Sanfu Motor Pte Ltd is as follows :

	Claimed	Revised
Cost of Repairs	\$ 832.00	\$ 604.00
Loss of Use (3days)	\$ 160.00	\$ 90.00 (3days x \$30)
LTA Search Fee	\$ 2.00	\$ 2.00

Amount of claim at **Liability 100%** \$ 696.00

Our Surveyor recommended 1day repair.

Enclose herewith the relevant supporting documents for your perusal.

For your approval please.

Regards,
Asher Sng Rong Yi
LKK Auto Consultants Pte Ltd

11/11/2019

Merimen e-Claims

Print Received Message

This mail is associated with :

***JFM39 (5598092275SG)**
[SCM262G]

TP
LIEW WEI MING
Jul 10 2019 12:00AM
[LAI SING KIEW]
Sanfu Motor Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 06/11/2019 14:45 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$696.00) - JFM39 - Claim Handler: MdNoor, Norsiah

Approved: 696.00.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jul 2019 Edit Reg		17 Jul 2019 00:00 Edit Adj Rpt	\$5604.00 Edit Estimates	\$5604.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: LAI SING KIEW , ID: S2567799D									
Main Claimant: LIEW WEI MING , ID: -									
Vehicle Reg. No.: JFM39		Date of Loss: 10/07/2019 00:00 - :59 [30 Months and 20 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 5598092275SG		Policy/Cover Note No.: 1800028688 (Comprehensive)							
Vehicle Reg. No. (Insured): SCM262G		Policy No. (Claimant):							
		Excess:							
Repairer: Sanfu Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6, #02-43 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 67447753									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 29/07/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (06/11/2019): Alert - Adj Mandate Approved (\$5696.00) - JFM39 - Claim Handler: MdNoor, Norsiah - AIG_SG (19/07/2019): TP GIA REPORT									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

*JFM39 (5598092275SG)
[SCM262G]

TP
LIEW WEI MING
Jul 10 2019 12:00AM
[LAI SING KIEW]
Sanfu Motor Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Video										1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print			
1	25/07/19 16:24	JFM 39 TP VIDEO							Load MP4				
Letters/Correspondences										1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown							Edit				
Assessment Reports										1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print			
1	09/10/19 11:47	Adjuster Immediate Advice							Load HTM				
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)							Thumbnail	Print			
1	19/07/19 16:17	Accident Statement From: SC - Reg. No: SCM262G, Claimant: LAI SING KIEW							Load HTM				
Photos/Images										3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print			
1	20/09/19 14:46	General View							Load JPG	☒			
2	20/09/19 14:46	General View							Load JPG	☒			
3	20/09/19 14:46	General View							Load JPG	☒			
4	20/09/19 14:46	General View							Load JPG	☒			
5	20/09/19 14:46	General View							Load JPG	☒			
6	20/09/19 14:47	General View							Load JPG	☒			
7	20/09/19 14:47	General View							Load JPG	☒			
8	20/09/19 14:47	General View							Load JPG	☒			
9	20/09/19 14:47	General View							Load JPG	☒			
10	20/09/19 14:47	General View							Load JPG	☒			
11	20/09/19 14:47	General View							Load JPG	☒			
12	20/09/19 14:47	General View							Load JPG	☒			
13	20/09/19 14:47	General View							Load JPG	☒			
14	20/09/19 14:47	General View							Load JPG	☒			
15	20/09/19 14:47	General View							Load JPG	☒			
16	20/09/19 14:47	General View							Load JPG	☒			
17	20/09/19 14:47	General View							Load JPG	☒			
18	20/09/19 14:47	General View							Load JPG	☒			
19	20/09/19 14:47	General View							Load JPG	☒			
20	20/09/19 14:47	General View							Load JPG	☒			
21	20/09/19 14:47	General View							Load JPG	☒			
22	20/09/19 14:47	General View							Load JPG	☒			
23	20/09/19 14:47	General View							Load JPG	☒			
24	20/09/19 14:47	General View							Load JPG	☒			
25	20/09/19 14:47	General View							Load JPG	☒			
26	20/09/19 14:47	General View							Load JPG	☒			
27	20/09/19 14:47	General View							Load JPG	☒			
28	20/09/19 14:47	General View							Load JPG	☒			
29	20/09/19 14:47	General View							Load JPG	☒			
30	20/09/19 14:47	General View							Load JPG	☒			
31	20/09/19 14:47	General View							Load JPG	☒			

Video			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
32	20/09/19 14:47	General View	 Load JPG	☒
33	20/09/19 14:47	General View	 Load JPG	☒
34	20/09/19 14:47	General View	 Load JPG	☒
35	20/09/19 14:47	General View	 Load JPG	☒
36	20/09/19 14:47	General View	 Load JPG	☒
37	20/09/19 14:47	General View	 Load JPG	☒
38	20/09/19 14:47	General View	 Load JPG	☒
39	20/09/19 14:47	General View	 Load JPG	☒
40	20/09/19 14:47	General View	 Load JPG	☒
41	20/09/19 14:47	General View	 Load JPG	☒
42	20/09/19 14:47	General View	 Load JPG	☒
43	20/09/19 14:47	General View	 Load JPG	☒
44	20/09/19 14:47	General View	 Load JPG	☒
45	20/09/19 14:47	General View	 Load JPG	☒
46	20/09/19 14:47	General View	 Load JPG	☒
47	20/09/19 14:47	General View	 Load JPG	☒
48	20/09/19 14:47	General View	 Load JPG	☒
49	20/09/19 14:47	General View	 Load JPG	☒
50	20/09/19 14:47	General View	 Load JPG	☒
51	20/09/19 14:47	General View	 Load JPG	☒
52	20/09/19 14:47	General View	 Load JPG	☒
53	20/09/19 14:47	General View	 Load JPG	☒
54	20/09/19 14:47	General View	 Load JPG	☒
55	20/09/19 14:47	General View	 Load JPG	☒
56	20/09/19 14:47	General View	 Load JPG	☒
57	20/09/19 14:47	General View	 Load JPG	☒
58	20/09/19 14:48	Dismantled Parts	 Load JPG	☒
59	20/09/19 14:48	Dismantled Parts	 Load JPG	☒
60	20/09/19 14:48	Dismantled Parts	 Load JPG	☒
61	20/09/19 14:48	Dismantled Parts	 Load JPG	☒
62	20/09/19 14:48	Dismantled Parts	 Load JPG	☒
63	20/09/19 14:48	Dismantled Parts	 Load JPG	☒
64	20/09/19 14:48	Dismantled Parts	 Load JPG	☒
65	20/09/19 14:48	Dismantled Parts	 Load JPG	☒
66	20/09/19 14:48	Dismantled Parts	 Load JPG	☒
67	20/09/19 14:48	Dismantled Parts	 Load JPG	☒
68	20/09/19 14:48	Dismantled Parts	 Load JPG	☒
69	20/09/19 14:48	Dismantled Parts	 Load JPG	☒
70	20/09/19 14:48	Dismantled Parts	 Load JPG	☒
71	20/09/19 14:48	Dismantled Parts	 Load JPG	☒
72	20/09/19 14:48	Dismantled Parts	 Load JPG	☒
73	20/09/19 14:48	Dismantled Parts	 Load JPG	☒
74	20/09/19 14:48	Dismantled Parts	 Load JPG	☒
75	20/09/19 14:48	Dismantled Parts	 Load JPG	☒
76	20/09/19 14:48	Dismantled Parts	 Load JPG	☒
77	20/09/19 14:48	Dismantled Parts	 Load JPG	☒
78	20/09/19 14:48	Dismantled Parts	Load JPG	☒
79	20/09/19 14:48	Dismantled Parts	Load JPG	☒
80	20/09/19 14:48	Dismantled Parts	Load JPG	☒
81	20/09/19 14:48	Dismantled Parts	Load JPG	☒
82	20/09/19 15:07	After Repair Photo	Load JPG	☒
83	20/09/19 15:07	After Repair Photo	Load JPG	☒
84	20/09/19 15:07	After Repair Photo	Load JPG	☒
85	20/09/19 15:07	After Repair Photo	Load JPG	☒
86	20/09/19 15:07	After Repair Photo	Load JPG	☒
87	20/09/19 15:07	After Repair Photo	Load JPG	☒

Video				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/07/19 10:40	EMAIL FROM AIG DD 17072019		Load PDF	
2	23/07/19 10:40	LOG CARD		Load PDF	
3	23/07/19 10:40	INS CERT		Load PDF	
4	23/07/19 10:40	TP POLICE REPORT		Load PDF	
5	23/07/19 19:15	TP ESTIMATE- MARKED		Load PDF	
6	25/07/19 16:29	LETTER TO OI		Load PDF	
7	09/10/19 11:43	TP LOD		Load PDF	
8	20/11/19 08:26	WORKSHOP INVOICE		Load PDF	
9	20/11/19 08:26	AUTHORISATION TO ACT FORM		Load PDF	
10	20/11/19 08:26	Release Voucher		Load PDF	
11	20/11/19 08:26	LOD		Load PDF	
12	20/11/19 08:26	GIA SEARCH		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SCM262G (Insd veh)	Model:	YAMAHA NMAX155 155CC
	JFM39 (TP veh)		
Date of Accident:	10/07/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	832.00
Final Repair Cost	:	\$	604.00
Loss of Use	:	\$	90.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	696.00

3.00 days at \$30.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Sanfu Motor Pte Ltd	:	\$ 696.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

20 Nov
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19012665/GEB3Q2

Date: 20/11/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800028688
 Claimant: JFM39 Insured Vehicle No : SCM262G
 Vehicle No : JFM39 Date of Loss: 10/07/2019 Nature of Claim: TP Claim No: 5598092275SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: JFM39
 Make & Model: YAMAHA NMAX155, 155cc Engine No: G3E4E0237654
 Reg. Date: 20/12/2016 (Man. Year: 2016) Chassis No: PMYSG3510G0005350
 Colour: Grey Odometer: 0 km
 Engine Capacity: 155 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/80-14 Rear Tyre Size: 140/70-14
 Front Left Side: Timsun 5 mm Rear Left Side: Timsun 5 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	632.00	504.00	128.00	20.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	200.00	100.00	100.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	832.00	604.00	228.00	27.40
+ Loss of Use (3.0 x S\$30.00/day) (S\$)		90.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		696.00		

INSPECTION

Date of Assignment: 17/07/2019
 Date Inspected: 17/07/2019 Inspected At: Sanfu Motor Pte Ltd (Kaki Bukit)
 1 Kaki Bukit Ave 6, #02-43 Autobay @
 Kaki Bukit
 Singapore 417883

Estimated Period of Repair: 1.0 days

Adjuster: XING GUO QIANG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cut	60.00 F	*60.00 FL
2	1		*MOLE SIDE COVER 1	Cut	40.00 F	*40.00 FL
3	1		*BOARD FOOTREST	Cut	30.00 F	*30.00 FL
4	1		*SIDE COVER	Not Necessary	40.00 F	*- FL
5	1		*BODY COWLING	Cut	60.00 F	*60.00 FL
6	1		*PANEL	Not Necessary	32.00 F	*- FL
7	1		*MOLE SIDE COVER 2	Cut	40.00 F	*40.00 FL
8	1		*LOWER FRONT PANEL	Cut	30.00 F	*30.00 FL
9	1		*HEADLAMP	Broken	300.00 F	*300.00 FL

F=Franchise part, L=ListItemDisc.

Sub Total (S\$)	632.00	560.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	56.00
Total Parts (S\$)	632.00	504.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING (NPA)	New	0.00	-
2	WORKMANSHIP TO RENEW DAMAGE PARTS	New	200.00	100.00
Gross Labour Cost (S\$)			200.00	100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >