

Asher.

Surveyor

62

REF:

Alg.

# ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

29/7 finalised \$ 604 with Lillian

31/7 finalised \$ 505 with Lillian

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Report Format :

Lump Sum / I.B.I.: (\$

Veh No.

IFM 39

Yr Regn:

20 Re-16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha Nmax

C.C

155

Colour

Grey

A/C: Insured / Std / NI / NA

Sp Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

PMYG3510G 000 5350

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

110 / 80 - 14

R:

140 / 70 - 14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

TIM SUN

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

17-07-19

Survey held at

w/s

5pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

and

The U/C / Chassis frame / Body Structure affected due to collision.

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) \$ + RS. \$

) Photos

) Others

TOTAL



**ASSESSMENT FOR REPAIR : JFM 39**

**YAMAHA NMAX**

**COE EXPIRY : 12 SEP 2021**

**Supplementary Parts**

| <u>Qty</u> | <u>Description</u>      | <u>Repairer's<br/>Estimate</u> |
|------------|-------------------------|--------------------------------|
| 1          | lower front panel / Cat | 30.00 ⑥                        |
| 1          | Headlamp / RAC.         | 300 ⑦                          |
|            |                         | <u>330.00</u>                  |

10% : 27

Gum Ri ng

29/7/19



**ASSESSMENT FOR REPAIR : JFM 39**  
**YAMAHA NMAX**  
**COE EXPIRY :**

~~Lump Sum~~ / Part by Part

| Qty | Description                | Repairer's Estimate |
|-----|----------------------------|---------------------|
| 1   | Front fender / Cut         | 60.00 /             |
| 1   | Mole side cover 1 / Cut    | 40.00 /             |
| 1   | Board Footrest / Cut       | 30.00 /             |
| 1   | Side Cover X <del>AN</del> | 40.00 X             |
| 1   | Body Cowling = 1 / Cut     | 60.00 /             |
| 1   | Panel X <del>AN</del>      | 32.00 X             |
| 1   | Mole side Cover 2 / Cut    | 40.00 /             |
|     |                            | <u>302.00</u>       |
|     |                            | 230 120             |
|     |                            | 10%: 207 108        |
|     |                            | 0.00                |

Special Nett Items

Total Parts

302.00

Labour Charges

|   |                                   |               |
|---|-----------------------------------|---------------|
| 1 | Towing                            | 0.00          |
| 2 |                                   | 0.00          |
| 3 |                                   | 0.00          |
| 4 | Workmanship to renew damage parts | 200.00 100    |
|   |                                   | <u>200.00</u> |

Total Parts & Labours Concluded

502.00

Total: 600  
505

1-2 Days.

~~Lump Sum Repair~~

After repair photos.

Gno@Riang - 8288 0282

12/7/19

SANFU MOTOR PTE LTD

Company Reg No.: 2006124876

1 Kaki Bukit Ave 6, #02-43, AutoBay@Kaki Bukit, Singapore 417883

Direct Line: 9061 3299 Tel: (65) 6744 7753 Fax: (65) 6744 6010

Email: sanfumotor0243@gmail.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: