



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref: CS3/SPF18015023/Grd3s2

ACCIDENT CLAIM SECTION(SINGAPORE POLICE
FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD
POLICE ACADEMY SINGAPORE 298333

Date: 03-09-2018



ATTN: FRANKIE

Code: SPF

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GZ 3371P	Veh. Inspected	GU 4394T
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/098	Excess (\$)	0.00
Assign From	FRANKIE	Assign Date	17/08/2018

2. Vehicle Particulars & Condition

Make & Model	NISSAN CABSTAR	c.c	3153
Engine No.	HIDDEN	Year of Reg.	2001
Chassis No.	JN1SF4F23Z0843811	Colour	SILVER
Odometer	287365 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	MAXXIS	5 mm
L/H Front Tyre	195 R15	MAXXIS	5 mm
R/H Rear Tyre	155 R12	MAXXIS	5 mm
L/H Rear Tyre	155 R12	MAXXIS	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/08/2018	Inspect Date / Time	17/08/2018 (05:45 PM)
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------

15/9/18

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. GU 4394T

Qty	Description of Parts	Condition	Recommended (\$)
	<u>REPLACEMENT OF PARTS</u>		
1	FRT BUMPER	CUT	663.60
1	FRT LH SIDE LAMP	CRACKED	156.80
1	WIPER PANEL GARNISH	CUT	390.70
1	FRT WINDSCREEN RUBBER	CUT	108.70
1	FRT WING MIRROR STAY	BROKEN	185.30
1	FRT LH DOOR (NPA)	TO REPAIR SEE LABOUR	-
1	FRT STEP PANEL TOP GARNISH	CUT	184.20
	LESS 10% DISCOUNT		-168.93
			1,520.37
	<u>LABOUR</u>		
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRT LH DOOR.		200.00
	SPRAY PAINT.		300.00
	WIRING.		30.00
	REMOVE & REFIT WINDSCREEN.		120.00
			650.00
	GRAND TOTAL		2,170.37

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)	1,700.00
---	-----------------

Report Ref No. CS3/SPF18015023/Grd3s2

XING GUO QIANG**M.MATAI, AMSAE-A****Automotive Assessor****K.K.LAU CPT(RET)****BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE****REGD Auto Consultant-SAE, Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.