



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 218A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER FOR BUMPER PRIMED (SN)	TO REPAIR SEE LABOUR	1,144.79	-
1	SPOILER SATIN BLACK (SN)	SERVICEABLE	252.03	-
1	ATTACHMENT STRIP (SN)	SERVICEABLE	178.03	-
1	FOAM INSERT (SN)	SERVICEABLE	126.41	-
1	BUMPER BRACKET (BUMPER REINFORCEMENT) (SN)	SERVICEABLE	754.12	-
1	GUIDE PIECE (LHS) (SN)	SERVICEABLE	76.72	-
2	SENSOR BRACKET (SN)	SERVICEABLE	38.96	-
2	SENSOR BRACKET (SN)	SERVICEABLE	38.96	-
1	SENSOR BRACKET PRIMED (SN)	SERVICEABLE	19.48	-
1	SENSOR BRACKET PRIMED (SN)	SERVICEABLE	19.48	-
1	BONDING AGENT FOR PLASTIC (SN)	SERVICEABLE	56.90	-
1	2K-PLASTIC ADHESIVE (SN)	SERVICEABLE	74.29	-
1	REAR TRUNK LID (SN)	BENT	2,734.69	2,734.69
1	INSCRIPTION CHROME (SHARAN) (SN)	NECESSARY	83.72	83.72
1	INSCRIPTION CHROME / RED / RE (SN)	NECESSARY	70.02	70.02
1	2K-GLASS GLUE APPLICATION (SN)	NECESSARY	123.02	123.02
1	PRIMER (SN)	NECESSARY	25.92	25.92
1	ACTIVATOR FOR PRECOATED W (SN)	NECESSARY	23.63	23.63
1	ADHESIVE REMOVER (SN)	NECESSARY	115.74	115.74
2	APPLICATOR (SN)	NECESSARY	18.96	18.96
2	RIVETTED CAP NUT (SN) (ADDITIONAL)	NECESSARY	3.76	3.76
1	RR NUMBER PLATE PACKING (SN) (ADDITIONAL)	NECESSARY	27.03	27.03
1	3RD BRAKE LIGHT (SN) (ADDITIONAL)	NECESSARY	208.66	208.66
1	VW SIGN CHROME COLORED / BI (SN) (ADDITIONAL)	NECESSARY	95.25	95.25
			6,310.57	3,530.40
	<u>LABOUR</u>			
	DIAGNOSTIC AND PROGRAMMING.		480.00	480.00
	CHECK SHORT CIRCUIT / HARNESS REPAIR HARNESS REPAIR AND SHORT CIRCUIT CHECK.	NOT NECESSARY	280.00	-
	SPRAY PAINTING.		3,200.00	1,600.00

Report Ref No. CS/GAI19012696/R1vf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RE+REINSTALLED REAR WSCREEN.		840.00	840.00
	TRANSFER BOOTLID PARTS.		840.00	420.00
	LABOUR. INCLUSIVE OF THE REPAIR OF COVER FOR BUMPER PRIMED.		3,360.00	1,680.00
			9,000.00	5,020.00
GRAND TOTAL			15,310.57	8,550.40
RECOMMENDED COST OF REPAIRS				8,550.40

Report Ref No. CS/GAI19012696/R1vf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.