

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 1831K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT FENDER INNER SHIELD	CUT	123.60	123.60
1	RH DOOR	BUCKLED	825.30	825.30
	LESS 15% DISCOUNT		-142.34	-142.34
			806.56	806.56
	SPECIAL NETT ITEMS			
1	RH DOOR CO. REG STICKER (SN)	NECESSARY	25.00	25.00
1	RIM HUB (SN)	SCRATCHED	125.00	125.00
			150.00	150.00
	<u>LABOUR</u>			
	ALIGNMENT.		60.00	60.00
	REMOVE AND REINSTALL RH DOOR FITTINGS & GLASS.		60.00	40.00
	REMOVE NECESSARY PARTS:JACKING, PANEL BEATING, REPAIR AND STRAIGHTEN RH ROCKER PANEL, FRONT FENDER RH AND INSTALLATION OF THE ABOVE.		500.00	350.00
	(EXTRA) PUTTY AND RESPRAY FRONT FENDER RH, RH DOOR AND RH ROCKER PANEL.		650.00	500.00
			1,270.00	950.00
	GRAND TOTAL		2,226.56	1,906.56

RECOMMENDED COST OF REPAIRS		1,906.56
(REPAIR COST NOT CONCLUDE)		

Report Ref No. CS/SPF19012709/R1tf3e2

NOTES: THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,000

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

XXX.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.