



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGA 8222K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (CONSISTENT)	CRACKED	1,152.90	1,152.90
1	REAR BUMPER REFLECTOR LH (CONSISTENT)	CRACKED	52.65	52.65
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	TO REPAIR SEE LABOUR	492.70	-
	LESS 25% DISCOUNT		-424.56	-301.38
			1,273.69	904.17
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR REVERSING SENSOR +INSTALLATION (4 PCS) (SN) (CONSISTENT)	DENTED	250.00	250.00
			250.00	250.00
	<u>LABOUR</u>			
	TO KNOCK DENTD ON REAR END PANEL AND RENEW OF PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT .		350.00	300.00
	TO SPRAY PAINT (INCLUDING REAR BUMPER REINFORCEMENT).		400.00	350.00
			750.00	650.00
	GRAND TOTAL		2,273.69	1,804.17
	RECOMMENDED COST OF REPAIRS			1,804.17

Report Ref No. CC4/ASM19012731/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.