

22/02/2002

ASS. REC. BY:

REF:

CS/MSG 19012758/1973/72

Special Instruction:

Surveyor:

marcus

ASSIGNMENT (Office)

From (Person): Monica Chung Kai Zhen

of

MS19

Date/Time: 19.7.19 10.48a.m

Estimated Cost:

Bill to:

OD TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBF 662U

Insured:

PBF 7398B

at Workshop m/s

100 Hax Kee

Tel:

67431913

of Bk 3007 ubi road 1 #01-406

Policy No:

MSD/VMS/18-38774-CA

Claim No:

MSC/VI/19-000418

Sum Insured:

Excess:

Make of Veh:

D.O.A.

4.4.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

mp

H.O.D. Endorsement:

Date/Time:

19.7.19 11.15a.m

Person Contacted:

shi min

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GBF 662U NA/INC18019572/24 noA=26/10/18

PBF 7398B x

30/7/19 12:00pm revised to Monica Chung via Meimian.

REF: ms9

ASSIGNMENT

From: _____ Date: 29.7.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBF 6662U

at Workshop m/s Joo Hak Kee

of 3007 ubi road 1 # 01-406

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: AXR 10000.m

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 50k

IDP Accident Report: Consistent? : Yes or No

GVA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lump Sum: 1.5% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBF66624 Yr Regn: 1 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (m)

Make: Toyota hiace c.c. 2982

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 73407 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or ?

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 4/4/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/5 Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

2/8/19 27A34701
P/P #1200 confirmed with Sh. min
(Used # 1451.45, 55%)

RECEIVED 05 AUG 2019

Date/Time, File Pass to?

11/05/18 finish

Date/Time, File Return to?

2)

Report Format: MER-TP

Lump Sum / I.B.I: (\$ 1200)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

150

11

161

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 30 Jul 2019

Preliminary Advice

Insured Vehicle No : FBF7398B
TP Vehicle No : GBF6662U
Make : TOYOTA HIACE
Date of Inspection : 29/07/2019
Inspection At : JOO HAK KEE AUTO PTE LTD (HQ)
BLK 3007 UBI ROAD 1, #01-406
SINGAPORE 408701

Accident Date : 04/04/2019
Assignment Date : 19/07/2019
Est. Duration of Repair : 3.00

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,750.00
Revised Amount	:S\$	1,257.80
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,257.80
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Apr 2019		19 Jul 2019 10:48 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	KIM JOO LEE, ID: S1475456C, Tel: +6590404672, Email: NOEMAIL								
Main Claimant:	J P L T EXPRESS SERVICES, Co. Reg. No.: 52973076J								
Vehicle Reg. No.:	GBF6662U	Date of Loss:	04/04/2019 11:00 - :59 [26 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/19-000418	Policy/Cover Note No.:	MSD/VMS/18-389774-CA (TP, Fire & Theft) Coverage: 02/11/2018 - 01/11/2019						
Vehicle Reg. No. (Insured):	FBF7398B	Policy No. (Claimant):							
		Excess:							
Repairer:	Joo Hak Kee Auto Pte Ltd (HQ) Blk 3007 Ubi Road 1, #01-406, 408701 Ubi - Tel: 67431913								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 20/07/2019]								
Driver/Custodian (Insured):	KIM JOO LEE (57 / Male), NRIC: S1475456C, Tel: +6590404672 Email: NOEMAIL								
Adj Asg. Remarks:	on WP, Liab: Dispute. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Bridget @ 6743 1913.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	076J
Vehicle Details	
Vehicle No.:	GBF6662U
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA HIACE VAN TURBO 5 DR MANUAL
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	1KD2681038
Chassis No.:	JTFHT02P900215047
Maximum Power Output:	-
Open Market Value:	\$27,952.00
Original Registration Date:	24 Jan 2017
First Registration Date:	24 Jan 2017
Transfer Count:	0
Actual ARF Paid:	\$1,398.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	23 Jan 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$46,369.00
COE Rebate Amount:	\$34,701.00
Total Rebate Amount:	\$34,701.00

The information contained herein is correct as at 29 Jul 2019

OK

ATTN: MOTOR CLAIMS DEPARTMENT
 OWNER: JPLT Express Services
 TP INSURER: MSIG Insurance (Singapore) Pte Ltd
 POLICY NO: 5097363968-01
 REFERENCE: TP CLAIM
 DOA: 04/04/2019

REPAIR ESTIMATE

Est. No. : E19070012
 Date : 29/07/2019
 Vehicle Num. : GBF6662U
 Make/Model : TOYOTA, HIACE
 Chassis/Eng# : JTFHT02P900215047
 Yr. of Manu : 2016

No	Description	Qty	U/P	Amt
----	-------------	-----	-----	-----

Section: LIST ITEMS

1	RH Rear Fender	1.00	1,059.42	1,059.42 X
2	RH Sliding Door	1.00	1,249.11	1,249.11 X
3	RH Rocker Panel	1.00	795.40	795.40 X
4	RH Rear Wheel Cap	1.00	210.40	210.40 ✓

Amt S\$ 3,314.33

Discount (20.00%) S\$ 662.87

Subtotal S\$ 2,651.46

Section: LABOUR

5	To Panel Beat The Necessary Parts	1.00	800.00	800.00
6	To Sand Down, Putty and Spray Paint On Necessary Parts	1.00	950.00	950.00

Amt S\$ 1,750.00

Discount (0.00%) S\$ 0.00

Subtotal S\$ 1,750.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LIST ITEMS Subtotal S\$ 2,651.46
 LABOUR Subtotal S\$ 1,750.00
Total S\$ 4,401.46

Joo Hak Kee Auto Pte. Ltd.

BLK 3007 UBI ROAD 1 #01-406, SINGAPORE 408701
 BLK 3014 UBI ROAD 1 #01-324, SINGAPORE 408702

TEL: 6743 1913 FAX: 6743 5234
 EMAIL: admin@jhk.com.sg

CO/GST REG NO: 201300082W
 WEBSITE: www.jhk.com.sg

bizSAFE₃

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19012758/UQF3N2

Date: 07/08/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/18-389774-CA
Claimant Vehicle No :	GBF6662U	Insured Vehicle No :	FBF7398B
Date of Loss:	04/04/2019	Nature of Claim:	TP
		Claim No:	MSC/V/19-000418

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF6662U	Engine No:	1KD2681038
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Chassis No:	JTFHT02P900215047
Reg. Date:	24/01/2017 (Man. Year: 2016)	Odometer:	73407 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,651.46	100.00	2,551.46	96.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,750.00	1,100.00	650.00	37.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	4,401.46	1,200.00	3,201.46	72.74
+ GST 7.00/7.00% (\$\$)	308.10	84.00	224.10	72.74
Nett Amount (\$\$)	4,709.56	1,284.00	3,425.56	72.74

INSPECTION

Date of Assignment:	19/07/2019		
Date Inspected:	29/07/2019	Inspected At:	Joo Hak Kee Auto Pte Ltd (HQ) Blk 3007 Ubi Road 1, #01-406 Singapore 408701
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Aug 2019)
Parts:	213	TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF6662U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH REAR FENDER	Repair	1,059.42 FL	*- FL
2	1		*RH SLIDING DOOR	Repair	1,249.11 FL	*- FL
3	1		*RH ROCKER PANEL	Repair	795.40 FL	*- FL
4	1		*RH REAR WHEEL CAP	Cut	168.32 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,272.25	100.00
- List Item Discount on L Items 20.00/25.00% (\$\$)	620.79	0.00
Total Parts (\$\$)	2,651.46	100.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT THE NECESSARY PARTS.	New	800.00	600.00
2	TO SAND DOWN, PUTTY AND SPRAY PAINT ON NECESSARY PARTS.	New	950.00	500.00
Gross Labour Cost (\$\$)			1,750.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >