

ASS. REC. BY:

REF:

CS/AGI 19012761/0413<sup>n2</sup>

Special Instruction:

Surveyor: ShrinASSIGNMENT (Office)

From (Person):

Julie Mengubet

of

AGI

Date/Time:

19/7/2019 @ 11:14 am

Estimated Cost:

Bill to:

OD-IT/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 1297D

Insured:

SLK 4918B

at Workshop m/s

Chunni Motor

Tel:

65425119

of

AMK Autopoint # 01-05/06

Policy No:

Claim No:

C10003538

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

17/07/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:23 am @ 19/7/19

Person Contacted:

IreneVehicle IN / OUT

Date/Time

Action/Instruction

Example (✓)

SHA 1297DNS/NC12000395/H1gnDOA: 5/1/12SLK 4918BCS/EC117015623/uvbn2DOA: 10/5/17

ASS. REC. BY:

## ASSIGNMENT

OB June 2027

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop no: \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Scem: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

12 days

Res.: Yes or No

Lump Sum: \_\_\_\_\_

20

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: \_\_\_\_\_

SHA 1297D

Yr Regn: \_\_\_\_\_

2019 June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: \_\_\_\_\_

Hyundai Ioniq

c.c

1580

Colour: \_\_\_\_\_

Blue

AC: \_\_\_\_\_

Insured / Std / NI / NA

Sp. Reading: \_\_\_\_\_

10452

T/Radio: \_\_\_\_\_

Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

G4LEKU295286

C/Noc: \_\_\_\_\_

KMHC851CVKU164286

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orDrives: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: \_\_\_\_\_

F: \_\_\_\_\_

195/65 R15

R: \_\_\_\_\_

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Michelin

Front

Rear

R/Bal. \_\_\_\_\_

6

mm

R/Bal. \_\_\_\_\_

6

mm

L/Bal. \_\_\_\_\_

6

mm

L/Bal. \_\_\_\_\_

6

mm

D.O.A. \_\_\_\_\_

17/07/2019

D.O.J. \_\_\_\_\_

19/07/2019

Survey held at \_\_\_\_\_

Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Front &amp; Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Auto 4 General SLK 4918B

Invoice 2/5 20000/- with 12 days of run  
 (Red. 14370.06 / 41%)

RECEIVED 06 SEP 2019

Date/Time, File Pass to?

1) 6/9 Typist

Date/Time, File Return to?

2)

Report Format: \_\_\_\_\_

TP

Lump Sum / I.B.I. (\$) 20,000/-

Days Of Repair: \_\_\_\_\_

12

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: \_\_\_\_\_

☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

3 + RS, 50

Photos

Others

TOTAL

450

## Nivitha (LKK Auto)

---

**From:** Julie Mangubat <julie.m@budgetdirect.com.sg>  
**Sent:** Friday, 19 July 2019 11:14 AM  
**To:** Admin-D (LKKAuto); SUR  
**Cc:** Justin Wong  
**Subject:** TPP survey: Claim ref: C10003538/KY || OI-SLK4918B TP-SHA1297D  
**Attachments:** 18072019170611.pdf; SHA1297D-TP.pdf; SLK4918B-OI.pdf

On behalf of Justin

Hi Team

We wish to appoint LKK to do TPPD survey on TP's vehicle.

Workshop name and address: **Kindly survey at AMK Autopoint, Soon Hock Motor, #01-05/06.**

Please find attached estimates, OI and TP gia reports.

**Note: workshop prefers Rasul to survey their client's vehicle.**

Thank you,  
-Julie

**From:** Chunni Motor <chunnimotor@gmail.com>  
**Sent:** Friday, 19 July, 2019 10:36 AM  
**To:** Julie Mangubat <julie.m@budgetdirect.com.sg>  
**Cc:** Justin Wong <justin.wong@budgetdirect.com.sg>  
**Subject:** Re: Accident involving veh no: SHA 1297D & SLK 4918B on 17.07.19 || Claim ref: C10003538/KY

Dear Sir,

We appoint LKK Auto Consultants P/L (Rasul)

Thank you

Regards,  
Chunni Motor Work P/L

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

MCD610054053 / ComfortDaiGoo Engineering Pte Ltd - Layang  
 ENTRY DATE & TIME: 18/07/2019 13:55  
 SUBMITTED BY: Janet Lim Siang Gek

## SINGAPORE ACCIDENT STATEMENT

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of this report being made available aforesaid.

**ACCIDENT STATEMENT**

Date Of Report	18/07/2019 13:55
Date Of Accident	17/07/2019 18:30
Exact Location Of Accident	SLE TOWARDS WOODLANDS BEFORE MANDAI
Country/State of Loss	SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number	SHA1297D
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
<b>Vehicle Particulars</b>	
Manufacturer	HYUNDAI
Model	IONIQ HYBRID
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088938MFSH
Cover Note Number	
<b>Driver</b>	
Name of Driver	LIM TEOW LEONG
NRIC No	S1472913E
Date Of Birth	23/05/1961
Occupation	OUTDOOR
Date Of Driving Pass	27/02/1979
Driving Experience	40 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91885062
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 210A COMPASSVALE LANE  
#06-158  
Postcode 541210  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER  
Vehicle Registration Number of Driver's Own Vehicle -  
-  
-  
Insurance Company of Driver's Own Vehicle -  
-  
-

**General Information of the Accident**

Type Of Accident CHAIN COLLISION  
Weather Conditions CLEAR  
Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
Number of vehicles (including own vehicle) involved in the accident 4  
Was any body injured in the Accident? YES  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 2  
Passenger 1  
NAME: : -  
GENDER: : MALE

**Details of Police Action**

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

**Circumstances of Accident**

REFER ATTACHED

**Attachment(s)**

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? YES  
Remarks/ Reasons: -  
Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SLK4918B  
Vehicle Make/Model/Colour TOYOTA  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver HUANG QIAN JUN  
NRIC/Passport Number G7520350R  
Contact Number  
Address  
Postcode  
Insurance Company Name

Nature Of Damage FRONT

No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number SMD2621U  
Vehicle Make/Model/Colour KIA  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver CHONG YOKE POH  
NRIC/Passport Number S7365233B  
Contact Number  
Address  
Postcode

Insurance Company Name

Nature Of Damage FRONT AND REAR

No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 3**

Vehicle Registration Number SLT5998R  
Vehicle Make/Model/Colour VOLKSWAGEN  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver LAW GEOK MEI  
NRIC/Passport Number S8560336A  
Contact Number 93255889  
Address  
Postcode

Insurance Company Name

Nature Of Damage REAR

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name LIM TEOW LEONG  
Approximate Age  
Injuries Sustain HEAD, NECK AND BACK  
Injured person in which vehicle? SHA1297D  
Were seat belts worn? YES  
Was this injured conveyed to hospital by ambulance? NO  
Address  
Postcode

**SKETCH PLAN****IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time: 18.07.2019

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 18.07.2019@13:hrs

Lisa  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## SKETCH PLAN



A-SHA 1297D

B-SLK 4918B

C-SMD 2621U

D-SLT 5998R

Along SLE TWDS Woodlands Before Mandai

Describe Circumstances of the Accident

On 17/07/2019 @ 18:30hrs.I was travelling along SLE towards Woodlands before Mandai.With 1 male passenger onboard.(is Mr Wong,Hp no:9747 5959)

I was on the extreme RH lane 1 ,I saw infront of my vehicles slowing down,So I follow too.Out of sudden,there was a loud impact coming from the rear portion and caused my taxi (A),to lose control and surge forward,and colliding onto veh (C ) rear portion.My taxi (A) front and rear portion was damaged.

I assessed the damages to my taxi (A) and come to know that there were 4 vehicles involved in the chain accident.

After the accident,I felt pain on my head,neck,back,will seek doctor later on.

The parties involved in the accident are:

A-SHA 1297D

B-SLK 4918B Mr Huang Qian Jun.G 7520350R.

C-SMD 2621U Mr Chong Yoke Poh.S 7365233B.

D-SLT 5998R Ms Law Geok Mei.S 8560336A.Hp:9325 5889.

## Declaration

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

policyholder's Signature  
Date & Time 18.07.2019

Driver's Signature(If driver is not the policyholder)  
Date & Time : 18.07.2019@13:20hrs

Reporting Centre Personnel's Signature  
Name :  
NRIC/FIN No :

Lisa



**CHUNNI MOTOR WORK PTE LTD****REPAIR ESTIMATE\***

VEHICLE NO : SHA 1297D

DATE : 18.07.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI IONIQ

FAX : 6542 6039

Auto &amp; General

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Radiator Grille broken			\$ 1,227.50	✓
	Sensor Assy -Parking NH			\$ 140.20	X
	Ultrasonic Sensor NH			\$ 132.00	X
	Unit Assy-SMART CRU (Radar Sensor) broken mounting			\$ 2,910.90	✓
	Front Bumper Cover broken/damaged			\$ 418.30	✓
	Front Bumper Sponge torn			\$ 86.90	✓
	Front Bumper Reinforcement Dented			\$ 1,075.10	✓
	Front Bumper Centre Moulding S/C			\$ 188.00	X
	Front Bumper Moulding (LH/RH) NH	\$	93.60	\$ 187.20	X
	Front Bumper Lower Stiffener NH			\$ 85.10	X
	Front Bumper Bracket Top (LH/RH) NH	\$	35.00	\$ 70.00	X
	Front Bumper Bracket (LH/RH) NH	\$	28.00	\$ 56.00	X
	Front Bumper Side Bracket Support NH	\$	12.00	\$ 24.00	X
	Front Bumper Clips 10 pcs NH			\$ 22.00	✓
	Headlamp Support Panel Assy CRACK			\$ 949.30	✓
	Headlamp (LH/RH) CRACK / mostly broken	\$	1,198.80	\$ 2,397.60	✓
	Radiator Inverter NH 15T			\$ 884.80	X ✓
	Radiator NH 15T			\$ 510.50	X ✓
	Radiator Air Guard (LH/RH) NH	\$	26.40	\$ 52.80	X
	Aircon Condenser NH 15T			\$ 663.60	X ✓
			11146.50		
			8917.20		
	SUB TOTAL			\$ 12,081.80	
	LESS 20%			\$ 2,416.36	
	DISCOUNTED TOTAL			\$ 9,665.44	
	Front Number Plate CRACK			\$ 25.00	Nett ✓
	Front No Plate Trim Cover 15T			\$ 30.00	Nett ✓
	Front Number Plate Garnish NH 15T			\$ 99.00	Nett X ✓
			144.00		
				\$ 154.00	
	Labour Charge				
	Panel Beating			\$ 1,000.00	600/-
	Spray Painting Charge			\$ 250.00	200/-
	Wiring Charge			\$ 50.00	50/-
	Towing Charge			\$ 90.00	NH
	Remove/Refix Aircon & Refill Gas			\$ 150.00	NH 80/-
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00	150/-
			1230.00		320/-
	TOTAL LABOUR			\$ 2,020.00	

SHA 1297D

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>1st</i>			\$ 2,480.40
	Boot Lid Hinge (LH/RH) <i>NH</i>		\$ 31.30	\$ 62.60
	Boot Lid Lock Upper <i>DM</i>			\$ 224.00
	Boot Lid 'H' Emblem <i>NH</i>			\$ 28.00
	Emblem -Hybrid <i>NH</i>			\$ 24.30
	Emblem -Ioniq <i>NH</i>			\$ 31.30
	Emblem -Blue Drive (LH/RH) <i>NH</i>		\$ 26.60	\$ 53.20
	Boot Lid Glass, Upper <i>NH</i>			\$ 543.30
	Boot Lid Glass, Lower <i>NH</i>			\$ 384.90
	Boot Lid Lamp (LH/RH) <i>1st mndy crack / scratched</i>		\$ 794.40	\$ 1,588.80
	Boot Lid Trimboard <i>NH</i>			\$ 159.70
	Boot Lid Trimboard Clips (10pcs) <i>NH</i>			\$ 11.00
	Rear Bumper <i>broken</i>			\$ 459.40
	Rear Bumper Reinforcement <i>broken</i>			\$ 294.80
	Rear Bumper Reinforcement Bracket (LH/RH) <i>Painted</i>		\$ 138.10	\$ 276.20
	Rear Bumper Centre Moulding Assy <i>broken</i>			\$ 451.25
	Rear Bumper Lower Centre Moulding Assy <i>Cut</i>			\$ 47.50
	Rear Bumper Stay <i>NH</i>			\$ 138.10
	Rear Bumper Side Bracket (LH/RH) <i>NH</i>		\$ 33.10	\$ 66.20
	Rear Bumper Cover Clips <i>NH</i>			\$ 22.00
	Rear Bumper Under Centre <i>destroyed / broken</i>			\$ 53.85
	Rear Bumper Reflector Lamp (LH/RH) <i>o/s broken</i>		\$ 31.90	\$ 63.80
	Tail Lamp (LH/RH) <i>white / broken mndy</i>		\$ 870.40	\$ 1,740.80
	Rear Panel <i>Base</i>			\$ 532.00
	Rear Panel Garnish <i>destroyed</i>			\$ 155.00
	Rear Panel Lower Panel <i>NS</i>		\$ 39.40	\$ 78.80
	Spare Tyre Holder <i>1st</i>			\$ 75.80
	Spare Tyre Panel <i>Base</i>			\$ 892.50
	Spare Tyre Panel Cushion <i>NH</i>			\$ 288.00
	Rear Towing Hook <i>NH</i>			\$ 94.60
	Rear Floor Chassis Member <i>NH</i>			\$ 2,332.60
	Spare Tyre Flip Board <i>NH</i>			\$ 338.80
	Exhaust Pipe Insulator <i>NH</i>			\$ 35.00
	Exhaust Silencer <i>Painted</i>			\$ 943.50
	Exhaust Pipe Hanger <i>NH</i>			\$ 29.20
	Exhaust Pipe Centre <i>NH</i>			\$ 573.60
	Rear Fender (LH/RH) <i>Painted</i>		\$ 1,768.30	\$ 3,536.60
	Rear Fender Inner Lining (LH/RH) <i>NH</i>		\$ 73.60	\$ 147.20
	Rear Windscreen Glass <i>NH</i>			\$ 607.20
	Rear Windscreen Moulding <i>NH</i>			\$ 28.20
			13889.90	
			11111.92	
	SUB TOTAL			\$ 19,894.00
	LESS 20%			\$ 3,978.80
	DISCOUNTED TOTAL			\$ 15,915.20

SHA 1297D

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid Comfort Logo & Tel No. Sticker <i>Nec</i>			\$ 30.00	Nett ✓
	Rear No. Plate <i>dislodged / broke</i>			\$ 25.00	Nett ✓
	Rear Bumper Reverse Sensor <i>Down</i>			\$ 135.70	Nett ✓
	Rear Bumper Rubber Mat <i>HF</i>			\$ 50.00	Nett X
	Rear Windscreen Sealant <i>Nec</i>		1136.70	\$ 46.00	Nett ✓
	Rear Reverse Camera <i>Shorten / Down</i>			\$ 900.00	Nett ✓
				\$ 1,186.70	
	<b>Labour Charge</b>				
	Panel Beating			\$ 1,800.00	900/-
	Spray Painting Charge			\$ 1,500.00	800/-
	Wiring Charge			\$ 50.00	30/-
	Tuff Kote			\$ 50.00	40/-
	Rear Chassis Alignment Charge			\$ 400.00	N/A
	Remove/Refix Cushion & Upholstery Rear		2070.00	\$ 150.00	120/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00	80/-
	Remove/Refix Reverse Sensor			\$ 120.00	40/-
	Remove/Refix Exhaust Pipe			\$ 150.00	60/-
	<b>TOTAL LABOUR</b>			\$ 4,340.00	
	<b>ESTIMATE TOTAL</b>			\$ 33,281.34	
	19/07/2019 @ 1130hr		24609.82	34370.06	
	LIA Andrew		466.72		
	2/5mth 12 days.		25076.54		
	<i>Ryan</i>		1/320000/-		
	LKK Auto				
	<p><b>LKK Auto Consultants</b> hereby notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged parts during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer Signature:</p>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

CHUNNI MOTOR WORK PTE LTD

**REPAIR ESTIMATE\***

VEHICLE NO : SHA 1297D (Supplementary)



DATE : 20.07.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI IONIQ

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Speaker Assy- VESS <i>Dented</i>			\$ 354.40
	Lamp Assy -Rear Fog <i>broken</i>			\$ 201.50
	Spare Tyre Lock Nut <i>replaced</i>		555.90	\$ 88.00
	SUB TOTAL		444.72	\$ 643.90
	LESS 20%			\$ 128.78
	DISCOUNTED TOTAL			\$ 515.12
	<div><div></div><div>24/07/2019</div><div>2kk Auto</div><div></div></div>			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
<b>AUTO &amp; GENERAL INSURANCE (S) PL</b>  (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref : CS/AGI19012761/Dtf3n2  Date : 10-09-2019  Code : AGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
<b>Insured Veh.</b>	SLK 4918B	<b>Veh. Inspected</b>	SHA 1297D
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	C10003538/KY	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	JULIE MANGUBAT	<b>Assign Date</b>	19/07/2019
<b>2. Vehicle Particulars &amp; Condition</b>			
<b>Make &amp; Model</b>	HYUNDAI IONIQ	<b>c.c</b>	1580
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2019
<b>Chassis No.</b>	KMHC851CVKU164286	<b>Colour</b>	BLUE
<b>Odometer</b>	10452	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>			
	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	195/65 R15	MICHELIN	6 mm
<b>L/H Front Tyre</b>	195/65 R15	MICHELIN	6 mm
<b>R/H Rear Tyre</b>	195/65 R15	MICHELIN	6 mm
<b>L/H Rear Tyre</b>	195/65 R15	MICHELIN	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
<b>Accident Date</b>	17/07/2019	<b>Inspection Date</b>	19/07/2019
<b>Survey held at</b>	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>		<b>12 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 1297D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	RADIATOR GRILLE	BROKEN	1,227.50	1,227.50
1	SENSOR ASSY-PARKING	NOT NECESSARY	140.20	-
1	ULTRASONIC SENSOR	NOT NECESSARY	132.00	-
1	UNIT ASSY-SMART CRU (RADAR SENSOR)	MOUNTING BROKEN	2,910.90	2,910.90
1	FRONT BUMPER COVER	BROKEN / DISTORTED	418.30	418.30
1	FRONT BUMPER SPONGE	TORN	86.90	86.90
1	FRONT BUMPER REINFORCEMENT	DENTED	1,075.10	1,075.10
1	FRONT BUMPER CENTRE MOULDING	SERVICEABLE	188.00	-
2	FRONT BUMPER MOULDING (LH/RH) @\$93.60	NOT NECESSARY	187.20	-
1	FRONT BUMPER LOWER STIFFNER	NOT NECESSARY	85.10	-
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$35.00	NOT NECESSARY	70.00	-
2	FRONT BUMPER BRACKET (LH/RH) @\$28.00	NOT NECESSARY	56.00	-
2	FRONT BUMPER SIDE BRACKET SUPPORT @\$12.00	NOT NECESSARY	24.00	-
10	FRONT BUMPER CLIPS	NECESSARY	22.00	22.00
1	HEADLAMP SUPPORT PANEL ASSY	CRACKED	949.30	949.30
2	HEADLAMP (LH/RH) @\$1198.80	CRACKED / MOUNTING BROKEN	2,397.60	2,397.60
1	RADIATOR INVERTER	BENT	884.80	884.80
1	RADIATOR	BENT	510.50	510.50
2	RADIATOR AIR GUARD (LH/RH) @\$26.40	NOT NECESSARY	52.80	-
1	AIRCON CONDENSER	BENT	663.60	663.60
1	BOOT LID	BENT	2,480.40	2,480.40
2	BOOT LID HINGE (LH/RH) @\$31.30	NOT NECESSARY	62.60	-
1	BOOT LID LOCK UPPER	DAMAGED	224.00	224.00
1	BOOT LID "H" EMBLEM	NECESSARY	28.00	28.00
1	EMBLEM-HYBRID	NECESSARY	24.30	24.30
1	EMBLEM-IONIQ	NECESSARY	31.30	31.30
2	EMBLEM-BLUE DRIVE (LH/RH) @\$26.60	NOT NECESSARY	53.20	-
1	BOOT LID GLASS,UPPER	NOT NECESSARY	543.30	-
1	BOOT LID GLASS,LOWER	NOT NECESSARY	384.90	-
2	BOOT LID LAMP (LH/RH) @\$794.40	MOUNTING CRACKED / SCRATCHED	1,588.80	1,588.80

Report Ref No. CS/AGI19012761/Dtf3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT LID TRIMBOARD	NOT NECESSARY	159.70	-
10	BOOT LID TRIMBOARD CLIPS	NOT NECESSARY	11.00	-
1	REAR BUMPER	BROKEN	459.40	459.40
1	REAR BUMPER REINFORCEMENT	BROKEN	294.80	294.80
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$138.10	DENTED	276.20	276.20
1	REAR BUMPER CENTRE MOULDING ASSY	BROKEN	451.25	451.25
1	REAR BUMPER LOWER CENTRE MOULDING ASSY	CUT	47.50	47.50
1	REAR BUMPER STAY	NOT NECESSARY	138.10	-
2	REAR BUMPER SIDE BRACKET (LH/RH) @\$33.10	NOT NECESSARY	66.20	-
10	REAR BUMPER COVER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER UNDER CENTRE	DISLODGE / BROKEN	53.85	53.85
2	REAR BUMPER REFLECTOR LAMP (LH/RH) @\$31.90	O/S BROKEN / N/S NOT NECESSARY	63.80	31.90
2	TAIL LAMP (LH/RH) @\$870.40	CRACKED / MOUNTING BROKEN	1,740.80	1,740.80
1	REAR PANEL	BUCKLED	532.00	532.00
1	REAR PANEL GARNISH	DEFORMED	155.00	155.00
2	REAR PANEL LOWER PANEL @\$39.40	NO SUCH PARTS	78.80	-
1	SPARE TYRE HOLDER	BENT	75.80	75.80
1	SPARE TYRE PANEL	BUCKLED	892.50	892.50
1	SPARE TYRE PANEL CUSHION	NOT NECESSARY	288.00	-
1	REAR TOWING HOOK	NOT NECESSARY	94.60	-
1	REAR FLOOR CHASSIS MEMBER	NOT NECESSARY	2,332.60	-
1	SPARE TYRE FLIP BOARD	NOT NECESSARY	338.80	-
1	EXHAUST PIPE INSULATOR	NOT NECESSARY	35.00	-
1	EXHAUST SILENCER	DENTED	943.50	943.50
1	EXHAUST PIPE HANGER	NOT NECESSARY	29.20	-
1	EXHAUST PIPE CENTRE	NOT NECESSARY	573.60	-
2	REAR FENDER (LH/RH) @\$1768.30	DENTED	3,536.60	3,536.60
2	REAR FENDER INNER LINING (LH/RH) @\$73.60	NOT NECESSARY	147.20	-
1	REAR WINDSCREEN GLASS	NOT NECESSARY	607.20	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	28.20	-
1	SPEAKER ASSY-VESS (ADDITIONAL)	DENTED	354.40	354.40
1	LAMP ASSY-REAR FOG (ADDITIONAL)	BROKEN	201.50	201.50
1	SPARE TYRE LOCK NUT (ADDITIONAL)	REPEATED	88.00	-

Report Ref No. CS/AGI19012761/Dtf3n2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	KEYLESS ENTRY ANTENNE (ADDITIONAL)	NOT NECESSARY	689.50	-
1	REAR BUMPER SIDE UNDER (RH) (ADDITIONAL)	DEFORMED / BROKEN	27.50	27.50
	LESS 20% DISCOUNT		-6,667.34	-5,123.96
			26,669.36	20,495.84
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT NO PLATE TRIM COVER (SN) }	BENT	30.00	45.00
1	FRONT NUMBER PLATE (SN) }	CRACKED	25.00	-
1	FRONT NUMBER PLATE GARNISH (SN)	BENT	99.00	99.00
1	BOOT LID COMFORT LOGO & TEL NO STICKER (SN)	NECESSARY	30.00	30.00
1	REAR NO PLATE (SN)	DISLODGE / BROKEN	25.00	25.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	135.70	135.70
1	REAR BUMPER RUBBER MAT (SN)	NOT FITTED	50.00	-
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR REVERSE CAMERA (SN)	SHORTED / DAMAGED	900.00	900.00
			1,340.70	1,280.70
	<b><u>LABOUR</u></b>			
	PANEL BEATING.		2,800.00	1,500.00
	SPRAY PAINTING CHARGE.		1,750.00	1,000.00
	WIRING CHARGE.		100.00	60.00
	TOWING CHARGE.	NOT NECESSARY	90.00	-
	REMOVE/REFIX AIRCON & REFILL GAS.		150.00	80.00
	DIAGNOSTIC RESETTING TO ERASE FAULT CODE.		480.00	320.00
	TUFF KOTE.		50.00	40.00
	REAR CHASSIS ALIGNMENT CHARGE.	NOT NECESSARY	400.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	120.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.		120.00	80.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	40.00
	REMOVE/REFIX EXHAUST PIPE.		150.00	60.00
			6,360.00	3,300.00
	<b>GRAND TOTAL</b>		<b>34,370.06</b>	<b>25,076.54</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>20,000.00</b>

Report Ref No. CS/AGI19012761/Dtf3n2



Report Ref No. CS/AGI19012761/Dtf3n2

**ANG BRYAN TANI**

Automotive Assessor / Investigator

**ADRIAN LING WAI PING**

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**