

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19012784/BEA3Q2

Date: 14/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SMC3974A **Insured Vehicle No :** SMD7586E

Date of Loss: 18/07/2019 **Nature of Claim:** TP **Claim No:** 2443082766SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC3974A		
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Engine No:	L15B5463149
Reg. Date:	29/06/2018 (Man. Year: 2018)	Chassis No:	GK81202765
Colour:	Black	Odometer:	64768 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,476.16	7,707.68	2,768.48	26.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,280.00	2,590.00	1,690.00	39.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,756.16	10,297.68	4,458.48	30.21
Approved Total (Overridden) (S\$)		8,200.00		
Nett Amount (S\$)	14,756.16	8,200.00	6,556.16	44.43
+ Car Rental (11.0 x S\$100.00/day + 7.00% GST) (S\$)		1,177.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		9,384.45		
Global Sum Settlement (S\$)		9,380.00		

INSPECTION

Date of Assignment: 18/07/2019

Date Inspected: 18/07/2019 Inspected At:

Team Autopro Pte Ltd - Sin Ming (HQ)
160 SIN MING DRIVE #02-12 SIN
MING AUTOCITY
Singapore 575722

Estimated Period of Repair: 8.0 days

Adjuster: Lim Teow Guan

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,874.00 FL	*1,300.00 FL
2	1		*TAILGATE LOGO	Necessary	51.00 FL	*51.00 FL
3	1		*TAILGATE EMBLEM SHUTTLE	Necessary	78.00 FL	*78.00 FL
4	1		*TAILGATE OUTER CHROME MOULDING	Broken	365.00 FL	*365.00 FL
5	1		*TAILGATE OUTER GARNISH	Broken	471.00 FL	*471.00 FL
6	1		*TAILGATE INNER LOCK ACTUATOR	Jammed	221.00 FL	*180.50 FL
7	1		*TAILGATE LOCK STRIKER	Bent	65.00 FL	*22.00 FL
8	1		*TAILGATE WEATHER STRIP	Distorted	176.00 FL	*176.00 FL
9	2		*TAILGATE MOTORIZED DAMPER	Not Necessary	738.00 FL	*- FL
10	1		*TAILGATE INNER TRIMBOARD	Broken	369.00 FL	*369.00 FL
11	1		*TAILGATE WINDSCREEN MOULDING	Necessary	129.00 FL	*129.00 FL
12	2		*TAILGATE REFLECTOR	Broken	710.00 FL	*710.00 FL
13	2		*REAR NO PLATE LAMP	Not Necessary	122.00 FL	*- FL
14	1		*REAR BUMPER	Crumpled	956.00 FL	*956.00 FL
15	2		*REAR BUMPER RETAINER	Necessary	182.00 FL	*182.00 FL
16	2		*REAR BUMPER BRACKET	Bent	244.00 FL	*179.00 FL
17	2		*REAR BUMPER REFLECTOR	Broken	169.00 FL	*169.00 FL
18	2		*REAR BUMPER REFLECTOR GARNISH	Broken	263.20 FL	*263.20 FL
19	2		*REAR BUMPER INNER SPONGE	Not Necessary	144.00 FL	*- FL
20	1		*REAR BUMPER TOW CAP	Cut	65.00 FL	*65.00 FL
21	1		*REAR END PANEL	Dented	512.00 FL	*512.00 FL
22	1		*REAR END PANEL TOP GARNISH	Broken	177.00 FL	*177.00 FL
23	1		*SPARE TYRE PANEL	Dented	752.30 FL	*752.30 FL
24	2		*SPARE TYRE PANEL EXTENSION PANEL	Not Necessary	484.00 FL	*- FL
25	1		*SPARE TYRE PANEL TOP BOARD	Not Necessary	287.60 FL	*- FL
26	1		*SPARE TYRE PANEL INSULATION PAD	Necessary	185.50 FL	*185.50 FL
27	1		*SPARE TYRE PANEL TOOLS TRAY	Broken	287.60 FL	*287.60 FL
28	2		*TAILLAMP	Broken	892.00 FL	*892.00 FL
29	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
30	1		*TAILGATE WINDSCREEN PRIMER AND CLEANER	Not Necessary	80.00 FS	*- FS
31	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
32	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*60.00 FS
33	1		*TAILGATE WINDSCREEN CLIPS	Necessary	50.00 FS	*30.00 FS
34	1		*TAILGATE OUTER GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
35	2		*TAILGATE REFLECTOR CLIPS	Necessary	100.00 FS	*60.00 FS
36	2		*TAILGATE REFLECTOR SEAL	Not Necessary	80.00 FS	*- FS
37	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
38	1		*TAILGATE AUTO SENSOR	Broken	250.00 FS	*250.00 FS
39	1		*TAILGATE RUBBER STRIP (PURPLE)	Necessary	30.00 FS	*30.00 FS
40	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
41	2		*TAILLAMP CLIPS	Necessary	100.00 FS	*60.00 FS
42	2		*TAILLAMP SEAL	Not Necessary	100.00 FS	*- FS
43	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
44	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
45	2		*REVERSE SENSOR C/W CONTROL MODULE	Shorted	400.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 12,670.20 9,402.10
- List Item Discount on L Items 20.00/20.00% (\$\$) 2,194.04 1,694.42

Total Parts (\$\$) 10,476.16 7,707.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R WIRE HARNESS TO FACILITATE REPAIR AND CHECK FUNCTION	New	100.00	50.00
2	R&R UPHOLSTERY	New	150.00	100.00
3	R&R REAR WINDSCREEN	New	300.00	180.00
4	R&R TAILGATE COMPONENT	New	180.00	100.00
5	R&R REVERSE SENSOR	New	150.00	60.00
6	PANEL BEAT	New	1,600.00	1,000.00
7	RUST PROOFING	New	200.00	100.00
8	SPRAY PAINTING	New	1,600.00	1,000.00
Gross Labour Cost (\$\$)			4,280.00	2,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >