

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19012788/KKA3Q2

Date: 16/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994421

Claimant
Vehicle No : SHC5216B **Insured Vehicle No :** SKJ662G

Date of Loss: 17/07/2019 Nature of Claim: TP Claim No: 8390678576SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC5216B**
 Make & Model: RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A) Engine No: M9R8839C000701
 Reg. Date: 19/02/2014 (Man. Year: 2013) Chassis No: VF1ABL15AUC276169
 Colour: Metallic White/Red Odometer: 798254 km
 Engine Capacity: 1995 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Giti 8 mm Rear Left Side: Giti 8 mm
 Front Right Side: Sailun 9 mm Rear Right Side: Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,697.45	1,904.92	13,792.53	87.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,180.00	880.00	14,300.00	94.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,877.45	2,784.92	28,092.53	90.98
Approved Total (Overridden) (S\$)		2,250.00		
(S\$)	30,877.45	2,250.00	28,627.45	92.71
+ GST 7.00/7.00% (S\$)	2,161.42	157.50	2,003.92	92.71
Nett Amount (S\$)	33,038.87	2,407.50	30,631.37	92.71
+ Car Rental (2.0 x S\$81.13/day) (S\$)		162.26		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		2,577.25		
Global Sum Settlement (S\$)		2,570.00		

INSPECTION

Date of Assignment: 18/07/2019

Date Inspected: 18/07/2019 Inspected At:

Trans-Cab Auto Services Pte Ltd (HQ)
2 Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: HOW MEI KWAN**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Buckled /Dented	1,259.42 FL	*1,259.42 FL
2	1		*BUMPER SPOILER FRT	Serviceable	181.75 FL	*- FL
3	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*- FL
4	1		*BUMPER RETAINER FRT RH	Serviceable	151.41 FL	*- FL
5	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
6	1		*BUMPER UNDERTRAY FRT	Serviceable	472.83 FL	*- FL
7	1		*BUMPER GRILLE LOWER FRT	Serviceable	266.80 FL	*- FL
8	1		*BUMPER FOG LAMP GRILLE RH	Serviceable	207.21 FL	*- FL
9	1		*BUMPER BEAM FRT	Repair	914.08 FL	*- FL
10	1		*HEADLAMP RH	Serviceable	1,184.43 FL	*- FL
11	1		*HEADLAMP PANEL FRT RH	Repair	152.15 FL	*- FL
12	1		*FENDER PANEL FRT RH	Bent	783.83 FL	*783.83 FL
13	1		*WHEELARCH FRT RH	Serviceable	278.84 FL	*- FL
14	1		*FENDER BRACKET LOWER RH	Serviceable	15.79 FL	*- FL
15	1		*FENDER INSULATOR RH	Serviceable	130.84 FL	*- FL
16	1		*TOW COVER FRT	Serviceable	28.61 FL	*- FL
17	1		*FRONT BRACE PANEL	Repair	177.22 FL	*- FL
18	1		*RADIATOR GRILLE	Serviceable	1,707.78 FL	*- FL
19	1		*RADIATOR GRILLE BADGE RENAULT	Serviceable	225.36 FL	*- FL
20	1		*RADIATOR GRILLE FRAME	Serviceable	1,353.75 FL	*- FL
21	1		*FRAME FULL SUPPORT PANEL	Serviceable	615.90 FL	*- FL
22	1		*FRAME FULL SUPPORT BRACKET	Repair	89.79 FL	*- FL
23	1		*BONNET	Repair	1,941.63 FL	*- FL
24	1		*BONNET INSULATOR	Serviceable	405.73 FL	*- FL
25	1		*BONNET STRUT LH	Serviceable	88.61 FL	*- FL
26	1		*BONNET STRUT RH	Serviceable	88.61 FL	*- FL
27	1		*BONNET HINGE LH	Repair	348.31 FL	*- FL
28	1		*BONNET HINGE RH	Repair	348.31 FL	*- FL
29	1		*BONNET LOCK	Repair	305.48 FL	*- FL
30	1		*BONNET CABLE	Serviceable	119.19 FL	*- FL
31	1		*BONNET CABLE COVER	Serviceable	161.03 FL	*- FL
32	1		*BONNER SEAL OUTER	Serviceable	92.36 FL	*- FL
33	1		*BONNER SEAL INNER	Serviceable	157.28 FL	*- FL
34	1		*WIPER RESERVOIR MOTOR	Serviceable	270.06 FL	*- FL
35	1		*WIPER RESERVOIR	Serviceable	348.25 FL	*- FL
36	1		*WIPER RESERVOIR NECK	Serviceable	136.11 FL	*- FL
37	1		*BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
38	1		*BUMPER BRACKET CLIP FRT RH	Not Necessary	12.00 FS	*- FS
39	1		*BUMPER SUPPORT CLIP FRT RH	Not Necessary	10.50 FS	*- FS
40	1		*BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS
41	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
42	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS
43	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
44	1		*WHEELARCH CLIP FRT RH	Not Necessary	30.50 FS	*- FS
45	1		*FRONT RIGHT TYRE	Serviceable	300.00 FS	*- FS
46	1		*FRONT RIGHT TYRE RIM	Serviceable	380.00 FS	*- FS
47	1		*SET FRONT LICENCE PLATE WITH HOLDER	Serviceable	80.00 FS	*- FS
48	1		*SET RADIATOR GRILLE SCREW	Not Necessary	16.00 FS	*- FS
49	1		*SET RADIATOR GRILLE FRAME CLIP	Not Necessary	52.00 FS	*- FS
50	1		*WINDSCREEN SEALANT	Not Necessary	253.80 FS	*- FS
51	1		*FRONT WINDSCREEN MOULDING	Not Necessary	120.00 FS	*- FS
52	1		*FRONT WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
53	6		*BONNET INSULATOR CLIP L70Y	Not Necessary	7.30 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	2		*BONNET STRUT L70Y	Serviceable	88.61 FS	*- FS
55	2		*BONNET CABLE CLIP L70Y	Not Necessary	6.31 FS	*- FS
56	2		*BONNET CABLE COVER SCREW L70Y	Not Necessary	10.85 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,250.18	2,109.25
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,552.73	204.33
Total Parts (\$\$)	15,697.45	1,904.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	440.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	6,000.00	400.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
4	TO TRANSFER OF FRONT WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	New	170.00	0.00
5	TO TRANSFER OF FRONT FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO TRANSFER OF FRONT BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
8	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
9	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
10	TO TRANSFER OF BONNET FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00
12	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR	New	380.00	0.00
13	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT	New	380.00	0.00
Gross Labour Cost (\$\$)			15,180.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >