

22/03/2002

ASS. REC. BY:

REF:

CS/FCI/9012839/K+FBⁿ²

Special Instruction:

Surveyor

Kenneth

ASSIGNMENT (Office)

From (Person):

Serene

of

FCI

Date/Time:

22.7.19 9.42a.m

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKZ 1767Y

Insured:

SHD 6519R

at Workshop m/s

Ah Lim Motor

Tel:

64831244

of

NO 10 AMK Ind Park 2A #01-09 AMC Autoprint

Policy No:

Claim No:

D19004727MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

17.7.2019

10300.m 23.7.19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

22.7.19 10.00a.m

Person Contacted:

Zila

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKZ1767Y NA/TM119008832/H4 NOA=15/5/19

SHD 6519R X

Part by Part \$13101 (Red: 1487.35; 530%)

Surrey: Kenneth

ASSIGNMENT

From: _____ Date: 23.7.2019

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SK2 17674

at Workshop m/s Ah Lim motor

of 100 10 Amk Ind Park 24 #01-09

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 10-304.m owner waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 821k

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 12/22 Person Contacted: _____

Vehicle: IN / OUT

Veh No: SK2 17674 Yr Regn: 01/08

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy Atio C.C. 1498

Colour: M. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 155044 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: N7E141 6063704

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD AirRim or

Tyre Size: F: 195/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 17/7/19

Rear

R/Bal. 8 mm

L/Bal. 8 mm

D.O.I. 23/7/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Acc body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

21.0001 - MV
14.737 - LTA
6263 - NV

RECEIVED 10 SEP 2019

Date/Time, File Pass to?

1) 10/9 Typist

Date/Time, File Return to?

2)

Report Format: TP

Lump Sum / (B): (\$ 1310)

☐: Preli. Report☒: Final Report

Days Of Repair: 3

Resurvey No. of Trip: 0

Add Fee: ☐: Site Insp (\$)☐: Interview (\$)☐: Tech. Invs (\$)☐: Weekend (\$)

Survey Fee:

Transportation:

S + RS: \$

Photos:

Others:

TOTAL

110

50

12

172

MOTOR SURVEY ASSIGNMENT

Date	19-07-2019	Our Ref No. D19004727MFSH
Accident Date	17-07-2019	Claim Type. Third Party
Insured Vehicle	SHD6519R	Third Party Vehicle. SKZ1767Y
Survey Location	NO. 10 ANG MO KIO IND PARK 2A #01-09 AMK AUTOPOINT	
Contact Person.	ZILA	
Contact No.	64831244/ 0	Fax No. 64836170
Survey Type	DIRECT SETTLEMENT: EST. COR \$2993.16	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	AH LIM MOTOR COMPANY	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 316H

Vehicle Details

Vehicle No.: SKZ1767Y
Vehicle to be Exported: No
Intended Deregistration Date: 18 Jul 2019
Vehicle Make: TOYOTA
Vehicle Model: COROLLA AXIO 1.5X A
Primary Colour: Silver
Manufacturing Year: 2007
Engine No.: 1NZC863088
Chassis No.: NZE1416063704
Maximum Power Output: 81.0 kW (108 bhp)
Open Market Value: \$11,961.00
Original Registration Date: 02 Jan 2008
First Registration Date: 02 Jan 2008
Transfer Count: 2
Actual ARF Paid: \$13,158.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Dec 2022
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$21,349.00
COE Rebate Amount: \$14,737.00
Total Rebate Amount: \$14,737.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 18 Jul 2019

OK

MV:

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : HUANG KE WEI NICHOLAS
629 ANG MO KIO AVE 4
#04-1014
SINGAPORE 560629

ATTN:

Your Ref No: SKZ1767Y
Claim Type: Third Party
Accident Date: 17/07/2019
TP Veh Reg No: SHD6519R

Estimate No: MC1900538
Date: 18 Jul 2019
Policy No: D19MTPV01000779
Veh Reg No: SKZ1767Y
Make/Model: TOYOTA COROLLA
AXIO 1.5X A

*Not Whelan
Money After Paint
3 days*

Estimate Repair Cost to Vehicle No :SKZ1767Y

Description	Quantity	List Price	Amount
		<u>SS</u>	<u>SS</u>
SPARE PARTS			
1 REAR DOOR LH	1 PC	973.20	X
2 REAR BUMPER	1 PC	484.20	✓
3 REAR BUMPER SIDE RETAINER LH	1 PC	79.05	✓
4 REAR BUMPER CLIPS	12 PC	46.68	✓
		1,583.13	
	Less 25%	395.78	1,187.35
Special Nett			
5 SPORT RIM LHR	1 PC	250.00	✓
6 TYRE LHR - CHECK PRICE	1 PC	0.00	X
		250.00	250.00
LABOUR			
7 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	600
8 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	120.00	X
9 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	X
10 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD. TO KNOCK & REPAIR REAR FENDER LH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	400
11 TO SPRAY REAR BUMPER,REAR DOOR LH,RR FENDER LH.	1 PC	600.00	✓
		1,360.00	1,360.00
Total			SS 2,797.35

Add GST @ 7% 195.81

Total Amount Payable SS 2,993.16

TOTAL: SINGAPORE DOLLAR TWO THOUSAND NINE HUNDRED NINETY THREE AND CENTS SIXTEEN ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before the repair work commences.
- To display damaged part(s) during resurvey.
- To provide a copy of the survey report to the repairer.
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : HUANG KE WEI NICHOLAS
629 ANG MO KIO AVE 4
#04-1014
SINGAPORE 560629

Claim No: MC1900538
No: MF1900562
Date: 09 Sep 2019
Policy No: D19MTPV01000779
Veh Reg No: SKZ1767Y
Make/Model: TOYOTA COROLLA
AXIO 1.5X A

ATTN:

Your Ref No: SKZ1767Y
Claim Type: Third Party
Accident Date: 17/07/2019
TP Veh Reg No: SHD6519R

Repair Cost to Vehicle No (For Finalization):SKZ1767Y

Description	Quantity	List Price S\$	Amount S\$
Special Nett			
1 SPORT RIM LHR	1 PC	250.00	250.00
LABOUR			
2 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	60.00	
3 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD. TO KNOCK & REPAIR REAR FENDER LH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	400.00	
4 TO SPRAY REAR BUMPER,REAR DOOR LH,RR FENDER LH.	1 PC	600.00	
		1,060.00	1,060.00
		Total	S\$ 1,310.00
		Less Excess	S\$ 0.00
		Amount Before GST	S\$ 1,310.00
		Add GST @ 7%	91.70
		Total Amount Payable	S\$ 1,401.70

TOTAL: SINGAPORE DOLLAR ONE THOUSAND FOUR HUNDRED AND ONE AND CENTS SEVENTY ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 23/07/2019

For AH LIM MOTOR COMPANY
AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170
AUTHORISED SIGNATURE

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : HUANG KE WEI NICHOLAS
629 ANG MO KIO AVE 4
#04-1014
SINGAPORE 560629

ATTN:

Your Ref No: SKZ1767Y
Claim Type: Third Party
Accident Date: 17/07/2019
TP Veh Reg No: SHD6519R

Estimate No: MC1900538
Date: 18 Jul 2019
Policy No: D19MTPV01000779
Veh Reg No: SKZ1767Y
Make/Model: TOYOTA COROLLA
AXIO 1.5X A

Not Wharw
Rebody After Paint
3 days

Estimate Repair Cost to Vehicle No :SKZ1767Y

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 REAR DOOR LH	1 PC	973.20	X
2 REAR BUMPER	1 PC	484.20	✓
3 REAR BUMPER SIDE RETAINER LH	1 PC	79.05	✓
4 REAR BUMPER CLIPS	12 PC	46.68	✓
		1,583.13	
	Less 25%	395.78	1,187.35
Special Nett			
5 SPORT RIM LHR	1 PC	250.00	✓
6 TYRE LHR CHECK PRICE	1 PC	0.00	X
		250.00	250.00
LABOUR			
7 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	601
8 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	120.00	X
9 TO SPRAY ANTI RUST COATING ON AFFECTED AREAS	1 PC	60.00	X
10 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD. TO KNOCK & REPAIR REAR FENDER LH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	4001
11 TO SPRAY REAR BUMPER, REAR DOOR LH, RR FENDER LH.	1 PC	600.00	✓
		1,360.00	1,360.00
Total			SS 2,797.35
Add GST @ 7%			195.81
Total Amount Payable			SS 2,993.16

TOTAL: SINGAPORE DOLLAR TWO THOUSAND NINE HUNDRED NINETY THREE AND CENTS SIXTEEN ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY


AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19012839/Ktf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 11-09-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6519R	Veh. Inspected	SKZ 1767Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004727MFSH	Excess (\$)	0.00	
Assign From	SERENE LER	Assign Date	22/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA AXIO (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	NZE1416063704	Colour	METALLIC SILVER	
Odometer	155044	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R15	YOKOHAMA	8 mm	
L/H Front Tyre	195/60 R15	YOKOHAMA	8 mm	
R/H Rear Tyre	195/60 R15	YOKOHAMA	8 mm	
L/H Rear Tyre	195/60 R15	YOKOHAMA	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/07/2019	Inspection Date	23/07/2019	
Survey held at	AH LIM MOTOR COMPANY NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 1767Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR DOOR LH	TO REPAIR SEE LABOUR	973.20	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	484.20	-
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	79.05	-
12	REAR BUMPER CLIPS	NOT NECESSARY	46.68	-
	LESS 25% DISCOUNT		-395.78	-
			1,187.35	-
SPECIAL NETT ITEMS				
1	SPORT RIM LHR (SN)	DENTED	250.00	250.00
1	TYRE LHR (NPA)(SN)	SERVICEABLE	-	-
			250.00	250.00
LABOUR				
	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.		80.00	60.00
	TO REMOVE AND REINSTALL CUSHIONS SEATS & BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	NOT NECESSARY	120.00	-
	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	NOT NECESSARY	60.00	-
	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD, TO KNOCK & REPAIR REAR FENDER LH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME. INCLUSIVE OF THE REPAIR OF REAR DOOR LH AND REAR BUMPER.		500.00	400.00
	TO SPRAY REAR BUMPER, REAR DOOR LH, RR FENDER LH.		600.00	600.00
			1,360.00	1,060.00
GRAND TOTAL			2,797.35	1,310.00
RECOMMENDED COST OF REPAIRS				1,310.00

Report Ref No. CS/FC19012839/Ktf3n2

MARKET VALUE: \$21,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$14,737.00=NETT VALUE: \$6,263.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.