



CYCLE & CARRIAGE

**CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE**

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
EQ INSURANCE COMPANY LTD 5 Maxwell Road #17-00 Tower Block, MND Complex, Singapore 069110 Contact No	Cust No/Name	KCV11104/Ms Tay Lee Koon, Teresa (zheng)
	Reg No/Reg Date	SMK7620C / 24/04/2019
	Date In/Mileage	20/07/2019/ 1763
	Chassis No	MMBSTA13AKH001547
	Engine No	3A92UHS1135
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	W05 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000061	Credit	22/07/2019/ 09:04	DS	218 / MarsLer	28849

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S MIPNT88088 DIAGNOSTIC / SCANNING				✓ 250.00
S MIPNT88088 TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS				80 100 .00
S MIPNT88088 TO REMOVE AND REPLACE REAR WINDSCREEN GLASS TO GIVE WAY ACCESS RENEWEL LHR OUTER FENDER				X 300.00
M SUNDRY SEALANT KIT ON REAR WINDSCREEN GLASS				X 100.00
S MIPNT88088 TO INSTALL RIKE COOL SOLAR FILM ON REAR WINDSCREEN GLASS				X 220.00
S MIPNT88088 TO REMOVE AND RE-INSTALL FUEL LINING & PIPING TO GIVE WAY ACCESS REPAIR ON LHR OUTER FENDER				X 600.00
S MIPNT88088 TO TRANSFER REAR BOOT COMPONENT & MECHANISM PARTS				300 600 .00
S MIPNT88088 TO REPLACE REAR REVERSE CAMERA LENS				X 350.00
S MIPNT88088 TO REMOVE AND RE-INSTALL TRIMMING AND ROOF LINING TO GIVE WAY FACILITATE REPAIR ON LHR OUTER FENDER				300 1200 .00
S MIPNT88088 TO REPLACE REAR BODY KIT -INCLUDE SPRAY & APPLY SEALANT KIT				600 800 .00
S MIPNT88088 TO REPLACE REAR BOOT,REAR BUMPER,ETC -CUT & RE-WELD REAR END PANEL AND LHR OUTER QUATER PANEL -REPAIR REAR FLOOR PAN AND RHR OUTER QAUTER PANEL STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS				3000 6000 .00
S MIPNT88088 TO APPLY SEALANT KIT ON NEW PANEL				200 300 .00
S MIPNT88088				X 600.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info	
EQ INSURANCE COMPANY LTD 5 Maxwell Road #17-00 Tower Block, MND Complex, Singapore 069110 Contact No	Cust No/Name	KCV11104/Ms Tay Lee Koon, Teresa (zheng)
	Reg No/Reg Date	SMK7620C / 24/04/2019
	Date In/Mileage	20/07/2019/ 1763
	Chassis No	MMBSTA13AKH001547
	Engine No	3A92UHS1135
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	W05 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
F0000061	Credit	22/07/2019/ 09:04	DS	218 / MarsLer	28849			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
S		TO REPLACE REAR EXHAUST MUFFLER ASSY						2520 2940.00
S		MIPNT98088 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS						✓ 280.00
S		MIPNT88088 REVERSE SENSOR SET <i>Payd</i>						✓ 50.00
M		SUNDRY C & C LOGO <i>neu</i>						✓ 50.00
M		SUNDRY MIVEC EMBLEM <i>neu</i>						✓ 740.00
M		JJ6410C750 FACE, RR BUMPER <i>repld</i>		1.00	740.00	0.00		✓ 740.00
P		JJM001623 CLIP,RR BUMPER <i>repld</i>		10.00	3.00	0.00		✓ 30.00
P		JJ6410C434 RH BRACKET, RR BUMPER <i>repld</i>		1.00	27.00	0.00		✓ 27.00
P		JJ6410C433 LH BRACKET, RR BUMPER <i>repld</i>		1.00	27.00	0.00		✓ 27.00
M		JJ8355A081 LH REFLECTOR <i>?</i>		1.00	22.00	0.00		✓ 22.00
M		JJ8355A082 RH REFLECTOR <i>?</i>		1.00	22.00	0.00		✓ 22.00
M		JJMZ330600-W54 ATTRAGE BODY KIT <i>repld</i>		1.00	1643.00	0.00		✓ 1643.00
P		JJ5281A631 PANEL,RR END <i>repld</i>		1.00	421.00	0.00		✓ 421.00
M		JJ8637A176 BUZZER, KEYLESS OPER <i>?</i>		1.00	90.00	0.00		✓ 90.00
M		JJ8637B115 ANTENNA, KEYLESS OPE <i>?</i>		1.00	95.00	0.00		✓ 95.00
M		JJ7835A023 DUCT,RR VENTILATOR <i>?</i>		1.00	30.00	0.00		✓ 30.00
P		JJ7835A032 COVER, RR VENTILATOR <i>?</i>		1.00	40.00	0.00		✓ 40.00
M		JJMB157530 CLIP,RR VENTILATOR D <i>neu</i>		3.00	3.00	0.00		✓ 9.00
M		JJ7240A172XA TRIM, RR END <i>?</i>		1.00	65.00	0.00		✓ 65.00
M		JJ7646A265 BOARD, TRUNK ROOM FL <i>to in.</i>		1.00	193.00	0.00		✓ 193.00
M		JJ5921A017 WEATHERSTRIP, TRUNK <i>up</i>		1.00	155.00	0.00		✓ 155.00
M		JJ5920A234 TRUNK LID PANEL <i>repld</i>		1.00	688.00	0.00		✓ 688.00
M		JJ5927A042 LATCH, TRUNK LID <i>repld</i>		1.00	216.00	0.00		✓ 216.00
P		JJ8341A200 GARNISH, RR END PANE <i>repld</i>		1.00	332.00	0.00		✓ 332.00
P		JJ7415A389 MARK, THREE-DIA <i>repld</i>		1.00	45.00	0.00		✓ 45.00
P		JJ7415A438 MARK, ATTRAGE <i>repld</i>		1.00	21.00	0.00		✓ 21.00
M		JJ5370B565 LH MUD GUARD,RR <i>repld</i>		1.00	40.00	0.00		✓ 40.00
M		JJ5370B566 RH MUD GUARD,RR <i>repld</i>		1.00	35.00	0.00		✓ 35.00
P		JJ5301F967 OTR LH QTR PANEL <i>repld</i>		1.00	748.00	0.00		✓ 748.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

**CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE**

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
EQ INSURANCE COMPANY LTD 5 Maxwell Road #17-00 Tower Block, MND Complex, Singapore 069110 Contact No	Cust No/Name	KCV11104/Ms Tay Lee Koon, Teresa (zheng)
	Reg No/Reg Date	SMK7620C / 24/04/2019
	Date In/Mileage	20/07/2019/ 1763
	Chassis No	MMBSTA13AKH001547
	Engine No	3A92UHS1135
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	W05 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000061	Credit	22/07/2019/ 09:04	DS	218 / MarsLer	28849

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
P JJ6131A233 GLASS,RR WINDOW <i>new</i>	1.00	599.00	0.00	* 599.00
M JJMR462285 STOPPER,WINDSHIELD G <i>new</i>	2.00	3.00	0.00	+ 6.00
M JJ6102A405 SPACER,RR WINDOW <i>new</i>	3.00	9.00	0.00	* 27.00
P JJ8330A851 LH LAMP ASSY, COMBIN <i>replaced</i>	1.00	332.00	0.00	- 332.00
P JJ8330A852 RH LAMP ASSY, COMBIN <i>replaced</i>	1.00	332.00	0.00	✓ 332.00
M JJMR482761 CLIP, TAIL LAMP <i>new</i>	2.00	3.00	0.00	✓ 6.00
M JJ1570C567 PIPE,EXHAUST TAIL <i>not new</i>	1.00	597.00	0.00	* 597.00

Z NOTES

ACCIDENT ON 19/07/2019 ALONG PIE TOWARDS JURONG
OWNER CLAIMING THIRD PARTY
REQUIRIED REPLACEMENT CAR
TP # SLG586Y TP INS : EQ

Estimate

*Admin G
R/P 22/07/19.
09 Days.*

Confirm & accepted by	Parts	7,633.00
	Labour	0.00
Authorized signatory and company stamp	Standard Menu	0.00
	Specialist Job	14,540.00
	Others(Lub,etc)	0.00
	Sundry	200.00
	Total(w/o GST)	22,373.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.