

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19012864/KPA3Q2

**Date:** 28/01/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**  
**Vehicle No :** SLW6065K **Insured Vehicle No :** SLG3500A

**Date of Loss:** 19/07/2019 **Nature of Claim:** TP **Claim No:** 8309819133SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW6065K		
Make & Model:	MAZDA 3, 1.5 (A)	Engine No:	HIDDEN
Reg. Date:	23/02/2018 (Man. Year: 2017)	Chassis No:	JM6BN22A8H0167963
Colour:	Metallic Black	Odometer:	69057 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,470.85	150.00	3,320.85	95.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,070.00	1,025.00	1,045.00	50.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>5,540.85</b>	<b>1,175.00</b>	<b>4,365.85</b>	<b>78.79</b>
<b>+ Loss of Use (3.0 x S\$60.00/day) (S\$)</b>		180.00		
<b>Nett Liability (S\$)</b>		<b>1,355.00</b>		

### INSPECTION

Date of Assignment: 22/07/2019

Date Inspected: 23/07/2019 Inspected At:

Supreme Auto Service Pte Ltd (HQ)  
176 Sin Ming Drive #02-01, Sin Ming  
Autocare  
Singapore 575721

Estimated Period of Repair: 3.0 days

**Adjuster:** KENNETH KONG

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	986.50 FL	*- FL
2	1		*REAR BUMPER DUST COVER	Serviceable	136.20 FL	*- FL
3	1		*REAR FENDER	Repair	1,075.30 FL	*- FL
4	1		*ALLOY RIM (LOCAL PURCHASE)	Scratched	968.22 FS	*150.00 FS
5	1		*REAR SHOCK ABSORBER	Serviceable	253.80 FL	*- FL
6	1		*REAR LOWER ARM	Serviceable	328.90 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>3,748.92</b>	<b>150.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	278.07	0.00
<b>Total Parts (\$)</b>	<b>3,470.85</b>	<b>150.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE, KNOCKING AND STRAIGHTEN UP THE NECESSARY AFFECTED AREAS	New	700.00	400.00
2	TO CHECK WIRING SYSTEM	New	30.00	10.00
3	TO APPLY PUTTY AND SPRAY PAINTING ON AFFECTED AREAS	New	600.00	540.00
4	TO APPLY WATERPROOF SEALANT ON AFFECTED AREAS	New	50.00	0.00
5	TO APPLY RUST PROOFING ON AFFECTED AREAS	New	50.00	0.00
6	TO REMOVE REAR WINDSCREEN GLASS TO ENABLE REPAIR	New	150.00	0.00
7	TO REMOVE CARPET ,TRIMMING AND SEATS TO ENABLE REPAIR	New	160.00	0.00
8	TO REMOVE AND INSTALL REAR UNDERCARRIAGE PARTS TO ENABLE REPAIR	New	120.00	0.00
9	TO REPLACE ALLOY RIM (S) AND PERFORM WHEEL BALANCING	New	80.00	15.00
10	TO PERFORM 4 WHEELS COMPUTERISED ALIGNMENT	New	80.00	60.00
11	TO INSTALL REVERSE SENSORS	New	50.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>2,070.00</b>	<b>1,025.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >