



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS3/SMO19007618/T1vd3e2-1

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 02-08-2019



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 8850K	Veh. Inspected	GBF 7628M
Policy No.	D19MTPCVE000629	Coverage (\$)	0.00
Claim No.	CMTD1902102	Excess (\$)	0.00
Assign From	MELVIN YE	Assign Date	23/07/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KDH2015024045	Colour	SILVER
Odometer	40924	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/80 R15	DUNLOP	6 mm
L/H Front Tyre	195/80 R15	DUNLOP	6 mm
R/H Rear Tyre	195/80 R15	DUNLOP	6 mm
L/H Rear Tyre	195/80 R15	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/04/2019	Inspection Date	02/05/2019
Survey held at	NGEE NGEE MOTOR BLK 1 NO: 22 PANDAN LOOP SINGAPORE 128219		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	15 Working Days
--	------------------------