

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III19012940/KPS3Q2
Date: 03/08/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SHC5557S	Insured Vehicle No :	SH9894K
Date of Loss:	12/07/2019	Nature of Claim:	TP
		Claim No:	MCT19070353

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5557S	Engine No:	M9R8839C001968
Make & Model:	RENAULT LATITUDE, 2.0 D dCi (A)	Chassis No:	VF1ABL15AUC279248
Reg. Date:	15/09/2014 (Man. Year: 2014)	Odometer:	0 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Giti 9 mm	Rear Left Side:	Giti 8 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	107,704.94	36,170.62	71,534.32	66.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	23,070.00	2,720.00	20,350.00	88.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	130,774.94	38,890.62	91,884.32	70.26
Approved Total (Overridden) (S\$)		17,000.00		

(S\$)	130,774.94	17,000.00	113,774.94	87.00
+ GST 7.00/7.00% (S\$)	9,154.25	1,190.00	7,964.25	87.00
Nett Amount (S\$)	139,929.19	18,190.00	121,739.19	87.00
+ Car Rental (8.0 x S\$81.13/day) (S\$)		649.04		
Nett Liability (S\$)		18,839.04		

INSPECTION

Date of Assignment: 22/07/2019

Date Inspected: 22/07/2019

Estimated Period of Repair: 8.0 days

Inspected At:

Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

Book Value: \$46,600.00(est) less LTA Rebate: \$29,314.00(est) = Nett Book Value :\$17,286.00(est)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Nov 2019)
Parts:	143	RENAULT LATITUDE 2.0 D dCi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC5557S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Missing	1,259.42 FL	*1,259.42 FL
2	1		*BUMPER SPOILER FRT	Missing	181.75 FL	*181.75 FL
3	1		*BUMPER ABSORBER FRT	Missing	394.68 FL	*394.68 FL
4	1		*BUMPER RETAINER FRT LH	Cracked	151.41 FL	*151.41 FL
5	1		*BUMPER SUPPORT FRT	Missing	123.88 FL	*123.88 FL
6	1		*BUMPER RETAINER FRT RH	Cracked	150.77 FL	*150.77 FL
7	1		*BUMPER SUPPORT FRT	Missing	123.88 FL	*123.88 FL
8	1		*BUMPER UNDERTRAY FRT	Cracked	472.83 FL	*472.83 FL
9	1		*BUMPER GRILLE LOWER FRT	Missing	266.80 FL	*266.80 FL
10	1		*BUMPER FOG LAMP GRILLE LH	Missing	207.21 FL	*207.21 FL
11	1		*BUMPER FOG LAMP GRILLE RH	Missing	207.21 FL	*207.21 FL
12	1		*BUMPER BEAM FRT	Bent	914.08 FL	*914.08 FL
13	1		*TOW COVER FRT	Missing	28.61 FL	*28.61 FL
14	1		*RADIATOR GRILLE	Missing	1,707.78 FL	*1,707.78 FL
15	1		*RADIATOR GRILLE BADGE RENAULT	Missing	225.36 FL	*225.36 FL
16	1		*RADIATOR GRILLE FRAME	Cracked	1,353.75 FL	*1,353.75 FL
17	1		*FRAME FULL SUPPORT PANEL	Cracked	615.90 FL	*615.90 FL
18	1		*FRAME FULL SUPPORT BRACKET	Bent	89.79 FL	*89.79 FL
19	1		*FRONT BRACE PANEL	Bent	177.22 FL	*177.22 FL
20	1		*HORN	Serviceable	314.17 FL	*- FL
21	1		*HORN BRACKET	Repair	40.45 FL	*- FL
22	1		*HEADLAMP LH	Cracked	1,184.43 FL	*1,184.43 FL
23	1		*HEADLAMP RH	Mtg Cracked	1,184.43 FL	*1,184.43 FL
24	1		*HEADLAMP PANEL FRT LH	Repair	152.15 FL	*- FL
25	1		*HEADLAMP PANEL FRT RH	Bent	152.15 FL	*152.15 FL
26	1		*BONNET	Buckled	1,941.63 FL	*1,941.63 FL
27	1		*BONNET INSULATOR	Serviceable	405.73 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*BONNET STRUT LH	Serviceable	88.61 FL	*- FL
29	1		*BONNET STRUT RH	Serviceable	88.61 FL	*- FL
30	1		*BONNET HINGE LH	Distorted	348.31 FL	*348.31 FL
31	1		*BONNET HINGE RH	Distorted	348.31 FL	*348.31 FL
32	1		*BONNET LOCK	Bent	305.48 FL	*305.48 FL
33	1		*BONNET CABLE	Serviceable	119.19 FL	*- FL
34	1		*BONNET CABLE COVER	Serviceable	161.03 FL	*- FL
35	1		*BONNET SEAL OUTER	Missing	92.36 FL	*92.36 FL
36	1		*BONNET SEAL INNER	Serviceable	157.28 FL	*- FL
37	1		*FENDER PANEL FRT LH	Bent	783.83 FL	*783.83 FL
38	1		*WHEELARCH FRT LH	Cracked	278.84 FL	*278.84 FL
39	1		*FENDER BRACKET LOWER LH	Repair	15.79 FL	*- FL
40	1		*FENDER INSULATOR LH	Serviceable	130.84 FL	*- FL
41	1		*FENDER PANEL FRT RH	Repair	130.84 FL	*- FL
42	1		*WHEELARCH FRT RH	Serviceable	278.84 FL	*- FL
43	1		*FENDER BRACKET LOWER RH	Serviceable	36.11 FL	*- FL
44	1		*FENDER INSULATOR RH	Serviceable	130.84 FL	*- FL
45	1		*WIPER RESERVOIR	Serviceable	348.25 FL	*- FL
46	1		*WIPER RESERVOIR NECK	Serviceable	136.11 FL	*- FL
47	1		*WIPER RESERVOIR MOTOR	Serviceable	270.06 FL	*- FL
48	1		*AIR CLEANER LOWER	Serviceable	271.26 FL	*- FL
49	1		*AIR CLEANER HOSE	Serviceable	76.14 FL	*- FL
50	1		*BASE BATTERY TRAY	Cracked	363.40 FL	*363.40 FL
51	1		*AIR CLEANER BOX	Serviceable	464.20 FL	*- FL
52	1		*TURBO DUCT	Serviceable	1,027.80 FL	*- FL
53	1		*A/C HEATER VALVE	Serviceable	484.50 FL	*- FL
54	1		*SUBFRAME OUTER FRT	Serviceable	2,652.45 FL	*- FL
55	1		*SUBFRAME BRACKET OUTER LH	Repair	92.36 FL	*- FL
56	1		*SUBFRAME BRACKET OUTER RH	Repair	92.36 FL	*- FL
57	1		*ENGINE UNDERTRAY	Serviceable	564.98 FL	*- FL
58	1		*A/C CONDENSER	Bent	2,020.37 FL	*2,020.37 FL
59	1		*A/C CONDENSER GARNISH LH UPPER	Serviceable	39.67 FL	*- FL
60	1		*A/C CONDENSER GARNISH RH UPPER	Serviceable	39.67 FL	*- FL
61	1		*A/C CONDENSER GARNISH LH	Serviceable	58.81 FL	*- FL
62	1		*A/C CONDENSER GARNISH RH	Serviceable	59.60 FL	*- FL
63	1		*A/C PIPE CONDENSER TO COMPRESSOR	Serviceable	208.39 FL	*- FL
64	1		*A/C PIPE CONDENSER TO EXPENSION VALVE	Serviceable	658.72 FL	*- FL
65	1		*A/C PIPE COMPRESSOR	Serviceable	334.29 FL	*- FL
66	1		*A/C PIPE	Serviceable	658.72 FL	*- FL
67	1		*A/C COMPRESSOR	Serviceable	2,684.61 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
68	1		*AIR COOLER	Bent / Punctured	792.60 FL	*792.60 FL
69	1		*AIR INTERCOOLER HOSE (LONG)	Serviceable	1,014.13 FL	*- FL
70	1		*AIR INTERCOOLER HOSE (SHORT)	Serviceable	375.14 FL	*- FL
71	1		*TRANSMISSION COOLER	Serviceable	1,219.30 FL	*- FL
72	1		*TRANSMISSION COOLER PAD	Serviceable	17.96 FL	*- FL
73	1		*RADIATOR	Punctured	1,202.20 FL	*1,202.20 FL
74	2		*RADIATOR STUD UPPER	Serviceable	14.41 FL	*- FL
75	2		*RADIATOR BUSH UPPER	Serviceable	50.12 FL	*- FL
76	2		*RADIATOR MTG LOWER	Serviceable	55.85 FL	*- FL
77	1		*RADIATOR FAN COWLING	Serviceable	820.54 FL	*- FL
78	1		*RADIATOR FAN MOTOR LH	Serviceable	967.36 FL	*- FL
79	1		*RADIATOR FAN MOTOR RH	Serviceable	1,479.46 FL	*- FL
80	1		*RADIATOR TANK	Serviceable	324.62 FL	*- FL
81	1		*RADIATOR HOSE UPPER	Serviceable	240.56 FL	*- FL
82	1		*RADIATOR HOSE LOWER	Serviceable	491.18 FL	*- FL
83	1		*RADIATOR TANK HOSE	Serviceable	61.18 FL	*- FL
84	1		*LOWER ARM LH L70Y	Serviceable	685.76 FL	*- FL
85	1		*KNUCKLE ARM LH L70Y	Serviceable	846.98 FL	*- FL
86	1		*ABSORBER FRT LH L70Y	Serviceable	360.54 FL	*- FL
87	1		*DRIVESHAFT LH	Repair	1,747.45 FL	*- FL
88	1		*STABILIZER BAR FRT	Serviceable	604.65 FL	*- FL
89	1		*DOOR PANEL FRT LH	Repair	2,844.66 FL	*- FL
90	1		*DOOR MIRROR ASSY LH	Serviceable	1,483.40 FL	*- FL
91	1		*DOOR HARNESS WIRE LH	Serviceable	2,670.00 FL	*- FL
92	1		*DOOR PANEL FRT RH	Repair	2,844.66 FL	*- FL
93	1		*DOOR MIRROR ASSY RH	Serviceable	1,483.40 FL	*- FL
94	1		*DOOR HARNESS WIRE RH	Serviceable	2,670.00 FL	*- FL
95	1		*AUTO COMPUTER	Serviceable	5,032.17 FL	*- FL
96	1		*INJECTION COMPUTER	Serviceable	4,706.30 FL	*- FL
97	1		*RHD HYDRAULIC POWER (ROCK & PINION)	Serviceable	5,154.52 FL	*- FL
98	1		*STEERING PUMP ELECTRIC L70Y	Serviceable	2,306.90 FL	*- FL
99	1		*STEERING PINION RACK L70Y	Serviceable	4,413.11 FL	*- FL
100	1		*WINDSCREEN FRNT	Cracked	1,364.06 FL	*1,364.06 FL
101	1		*RAIN SENSOR	Serviceable	509.48 FL	*- FL
102	1		*SHELF ASSY (WINDSCREEN UNDER PANEL)	Repair	443.76 FL	*- FL
103	1		*WINDSCREEN LOW GRILLE COVER	Serviceable	310.60 FL	*- FL
104	1		*WINDSCREEN INNER GARNISH RH	Serviceable	257.40 FL	*- FL
105	1		*WINDSCREEN INNER GARNISH LH	Serviceable	257.40 FL	*- FL
106	1		*SEATBELT LH	Jammed	2,937.80 FL	*2,937.80 FL
107	1		*SEATBELT RH	Jammed	2,937.80 FL	*2,937.80 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
108	1		*SEATBELT BUCKLE LH	Serviceable	984.13 FL	*- FL
109	1		*SEATBELT BUCKLE RH	Serviceable	984.13 FL	*- FL
110	1		*PASSENGER AIRBAG	Burst	3,412.40 FL	*3,412.40 FL
111	1		*STEERING AIRBAG	Burst	2,525.75 FL	*2,525.75 FL
112	1		*AIRBAG COMPUTER	Necessary	1,259.82 FL	*1,259.82 FL
113	1		*AIRBAG SENSOR	Necessary	724.63 FL	*724.63 FL
114	1		*DASHBOARD	Torn	4,900.54 FL	*4,900.54 FL
115	1		*FUSE BOX	Serviceable	987.39 FL	*- FL
116	1		*ENGINE MOUNTING RH	Serviceable	552.55 FL	*- FL
117	2		*ENGINE MOUNTING LOWER	Serviceable	562.42 FL	*- FL
118	1		*ENGINE MOUNTING UPPER	Serviceable	592.02 FL	*- FL
119	1		*OIL PAN ASSEMBLY	Serviceable	2,283.91 FL	*- FL
120	1		*GLOVE BOX	Serviceable	1,039.78 FL	*- FL
121	1		*GLOVE BOX FLAP	Serviceable	1,278.96 FL	*- FL
122	1		*FACE CONSOLE	Serviceable	949.60 FL	*- FL
123	1		*ENGINE HARNESS L70Y	Serviceable	4,084.54 FL	*- FL
124	1		*WINDSCREEN SEALANT	Necessary	228.42 FS	*40.00 FS
125	1		*SET RADIATOR GRILLE FRAME CLIP	Necessary	52.00 FS	*52.00 FS
126	1		*SET BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
127	1		*BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	*- FS
128	1		*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	*- FS
129	1		*BUMPER BRACKET CLIP FRT RH	Not Necessary	12.00 FS	*- FS
130	1		*BUMPER SUPPORT CLIP FRT RH	Not Necessary	10.50 FS	*- FS
131	1		*TOW COVER FRT	Not Necessary	14.50 FS	*- FS
132	1		*SET RADIATOR GRILLE SCREW	Not Necessary	16.00 FS	*- FS
133	1		*SET BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS
134	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
135	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS
136	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
137	1		*WINDSCREEN MOULDING	Necessary	120.00 FS	*120.00 FS
138	1		*FRONT WINDSCREEN SEALANT	Repeated	253.80 FS	*- FS
139	1		*FRONT WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
140	1		*SET FRONT LICENCE PLATE WITH HOLDER	Missing	80.00 FS	*45.00 FS
141	1		*SET WHEELARCH CLIP FRT LH	Necessary	30.50 FS	*30.50 FS
142	1		*SET WHEELARCH CLIP FRT RH	Not Necessary	30.50 FS	*- FS
143	1		*FRONT LEFT TYRE	Serviceable	330.00 FS	*- FS
144	1		*FRONT LEFT TYRE RIM	Serviceable	380.00 FS	*- FS
145	1		*FRONT RIGHT TYRE	Serviceable	330.00 FS	*- FS
146	1		*FRONT RIGHT TYRE RIM	Serviceable	380.00 FS	*- FS
147	6		*BONNET INSULATOR CLIP L70Y	Not Necessary	7.30 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
148	2		*BONNET STRUT L70Y	Not Necessary	88.61 FS	*- FS
149	2		*BONNET CABLE CLIP L70Y	Not Necessary	6.31 FS	*- FS
150	2		*BONNET CABLE COVER SCREW L70Y	Not Necessary	10.85 FS	*- FS
151	1		*FRONT LH DOOR STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
152	1		*FRONT LH DOOR STICKER CLASSIC	Not Necessary	80.00 FS	*- FS
153	1		*FRONT RH DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
154	1		*FRONT RH DOOR STICKER CLASSIC	Necessary	80.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	119,330.07	40,141.97
- List Item Discount on L Items 10.00/10.00% (\$)	11,625.13	3,971.35
Total Parts (\$)	107,704.94	36,170.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	90.00
2	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	7,500.00	700.00
3	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	New	170.00	0.00
4	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	New	380.00	0.00
5	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	New	380.00	0.00
6	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET VEHICLE WARNING INDICATORS.	New	480.00	220.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	0.00
8	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	New	380.00	0.00
9	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	7,500.00	1,320.00
10	TO TRANSFER OF FRONT BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
11	TO REPLACE, REFILL AND TOP UP COOLANT FOR RADIATOR.	New	170.00	50.00
12	TO VACUUM, REPLACE, REFILL AND RECHARGE AIR CONDENSER.	New	380.00	100.00
13	TO VACUUM, REPLACE, REFILL AND RECHARGE AIR INTERCOOLER.	New	170.00	50.00
14	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	350.00	0.00
15	TO TRANSFER OF FRONT WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	New	200.00	120.00
16	TO TRANSFER BONNET FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
17	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.	New	380.00	0.00
18	TO REMOVE AND RENEW POWER STEERING PUMP, OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	New	440.00	0.00
19	TO CHECK ABS AND BRAKE EFFICIENCY, FINAL CHECKING AND TESTING.	New	380.00	0.00
20	TO TRANSFER OF FRONT DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	450.00	0.00
21	TO LIFT-UP ENGINE WITH GEAR BOX AND REFIT.	New	440.00	0.00
22	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT, VACUUM AND CHARGE-IN-GAS.	New	380.00	0.00
23	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	170.00	20.00
24	TO REPLACE AND REFILL POWER STEERING FLUID.	New	170.00	0.00
25	TOWING FESS.	New	120.00	50.00
26	TO DISMANTLE AND REFIT ENGINE CROSS-MEMBER AND ENGINE MOUNTING.	New	380.00	0.00
27	TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	New	170.00	0.00
28	TO CONDUCT AND PERFORM A COMPREHENSIVE ENGINE DIAGNOSTIC CHECK.	New	380.00	0.00

Report was unsubmitted during this print-out.

No	Particulars	Lab.Type	Repairer's	Amount
Gross Labour Cost (S\$)			23,070.00	2,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >