

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG19012963/KGS3Q2
Date: 16/07/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SLV5636A	Insured Vehicle No :	SDA6311K
Date of Loss:	22/07/2019	Nature of Claim:	TP
		Claim No:	9418436322SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV5636A	Engine No:	0
Make & Model:	BYD E6H, (A)	Chassis No:	LC0CE4DB4H1021754
Reg. Date:	03/01/2018 (Man. Year: 2017)	Odometer:	92380 km
Colour:	White		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/65 R17	Rear Tyre Size:	225/65 R17
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 9 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,280.83	1,186.52	1,094.31	47.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,280.00	960.00	320.00	25.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	3,560.83	2,146.52	1,414.31	39.72
+ Loss of Use (3.0 x S\$110.00/day) (S\$)		330.00		
+ Doc/Search Fee (S\$)		2.00		

Nett Liability (S\$)	2,478.52
Global Sum Settlement (S\$)	2,470.00

INSPECTION

Date of Assignment: 23/07/2019

Date Inspected: 23/07/2019

Inspected At:

Soon Hock Motor Pte Ltd (HQ)
Blk 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint
Singapore 568047

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Recommended Parts

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	600.00	400.00
2	SPRAYPAINTING CHARGES	New	600.00	500.00
3	RESET FRONT & REAR DOOR POWER WINDOW SYSTEM	New	80.00	60.00
Gross Labour Cost (\$\$)			1,280.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >