

22/07/2019

ASS. REC. BY:

REF:

CS/FCI 19012971/A143ⁿ²

Special Instructions:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Henry Kao

of

FCI

Date/Time: 2:15pm @ 23/7/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGX 2007J

Insured:

SHA 8099M

at Workshop n/s

Success United

Tel:

67461515

of

2 Kaki Bukit Ave 2 #01-33

Policy No:

Claim No:

D19004623 MFS4

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 12/7/2019

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time: 2:28pm @ 23/7/19

Person Contacted:

Srinan

Vehicle IN OUT

Date/Time	Action/Instruction	Estimate	✓
	SGX 2007J	CL6/A1G 15002483/Gpa 3g 2	NOA = 7/2/15
	SHA 8099M	CS3/FCI 14023841/G+bK3	NOA = 21/12/14
	lump sum \$3000+ (red: 4126.81, 57%), 3 days.		

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SGX2007J Yr Regn: 2015 Augst.

Type: M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Bmw 116D C.C. 1496

Colour Black A/C: Insured / Std / NI / NA

Sp. Reading 62683 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA1V720X05C06683

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 25/07/19

Survey held at Success United

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Front n/s.

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

29 July @ 4:32pm - sent email pending estimate.

MV:

PV:

Nett:

Date/Time, File Pass to?

Date/Time, File Return to?

1) 2918 Typist

2)

3)

4)

5)

6)

Preli Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS. Si

Photos

Others

TOTAL

150
50
13
213

MOTOR SURVEY ASSIGNMENT

Date	15-07-2019	Our Ref No. D19004623MFSH
Accident Date	12-07-2019	Claim Type. Third Party
Insured Vehicle	SHA8099M	Third Party Vehicle. SGX2007J
Survey Location	2 KAKI BUKIT AVE 2 #01-33 & #02-29KAKI BUKIT AUTOHUB	
Contact Person.	TEO WEE KEONG	
Contact No.	67461515/ 86512856	Fax No. 67485015
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SUCCESS UNITED PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 29 July 2019 4:32 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Henry Kao'; SUR
Subject: RE: SURVEY ASSESSMENT - D19004623MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SGX 2007J on 25/07/2019
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Tuesday, 23 July 2019 2:29 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19004623MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 23 July 2019 2:15 PM
To: ASSIGNMENTS@LKKAUTO.COM

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

804E

Vehicle Details

Vehicle No.:

SGX2007J

Vehicle to be Exported:

No

Intended Deregistration Date:

22 Jul 2019

Vehicle Make:

B.M.W.

Vehicle Model:

116D 5DR HATCHBACK DSC LED

Primary Colour:

Brown

Manufacturing Year:

2015

Engine No.:

38779286B37D15A

Chassis No.:

WBA1V720X05C06683

Maximum Power Output:

85.0 kW (113 bhp)

Open Market Value:

\$24,003.00

Original Registration Date:

14 Aug 2015

First Registration Date:

14 Aug 2015

Transfer Count:

0

Actual ARF Paid:

\$10,605.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

13 Aug 2025

PARF Rebate Amount:

\$7,953.00

Intended COE Rebate Details

COE Expiry Date:

13 Aug 2025

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$56,209.00

COE Rebate Amount:

\$34,057.00

Total Rebate Amount:

\$42,010.00

The information contained herein is correct as at 22 Jul 2019

OK

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub, Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

MS First Capital Insurance Limited

36 Robinson Road

#16-01 City House

Singapore 068877

Attention : Motor Claim Department

Contact : 65073848 Fax No. : 65073849

Estimate : TP19-096

Date : 22/07/2019

Vehicle Num. : SGX2007J

Make/Model : BMW 116D-2015

Chassis/Eng# : WBA1V720X05C06683/38779286B371

Accident Date : 12/07/2019

Claim No. : 019004623MFSH

Reference :

Policy No. : (13/08/2019)

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1 pc	LIST ITEMS :		
2.	1 pc	Frt Bumper		981.20 ✓
3.	1 pc	Frt Bumper Side Holder LH		32.05 ✓
4.	1 pc	Frt Bumper Bracket LH		38.05 ✓
5.	1 pc	Frt Bumper Inner Sponge		55.43 ✓
6.	1 pc	Frt Bumper Reinforcement		378.10 ✓
7.	2 pcs	Frt PDC Sensor	3354.80	796.20 ✓
8.	1 pc	Frt Foglamp Garnish LH		129.70 ✓
9.	1 pc	Headlamp LH	3187.06	2,341.55 ✓
10.	1 pc	Frt Headlamp Bracket LH		153.10 ✓
11.	1 pc	Frt Fender LH		597.25 ✓
		Frt Fender Inner Liner LH		209.80 ✓

List TotalS\$:

5,712.43

5.00% Discount S\$:

285.62

580

5,426.81

LABOUR :

To remove, rearrange electrical wirings, check lighting

100.00 30

To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident

1,000.00 300

To putty and respray painting on affected area.

600.00 250

Labour Total S\$:

1,700.00

Total S\$: 7,126.81

=====

SUCCESS UNITED PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adm Lj

W/S 25/07/19.

03 Days.

total: 3767.06.

W/S: BIC.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19012971/Atf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 05-09-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8099M	Veh. Inspected	SGX 2007J	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004623MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	23/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	BMW 116D	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WBA1V720X05C06683	Colour	BLACK	
Odometer	62683	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	YOKOHAMA	6 mm	
L/H Front Tyre	205/55 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/07/2019	Inspection Date	25/07/2019	
Survey held at	SUCCESS UNITED PTE LTD 2 KAKI BUKIT AVE 2 #01-33 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGX 2007J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRT BUMPER	DEFORMED	981.20	981.20
1	FRT BUMPER SIDE HOLDER LH	NECESSARY	32.05	32.05
1	FRT BUMPER BRACKET LH	NOT NECESSARY	38.05	-
1	FRT BUMPER INNER SPONGE	NOT NECESSARY	55.43	-
1	FRT BUMPER REINFORCEMENT	NOT NECESSARY	378.10	-
2	FRT PDC SENSOR @\$398.10	NOT NECESSARY	796.20	-
1	FRT FOGLAMP GARNISH LH	NOT NECESSARY	129.70	-
1	HEADLAMP LH	CRACKED	2,341.55	2,341.55
1	FRT HEADLAMP BRACKET LH	NOT NECESSARY	153.10	-
1	FRT FENDER LH	NOT NECESSARY	597.25	-
1	FRT FENDER INNER LINER LH	NOT NECESSARY	209.80	-
	LESS 5% DISCOUNT		-285.62	-167.74
			5,426.81	3,187.06
LABOUR				
	TO REMOVE,REARRANGE ELECTRICAL WIRINGS,CHECK LIGHTING.		100.00	30.00
	TO REMOVE,REPAIR AND REPLACED DAMAGED BODYPARTS,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	300.00
	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA.		600.00	250.00
			1,700.00	580.00
GRAND TOTAL			7,126.81	3,767.06
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,000.00

Report Ref No. CS/FC119012971/Atf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.