

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 4854U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,150.60	-
10	REAR BUMPER CLIP @\$3.90	NECESSARY	39.00	30.00
1	REAR TAILGATE	DENTED	1,193.00	1,193.00
1	REAR LOGO (SHUTTLE)	NECESSARY	55.00	55.00
1	REAR LOGO (HYBRID)	NECESSARY	80.10	80.10
	LESS 20% DISCOUNT		-503.54	-271.62
			2,014.16	1,086.48
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR (SN)	NOT NECESSARY	200.00	-
1	SEALANT (SN)	NECESSARY	40.00	40.00
			240.00	40.00
	<u>LABOUR</u>			
	TO DISMANTLE & CHANGE REAR BUMPER, REAR TAILGATE, KNOCKING & PULL STRAIGHT REAR END PANEL AND ALL AREA AFFECTED BY ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		800.00	500.00
	TO PERFORM WIRE CHECKING.		20.00	20.00
	TO DISMANTLE & REFIT REAR WINDSCREEN.		100.00	100.00
	TO DISMANTLE & REFIT REAR BUMPER SENSOR.	NOT NECESSARY	60.00	-
	TO DISMANTLE & TRANSFER REAR TAILGATE MECHANISM AND FITTING TO NEW TAILGATE.		60.00	50.00
	TO SPRAY REAR BUMPER, REAR TAILGATE AND REAR PANEL.		800.00	600.00
			1,840.00	1,270.00
GRAND TOTAL			4,094.16	2,396.48

RECOMMENDED COST OF REPAIRS			2,396.48
------------------------------------	--	--	-----------------

Report Ref No. CS/FCI19012994/Eyd3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.