

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

320 UBI ROAD 3

Singapore 408649

Email: denisteo@cdge.com.sg

INSURER: **EQ Insurance Company Ltd (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCHHQ19-00056	Date of Loss:	15/06/2019
Vehicle Reg. No.:	GBJ2804H	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	DEI HOLDING PTE LTD		

Make/Model:	NISSAN NV350, 2.5 5AT 5DR EURO V (A)	Vehicle Reg. Date:	08/03/2019
Vehicle Colour:	WHITE		
Engine No:	YD25042597B	Chassis No:	JN1MC2E26Z0030859
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	10

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (UBI)

COST OF CLAIMS

	Amount
Parts	13,906.40
Miscellaneous Items	0.00
Labour	7,140.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	21,046.40
+ GST 7.00% (\$\$)	1,473.25
Nett Amount (\$\$)	22,519.65

This claim is handled by: CHNG KING LYE JASMINE

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 23 Jul 2019)

Parts: N/A NISSAN NV350 2.5 5AT 5DR EURO V (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/GBJ2804H/23/07/2019 12:24

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT CONER PANEL RH <i>3 Buckled</i>	0.00	0.00	*250.00 F ✓
2	1		*FRONT CONER PANEL LH <i>2 Bays</i>	0.00	0.00	*250.00 F +
3	1		*FRONT GRILLE WIYH CHROME MOULDING <i>cracked</i>	0.00	0.00	*420.00 F ✓
4	1		*FRONT GRILLE EMBLEM <i>new</i>	0.00	0.00	*55.00 F ✓
5	2		*FRONT GRILLE BRACKET <i>2 new</i>	0.00	0.00	*170.00 F ✓
6	1		*FRONT BUMPER SIDE RETAINER RH <i>3 new</i>	0.00	0.00	*100.00 F ✓
7	1		*FRONT BUMPER SIDE RETAINER LH	0.00	0.00	*100.00 F ✓
8	1		*FRONT BUMPER <i>Distorted</i>	0.00	0.00	*400.00 F ✓
9	10		*FRONT BUMPER CLIPS <i>new</i>	0.00	0.00	*20.00 F ✓
10	1		*FRONT BUMPER LOWER GRILLE <i>cracked</i>	0.00	0.00	*480.00 F ✓
11	1		*FRONT BUMPER SIDE COVER RH <i>cracked</i>	0.00	0.00	*75.00 F ✓
12	1		*FRONT BUMPER SIDE COVER LH <i>Missing</i>	0.00	0.00	*75.00 F ✓
13	1		*FRONT BUMPER REINFORCEMENT <i>new</i>	0.00	0.00	*380.00 F +
14	1		*FRONT BUMPER REINFORCEMENT BRACKET RH <i>3 new</i>	0.00	0.00	*55.00 F +
15	1		*FRONT BUMPER REINFORCEMENT BRACKET LH	0.00	0.00	*55.00 F +
16	1		*FRONT TOP REINFORCEMENT <i>new</i>	0.00	0.00	*140.00 F ✓
17	1		*FRONT TOP REINFORCEMENT BRACKET RH <i>3 Bent</i>	0.00	0.00	*40.00 F ✓
18	1		*FRONT TOP REINFORCEMENT BRACKET LH	0.00	0.00	*40.00 F ✓
19	1		*LHF COOLER <i>Dented</i>	0.00	0.00	*500.00 F ✓
20	1		*LHF COOLER AIR DUCT <i>cracked</i>	0.00	0.00	*110.00 F ✓
21	3		*LHF COOLER AIR DUCT CLIPS <i>new</i>	0.00	0.00	*6.00 F ✓
22	1		*RHF AIR COOLER <i>Dented</i>	0.00	0.00	*1,450.00 F ✓
23	1		*RHF AIR COOLER AIR DUCT <i>cracked</i>	0.00	0.00	*100.00 F ✓
24	1		*RHF A - PILLER <i>Dented</i>	0.00	0.00	*800.00 F ✓
25	1		*RHF DOOR <i>Distorted</i>	0.00	0.00	*650.00 F ✓
26	1		*RHF DOOR TOP HINGE <i>3 Bent</i>	0.00	0.00	*35.00 F ✓
27	1		*RHF DOOR BOTTOM HINGE	0.00	0.00	*35.00 F ✓
28	1		*RHF DOOR CHECKER <i>2 new</i>	0.00	0.00	*32.00 F ✓
29	1		*RHF DOOR INNER TRIM <i>new</i>	0.00	0.00	*380.00 F +
30	1		*RHF DOOR RUBBER <i>new</i>	0.00	0.00	*75.00 F +
31	1		*RHF DOOR LOCK <i>new</i>	0.00	0.00	*120.00 F +
32	1		*RH B-PILLER <i>Dented</i>	0.00	0.00	*900.00 F ✓
33	1		*RH B-PILLER MUDFLAT <i>new</i>	0.00	0.00	*88.00 F ✓
34	1		*RHF STEP GARNISH <i>new</i>	0.00	0.00	*35.00 F +
35	1		*REAR TAIL GATE <i>Dented</i>	0.00	0.00	*1,100.00 F ✓
36	1		*REAR TAIL GATE RUBBER <i>new</i>	0.00	0.00	*90.00 F +
37	1		*RHR TAIL LAMP <i>cracked</i>	0.00	0.00	*125.00 F ✓
38	1		*RHR TAIL LAMP PANEL <i>Dented</i>	0.00	0.00	*380.00 F ✓
39	1		*RHR FENDER PANEL <i>Distorted</i>	0.00	0.00	*1,200.00 F ✓
40	1		*RHR PETROL OUTER COVER <i>new</i>	0.00	0.00	*80.00 F +
41	1		*RHR PETROL OUTER SWITCH ?	0.00	0.00	*95.00 F ?
42	1		*RHR AIR VENT <i>cracked</i>	0.00	0.00	*40.00 F ✓
43	1		*REAR BUMPER <i>Distorted</i>	0.00	0.00	*280.00 F ✓
44	1		*REAR BUMPER SIDE CLIPS RH <i>new</i>	0.00	0.00	*8.00 F ✓
45	10		*REAR BUMPER CLIPS <i>new</i>	0.00	0.00	*20.00 F ✓

ComfortDelGro Engineering Pte Ltd/GBJ2804H/23/07/2019 12:24. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*REAR BUMPER INNER BRACKET ?	0.00	0.00	*100.00 F ?
47	1		*REAR EMBLEM	0.00	0.00	*40.00 F ✓
48	1		*NV 350 WORDING } <i>new</i>	0.00	0.00	*65.00 F ✓
49	1		*URVAN WORDING	0.00	0.00	*40.00 F ✓
50	1		*70 KM / H	0	0.00	*10.00 FS ✓
51	1		*COMPANY STICKER <i>new</i>	0	0.00	*10.00 FS ✓
52	1		*RHF STEEL RIM <i>rented</i>	0.00	0.00	*180.00 F ✓
53	1		*RHF TYRE 195 /R15 <i>new</i>	0.00	0.00	*240.00 F ✓
54	1		*RHF STEEL RIM COVER <i>new</i>	0.00	0.00	*120.00 F ✓

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	12,644.00
+ Margin on L,N Items 10.00% (\$\$)	1,262.40
Total Parts (\$\$)	13,906.40

ComfortDelGro Engineering Pte Ltd/GBJ2804H/23/07/2019 12:24. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO DISCONNCT & CHECK ELECTRICAL WIRING , WIRE SOCKET ETC FOR FRONT AND REAR.	New	180.00 60
2	TO REMOVE & REINSTALL FRONT & REAR WINDSCREEN.	New	280.00 240
3	TO REMOVE & REINSTALL REVERSE SENSOR	New	100.00 50
4	TO DISMANTALL & TRANSFER REAR TAIL GATE & RHF DOOR FITTINGS AND MECHANISM TO NEW DOOR / FACILITATE REPAIR.	New	480.00 160
5	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	New	100.00 80
6	TO CUT & WELD RHF A-PILLER, RH B-PILLER ,RHR FENDER PANEL,RHR TAIL LAMP,KNOCK &REPAIR FRONT PANEL,A-PILLER INNER PANEL,RHF FLOOR PANEL,END PANEL AND AFFCETED AREA.	New	3,200.00 2800
7	TO PUTTY & SPRAY FRT PANEL,FRT BUMPER,A-PILLER,B-PILLER,RHF FLOOR PANEL,RHF DOOR,RHR FENDER PANEL,RHR TAIL LAMP PANEL,END PANEL,REAR BUMPER,REAR TAIL GATE AND AFFECTED AREA	New	2,800.00 1700
Gross Labour Cost (\$\$)			7,140.00

ComfortDelGro Engineering Pte Ltd/GBJ2804H/23/07/2019 12:24. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ly
P/P 24/07/18.

18 Days.

Not Authorised

Excess : 3.5K.