

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19013021/EKA3Q2

Date: 05/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800135569

Claimant
Vehicle No : SHB5506U **Insured Vehicle No :** SKJ8213S

Date of Loss: 20/07/2019 Nature of Claim: TP Claim No: 7618411271SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB5506U		
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Engine No:	2ZRS099950
Reg. Date:	01/11/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU703573278
Colour:	Maroon	Odometer:	184884 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,373.40	0.00	1,373.40	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	436.00	200.00	236.00	54.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	1,809.40	200.00	1,609.40	88.95
+ Loss of Use (3.0 x S\$50.00/day) (\$\$)		150.00		
+ Car Rental (3.0 x S\$112.35/day) (\$\$)		337.05		
		(S\$)		
		687.05		
Liabile Amount (50.00%) (\$\$)		343.53		
+ Doc/Search Fee (\$\$)		7.00		
Nett Liability (\$\$)		350.53		
Global Sum Settlement (\$\$)		400.00		

INSPECTION

Date of Assignment: 23/07/2019

Date Inspected: 23/07/2019 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 1.0 days

Adjuster: CHEN TSUE YEE**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MIRROR ASSY , OUTER REAR VIEW LH	Not Necessary	1,283.90 F	*- F
2	1		*COVER , OUTER MIRROR LH	Repair	89.50 F	*- F
F=Franchise part.						
					Total Parts (S\$)	1,373.40 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINT	New	180.00	80.00
2	TO REMOVE AND REFIX WING MIRROR	New	120.00	60.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
4	TOWING CHARGE	New	56.00	40.00
Gross Labour Cost (\$\$)			436.00	200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >