

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG19013038/KEA3Q2**Date:** 07/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994248
Claimant Vehicle No :	GBF6358Z	Insured Vehicle No :	SMD2051P
Date of Loss:	16/07/2019	Nature of Claim:	TP
		Claim No:	5024218959SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF6358Z	Engine No:	YD25407202A
Make & Model:	NISSAN NV350, 2.5 5MT 5DR EURO V (A)	Chassis No:	JN1MC2E26Z0007284
Reg. Date:	09/01/2017 (Man. Year: 2016)	Odometer:	70134 km
Colour:	White		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	CST 9 mm	Rear Left Side:	KAPSEN 8 mm
Front Right Side:	CST 9 mm	Rear Right Side:	KAPSEN 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,668.95	3,014.97	1,653.98	35.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,190.00	1,570.00	620.00	28.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,858.95	4,584.97	2,273.98	33.15
Approved Total (Overridden) (S\$)		3,650.00		
(S\$)	6,858.95	3,650.00	3,208.95	46.78
+ GST 7.00/7.00% (S\$)	480.13	255.50	224.63	46.79
Nett Amount (S\$)	7,339.08	3,905.50	3,433.58	46.78
+ Car Rental (8.0 x S\$100.00/day + 7.00% GST) (S\$)		856.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		4,797.95		
Global Sum Settlement (S\$)		4,790.00		

INSPECTION

Date of Assignment:	24/07/2019	Chew Goon Motor (AMK)
Date Inspected:	24/07/2019 Inspected At:	Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint
Estimated Period of Repair:	5.0 days	Singapore 568047

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled / Dented	514.70 FN	*514.70 FN
2	10		*FRONT BUMPER CLIPS	Necessary	50.00 FN	*50.00 FN
3	1		*FRONT BUMPER TOP RETAINER LH	Serviceable	147.00 FN	*- FN
4	1		*FRONT BUMPER CORNER HOLDER LH	Serviceable	104.70 FN	*- FN
5	1		*FRONT BUMPER FOG LAMP	Serviceable	323.70 FN	*- FN
6	1		*FRONT BUMPER FOG LAMP COVER	Serviceable	130.10 FN	*- FN
7	1		*HEADLAMP LH	Cut	403.00 FN	*403.00 FN
8	1		*FRONT DOOR LOWER STEP BOARD	Cut	72.50 FN	*72.50 FN
9	1		*FRONT DOOR LOWER RUBBER SEAL	Serviceable	75.00 FN	*- FN
10	1		*FRONT WHEEL CAP LH	Dented	162.80 FN	*162.80 FN
11	1		*FRONT MUDFLAP LH	Cracked	155.00 FN	*155.00 FN
12	1		*SLIDING DOOR LH	Bent	1,777.00 FN	*1,525.30 FN
13	1		*FRONT DOOR REG LEBEL LH	Necessary	45.00 FS	*20.00 FS
14	1		*SLIDING DOOR BODY STICKER (CUSTOMISED)	Scratched	550.00 FS	*400.00 FS
15	1		*REAR FENDER BODY STICKER (CUSTOMISED)	Not Necessary	550.00 FS	*- FS
F=Franchise part. S=SpcNett. N=NettItemDisc.						
Sub Total (S\$)					5,060.50	3,303.30
- Nett Item Discount on N Items 10.00/10.00% (S\$)					391.55	288.33
Total Parts (S\$)					4,668.95	3,014.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CONDUCT ELECTRICAL CHECK ,FOCUS HEADLAMP	New	30.00	20.00
2	TO DISMANTLE /TRANSFER SLIDING DOOR FITTINGS AND ACCESSORIES	New	120.00	60.00
3	TO APPLY RUST PROOFING /RESEAL TUFF COATING	New	60.00	30.00
4	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT TEST	New	80.00	60.00
5	LABOUR CHARGE-PANEL BEATING ,REPAIRING OF FRONT DOOR ,STEP PANEL,DOOR B PILLAR ,REAR FENDER AND PARTS REPLACEMENT	New	700.00	550.00
6	TO RESPRAY AFFECTED AREAS	New	1,200.00	850.00
Gross Labour Cost (\$\$)			2,190.00	1,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >