

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG19013041/UKA3Q2

**Date:** 19/10/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100338435

**Claimant**  
**Vehicle No :** SLV7906H **Insured Vehicle No :** SFF500X

Date of Loss: 20/07/2019 Nature of Claim: TP Claim No: 7316857337SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLV7906H</b>		
Make & Model:	NISSAN NOTE, 1.2 CVT (A)	Engine No:	HR12276954B
Reg. Date:	16/01/2018 (Man. Year: 2017)	Chassis No:	JN1TAAE12Z0980172
Colour:	Blue	Odometer:	16670 km
Engine Capacity:	1198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Continental 7 mm	Rear Left Side:	Continental 7 mm
Front Right Side:	Continental 7 mm	Rear Right Side:	Continental 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,959.45	3,400.69	2,558.76	42.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,130.00	1,750.00	380.00	17.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>8,089.45</b>	<b>5,150.69</b>	<b>2,938.76</b>	<b>36.33</b>
<b>+ Loss of Use (6.0 x S\$30.00/day) (S\$)</b>		180.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>5,338.14</b>		
<b>Global Sum Settlement (S\$)</b>		<b>5,300.00</b>		

### INSPECTION

Date of Assignment: 24/07/2019

Date Inspected: 24/07/2019 Inspected At:

Chin Meng Motors (HQ)  
1 Kaki Bukit Ave 6 #01-40/63, Autobay  
@ Kaki Bukit  
Singapore 417883

Estimated Period of Repair: 5.0 days

**Adjuster:** MARCUS CHUA

**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	976.40 FN	*976.40 FN
2	1		*TAILGATE EMBLEM -NOTE	Necessary	73.60 FN	*73.60 FN
3	1		*TAILGATE EMBLEM -NISSAN	Necessary	65.70 FN	*65.70 FN
4	1		*TAILGATE INNER LOCK	Dented / Shorted	198.60 FN	*198.60 FN
5	2		*TAILGATE HINGES	Not Necessary	130.20 FN	*- FN
6	1		*TAILGATE BOARD	Not Necessary	328.60 FN	*- FN
7	1		*TAILGATE WEATHERSTRIP	Twisted	98.60 FN	*98.60 FN
8	1		*TAILGATE CENTRE GARNISH	Not Necessary	288.60 FN	*- FN
9	2		*TAILGATE SIDE STOPPERS	Not Necessary	25.00 FN	*- FN
10	1		*TAILGATE CENTREAL LOCK	Not Necessary	199.60 FN	*- FN
11	1		*REAR WINDSCREEN MOULDING	Necessary	68.00 FN	*68.00 FN
12	1		*REAR BUMPER	Distorted	464.00 FN	*414.00 FN
13	2		*REAR BUMPER RETAINERS	Not Necessary	110.80 FN	*- FN
14	1		*REAR BUMPER BRACKETS	O/S Dented	197.00 FN	*65.50 FN
15	8		*REAR BUMPER CLIPS	Necessary	36.00 FN	*36.00 FN
16	1		*REAR BUMPER SIDE COVER	O/S Twisted	97.00 FN	*48.50 FN
17	2		*REAR BUMPER REFLECTOR	Not Necessary	117.00 FN	*- FN
18	1		*REAR BUMPER FOAM	Torn	133.90 FN	*133.90 FN
19	1		*REAR REVERSE SENSOR	Shorted	225.00 FS	*200.00 FS
20	1		*REAR END PANEL	Badly Dented	500.20 FN	*500.20 FN
21	1		*REAR END PANEL GARNISH	Twisted	98.50 FN	*98.50 FN
22	1		*REAR FENDER INNER TRIM BOARD	O/S Torn	756.80 FN	*378.40 FN
23	1		*TAILLAMPS	O/S Cracked	931.40 FN	*293.70 FN
24	2		*TAILLAMP CLIP	Not Necessary	25.00 FN	*- FN
25	1		*REAR NO.PLATE WITH COVER	Necessary	45.00 FS	*40.00 FS
26	1		*REAR NO.OPC SEAL	Necessary	21.00 FS	*16.05 FS
27	1		*REAR WINDSCREEN GUM	Necessary	40.00 FS	*40.00 FS
28	1		*REAR VIEW CAMERA	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

<b>Sub Total (S\$)</b>	<b>6,551.50</b>	<b>3,745.65</b>
<b>- Nett Item Discount on N Items 10.00/10.00% (S\$)</b>	592.05	344.96
<b>Total Parts (S\$)</b>	<b>5,959.45</b>	<b>3,400.69</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO PANEL BEATING ,WELDING ,REMOVING DAMAGED PARTS AND REPLACEMENT OF THE NEW PARTS AS MENTIONED ABOVE ETC	New	900.00	650.00
2	TO APPLY UNDERSEAL	New	80.00	60.00
3	TO REMOVE AND REFIT REAR WINDSCREEN	New	120.00	120.00
4	TO RESPRAY AFFECTED PART	New	1,000.00	900.00
5	TO CHECK WIRINGS	New	30.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,130.00</b>	<b>1,750.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >