



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## General Details

Involving

1 2015 FIAT DOBLO CARGO MAXI 1.6 MTJ (GBH6866M)

Date of Loss

19 July 2019

Time of Loss

12.40

Loss Description

GBH6866M (INSD) HIT REAR OF GBG7202C (TP)

Comment

## Workshop Details

Total Rebate Amount

14269

Nett Loss Amount

\$24,731.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion \*

20



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

### Vehicle & Driver Details



Vehicle Registration#	GBH6866M	Purchase Date	<input type="text" value="dd/mm/yyyy"/>
Registration State	<input type="text" value="SINGAPORE"/>	Registration Date *	<input type="text" value="15/12/2015"/>
Mileage	<input type="text" value="155600"/>	Age of Vehicle	3

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2015	<input type="text" value="2015"/>
Make	FIAT	<input type="text" value="FIAT"/>
DORLO CARGO		<input type="text"/>

### Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	NG SENG HUAT	<input type="text"/>
Date of Birth	10 January 1979	<input type="text" value="dd/mm/y"/>

Model CATEGORY	DOBLO CARGO MAXI 1.6 MTJ POLICY INFORMATION	DOBLO CARGO INFORMATION
Type		<input type="text"/>
Type of Paint		<input type="text"/>
Chassis No	ZFA26300006B30730	<input type="text" value="ZFA26300006B"/>
Engine No	263A50007454927	<input type="text" value="263A50007454"/>
Engine Capacity		<input type="text" value="1598"/>
Sum Insured	0	<input type="text" value="0"/>
Market Value	0	<input type="text" value="39000"/>

CATEGORY Age	FNOL INFORMATION 40	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text"/>
Education Qualification	Other	<input type="text"/>
Driving Experience	5	
Driver License #		<input type="text"/>
License Type		<input type="text"/>
License Issue Date	1 January 2014	<input type="text" value="dd/mm/y"/> 
License Expiration Date		<input type="text" value="dd/mm/y"/> 

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Address	BLK 132 SIMEI STREET 1, #04-120, 520132, Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="▼"/>
Gender	Male	<input type="text" value="▼"/>
Marital status	Unknown	<input type="text" value="▼"/>
Identification #	S7901364A	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Detailed Assessment

Inspection Date \*

24/07/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

600

Young/Inexperienced/  
Unnamed Driver  
Excess

0

### Condition of Vehicle at time of survey

General condition

Fair ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake  
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair ▾

Other Excess

Tyre Condition

Age of Tyres	<input type="text"/>	Spare wheel	<input type="text"/>
Front Tyre Size	<input type="text" value="195/60R16"/>	Rear Tyre Size	<input type="text" value="195/60R16"/>
Front left side	<input type="text" value="KUMHO6mm"/>	Rear left side	<input type="text" value="KUMHO6mm"/>
Front right side	<input type="text" value="KUMHO6mm"/>	Rear right side	<input type="text" value="KUMHO6mm"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text"/>	Salvage%	<input type="text"/>
Discount%	<input type="text" value="10"/>	Settlement%	<input type="text" value="100"/>

## Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Paint Material Ratio	<input type="text" value="80"/>
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save





SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

























Add

























Approve

Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		BONNET	Buckled	0	694.64	No		10			625.18	Reviewii
		0	1		BONNET, HINGE - LH	Serviceable	0	0	No		10			0	Deny
		0	1		BONNET, HINGE - RH	Serviceable	0	0	No		10			0	Deny
		0	1		HEADLAMP LHS	Cracked	0	747.18	No		10			672.46	Reviewii
		0	1		HEADLAMP RHS	Cracked	0	747.18	No		10			672.46	Reviewii
		0	1		RADIATOR GRILLE	Deformed	0	411.86	No		10			370.67	Reviewii
		0	1		FRONT BUMPER, TOP	Deformed	0	779.92	No		10			701.93	Reviewii
		0	1		FRONT BUMPER, LOWER	Deformed	0	665.28	No		10			598.75	Reviewii

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		BUMPER BRACKET LHS	Necessary	0	23.94	No		10			21.55	Reviewii
		0	1		BUMPER BRACKET RHS	Necessary	0	23.94	No		10			21.55	Reviewii
		0	1		MAKE MEDALLION (FIAT EMBLEM)	Missing	0	68.8	No		10			61.92	Reviewii
		0	1		LIC. PLATE SUPPORT (LICENSE PLATE HOLDER SUPPORT)	Cracked	0	74.46	No		10			67.01	Reviewii
		0	1		FRONT FENDER LHS	Bent	0	245.02	No		10			220.52	Reviewii
		0	1		FRONT FENDER RHS	Bent	0	245.02	No		10			220.52	Reviewii
		0	1		WICK, FR BUMPER	Cut	0	109.89	No		10			98.9	Reviewii
		0	1		REINFORCEMENT, BUMPER - TOP (PLASTIC)	Serviceable	0	0	No		10			0	Deny
		0	1		A/C CONDENSER	Bent	0	475	No		10			427.5	Reviewii
		0	1		RADIATOR	Bent	0	410	No		10			369	Reviewii
		0	1		RADIATOR FAN MOTOR ASSY	Serviceable	0	0	No		10			0	Deny
		0	1		BONNET LOCK	Damaged	0	119.32	No		10			107.39	Reviewii

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		CONVEYOR, RADIATOR - TOP	Cracked	0	71.21	No		10			64.09	Reviewii
		0	1		MOULDING, FT PILLAR - LH	Serviceable	0	0	No		10			0	Deny
		0	1		MOULDING, FT PILLAR - RH	Serviceable	0	0	No		10			0	Deny
		0	1		FR MUDGUARD PROTECTION - LH	Serviceable	0	0	No		10			0	Deny
		0	1		FR MUDGUARD PROTECTION - RH	Serviceable	0	0	No		10			0	Deny
		0	1		ORNAMENT, BUMPER LHS	Cracked	0	52.59	No		10			47.33	Reviewii
		0	1		ORNAMENT, BUMPER RHS	Cracked	0	52.59	No		10			47.33	Reviewii
		0	1		END PLATE RHS HEADLAMP	Cracked	0	141.36	No		10			127.22	Reviewii
		0	1		CROSSRAIL - TOP	Bent	0	311.51	No		10			280.36	Reviewii
		0	1		END PLATE LHS HEADLAMP	Serviceable	0	0	No		10			0	Deny
		0	1		CONVEYOR, RADIATOR- BOTTOM (SQUARE)	Cracked	0	84.55	No		10			76.1	Reviewii
		0	1		CROSSRAIL, FR BUMPER (REINFORCEMENT)	Bent	0	349.1	No		10			314.19	Reviewii

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		ELECTROVALVE	Cracked	0	175	No		10			157.5	Reviewii
		0	1		CLAMPED COLLAR	Necessary	0	3.37	No		10			3.03	Reviewii

Labour

Add

Approve

Deny

Submit All

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
		0		TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC	0	2400	0	0	Reviewing	
		0		TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK	0	180	0	0	Reviewing	
		0		TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	0	1400	0	0	Reviewing	
		0		TO REMOVE AND REFIX AIRCON SYSTEM AND TOP UP GAS. TO CHECK FUNCTION	0	600	0	0	Reviewing	
		0		TO REMOVE AND REFIX RADIATOR. TO CHECK FUNCTION	0	300	0	0	Reviewing	



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details    Vehicle & Driver Details    Vehicle Condition    Taxes & Ratio    Parts & Labour    Miscellaneous    Summary

Add

Approve

Deny

Submit All

EDIT

SR  
NO

NAME

ACTION

ESTIMATED  
AMOUNT

ADJUSTED  
AMOUNT

COMMENT

REMOVE



0

DAYS OF  
REPAIR : 7  
DAYS

Reviewing

0



0

NUMBER  
PLATE

Reviewing

25

MISSING



0

COOLANT

Reviewing

45

NECESSARY



0

SUNDRIES

Deny

0

NOT  
NECESSARY







# Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount		\$0.00		Adjusted Claim Amount		\$10,724.46	
CATEGORY		ESTIMATE		ADJUSTED			
Spare Parts		\$0.00		\$6,374.46			
Labour		\$0.00		\$4,880.00			
Miscellaneous		\$0.00		\$70.00			
Excess				-\$600.00			

Submit for Review