NS, COAT OVACUE	Stary 004/ASM19013	054 / TI Was DAG 128782
Surveyor:	MY ASSIGNME	
Pre-assign / CCU/		Registered in Merimen:
Insured Vehicle No.	GBE 96675	Claim No. : 89M0\V06
Name of Insured	Starulia humagement company the Utd	- VI
Insured Tel No.	HP:	Make / Model :
Excess Sec II :SS	DOA: 74/7/19 (WW)	Place of Accident :
Is driver the owner?	(YES /NO) Nature of Accident :	- (a)
If NO, Driver Name Driver Tel N		OI GIA REPORT: (E)/NO; TP GIA REPORT: (D)/NO Insured Liability: % Final? Yes/No
SLB 4324		model Elebrity . 76 Final , 165/170
INSRS: WSP: Auto wh Tel: Liability: RMKS:	uls INSRS: WSP: Tel: Liability: RMKS:	INSRS: WSP: Tel: Liability: RMKS: INSRS: WSP: Tel: Liability: RMKS:
Date/ Time	610,000,000	len en
	GBE 96675 JX	STAGE DATE / PIC Non-Reporting ltr (1st):
	19	Non-Reporting ltr (2nd): Non-Reporting ltr (Final):
alalia	* 1 * 1	Notification ltr (if non-pickup): Call OI:
818111	continu accordent defails letter	Pocumentation Check List: Handler Typist
2011olia	Tile -) Syvunm to well DI In	Documentation Check List: Handler Typist Notification ltr (if non-pickup)
- 11 1	580	After call ltr to OI:
		Release Voucher:
		Final Repair Bill:
W.		Car Rental Invoice:
		LTA/GIA:
		Medical Bill:
		PIR
		Manate/Reject Instruction:
		Payment Breakdown Form:
RELIMINARY ADVICE	Date/Time: Sent By:	Post-Repair Photos:
DULLIZATION /	D	Others:
INALIZATION epair Cost:	Date/Time: Confirm with: S\$ (days) Reduction:	Confirm by:
INAL SETTLEMENT	Date/Time: 29 10 Confirm with	Email Call
inal Liability:	% (Agreed / Assessed) BOKA S(N No. 3 2	If NO or B 28, Ass. Lia:
tepair Cost. W 667	SS 7864. PV	
oss of Rental (LOR): oss of Use (LOU):	S\$ - (- days) S\$ 644 \(\text{S} \text{ (x \ \text{ (days)} \)}	
oss of Income (LOI):	SS (\$ — x - days)	COMPAN STANT
OR only LOU only	LOR + LOU LOR + LOI Tick only one	(Settler)
BIA/LTA Search	ss 7.45	
Medical:	SS - (T) (1)	Claim status: Normal/Reject/Private Settle
Disbursement: Legal Cost	SS (OV - W (e.g. 109) Independent	2) Report Format: 3) Survey fee: 2350. W
Fotal:	SS 8571.95 Global Sum SS: 8500-0	
INAL PAYMENT	Date/Time: Confirm with:	Email Call
Payee 1:	SI 8500 W Name 1: Auto whee	Is Motorworks PtR Utcl
Payee 2: (Strike if N.A.)	S\$ Name 2:	A second
Payee 3: (Strike if N.A.)	S\$ Name 3:	
10 1000		

ASSIGNMENT

From: Date:	Veh No. SLB 4324 L. Yr Regn. 2016 / April			
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /			
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or			
Te Inspect Vehicle No:	Make: Toyak Axis. cc/49C			
at Workshop m/s	Make: Toyok Axio. cc/496 Colour Sylver A/C: Insured/Std/NI/NA			
of	Sp.Reading / 32706 T/Radio: Insured / Std / NI / NA			
Insured:	Eng/No:			
Policy No.	C/No: NRE/6/00/12-/3			
Claims No.	Gen. Cond: (abod) / Fair / Poor / Burnt			
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or			
(Client's Record)	Brake: knorder / Jammed / Leaked / Burnt or			
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or			
	Tyre Size: F: (85/60/1)			
(Policy Condition)	R: ~ ~			
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /			
repair at the time of inspection.	TOYOTYOKO OF GOOGLOTCH			
Ball, or Market Value: 456K	Front Rear			
IDAC Accident Rport: Consistent? : Yes or No	R/Ball, C mm R/Ball, G mm			
GIA / PR Seen; Consistent? : Yes or No	L/Bal. 6 mm			
Est. Repairs: Od days Res.: Yes or No	D.O.A. D.O.I. 25/7/190 245/20			
Lum Sum: 20 % 3 Val. Yes or No	Survey held at My to wheel But Bth WCEG H.			
- wp.	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or			
CA / REV / REP. / 24 HRS Vehicle: IN / OUT				
Date: Person Contacted: Lows	The U/C / Chassis frame / Body Structure affected due to collision.			
Date / Time Action / Instruction				
US # 7350 CReel \$ at 29m = 11d	9185. 80/567.).			
Dale/Time, File Pass to? : Prell. Report	Days Of Repair:			
1) : Final Report Date/Time, File Rotum to?	Resurvey No. of Trip: Survey Fee: Transportation:			
a Add Fee	(
	: Interview (\$) Photos			
Report Formst:	: Tech, Inve (3) open			
Lump Sum / LE ft /2	: Westerd (\$			
	109.0			

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particula	ers
Owner ID Type:	Business
Owner ID: Vehicle Details	662M
Vehicle No.:	SLB4324L
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5X
	CVT ABS D/AIRBAG 2WD
Primary Colour:	Gold
Manufacturing Year:	2015
Engine No.:	2NR8524700
Chassis No.:	NRE1610011213
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$14,472.00
Original Registration Date:	07 Apr 2016
First Registration Date:	07 Apr 2016
Transfer Count:	2
Actual ARF Paid:	\$9,472.00
Intended PARF Rebate	Details
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Apr 2026
PARF Rebate Amount: Intended COE Rebate D	\$7,104.00 retails
COE Expiry Date:	06 Apr 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,000.00
COE Rebate Amount:	\$30,135.00
Total Rebate Amount:	\$37,239.00
	CONTROL OF THE PROPERTY OF THE

The information contained herein is correct as at 26 Jul 2019

ОК

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#02-40 SINGAPORE 658064

ATTN: AXA INSURANCE

ESTIMATION

DATE:

24/07/2019

VEHICLE NO:

SLB4324L

MODEL:

AXIO

YEAR:

2016

ACCIDENT DATE:

TYPE OF CLAIM:

24/07/2019

CLAIM ADVISOR: LOUIS ONG (91928963)

EMAIL: louisongautowheels@yahoo.com

NRE /6100

		10 a
DESCRIPTION	QTY	LIST PRICE
PARTS		
REAR WINDSCREEN	1	\$ - 1,064.20 Crg -
REAR WINDSCREEN MOULDING	1	\$ 198.70101
REAR FENDER UPPER INNER TRIM	2	\$ 698.60 F
BOOTLID	1	\$ 986.3001
BOOTLID HINGE	2	\$ 299.40 67
BOOTLID STOPPER	2	\$ 44.60 10
BOOTLID OUTER CHROME GARNISH	1	\$ ~ 218.30 and ~
REAR NUMBER PLATE LAMP	2	\$ × 398.60 × 500
BOOTLID LOCK	1	* 5 ds/v 368.30? plusto Distrited
REAR EMBLEM	1	\$ 55.30 49
REAR LOGO - COROLLA	1	\$ 52.30 ~
REAR LOGO – AXIO	1	\$ 54.20
REAR BUMPER	1	\$ ~ 789.50 dis-
REAR BUMPER CLIPS	10	\$ V 30.00 10 /17
REAR BUMPER RETAINER - LONG	2	15 42.40 80-80 L4-8 KH- US-
REAR BUMPER RETAINER - SHORT	2	V 5 34.20 68.40 LH - 21 -11
REAR BUMPER REFLECTOR	2	V \$ 244.304886064-4, RH-art
TAILLAMP	2	\$ \$ 882.60 04
TAILLAMP SEAL	2	\$ 66.80 40(-
TAILLAMP CLIPS	2	\$ 24.60/20
TAILLAMP PANEL	2	5 244.30 488.60 LH-RY, EH-W
END PANEL	1	S 596.30 DL
SPARE TYRE PANEL	1	c x 797 30 RY
SPARE TYRE BOARD	1	\$ × 399.70 × nn
END PANEL TOP GARNISH	1	* \$ \ 255.60? Deform de
REAR WEATHER STRIP	1	+ \$ V 249.70 ? (W) Defur

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

HO2-40 SINGAPORE 658064

ATTN: AXA INSURANCE

FSTIMATION

RH REAR FENDER RH REAR FENDER INNER PANEL RH REAR FENDER INNER SHIELD RH REAR FENDER INNER SHIELD CLIPS RH REAR DOOR RH REAR CHASSIS LH REAR FENDER REAR FENDER INNER TRIM REAR SPEAKER BOARD TRIM **EXHAUST PIPE** EXHAUST PIPE GASKET EXHAUST PIPE MOUNTING ROOF PANEL TRIM

24/07/2019 DATE: SLB4324L VEHICLE NO:

MODEL: YEAR:

ACCIDENT DATE:

TYPE OF CLAIM: CLAIM ADVISOR:

LOUIS ONG (91928963)

EMAIL: louisongautowheels@yahoo.com

AXIO

2016

TP

24/07/2019

1			\$	976.90 buc-
1				DEDAIR
1			\$	196.50 X 5 V C
10			\$	196.50 X SVC 30.00 7 XN/N
1				REPAIR 1,318.30
1				REPAIR
1				REPAIR REPAIR 692.80 H-X, RH-7, Defor
1 2		ж	\$ 341.	40 682.80 H-X RH- V CEFON
1			\$	450.50 / /
1			\$	986.40 82
1	9 95		5	45.30 ? x SVC
2			\$	188.60 ? X SVC
1			\$	1,023.30 X SVC
				8 120.2

14,234.40

3,558.60 10,675.80

6,090.15

LKK Auto Consultants hence notify the Repairer of the following:

\$

TOTAL: \$

DISCOUNT 25%: \$

- To resurvey before/after spray car long
- To display damaged part(s) corning recurvey Parts prices are subject to confirmator
- Third party survey is on a "without Prejudice" basis
- No illegal modification(s) is blowed.
- Supplementary item(s) more recovered and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

MOTORWORKS PTE LTD

WCFGA PLAZA NO 1	BUKIT	BATOK	CRESCENT
------------------	-------	-------	----------

#07-40 SINGAPORE 658064

ATTN: AXA INSURANCE	DATE: VEHICLE NO:	24/07/2019 SLB4324b
	MODEL:	AXIO
		2016

YEAR: 2016
ACCIDENT DATE: 24/07/2019

TYPE OF CLAIM:

CLAIM ADVISOR: LOUIS ONG (91928963)

1000	1000	71	19	R
EST	IVIA	11	12	IV

		PRICE		
S/NET	1	\$	250.0020011	
REVERSIL SENSOR	1	\$	50.00 45 bt	
REAR NUMBER PLATE	1	\$	100.00 40me	
END PANEL SEALANT	í	s	150.00 × 174	345
SPARE TYRE PANEL BLACK STICKER	1	\$	100.00 × NM	2000
PANEL SEALANT	1	\$	100.00 Cone	
REAR WINDSCREEN SEALANT	•	\$	750.00	

20040 SM28	PRIC	E
LABOUR	\$	1,800.00/400
LABOUR FOR FACILITATE REPAIR	ė	300.00 200
TO RESPRAY AFFECTED AREAS - REAR BUMPER	,	300.00 200
TO RESPRAY AFFECTED AREAS - END PANEL	\$	300.00 200
TO RESPRAY AFFECTED AREAS - LH REAR FENDER	\$	300.00
TO RESPRAT AFFECTED AREAS BY BEAR SENDER AND INNER PANEL	\$	300.00 250
TO RESPRAY AFFECTED AREAS - RH REAR FENDER AND INNER PANEL	9	300.00 XU7
TO RESPRAY AFFECTED AREAS - RH REAR DOOR	,	300 00 X A A
TO RESPRAY AFFECTED AREAS - RH REAR CHASSIS	3	NN X 300.00 200 ? pho to.
TO STRAIGHTEN AND ALIGN RH REAR CHASSIS	\$	150.00 /2.5.
TO REMOVE AND REFIT REAR WINDSCREEN	\$	
RUST PROOFING	\$	80.00 4 5
	1:46\$	50.00 20-
SUNDARIES	R BOARI S	250.00 /00
TO REMOVE AND REFIT REAR SEAT, SPEAKER BOAR, ROOF LINING, FLOO	H. S.	2530

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#02-40 SINGAPORE 658064

ATTN: AXA INSURANCE

ESTIMATION

DATE:

24/07/2019

VEHICLE NO:

SLB4324L

24/07/2019

MODEL:

AXIO

YEAR:

2016

ACCIDENT DATE:

TO

TYPE OF CLAIM:

17

CLAIM ADVISOR:

LOUIS ONG (91928963)

EMAIL: louisongautowheels@yahoo.com

TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR
TO REMOVE AND REFIT REAR EXHAUST
TO REMOVE AND REFIT REVERSE SENSOR
TO VACUUM AND CLEAN UP FRAGMENT GLASS
TO CHECK AND RECONNECT ALL NECESSARY WIRING

	\$ 250.00	60	220
	\$ 150.00	60.	
	\$ 100.00	30	
	\$ 80.00	40.	
	\$ 100.00	30	2,7.50
TOTAL:	\$ 5,110.00		0.0

TOTAL: \$ 16,535.80 7% GST: \$ 1,157.51 \$ 17,693.31 7.185.15

Phupsum
Resum offer reprir
tauffun (Mando 10 m.

3/10 Enrol louis

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#02-40 SINGAPORE 658064

ATTN: AXA INSURANCE

ESTIMATION

DATE:

24/07/2019

VEHICLE NO:

SLB4324L

MODEL:

AXIO

YEAR:

2016

ACCIDENT DATE:

24/07/2019

TYPE OF CLAIM:

CLAIM ADVISOR:

LOUIS ONG (91928963)

DESCRIPTION	QTY	LI	ST PRICE
PARTS			
REAR WINDSCREEN	1	\$	1,064.20 (19)
REAR WINDSCREEN MOULDING	1	\$	198.70191
REAR FENDER UPPER INNER TRIM	2	\$	698.60 F
BOOTLID	1	\$	986.30 0/
BOOTLID HINGE	2	\$	299.40 67
BOOTLID STOPPER	2	\$	44.60 10
BOOTLID OUTER CHROME GARNISH	1	\$	218.3000
REAR NUMBER PLATE LAMP	2	\$	398.60 ?
BOOTLID LOCK	1	\$	368.30 ? plu to
REAR EMBLEM	1	\$	55.30 10
REAR LOGO - COROLLA	1	\$	52.30 AA
REAR LOGO – AXIO	1	\$	54.20 AN
REAR BUMPER	1	\$	789.50 dis
REAR BUMPER CLIPS	10	\$	30,00 14
REAR BUMPER RETAINER - LONG	2	\$	84.80 LH-?, KH-US-
REAR BUMPER RETAINER - SHORT	2	\$	68.40 LH-? RH-di-
REAR BUMPER REFLECTOR	2	\$	488.60LH-4, RH-wh
TAILLAMP	2	\$	882.60 CM
TAILLAMP SEAL	2	\$	66.80 400
TAILLAMP CLIPS	2	\$	24.60 Net
TAILLAMP PANEL	2	\$	488.60 LH - RY, EM - W
END PANEL	1	\$	596.30 bt
SPARE TYRE PANEL	1	\$	782.30 RY
SPARE TYRE BOARD	1	\$	399.70 ?
END PANEL TOP GARNISH	1	\$	255.60 ?
REAR WEATHER STRIP	1	\$	249.70 ? (hut

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#02-40 SINGAPORE 658064

ATTN: AXA INSURANCE

DATE:

24/07/2019

VEHICLE NO:

SLB4324L

MODEL:

AXIO

YEAR:

2016

ACCIDENT DATE:

24/07/2019

TYPE OF CLAIM:

TP

CLAIM ADVISOR:

LOUIS ONG (91928963)

FST	FR /	1/4"	771	MA
ESI	IIVI	MI	ш	$\cup \cap$

RH REAR FENDER	1	\$ 976.90 buc-
RH REAR FENDER INNER PANEL	1	REPAIR
RH REAR FENDER INNER SHIELD	1	\$ 196.50 ?
RH REAR FENDER INNER SHIELD CLIPS	10	\$ 30.00 ?
RH REAR DOOR	1	REPAIR
RH REAR CHASSIS	1	REPAIR
LH REAR FENDER	1	REPAIR
REAR FENDER INNER TRIM	2	\$ 682.80 H-Y, R4-?
REAR SPEAKER BOARD TRIM	1	\$ 458.30
EXHAUST PIPE	1	\$ 986.40 R×
EXHAUST PIPE GASKET	1	\$ 45.30 ?
EXHAUST PIPE MOUNTING	2	\$ 188.60 ?
ROOF PANEL TRIM	1	\$ 1,023.30 ×

	\$ 10,675.80
DISCOUNT 25%:	\$ 3,558.60
TOTAL:	\$ 14,234.40

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#02-40 SINGAPORE 658064

ATTN: AXA INSURANCE

DATE:

24/07/2019

VEHICLE NO:

SLB4324L

MODEL:

AXIO

YEAR:

2016

ACCIDENT DATE:

24/07/2019

TYPE OF CLAIM:

1.5

CLAIM ADVISOR:

LOUIS ONG (91928963)

gen yet squa	1000	A 19		- III I
F- 2 1 1	111/1	11 1	11	1.05J
EST	IVI	mi	110	I:M

S/NET		PRICE	
REVERSE SENSOR	1	\$	250.00 200 NW
REAR NUMBER PLATE	1	\$	50.00 45 bt
END PANEL SEALANT	1	\$	100.00 40me
SPARE TYRE PANEL BLACK STICKER	1	\$	150.00 ×
PANEL SEALANT	1	\$	100.00 ≻
REAR WINDSCREEN SEALANT	1	\$	100.00 Com
		\$	750.00

LABOUR	PRICE	
LABOUR FOR FACILITATE REPAIR	\$	1,800.00/400
TO RESPRAY AFFECTED AREAS - REAR BUMPER	\$	300.00 200
TO RESPRAY AFFECTED AREAS - END PANEL	\$	300.00 Zov
TO RESPRAY AFFECTED AREAS - LH REAR FENDER	\$	300.00 200
TO RESPRAY AFFECTED AREAS - RH REAR FENDER AND INNER PANEL	\$	300.00 250
TO RESPRAY AFFECTED AREAS - RH REAR DOOR	\$	300.00 X
TO RESPRAY AFFECTED AREAS - RH REAR CHASSIS	\$	300.00 ×
TO STRAIGHTEN AND ALIGN RH REAR CHASSIS	\$	300.00 200 ? plus to.
TO REMOVE AND REFIT REAR WINDSCREEN	S	150.00 /20
RUST PROOFING	\$	80.00 4 2.
SUNDARIES	\$	50.00 20-
TO REMOVE AND REFIT REAR SEAT, SPEAKER BOAR, ROOF LINING, FLOOR BOAR	\$	250.00 /00

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#02-40 SINGAPORE 658064

ATTN: AXA INSURANCE

DATE:

24/07/2019

VEHICLE NO:

SLB4324L

MODEL:

AXIO

YEAR:

2016

ACCIDENT DATE:

24/07/2019

TYPE OF CLAIM:

CLAIM ADVISOR:

LOUIS ONG (91928963)

EMAIL: louisongautowheels@yahoo.com

ESTIMATION

TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR

TO REMOVE AND REF!T REAR EXHAUST

TO REMOVE AND REFIT REVERSE SENSOR

TO VACUUM AND CLEAN UP FRAGMENT GLASS

TO CHECK AND RECONNECT ALL NECESSARY WIRING

TOTAL:	\$ 5,110.00	
	\$ 100.00	30
	\$ 80.00	40
	\$ 100.00	30
	\$ 150.00	60.
	\$ 250.00	60

TOTAL: \$ 16,535.80 7% GST: \$ 1,157.51 \$ 17,693.31

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9-10 days. 25/7/190245pm.

Menu

P. Louis

7: 3.76 p.m

v: 14

6: 1



Service Request Details

Claim

S9M01V06

Reference

None @

Loss Date

July 24, 2019

Report Date

Jul 24, 2019 2:54:42 PM

Request Date

July 24, 2019

Due Date

July 31, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLB4324L

LKK AUTO CONSULTANTS PTE LTD (TP) +

Model

...

CORALLA

Service Address

Primary Contact/Insured

STARWHIZ MANAGEMENT COMPANY PTE LTD BLK 1 WHOLESALE CENTRE, #03-11, 110001, Singapore 65674755

Claim Handler

NG Stacey 6568804351 stacey.ng@axa.com.sg

Additional Instructions
GIA NOT REPORTED

Messages

Invoices

History

Documents1

Assessment

Metrics

Notes

Menu

New Message

Catherine Chong (LKK Auto)

From:

Louis Ong <louisongautowheels@yahoo.com>

Sent:

Wednesday, 24 July, 2019 2:05 PM

To:

SG AXA Insurance SM AXA SGP - Motor Survey

Subject:

Accident invovled with vehicle SLB4324L and GBE9667S(TP) on 24/07/2019 along

Junction of Marymount road towards Thomson

Attachments:

LTA Search fee.pdf; TOYOTA AXIO - SLB 4324 L @ GIA.pdf

Categories:

Shekhar

Hi,

We would like to do a Direct Settlement with you if our liability is 100%.

Can advise us on the liability and arrange for survey.

Vehicle is in.

We would like LKK to survey the vehicle.

Thanks

Auto Wheels Motorworks PTE LTD

No1 Bukit Batok Crescent

#02-40 WCEGA PLAZA

Louis Ong

91928963

Hsiao Tong (LKKAuto)

From:

Louis Ong <louisongautowheels@yahoo.com>

Sent:

Friday, 11 October 2019 8:21 PM

To:

Mei Kwan (LKKAuto); Vivian Lau (LKKAuto)

Subject:

Re: Accident invovled with vehicle SLB4324L and GBE9667S(TP) on 24/07/2019

along Junction of Marymount road towards Thomson *** LKK REF:

CC4/ASM19013054/wa3

Attachments:

LOA.pdf; LOD.pdf; LTA Search fee.pdf; TAX INVOICE.PDF; TOWING.PDF

Hi.

The above attachment is our LOD, Tax Invoice, LOA, LTA search fee and towing invoice.

Breakdown:

	9,291.95	S\$	Total	
2. Loss of Use (\$120 x 9 days and 2 Sundays) S\$	100.00	S\$	Towing Receipt	4.
1200 12000 12000 1200 1200 1200 1200 12	7.45	S\$	Third Party Insurer Enquiry Fee (\$7.00 x 7% GST)	3.
(2) 1,000 (4) 1,				
1200 12000 12000 1200 1200 1200 1200 12	1,320.00	S\$	Loss of Use (\$120 x 9 days and 2 Sundays)	2.
TORSE OF THE STATE	7,864.50	S\$	Cost of Repair (\$7,350 + 7% GST)	1.

Please check and revert.

Thanks

Auto Wheels Motorworks PTE LTD Louis Ong 91928963

On Thursday, 25 July 2019, 02:52:46 pm GMT+8, Mei Kwan (LKKAuto) <Meikwan@lkkauto.com> wrote:

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Dear Sir / Madam,

We refer to the above matter.

Please be informed that OI has reported. Please refer to the below OI's sketch plan and statement.

SKETCH PLAN					
in the	9.	111			
		111			
t say when the					
	11111	1441			
		14			
Standa Liller					
DESCRIBE CIRCUMSTANC	ES OF THE ACCIDENT	1			Contractor (Sec
Ign workin		7537APN	HIZMANO	TEMENT 91	10
Using the					
accident	and refer	to atta	ched po	ice repon	/
1/0.7/20/					

Brief Details.

On 24/07/2019 at about 1040hrs, I was driving along Marymount Rd in my lorry bearing GBE9667S. I was on the second lane wanting to make a right turn when the car in front of my lorry bearing plate number SLB4324L whom was moving forward suddenly slowed down. Thus I was unable to brake in time thus collided with the rear of the car. Police and ambulance then arrived to assist.

Please note that for liability, claim negotiation and settlement, please contact Vivian at 6841 8625.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Louis Ong <louisongautowheels@yahoo.com> Sent: Wednesday, 24 July, 2019 2:05 PM To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg> Subject: Accident invovled with vehicle SLB4324L and GBE9667S(TP) on 24/07/2019 along Junction of Marymount road towards Thomson</motor.survey@axa.com.sg></louisongautowheels@yahoo.com>
Hi,
We would like to do a Direct Settlement with you if our liability is 100%.
Can advise us on the liability and arrange for survey.
Vehicle is in.
We would like LKK to survey the vehicle.
Thanks
Auto Wheels Motorworks PTE LTD
No1 Bukit Batok Crescent
#02-40 WCEGA PLAZA
Louis Ong
91928963



<TP - Mandate IA> - S9M01V06 [ACCIDENT INVOLVING GBE 9667S(OI) & SLB 4324L(TP) ON 24/07/2019]

Type

Question

Message

Liability: 100%. Insured driver rear-ended third party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$8,631.95(all-in). TP-Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 14-Oct-19

Reply



51 UBLAVE 1, #02-25 PAYA UBLINDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To: AXA Insurance Pte Ltd

Date: 14/10/2019

Survey Details:

Date of loss	24-Jul-19	
Date of appointment	24-Jul-19	
Date of survey	25-Jul-19	
Location of survey	AUTO WHEELS MOTORWORKS PTE LTD	

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM	
Vehicle number	SLB4324L	
Make and Model	TOYOTA COROLLA AXIO 1.53	
Date of registration	7-Apr-16	
Parf Rebate		
Market Value	\$	56,000.00
Parf Rebate	\$	37,251.00
Nett Loss	\$ 18,749.00	

Repair details:

Initial Estimate	16,535.80

Proposed/Revised repair cost:

Parts	\$ 6,435.15
Check items (estimate)	NIL
Labour	\$ 2,750.00
Total	\$ 9,185.15
Lump Sum(if applicable)	\$ 7,350.00

Number of days for repair	9.0



51 UBLAVE 1, #02-25 PAYA UBLINDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Remarks:

OID REAR-ENDED THIRD PARTY.	

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 7,864.50	
Loss of use	\$ 660.00	(11days x \$60.00)
Loss of rental	NIL	no. of days
Loss of income	NIL	no. of days
LTA search fees	\$ 7.45	9
Others (Towing Fee)	\$ 100.00	
Proposed Total	\$ 8,631.95	

Hsiao Tong (LKKAuto)

From:

Mei Kwan (LKKAuto)

Sent:

Tuesday, 15 October 2019 1:23 PM

To:

Hsiao Tong (LKKAuto)

Subject:

FW: New message for service request 128282, vehicle number SLB4324L

15/10/19 11:49 AM

*** PLS PROCEED - NG Stacey

----Original Message-----

From: stacey.ng@axa.com.sg <stacey.ng@axa.com.sg>

Sent: Tuesday, 15 October, 2019 11:50 AM

To: admin-d@lkkauto.com

Subject: New message for service request 128282, vehicle number SLB4324L

AXA Insurance has sent you a message for claim number S9M01V06.

Please click here https://vp.smartclaims.axa.com.sg/claim-portal/ to view the message in Vendor Portal. This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Hsiao Tong (LKKAuto)

From: Sent:	Louis Ong <louisongautowheels@yahoo.com> Saturday, 26 October 2019 12:07 PM</louisongautowheels@yahoo.com>
To: Cc:	Hsiao Tong (LKKAuto) Admin A; Su Li (LKK Auto)
Subject:	Re: Accident invovled with vehicle SLB4324L and GBE9667S(TP) on 24/07/2019
	along Junction of Marymount road towards Thomson *** LKK REF: CC4/ASM19013054/wa3
Hi Hsiao Tong,	
We accept the offer.	
Please kindly forwards us th	e DV.
Thanks	
Auto Wheels Motorworks PT Louis Ong	TE LTD
91928963	
On Saturday, 26 October 2019, 11	1:49:53 am GMT+8, Hsiao Tong (LKKAuto) <chewht@lkkauto.com> wrote:</chewht@lkkauto.com>
Without Prejudice	
Dear Sirs/Mdm,	
We refer to the above matter.	
we refer to the above matter.	
We propose settlement at a glo	obal sum of \$8,500.00(all-in).
Please confirm acceptance.	
construed as an admission of liabil	correspondence with you is strictly on a without prejudice basis and should not be lity on our part and/or that of our policyholder and/or the authorised driver. The terms nt should not be disclosed in any other related matter(s) in respect of this accident nor lated claims."

Best Regards,	
Hsiao Tong, Chew (Ms) Case Handler	•
LKK Auto Consultants Pte Ltd	
Phone: 6742-3197 email: <u>chewht@lkkauto.com</u> fax: 6741-4108	
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 S(408933)	
From: Su Li (LKK Auto) <suli@lkkauto.com> Sent: Monday, 14 October 2019 8:48 AM</suli@lkkauto.com>	
To: Louis Ong <louisongautowheels@yahoo.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com> Cc: Admin A <admin-a@lkkauto.com> Subject: FW: Accident invovled with vehicle SLB4324L and GBE9667S(TP) on 24/07/2019 along Jun</admin-a@lkkauto.com></chewht@lkkauto.com></louisongautowheels@yahoo.com>	action
of Marymount road towards Thomson *** LKK REF: CC4/ASM19013054/wa3	ictioi
Without Prejudice	
Dead Cir / Madaire	
Dear Sir / Madam,	
Thank you for your email.	
Please be informed that this matter is now handled by my colleague, Ms Hsiao Ting.	
Hi Hsiao Tong,	
FYNA, our ref CC4/ASM19013054/T1pa3	
Thank you.	
Best Regards,	

Su Li | Admin Support

LKK Auto Consultants Pte Ltd

Phone: 6841 2157 (Ext:119) Email: SuLi@lkkauto.com Fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Louis Ong [mailto:louisongautowheels@yahoo.com]

Sent: Friday, 11 October 2019 8:21 PM

To: Mei Kwan (LKKAuto); Vivian Lau (LKKAuto)

Subject: Re: Accident invovled with vehicle SLB4324L and GBE9667S(TP) on 24/07/2019 along Junction

of Marymount road towards Thomson *** LKK REF: CC4/ASM19013054/wa3

Hi,

The above attachment is our LOD, Tax Invoice, LOA, LTA search fee and towing invoice.

Breakdown:

2. Loss of Use (\$120 x 9 days and 2 Sundays) S\$ Third Party Insurer Enquiry Fee (\$7.00 x 7% GST) 4. Towing Receipt S\$	9,291.95
2. Loss of Use (\$120 x 9 days and 2 Sundays) S\$	100.00
1353 A 13 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3	7.45
 Cost of Repair (\$7,350 + 7% GST) 	7,864.50 1,320.00

Please check and revert.

Thanks

Auto Wheels Motorworks PTE LTD

Louis Ong

91928963

On Thursday, 25 July 2019, 02:52:46 pm GMT+8, Mei Kwan (LKKAuto) < Meikwan@lkkauto.com > wrote:

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Dear Sir / Madam,

We refer to the above matter.

Please be informed that OI has reported. Please refer to the below OI's sketch plan and statement.

SKETCH PLAN					
Lancin'					
2000					
14.7.5	- 1	5 1 Tan -			
h 10 h 12	1111111111		OF STREET	sa Egit Li	
	and the fire	111	- Chester		
	1 1 1 1 1 1 1	1 1 1		- 11	
				014414	
	2 11 11 11 11	1 (1)			
		1 4			- 1+
		100			
	ب سارک باد اداد داد د	A	and the state of the state of		House of a cla
DESCRIBE CIRCUMSTANCE		845.0E			
Igm working	FORPIL	75STARV	PHIZMANO	TEMENT 9	00
USING EHR	vehicle	Fordelv	elf at t	the time	
accident	and refer	to att	riched po	ice repor	1
1/0.7/2019					

Brief Details.

On 24/07/2019 at about 1040hrs, I was driving along Marymount Rd in my lorry bearing GBE9667S. I was on the second lane wanting to make a right turn when the car in front of my lony bearing plate number SLB4324L whom was moving forward suddenly slowed down. Thus I was unable to brake in time thus collided with the rear of the car. Police and ambulance then arrived to assist.

Please note that for liability, claim negotiation and settlement, please contact Vivian at 6841 8625.

ŧ

To check availability of the case handler, you may contact the undersigned.	
Thank you.	
Best Regards,	
Mei Kwan Admin	
LKK Auto Consultants Pte Ltd	
Phone: 6366 0055 email: MeiKwan@lkkauto.com fax: 67414108	
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 S(408933)	
From: Louis Ong < louisongautowheels@yahoo.com> Sent: Wednesday, 24 July, 2019 2:05 PM To: SG AXA Insurance SM AXA SGP - Motor Survey < motor.survey@axa.com.sg> Subject: Accident invovled with vehicle SLB4324L and GBE9667S(TP) on 24/07/2019 along Junction of Marymoroad towards Thomson	unt
Hi,	
We would like to do a Direct Settlement with you if our liability is 100%.	
Can advise us on the liability and arrange for survey.	
Vehicle is in.	

We would like LKK to survey the vehicle.

Thanks

Auto Wheels Motorworks PTE LTD

No1 Bukit Batok Crescent

#02-40 WCEGA PLAZA

Louis Ong

91928963

MOTORWORKS PTE LTD

11/10/2019

AXA INSURANCE

<u>Subject: Accident between SLB4324L and GBE9667S(TP) on 24/07/2019 along Junction of Marymount road towards Thomson.</u>

We refer to the above case.

We are instructed by our client to file claim for the damages against your insured.

Our client has suffered loss and damage as a result of your Insured's negligence in the driving of vehicle No. SLB4324L.

We quantify our client's claim as follows:

1.	Cost of Repair (\$7,350 + 7% GST)	S\$	7,864.50
2.	Loss of Use (\$120 x 9 days and 2	\$\$	1,320.00
	Sundays)		
3.	Third Party Insurer Enquiry Fee	S\$	7.45
	(\$7.00 x 7% GST)		
4.	Towing Receipt	S\$	100.00
	Total	S\$	9,291.95

We hereby append the following relevant documents for your perusal:

- Repair Bill Tax Invoice
- II. Third Party Insurer Enquiry Tax Invoice
- III. Towing Receipt

Please let us know within the next 7 days from the receipt of this letter, whether you are prepared to accept all the above amount.

Best regards,

Louis Ong Motor Claims Officer

Auto Wheels Motorworks PTE LTD

Tel: 9192 8963

Email: louisongautowheels@yahoo.com

AUTO WHEELS MOTORWORKS PTE LTD

No 1 BUKIT BATOK CRESCENT #02-40 WCEGA PLAZA SINGAPORE 658064

TAX INVOICE

AXA INSURANCE PTE LTD

Invoice Date

Tel & Fax: 6795 4101

10 Oct 2019

Invoice Number INV-042252

Reference

TOTOA AXIO - SLB 4324 L

UEN / GST Reg. No. 201226886H

Description	Quantity	Unit Price	Tax	Amount SGD
LUMPSUM REPAIR FOR SLB 4324 L	1.00	7,350.00	7%	7,350.00
			Subtotal	7,350.00
		TOTAL SALES	GST 7%	514.50
		то	TAL SGD	7,864.50

Due Date: 10 Oct 2019

Received In Good Order & Condition Goods Sold Are Not Refundable/Return

** Any defects or unsatisfied conditions after servicing are to be informed within THREE (3) DAYS from DATE OF INVOICE.

** Services rendered will be taken as accepted if no feedback is received within THREE (3) DAYS from DATE OF INVOICE.

** Interest rate of 5% per month, calculated on a daily basis, is levied on payment for OVERDUE AMOUNT(s)/ACCOUNT(s) owing to Auto Wheels MotorWorks Pte Ltd after SEVEN (7) DAYS from DATE OF INVOICE.

** Cheque should be crossed and make payable to "AUTO WHEELS MOTORWORKS PTE LTD".

Customer's Signature/ Co. Stamp Auto Wheels Motorwork #Pt201226886H E.& O. E. (BB) E & O. E.



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation In	ternationale Des Experts En Autor	nobile
AXA INSURANCE PT	E LTD	Ref : CC4/ASM1901	3054/T1pa3s2
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: STACEY NG		Date: 07-11-2019 Code: ASM	
1.	Policy Partic	culars :- THIRD PARTY CLA	IM
Insured Veh.	GBE 9667S	Veh. Inspected	SLB 4324L
Policy No.	VCA/P1770763	Coverage (\$)	0.00
Claim No.	S9M01V06	Excess (\$)	0.00
Assign From	STACEY NG	Assign Date	24/07/2019
2.	Vehicle	Particulars & Condition	
Make & Model	TOYOTA AXIO	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	NRE1610011213	Colour	SILVER
Odometer	132206	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		67 - G 1812- 20120-2012
3.	C	Conditions of Tyres	
	Size	Make	Balance
R/H Front Tyre	185/60 R15	GOODRICH	6 mm
L/H Front Tyre	185/60 R15	GOODRICH	6 mm
R/H Rear Tyre	185/60 R15	GOODRICH	6 mm
L/H Rear Tyre	185/60 R15	GOODRICH	6 mm
4.	Des	scription of Damages	
THE VEHICLE SI	JSTAINED DAMAGES AT TI DETAILS.	HE REAR PORTION.	
5.	G	eneral Information	
Accident Date	24/07/2019	Inspection Date	25/07/2019
Survey held at	AUTO WHEELS MOTOR	WORKS PTE LTD	
83	NO 1 BUKIT BATOK CRE #02-40 WCEGA PLAZA SINGAPORE 658064	ESCENT	
5a.		Remarks	
A)THE INSPECT B)IN ACCORDAN	ON WAS CONDUCTED ON ICE TO YOUR INSTRUCTION	A"WITHOUT PREJUDICE" BAS ONS, WE HAVE NOT AUTHORIS	IS. ED REPAIRS.
5b.		timate Days of Repair	

9 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR:



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 4324L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN (CONSISTENT)	CRACKED	1,064.20	1,064.20
1	REAR WINDSCREEN MOULDING (CONSISTENT)	NECESSARY	198.70	198.70
2	REAR FENDER UPPER INNER TRIM (CONSISTENT)	NOT NECESSARY	698.60	
1	BOOTLID (CONSISTENT)	BENT	986.30	986.30
2	BOOTLID HINGE (CONSISTENT)	BENT	299.40	299.40
2	BOOTLID STOPPER (CONSISTENT)	NECESSARY	44.60	44.60
1	BOOTLID OUTER CHROME GARNISH (CONSISTENT)	NECESSARY	218.30	218.30
2	REAR NUMBER PLATE LAMP (CONSISTENT)	SERVICEABLE	398.60	X10 20000
1	BOOTLID LOCK (CONSISTENT)	DISTORTED	368.30	368.30
1	REAR EMBLEM (CONSISTENT)	NECESSARY	55.30	55.30
1	REAR LOGO - COROLLA (CONSISTENT)	NECESSARY	52.30	52.30
1	REAR LOGO - AXIO (CONSISTENT)	NECESSARY	54.20	54.20
1	REAR BUMPER (CONSISTENT)	DISTORTED	789.50	789.50
10	REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	30.00	30.00
2	REAR BUMPER RETAINER - LONG (CONSISTENT)	N/S NOT NECESSARY / O/S DISTORTED	84.80	42.40
2	REAR BUMPER RETAINER - SHORT (CONSISTENT)	N/S NOT NECESSARY / O/S DISTORTED	68.40	34.20
2	REAR BUMPER REFLECTOR (CONSISTENT)	N/S NOT NECESSARY / O/S CUT	488.60	244.30
2	TAILLAMP (CONSISTENT)	CRACKED	882.60	882.60
2	TAILLAMP SEAL (CONSISTENT)	NECESSARY	66.80	66.80
2	TAILLAMP CLIPS (CONSISTENT)	NECESSARY	24.60	24.60
2	TAILLAMP PANEL (CONSISTENT)	N/S TO REPAIR SEE LABOUR / O/S BENT	488.60	244.30
1	END PANEL (CONSISTENT)	BENT	596.30	596.30
1	SPARE TYRE PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	782.30	8.
1	SPARE TYRE BOARD (CONSISTENT)	NOT NECESSARY	399.70	8.5
1	END PANEL TOP GARNISH (CONSISTENT)	DEFORMED	255.60	255.60

Report Ref No. CC4/ASM19013054/T1pa3s2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR WEATHER STRIP (CONSISTENT)	DEFORMED	249.70	249.70
1	RH REAR FENDER (CONSISTENT)	BUCKLED	976.90	976.90
1	RH REAR FENDER INNER PANEL (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	12	
1	RH REAR FENDER INNER SHIELD (CONSISTENT)	SERVICEABLE	196.50	
10	RH REAR FENDER INNER SHIELD CLIPS (CONSISTENT)	NOT NECESSARY	30.00	
1	RH REAR DOOR (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	25	
1	RH REAR CHASSIS (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	ā	
1	LH REAR FENDER (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR		
2	REAR FENDER INNER TRIM (CONSISTENT)	N/S NOT NECESSARY / O/S DEFORMED	682.80	341.40
1	REAR SPEAKER BOARD TRIM (CONSISTENT)	SERVICEABLE	458.30	
1	EXHAUST PIPE (CONSISTENT)	TO REPAIR SEE LABOUR	986.40	0.5
1	EXHAUST PIPE GASKET (CONSISTENT)	SERVICEABLE	45.30	
2	EXHAUST PIPE MOUNTING (CONSISTENT)	SERVICEABLE	188.60	1 12
1	ROOF PANEL TRIM (CONSISTENT)	SERVICEABLE	1,023.30	
	LESS 25% DISCOUNT		-3,558.60	-2,030.05
			10,675.80	6,090.15
	SPECIAL NETT ITEMS			
1	REVERSE SENSOR (SN) (CONSISTENT)	NOT WORKING	250.00	200.00
1	REAR NUMBER PLATE (SN) (CONSISTENT)	BENT	50.00	45.00
1	END PANEL SEALANT (SN) (CONSISTENT)	NECESSARY	100.00	40.00
1	SPARE TYRE PANEL BLACK STICKER (SN) (CONSISTENT)	NOT NECESSARY	150.00	· ·
1	PANEL SEALANT (SN) (CONSISTENT)	NOT NECESSARY	100.00	
1	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	100.00	60.00
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	50.00	20.00
			800.00	365.00

Report Ref No. CC4/ASM19013054/T1pa3s2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR			
	LABOUR TO FACILITATE REPAIR. INCLUSIVE OF THE REPAIR OF N/S TAILLAMP PANEL, SPARE TYRE PANEL, RH REAR FENDER INNER PANEL, RH REAR DOOR, RH REAR CHASSIS, LH REAR FENDER AND EXHAUST PIPE.		1,800.00	1,400.00
	TO RESPRAY AFFECTED AREAS - REAER BUMPER.		300.00	200.00
	TO RESPRAY AFFECTED AREAS - END PANEL.		300.00	200.00
	TO RESPRAY AFFECTED AREAS - LH REAR FENDER.		300.00	200.00
	TO RESPRAY AFFECTED AREAS - RH REAR FENDER AND INNER PANEL.		300.00	250.00
	TO RESPRAY AFFECTED AREAS - RH REAR DOOR.	NOT NECESSARY	300.00	-
	TO RESPRAY AFFECTED AREAS - RH REAR CHASSIS.	NOT NECESSARY	300.00	-
	TO STRAIGHTEN AND ALIGN RH REAR CHASSIS.	NOT NECESSARY	300.00	-
	TO REMOVE AND REFIT REAR WINDSCREEN.		150.00	120.00
	RUST PROOFING.		80.00	40.00
	TO REMOVE AND REFIT REAR SEAT, SPEAKER BOARD, ROOF LINING, FLOOR BOARD.		250.00	100.00
	TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR.		250.00	60.00
	TO REMOVE AND REFIT REAR EXHAUST.		150.00	60.00
	TO REMOVE AND REFIT REVERSE SENSOR.		100.00	30.00
	TO VACUUM AND CLEAN UP FRAGMENT GLASS.		80.00	40.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRING.		100.00	30.00
			5,060.00	2,730.00
	GRAND TOTAL		16,535.80	9,185.15

RECOMMENDED COST OF LUMP SUM REPAIRS	7,350.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC4/ASM19013054/T1pa3s2

MOHAMAD TAUFIKH

pupin.

M.MATAI, AMSAE-A

HO LEONG CHUAN

Automotive Assessor

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.