Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19013055/UBA3Q2

Date: 11/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100447538 Claimant FBF5919L Insured Vehicle No: SKZ1716U Vehicle No:

Date of Loss: 11/07/2019 Nature of Claim: TP Claim No: 6255888326SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

FBF5919L Reg No:

Make & Model: YAMAHA XVS950, 942cc Engine No: N602E005938

Reg. Date: 08/09/2011 (Man. Year: 2011) Chassis No: JYAVN021000005768

Colour: Odometer: 54236 km Black

Engine Capacity: 942 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 130-70-18 Rear Tyre Size: 170-70-16 Rear Left Side: Front Left Side: Shinko 6 mm Shinko 6 mm Front Right Side: Rear Right Side: 0 mm 0 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|------------|------------|------------|--------|
| Parts | 5,494.00 | 4,345.30 | 1,148.70 | 20.91 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 399.00 | 265.00 | 134.00 | 33.58 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 5,893.00 | 4,610.30 | 1,282.70 | 21.77 |
| Approved Total (Overridden) (S\$) | | 3,680.00 | | |
| (S\$) | 5,893.00 | 3,680.00 | 2,213.00 | 37.55 |
| + GST 7.00/7.00% (S\$) | 412.51 | 257.60 | 154.91 | 37.55 |
| Nett Amount (S\$) | 6,305.51 | 3,937.60 | 2,367.91 | 37.55 |
| + Loss of Use (2.0 x S | 60.00 | | | |
| + Doc/S | 2.00 | | | |
| Ne | 3,999.60 | | | |
| Global Sum | 3,900.00 | | | |

INSPECTION

Date of Assignment: 24/07/2019

Date Inspected: 24/07/2019 Inspected At: Ban Hock Hin Co. Pte Ltd (HQ)

No. 6 Defu Lane 4 Singapore 539410

Estimated Period of Repair: 3.0 days Adjuster Report Page 2 of 4

Adjuster: MARCUS CHUA Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount | |
|-------|---|-------------|--|--------------------------------|------------|--------------|--|
| 1 | 1 | | *FOOTREST FRONT LH ASSY (CUT) | Not Consistent With The Impact | 454.00 F | *-FL | |
| 2 | 1 | | *FOOTREST FRONT RH ASSY | Bent | 454.00 F | *454.00 FL | |
| 3 | 1 | | *LEVER CLUTCH (Scratched) | Not Consistent With The Impact | 58.00 F | *-FL | |
| 4 | 1 | | *MIRROR LH ASSY | Not Necessary | 149.00 F | *-FL | |
| 5 | 1 | | *MIRROR RH ASSY | Cut | 149.00 F | *149.00 FL | |
| 6 | 1 | | *MUFFLER ASSY 1 | Dented | 3,353.00 F | *3,353.00 FL | |
| 7 | 1 | | *PLATE NUMBER REAR (6.5 INCH X 9 INCH) | Cut | 16.00 FS | *10.00 FS | |
| 8 | 1 | | *SEAT BASE | Bent | 7.00 F | *7.00 FL | |
| 9 | 1 | | *TAIL LIGHT ASSY | Broken | 158.00 F | *158.00 FL | |
| 10 | 2 | | *COVER UNDER 1 | Dented | 644.00 F | *644.00 FL | |
| 11 | 1 | | *LEVER BRAKE ASSY | Scratched | 52.00 F | *52.00 FL | |
| F=Fra | anchise | part. S=S | SpcNett. L=ListItemDisc. | | | | |
| | | | | Sub Total (S\$) | 5,494.00 | 4,827.00 | |
| | - List Item Discount on L Items 0.00/10.00% (S\$) | | | | | 481.70 | |
| | | | | Total Parts (S\$) | 5,494.00 | 4,345.30 | |
| | Report was unsubmitted during this print-out. | | | | | | |
| | | | : ispent mas ansasmines | | | | |

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-----|--|-------------------|------------|--------|
| Lab | our Items | | | |
| 1 | TRANSPORT CHARGES | New | 35.00 | 0.00 |
| 2 | LABOUR-FOR DISMANTLE AND ASSEMBLING OF PARTS | New | 175.00 | 175.00 |
| 3 | LABOUR -FOR DISMANTLE AND ASSEMBLING OF PARTS QUOTED | New | 189.00 | 90.00 |
| | Gross Labour Cost (S\$) | | 399.00 | 265.00 |
| | Report was unsubmitted durin | g this print-out. | | |

< END OF ESTIMATES >