

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG19013067/AKA3Q2

**Date:** 27/04/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**

**Vehicle No :** SJY8869H

**Insured Vehicle No :** SKM336H

Date of Loss: 23/07/2019

Nature of Claim: TP

Claim No: 6994279684SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJY8869H**

Make & Model: AUDI A3, 999cc SEDAN TFSI (A)

Engine No: CHZ575944

Reg. Date: 16/12/2017 (Man. Year: 2017)

Chassis No: WAUZZZ8V7J1022748

Colour: Red

Odometer: 25703 km

Engine Capacity: 999 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	13,977.00	6,176.48	7,800.52	55.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,712.00	3,662.00	3,050.00	45.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>20,689.00</b>	<b>9,838.48</b>	<b>10,850.52</b>	<b>52.45</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,448.23</b>	<b>688.69</b>	<b>759.54</b>	<b>52.45</b>
<b>Nett Amount (S\$)</b>	<b>22,137.23</b>	<b>10,527.17</b>	<b>11,610.06</b>	<b>52.45</b>
<b>+ Loss of Use (6.0 x S\$60.00/day) (S\$)</b>		360.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>10,889.17</b>		

### INSPECTION

Date of Assignment: 26/07/2019

Date Inspected: 26/07/2019 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 5.0 days

**Adjuster:** ADRIAN LING

**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Deformed	1,830.00 FS	*1,464.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	170.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION -RH	Damaged	35.00 FS	*27.76 FS
4	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE	Not Necessary	488.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT -RH	Not Necessary	270.00 FS	*- FS
6	1		*FRONT BUMPER COVER TRIM -RH	Not Necessary	148.00 FS	*- FS
7	1		*FRONT BUMPER ADAPTER -RH	Not Necessary	34.00 FS	*- FS
8	1		*AIR GUIDE GRILLE -RH	Not Necessary	171.00 FS	*- FS
9	1		*SIDE REINFORCEMENT	Not Necessary	660.00 FS	*- FS
10	1		*FOAM FILLER PIECE	Not Necessary	172.00 FS	*- FS
11	1		*FRONT BUMPER COVER	Not Necessary	111.00 FS	*- FS
12	1		*SIGNAL HORN -LOW TONE RH	Not Necessary	182.00 FS	*- FS
13	1		*FENDER -RH	Dented	778.00 FS	*622.00 FS
14	1		*POP RIVET	Necessary	15.00 FS	*12.00 FS
15	1		*FENDER BRACKET -RH	Bent	35.00 FS	*27.52 FS
16	1		*FENDER SUPPORT	Not Necessary	88.00 FS	*- FS
17	1		*WHEEL HOUSING LINER -RH	Not Necessary	158.00 FS	*- FS
18	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	81.00 FS	*- FS
19	1		*BONNET	Repair	2,898.00 FS	*- FS
20	1		*BONNET ATTACHMENT PARTS	Not Necessary	149.00 FS	*- FS
21	1		*EDGE PROTECTION	Not Necessary	25.00 FS	*- FS
22	1		*LED HEADLIGHT -RH	Cut	5,029.00 FS	*4,023.20 FS
23	1		*LIFT CYLINDER	Not Necessary	128.00 FS	*- FS
24	1		*AIR GUIDE -RH	Not Necessary	22.00 FS	*- FS
25	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$) 13,977.00 6,176.48**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER ,RHS FENDER ,BONNET AND RHS HEADLIGHT .RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	3,150.00	1,250.00
3	TO RESPRAY FRONT BUMPER ,BONNET AND RHS FRONT FENDER .	New	2,800.00	1,650.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
5	TO CARRY OUT PAIANT PROTECTION -BY OWNER	New	210.00	210.00
<b>Gross Labour Cost (S\$)</b>			<b>6,712.00</b>	<b>3,662.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >