

ASS. REC. BY:

REF: CS/INC19013073/Kvd3<sup>n2</sup>

Special Instruction:

Surveyor: Kenneth

## ASSIGNMENT (Office)

From (Person): Cynthia Ang

of

INC

Date/Time: 24/7/19 @ 9.47am

Estimated Cost:

Bill to:

OD: ☒ WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ 2069H

Insured:

SLK 99264

at Workshop m/s

Esteem performance

Tel:

8799 0066

of

385 Sin Ming Drive

65662112

Policy No:

Claim No:

MT/1054563-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/7/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9.51am @ 24/7/19

Person Contacted:

Carmen

Vehicle: ☒ IN/OUT

Date/Time	Action/Instruction	Estimate	✓
	SLQ 2069H-X		
	SLK 99264-X		
20/8	B 2276.47 Car from	(Red 9943.62, 819)	



ASS. REC. BY:

REF: INC /

## ASSIGNMENT

From: \_\_\_\_\_

Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

0-3

days

Res.: Yes or No

Lum Sum: \_\_\_\_\_

1-B1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: \_\_\_\_\_

SLQ 206911 Yr Regn: 06.17Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: \_\_\_\_\_

Toy Prius c.c. 1758

Colour: \_\_\_\_\_

M. Silver

A/C: Insured / Std / NI / NA

Sp. Reading: \_\_\_\_\_

112286

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: \_\_\_\_\_

JTDKB3FU603588813Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD / A/Rim or

Tyre Size: F: \_\_\_\_\_

R: \_\_\_\_\_

P5165R15BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal. \_\_\_\_\_

mm

R/Bal. \_\_\_\_\_

mm

L/Bal. \_\_\_\_\_

mm

L/Bal. \_\_\_\_\_

mm

D.O.A. \_\_\_\_\_

22/7/19

D.O.I. \_\_\_\_\_

24/7/19

Survey held at \_\_\_\_\_

2:03pmDes. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to

RECEIVED 20 AUG 2019

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 2018 - typistDays Of Repair: 3Resurvey No. of Trlp: 2

Survey Fee:

Transportation:

S - RS. SI

Fixtures

Others

TOTAL

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

Report Format:

TP

Lump Sum / I.B.I. (\$) \_\_\_\_\_

2276.47250



## Nivitha (LKK Auto)

**From:** Cynthia Ang <Cynthia.Ang@income.com.sg>  
**Sent:** Wednesday, 24 July 2019 11:38 AM  
**To:** 'assignments@lkkauto.com'; Admin-D (LKKAuto)  
**Cc:** Cynthia Ang  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 24/07/2019

Dear LKK,

Resend with following details.

Thank you.

With Regards

**Cynthia Ang**  
Admin Assistant  
Motor Insurance  
T +65 6430 7900  
[www.income.com.sg](http://www.income.com.sg)



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.  
**Find out more at [Income.com.sg/careers](http://Income.com.sg/careers)**

**in** with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

**From:** Cynthia Ang  
**Sent:** Wednesday, 24 July 2019 9:47 AM  
**To:** 'assignments@lkkauto.com' <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>  
**Cc:** Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>; Cynthia Ang <Cynthia.Ang@income.com.sg>  
**Subject:** TP CASES FARMED OUT TO LKK ON 24/07/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI Veh	DOA	Additional Remarks
1	Eric Tang	MT/1054041-002	SKP40U	AUBURN AUTO PTE LTD	176 SING MING DRIVE #04-18 SING MING AUTOCARE SINGAPORE 575721	SAM NG /		SJX5746D	18/07/2019	
2		*Pending advise*	SLD8749H	COMFORTDELGRO ENGINEERING PTE LTD	205 BRADDELL ROAD EAST WING 3RD FLR SINGAPORE 579701	ANDREW / 63837656				
3	Fiona Shen	MT/1054783-001	SLK1780A	ESTEEM PERFORMANCE PTE LTD	385 SIN MING DRIVE VICOM INSPECTION CENTRE SINGAPORE 575718	carmen / 87990066	10:00-12:00	GBD9099L	12/07/2019	
4	Eng Huey Huey	MT/1053378-002	SLG3325P	ESTEEM PERFORMANCE PTE LTD	385 SIN MING DRIVE VICOM INSPECTION CENTRE SINGAPORE 575718	CARM / 87990066	10:30-12:30	SMC4602S	13/07/2019	



5	Fiona Shen	MT/1054563-002	SLQ2069H	ESTEEM PERFORMANCE PTE LTD	385 SIN MING DRIVE VICOM INSPECTION CENTRE SINGAPORE 575718	SERENE CHEE / 87990066		SLK9926U	22/07/2019
6	Jeff Lin	MT/1051997-002	SKF8917R	LAI HUAT MENG KEE MOTOR PTE LTD	160 SIN MING DRIVE #04-01 SIN MING AUTOCITY SINGAPORE 575722	DEBORAH LAI / 64538110		SJS5571S	05/07/2019
7		<b>*Pending advise*</b>	SME7036X	LEONG AUTO PTE LTD	160 SIN MING DRIVE #02-13 SIN MING AUTOCITY	DANIEL TAN/CADY LEE / 9692 4113			
8	Eng Huey Huey	MT/1052391-002	SMC660A	MOTOR IMAGE ENTERPRISES PTE LTD	19 LORONG 8 TOA PAYOH SINGAPORE 319255	DANIEL A JUDE / 86113195	10:00-12:00	SLT8341R	07/07/2019
9	Jared Liu	MT/1054437-002	SMH6433Z	SKS AUTOMOBILE SOLUTION	176 SIN MING DRIVE #01-17 SIN MING AUTOCARE SINGAPORE 575721	MS YIWEN / 64550747		SME7134X	20/07/2019
10		<b>*Pending advise*</b>	SMC7382G	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	STEVEN / 82636295			
11	Jeff Lin	MT/1054330-002	SLG586Y	VIN'S AUTOMOTIVE GROUP	160 SIN MING DRIVE #08-09 SIN MING DRIVE SINGAPORE 575722	RAYMOND TEO / 64532121		SLQ6072X	20/07/2019

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Cynthia Ang

Admin Assistant

Motor Insurance

T +65 6430 7900

[www.income.com.sg](http://www.income.com.sg)



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.  
Find out more at [income.com.sg/careers](http://income.com.sg/careers)

**in** with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: [www.eesteempref.com.sg](http://www.eesteempref.com.sg)

## Repair Estimates

SLQ 2069 H

<b>Parts</b>	(a) Cost / List Price Items	\$	11,325.45
	Plus/Less 25%	\$	2,831.36
	<b>Total of Cost / List</b>	\$	<b>8,494.09</b>
	(b) Nett Price Items		
	Less		
	<b>Total of Nett Item</b>		
	(c) Special Nett Items	\$	345.00
<b>Total Parts Cost</b>		\$	<b>8,839.09</b>
<b>Labour</b>		\$	<b>3,380.00</b>
<b>Total</b>		\$	<b>12,219.09</b>

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Mennoth

Company : LKK

Survey conducted on : 24/7/19 at \_\_\_\_\_

## Remarks By Surveyor

(a) The repair of this vehicle is ~~not~~ authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 3 day(s)

(c) Resurvey	Required / <del>Not Required</del>
--------------	------------------------------------

(d) Excess :\$ \_\_\_\_\_

(e) Signature of surveyor: *LC* Date: *24/7/19*





# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

## Spare Parts

Vehicle No. : SLQ 2069 H  
Make & Model : TOYOTA PRIUS  
Chassis No : JTDKB3FU603562613

Submit By : SERENCE  
Year Manufacture : 2017  
Engine No. :

## Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor <i>Short</i>	1	\$200.00	S.N	✓
2	Rear bumper <i>Bu</i>	1	\$497.50		✓
3	Rear bumper clip <i>mc</i>	10	\$40.00		✓
4	Rear bumper side retainer LH <i>su</i>	1	\$112.70		✓
5	Rear bumper side retainer RH <i>su</i>	1	\$112.70		✓
6	Rear bumper reinforcement <i>Bt</i>	1	\$398.90		✓
7	Rear bumper lower garnish centre <i>Bt</i>	1	\$582.60		✓
8	Rear bumper lower garnish LH <i>su</i>	1	\$149.70		✓
9	Rear bumper lower garnish RH <i>my cm su</i>	1	\$149.70		✓
10	Rear bumper tow cover <i>su</i>	1	\$31.70		✓
11	Rear bumper under cover <i>su</i>	1	\$355.20		✓
12	Rear bumper under cover LH <i>su</i>	1	\$187.60		✓
13	Rear bumper under cover RH <i>su</i>	1	\$187.60		✓
14	Rear bumper under cover clip <i>mc</i>	4	\$14.00		✓
15	Tail door <i>R</i>	1	\$1,122.50		✓
16	Tail door lock <i>R</i>	1	\$487.70		✓
17	Tail door emblem <i>mc</i>	1	\$61.70		✓
18	Wording "PRIUS" <i>mc</i>	1	\$51.90		✓
19	Wording "HYBRID" <i>mc</i>	1	\$55.47		✓
20	Tail door hinge LH <i>R</i>	1	\$87.60		✓
21	Tail door hinge RH <i>R</i>	1	\$87.60		✓
22	Tail door plate garnish <i>su</i>	1	\$782.50		✓
23	Tail door inner trim <i>su</i>	1	\$278.90		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



**Spare Parts**

Vehicle No. : **SLQ 2069 H**  
 Make & Model : **TOYOTA PRIUS**  
 Chassis No. : **JTDKB3FU603562613**

Submit By : **SERENCE**  
 Year Manufacture : **2017**  
 Engine No. : **0**

**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Tail door inner trim clip <i>nn</i>	10	\$28.00		X
25	Tail end panel <i>n</i>	1	\$596.60		X
26	Tail end panel garnish <i>ng di</i>	1	\$151.60		2
27	Tail end panel garnish clip <i>n</i>	10	\$35.00		2
28	Boot weatherstrip <i>Sn</i>	1	\$353.10		} X
29	Spare tyre well panel <i>n</i>	1	\$793.15		
30	Spare tyre board <i>Sn</i>	1	\$566.79		
31	Spare tyre compartment sponge LH <i>Sn</i>	1	\$297.67		
32	Spare tyre compartment sponge RH <i>Sn</i>	1	\$297.67		
33	Spare tyre compartment centre <i>Sn</i>	1	\$251.70		
34	Tail lamp LH - UPPER <i>Sn</i>	1	\$498.75		
35	Tail lamp RH - UPPER <i>Sn</i>	1	\$498.75		
36	Tail lamp LH - LOWER <i>Sn</i>	1	\$511.60		
37	Tail lamp RH - LOWER <i>Sn</i>	1	\$511.60		
38	Taildoor glass sealant <i>nn</i>	1	\$50.00	S.N	
39	Rear windscreen moulding <i>Sn</i>	1	\$97.70		
40	Rear windscreen sealant <i>nn</i>	1	\$50.00	S.N	
41	Rear number plate <i>Sn</i>	1	\$45.00	S.N	
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.





## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Labour

Vehicle No. : **SLQ 2069 H** Submit By : **SERENCE**  
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, TAILDOOR, TAILDOOR PLATE GARNISH, SPARE TYRE COMPARTMENT,	\$1,200.00	300
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, TAILDOOR, TAILDOOR PLATE GARNISH, SPARE TYRE COMPARTMENT,	\$1,200.00	320
3	To tuff coat. <i>nn</i>	\$150.00	X
4	TO Check wiring	\$50.00	150
5	To transfer boot mechanism to new boot <i>nn</i>	\$120.00	X
6	To conduct water leakage tests to ensure proper air and sealing <i>nn</i>	\$120.00	X
7	To remove & refit reverse sensor	\$150.00	500
8	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load. <i>nn</i>	\$150.00	X
9	To remove & refit Taildoor glass to assist work load <i>nn</i>	\$120.00	X
10	To remove & refit rear windscreen. <i>nn</i>	\$120.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**DAMAGE ASSESSMENT REPORT**

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19013073/Kvd3n2  
73 BRAS BASAH ROAD Date: 22-08-2019  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556



ATTN: FIONA SHEN

Code: INC

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	SLK 9926U	Veh. Inspected	SLQ 2069H
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1054563-002	Excess (\$)	0.00
Assign From	CYNTHIA ANG	Assign Date	24/07/2019

**2. Vehicle Particulars & Condition**

Make & Model	TOYOTA PRIUS (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU603562613	Colour	METALLIC SILVER
Odometer	112246 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	195/65 R15	PIRELLI	8 mm
L/H Front Tyre	195/65 R15	PIRELLI	8 mm
R/H Rear Tyre	195/65 R15	PIRELLI	6 mm
L/H Rear Tyre	195/65 R15	PIRELLI	6 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

**5. General Information**

Accident Date	22/07/2019	Inspect Date / Time	24/07/2019 ( 02:03 PM )
Survey held at	385 SIN MING DRIVE		
Repairer	ESTEEM PERFORMANCE PTE LTD		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 2069H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	REAR BUMPER	BUCKLED	497.50	497.50
10	REAR BUMPER CLIP	NECESSARY	40.00	40.00
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	112.70	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	112.70	-
1	REAR BUMPER REINFORCEMENT	BENT	398.90	398.90
1	REAR BUMPER LOWER GARNISH CENTRE	BENT	582.60	582.60
1	REAR BUMPER LOWER GARNISH LH	SERVICEABLE	149.70	-
1	REAR BUMPER LOWER GARNISH RH	MTG CRACKED	149.70	149.70
1	REAR BUMPER TOW COVER	SERVICEABLE	31.70	-
1	REAR BUMPER UNDER COVER	SERVICEABLE	355.20	-
1	REAR BUMPER UNDER COVER LH	SERVICEABLE	187.60	-
1	REAR BUMPER UNDER COVER RH	SERVICEABLE	187.60	-
4	REAR BUMPER UNDER COVER CLIP	NOT NECESSARY	14.00	-
1	TAIL DOOR	TO REPAIR SEE LABOUR	1,122.50	-
1	TAIL DOOR LOCK	TO REPAIR SEE LABOUR	487.70	-
1	TAIL DOOR EMBLEM	NOT NECESSARY	61.70	-
1	WORDING "PRIUS"	NOT NECESSARY	51.90	-
1	WORDING "HYBRID"	NOT NECESSARY	55.47	-
1	TAIL DOOR HINGE LH	TO REPAIR SEE LABOUR	87.60	-
1	TAIL DOOR HINGE RH	TO REPAIR SEE LABOUR	87.60	-
1	TAIL DOOR PLATE GARNISH	SERVICEABLE	782.50	-
1	TAIL DOOR INNER TRIM	SERVICEABLE	278.90	-
10	TAIL DOOR INNER TRIM CLIP	NOT NECESSARY	28.00	-
1	TAIL END PANEL	TO REPAIR SEE LABOUR	596.60	-
1	TAIL END PANEL GARNISH	MTG DISTORTED	151.60	151.60
10	TAIL END PANEL GARNISH CLIP	NECESSARY	35.00	35.00
1	BOOT WEATHERSTRIP	SERVICEABLE	353.10	-

Report Ref No. CS/INC19013073/Kvd3n2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPARE TYRE WELL PANEL	TO REPAIR SEE LABOUR	793.15	-
1	SPARE TYRE BOARD	SERVICEABLE	566.79	-
1	SPARE TYRE COMPARTMENT SPONGE LH	SERVICEABLE	297.67	-
1	SPARE TYRE COMPARTMENT SPONGE RH	SERVICEABLE	297.67	-
1	SPARE TYRE COMPARTMENT CENTRE	SERVICEABLE	251.70	-
1	TAIL LAMP LH-UPPER	SERVICEABLE	498.75	-
1	TAIL LAMP RH-UPPER	SERVICEABLE	498.75	-
1	TAIL LAMP LH-LOWER	SERVICEABLE	511.60	-
1	TAIL LAMP RH-LOWER	SERVICEABLE	511.60	-
1	REAR WINDSCREEN MOULDING	SERVICEABLE	97.70	-
	LESS 25% DISCOUNT		-2,831.36	-463.83
			8,494.09	1,391.47
	<b>SPECIAL NETT ITEMS</b>			
1	TAILDOOR GLASS SEALANT (SN)	NOT NECESSARY	50.00	-
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	50.00	-
1	REAR NUMBER PLATE (SN)	SERVICEABLE	45.00	-
1	REVERSE SENSOR (SN)	SHORTED	200.00	200.00
			345.00	200.00
	<b>LABOUR</b>			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(REAR BUMPER,END PANEL,TAILDOOR,TAILDOOR PLATE GARNISH,SPARE TYRE COMPARTMENT).INCLUSIVE OF THE REPAIR OF TAIL DOOR,TAIL DOOR LOCK,TAIL DOOR HINGE LH,TAIL DOOR HINGE RH,TAIL END PANEL AND SPARE TYRE WELL PANEL.		1,200.00	300.00
	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(REAR BUMPER,END PANEL,TAILDOOR,TAILDOOR PLATE GARNISH,SPARE TYRE COMPARTMENT).		1,200.00	320.00
	TO TUFF COAT.	NOT NECESSARY	150.00	-
	TO CHECK WIRING.		50.00	15.00
	TO TRANSFER BOOT MECHANISM TO NEW BOOT.	NOT NECESSARY	120.00	-
	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.	NOT NECESSARY	120.00	-

Report Ref No. CS/INC19013073/Kvd3n2





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REFIT REVERSE SENSOR.		150.00	50.00
	TO REMOVE & REFIT SPARE TYRE, SPARE TYRE BOARD, CARPET TRIM TO ASSIST WORK LOAD.	NOT NECESSARY	150.00	-
	TO REMOVE & REFIT TAILDOOR GLASS TO ASSIST WORK LOAD.	NOT NECESSARY	120.00	-
	TO REMOVE & REFIT REAR WINDSCREEN.	NOT NECESSARY	120.00	-
			3,380.00	685.00
GRAND TOTAL			12,219.09	2,276.47
RECOMMENDED COST OF REPAIRS (CONFIRMED)				2,276.47

Report Ref No. CS/INC19013073/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,  
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or fort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.