

ASS. REC. BY:

REF: CS/FCI 19013086/K12f3ⁿ² Special Instruction:Assignee: Kalvin

CWS

ASSIGNMENT (Office)

From (Person): Henry Kao

of

FCI

Date/Time: 3:05pm @ 24/7/19

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 6306T

Insured:

SHB 2280P

at Workshop m/s:

Premier Automotive

Tel:

6544 6689

of

23 Changi South Ave 2 #01-02

Policy No:

Claim No:

D19004804MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/7/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

4:40pm @ 24/7/19

Person Contacted:

Vincent

Vehicle:

IN/OUT

Date/Time

Action/Instruction

Informed ✓

SHC 6306T NJA/FCI10019155/Y1 nca = 23/9/10

SHB 2280P CS/FCI19012651/USF3A2 nca = 16/7/19

26/7/19 @

11:13am revised to Henry Kao by email.

INSURANCE BY: **Kah**

REF: **FCI**

ASSIGNMENT

From: _____ Date: **25/7/19**

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SHC 6306T**

at Workshop m/s: **Premier Automotive**

of **23 cheneji south ave 2 # 01-02**

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **3** days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS **Cup**

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SHC 6306T** Yr Regn: **25/Nov/2014**

Type: M.Car / M.Cycle / Bus / Van / Lorry / T/Tr / Prime Mover /

Truck / Trailer or

Make: **KIA optima** CC **1685**

Colour: **Silver** A/C: **Insured / Std / NI / NA**

Sp. Reading: **424440** T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: **1CNA6A414 MF5555085**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: **In order** / Jammed / Leaked / Burnt or

Brake: **In order** / Jammed / Leaked / Burnt or

Modi: **Nil** / S/Rim / STD A/Rim or

Tyre Size: F: **205/65R16**

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **Maxxis**

Front

Rear

R/Bal. **7** mm

R/Bal. **7** mm

L/Bal. **7** mm

L/Bal. **7** mm

D.O.A. **23/7/19**

D.O.I. **25/7/19**

Survey held at **Premier**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

n/s Prem

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
19/8/19	Chd 41583600/ 3 Pys. (red & m4.50i 38%)

42

RECEIVED 19 AUG 2019

Date/Time, File Pass to?



: Preli. Report

11/9/18 **turkey**



: Final Report

Date/Time, File Return to?

3

Days Of Repair: **3**

Resurvey No. of Trip: **1**

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Insp (\$)

☐ : West end (\$)

Survey Fee:

Transportation:

S & PS: \$

Photo:

Other:

TOTAL

140

50

50

43

283

Report Format: **7P**

Lump Sum / 11/11/18 **3600**



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19004804MFSH
Our Ref: CS/FCI19013086/K1qf3

Date: 26 July 2019

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 6306T .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 25/07/2019 at the premises of M/s PREMIER AUTOMOTIVE, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>5,605.70</u> .
Revised Estimate Amount	: S\$ <u>2,962.30</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the n/s front portion.



Yours faithfully

Kalvin
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	23-07-2019	Our Ref No. D19004804MFSH
Accident Date	19-07-2019	Claim Type. Third Party
Insured Vehicle	SHB2280P	Third Party Vehicle. SHC6306T
Survey Location	23 CHANGI SOUTH AVENUE 2 #01-02	
Contact Person.	VINCENT CHUA	
Contact No.	62148880/ 65446689	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 26 July 2019 11:13 AM
To: 'CWS Motor Claims'; assignments
Cc: 'Henry Kao'; SUR
Subject: RE: SURVEY ASSESSMENT - D19004804MFSH/1
Attachments: CSFC19013086K1qf3.pdf

Dear Henry,

Enclosed herewith preliminary advice of SHC 6306T.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Wednesday, 24 July 2019 4:43 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19004804MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that repairer agreed survey on 25/07/2019.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 24 July 2019 3:05 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004804MFSH/1

Dear Sir/Mdm,

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	25 Nov 2014 / 09:15:20	Receipt No.:	AACCK001-AX239-141125-000006
Asset Type:	Vehicle	Transaction Amount:	\$64,194.00
Asset ID:	SHC6306T	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20141125091520280830		

Vehicle No.:	SHC6306T
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	25 Nov 2014
Original Registration Date:	25 Nov 2014
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414MF5555085
Engine No.:	D4FDEH311820
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2014
Open Market Value:	\$20,155.00
Minimum PARF Benefit:	\$7,630.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	25 Nov 2014 09:15:20
COE No.:	2014112501001363Z
COE Expiry Date:	24 Nov 2022
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$51,337.00
Lifespan Expiry Date:	24 Nov 2022
Owner ID Type:	Company

CASH SALE/WORK ORDER

No: Z 3924



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717

TEL : 6743 1987 (3 LINES) FAX : 6743 0013

Reg No: 200415052W

Date: 23/11/19

寶號

Messrs:

車號

Vehicle No:

由

From:

到

To:

其他

Remark:

時間

Time:

11:30-12:00

AMOUNT: \$

注意: 本公司對所拖之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

經手人

Authorised by:

收貨人

Received by:

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

25-Jul-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6306 T

1 pc	Front bumper	—	531.00
1 pc	Front bumper emblem	—	44.00
1 pc	Front bumper tow hook cap	X	14.00
2 pc	Front bumper n/s & o/s side retainer	X	32.00
1 pc	Front n/s fender inner shield	X	120.00
1 pc	Front n/s fender	—	384.00
1 pc	Front n/s wheel cover	X	116.00
1 pc	Front n/s head lamp	—	1,028.00
1 pc	Front n/s rim	X	246.00
1 pc	Front n/s lower arm	—	439.00
1 pc	Front n/s shock absorber	—	330.00
1 pc	Front n/s ball joint	X	59.00
1 pc	Front n/s knuckle arm	—	547.00
1 pc	Front n/s knuckle bearing	—	157.00
1 pc	Front n/s stabilizer link	X	86.00
			\$ 4,133.00
		Less 10%	\$ 413.30
			\$ 3,719.70

S/NETT

1 pc	Front bumper clips	—	48.00
1 pc	Front n/s fender sticker	X	30.00
1 set	Front n/s fender inner shield clips	—	28.00
	Sundry	—	50.00
	Towing Fee	—	50.00
	To check front n/s wheel alignment	—	80.00
	To refit / dismantle front n/s wheel undercarriage	—	250.00
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	—	180.00
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.	—	650.00
	To putty and spray painting on front bumper, front n/s fender	—	500.00
	To apply rustproofing on the repaired and replaced panels.	—	120.00
			\$ 5,605.70

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

5941.50

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey but neither spray painting
• To display damaged parts with no resurvey
• Parts prices are subject to LKK Auto Consultants
• Third party survey is on a "best offer" basis
• No illegal modifications in all areas
• Supplementary terms must be approved and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Kahin (Uly)
25/7/19 10:15h
3 by

4/5
After Repair

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

25-Jul-19

SUPPLEMENTARY ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6306 T

1 pc	Front n/s tie rod end	—	<i>Boat</i>	\$	61.00
1 pc	Front n/s tie rod	—	<i>Boat</i>	\$	96.00
1 pc	front n/s insulator assy strut	—	<i>Boat</i>	\$	105.00
				\$	262.00
				Less 10%	\$ 26.20
				\$	235.80

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19013086/K1qf3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 19-08-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 2280P	Veh. Inspected	SHC 6306T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004804MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	24/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KNAGM414MF5555085	Colour	SILVER	
Odometer	424440	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	MAXXIS	7 mm	
L/H Front Tyre	205/65 R16	MAXXIS	7 mm	
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/07/2019	Inspection Date	25/07/2019	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6306T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	CRACKED	531.00	531.00
1	FRONT BUMPER EMBLEM	NECESSARY	44.00	44.00
1	FRONT BUMPER TOW HOOK CAP	SERVICEABLE	14.00	-
2	FRONT BUMPER N/S & O/S SIDE RETAINER	SERVICEABLE	32.00	-
1	FRONT N/S FENDER INNER SHIELD	TORN	120.00	120.00
1	FRONT N/S FENDER	BUCKLED	384.00	384.00
1	FRONT N/S WHEEL COVER	TO REPAIR SEE LABOUR	116.00	-
1	FRONT N/S HEAD LMAP	GRAZED	1,028.00	1,028.00
1	FRONT N/S RIM	SERVICEABLE	246.00	-
1	FRONT N/S LOWER ARM	BENT	439.00	439.00
1	FRONT N/S SHOCK ABSORBER	BENT	330.00	330.00
1	FRONT N/S BALL JOINT	SERVICEABLE	59.00	-
1	FRONT N/S KNUCKLE ARM	BENT	547.00	547.00
1	FRONT N/S KNUCKLE BEARING	NECESSARY	157.00	157.00
1	FRONT N/S STABILIZER LINK	SERVICEABLE	86.00	-
1	FRONT N/S TIE ROD END (ADDITIONAL)	BENT	61.00	61.00
1	FRONT N/S TIE ROD (ADDITIONAL)	BENT	96.00	96.00
1	FRONT N/S INSULATOR ASSY STRUT (ADDITIONAL)	BENT	105.00	105.00
	LESS 10% DISCOUNT		-439.50	-384.20
			3,955.50	3,457.80
SPECIAL NETT ITEMS				
1	FRONT BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	FRONT N/S FENDER STICKER (SN)	NOT NECESSARY	30.00	-
1	SET FRONT N/S FENDER INNER SHIELD CLIPS (SN)	NECESSARY	28.00	28.00
1	SUNDRY (N)	NECESSARY	50.00	20.00
			156.00	96.00
LABOUR				
	TOWING FEE.		50.00	50.00
	TO CHECK FRONT N/S WHEEL ALIGNMENT.		80.00	60.00

Report Ref No. CS/FCI19013086/K1qf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REFIT/DISMANTLE FRONT N/S WHEEL UNDERCARRIAGE.	NOT NECESSARY	250.00	-
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS, INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE SAME, ETC. INCLUSIVE OF THE REPAIR OF FRONT N/S WHEEL COVER.		650.00	400.00
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER, FRONT N/S FENDER.		500.00	410.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		120.00	50.00
			1,830.00	970.00
GRAND TOTAL			5,941.50	4,523.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,600.00

Report Ref No. CS/FCI19013086/K1qf3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.