

ASS. REC. BY:

REF: CS/FCI19013098/Kv43ⁿ² Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

CWS

From (Person): Henry Kao

of

FCI

Date/Time: 9:26am @ 25/7/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMJ 8179J

Insured:

SHB2438C

at Workshop m/s:

Hui Yang Motor

Tel:

64515752

of

Blk 176 Sin Ming Drive # 04-02

Policy No:

Claim No:

D19004839MFST

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/7/2019

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

9:57am @ 25/7/19

Person Contacted:

Belle

Vehicle:

IN / OUT

Date/Time

Action/Instruction

Vehicle 1

SMJ 8179J X

SHB 2438C

CS/FCI18004379/Kvd3e2 ROA = 2/3/18

26/7/19

Email preli revised to FCI

1/8

6/1/19 @ 2:00pm email & confirm (Ref 3134.28, 5490)

REF: FCI

ASSIGNMENT

From: Date: 25/7/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMJ8179J
at Workshop m/s Hui Yang Motor
of 176 Sin Ming Drive # 04-02

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 895k

IDAC: Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{cup}

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SMJ8179J Yr Regn: 03 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 01 AUG 2019

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2) 1/8 - typist

Report Format:

Lump Sum / L/R: L/S \$2700k

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Insp (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS: SI

Folio:

Other:

TOTAL

140

50

50+50

19

309



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19004839MFSH

Our ref: CS/FCI19013098/Kvf3

Date : 26/7/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SMJ 8179J


We thank for your instruction on 25/7/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 25/7/2019 at the premises of M/s HUI YANG MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$5,834.28
Revised Estimate Amount	: S\$3,285.56
"Check" Items Amount	: S\$134.80
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	24-07-2019	Our Ref No. D19004839MFSH
Accident Date	23-07-2019	Claim Type. Third Party
Insured Vehicle	SHB2438C	Third Party Vehicle. SMJ8179J
Survey Location	BLK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE	
Contact Person.	BEL	
Contact No.	6451 5752/ 0	Fax No. 6451 4658
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUI YANG MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 26 July 2019 11:31 AM
To: 'CWS Motor Claims'
Cc: 'Henry Kao'; SUR
Subject: RE: SURVEY ASSESSMENT - D19004839MFSH/1-SMJ 8179J
Attachments: SMJ 8179J PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SMJ 8179J
Date of survey: 25/7/2019
Number of days : 4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Thursday, 25 July 2019 10:03 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19004839MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 25 July 2019 9:26 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004839MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

辉陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

23/07/2019

Owner: ACE FLEET MANAGEMENT PTE LTD

ESTIMATE TO REPAIR HONDA FREED - SMJ8179J

1pc	rear tailgate
1pc	rear tailgate "H" logo
1pc	rear tailgate "FREED" emblem
1pc	rear tailgate "HYBRID" emblem
1pc	rear tailgate inner garnish
1pc	rear tailgate inner lock
1pc	rear tailgate inner rubber
1pc	rear tailgate inner handle
1pc	rear bumper 929
1pc	rear end panel
1pc	rear end panel inner garnish
1pc	rear windscreen moulding

less 20%

By	\$	1,207.90	✓
re	\$	50.25	✓
re	\$	48.20	✓
re	\$	65.10	✓
re	\$	265.30	X
Ad re	\$	187.50	✓
su	\$	168.50	X
re	\$	27.50	X
Bu/ins	\$	991.20	✓
SR	\$	623.70	X
SL	\$	100.90	X
re re	\$	181.80	✓

\$ 3,917.85

\$ 783.57

\$ 3,134.28

1set	reverse sensor
	sealant

Phat	s.nett	\$	280.00	2000
re	s.nett	\$	120.00	4000

remove & refix rear windscreen
tuffkote
wiring
spray painting
labour charges
Total

\$	120.00	✓
\$	100.00	300
\$	80.00	200
\$	1,000.00	400
\$	1,000.00	400
\$	5,834.28	



LK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19013098/Kvf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 02-08-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 2438C	Veh. Inspected	SMJ 8179J	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004839MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	25/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FREED (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	GB71068582	Colour	METALLIC GREY	
Odometer	30803	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	DUNLOP	7 mm	
L/H Front Tyre	185/65 R15	DUNLOP	7 mm	
R/H Rear Tyre	185/65 R15	DUNLOP	7 mm	
L/H Rear Tyre	185/65 R15	DUNLOP	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/07/2019	Inspection Date	25/07/2019	
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 8179J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TAILGATE	BENT	1,207.90	1,207.90
1	REAR TAILGATE "H" LOGO	NECESSARY	50.25	50.25
1	REAR TAILGATE "FREED" EMBLEM	NECESSARY	48.20	48.20
1	REAR TAILGATE "HYBRID" EMBLEM	NECESSARY	65.10	65.10
1	REAR TAILGATE INNER GARNISH	SERVICEABLE	265.30	-
1	REAR TAILGATE INNER LOCK	DENTED	187.50	187.50
1	REAR TAILGATE INNER RUBBER	SERVICEABLE	168.50	-
1	REAR TAILGATE INNER HANDLE	SERVICEABLE	27.50	-
1	REAR BUMPER	BUCKLED / DENTED	991.20	929.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	623.70	-
1	REAR END PANEL INNER GARNISH	SERVICEABLE	100.90	-
1	REAR WINDSCREEN MOULDING	NECESSARY	181.80	181.80
	LESS 20% DISCOUNT		-783.57	-533.95
			3,134.28	2,135.80
<u>SPECIAL NETT ITEMS</u>				
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SEALANT (SN)	NECESSARY	120.00	40.00
			400.00	240.00
<u>LABOUR</u>				
	REMOVE & REFIX REAR WINDSCREEN.		120.00	120.00
	TUFFKOTE.		100.00	30.00
	WIRING.		80.00	20.00
	SPRAY PAINTING.		1,000.00	440.00
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,000.00	400.00
			2,300.00	1,010.00
GRAND TOTAL			5,834.28	3,385.80



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,700.00
---	--	--	----------

Report Ref No. CS/FCI19013098/Kvf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.