



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2003953
INV Date 15/05/2020
Reference CC6/CTI19013105/Aha3n2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SKM 4022L
Insured Veh. SBH 19G
Claim No. SNM19D203495
Policy No. DMPCSN1675361902
Accident Date 23/07/2019
Inspection Date 24/07/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI19013105/Aha3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 15-05-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SBH 19G	Veh. Inspected	SKM 4022L
Policy No.	DMPCSN1675361902	Coverage (\$)	0.00
Claim No.	SNM19D203495	Excess (\$)	0.00
Assign From		Assign Date	24/07/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA CAMRY	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	MR053BK4007012133	Colour	GREY
Odometer	243447	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	YOKOHAMA	6 mm
L/H Front Tyre	215/60 R16	YOKOHAMA	6 mm
R/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm
L/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/07/2019	Inspection Date	24/07/2019
Survey held at	DYNAMIC AUTOWORK PTE LTD 8 KAKI BUKIT AVE 4 #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	14 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKM 4022L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	520.00	520.00
1	FRONT BUMPER BOTTOM COVER GARNISH	NOT NECESSARY	275.00	-
2	FRONT BUMPER FOGLAMP @\$215.00	NOT NECESSARY	430.00	-
2	FRONT BUMPER FOGLAMP COVER @\$70.00	NOT NECESSARY	140.00	-
1	FRONT BUMPER TOW HOOK COVER	DEFORMED	30.00	30.00
1	FRONT BUMPER GRILLE (UPPER)	CRACKED	570.00	570.00
1	FRONT BUMPER GRILLE (LOWER)	NOT NECESSARY	158.00	-
1	FRONT BUMPER GRILLE LOGO	NECESSARY	65.00	65.00
2	FRONT BUMPER RETAINER @\$85.00	NECESSARY	170.00	170.00
1	FRONT BUMPER REINFORCEMENT	BENT	465.00	465.00
1	FRONT BUMPER SPONGE	DEFORMED	140.00	140.00
2	HEADLAMP @\$2596.00	CRACKED	5,192.00	5,192.00
1	FRONT FENDER	TO REPAIR SEE LABOUR	820.00	-
2	FRONT FENDER INNER COWLING @\$175.00	NOT NECESSARY	350.00	-
1	BONNET	DISTORTED	1,425.00	1,425.00
2	BONNET DAMPER @\$130.00	NOT NECESSARY	260.00	-
1	BONNET INSULATOR	NOT NECESSARY	505.00	-
2	BONNET HINGE @\$70.00	NOT NECESSARY	140.00	-
1	BONNET RUBBER	CUT	75.00	75.00
1	BONNET LOCK	DAMAGED	150.00	150.00
2	BONNET STOPPER @\$20.00	NOT NECESSARY	40.00	-
1	BRACE PANEL	BENT	125.00	125.00
1	RADIATOR SUPPORT PANEL	DISTORTED	1,035.00	1,035.00
1	FRONT WIPER WASHER TANK	NOT NECESSARY	185.00	-
1	FRONT WIPER WASHER TANK MOTOR	NOT NECESSARY	123.00	-
1	OIL COOLING PIPE	NOT NECESSARY	187.00	-
1	AIR DUCT	DEFORMED	185.00	185.00
1	AIR CLEANER	NOT NECESSARY	296.00	-
2	HORN @\$120.00	BENT	240.00	240.00
1	AIRCON CONDENSOR	DENTED	1,620.00	1,620.00

Report Ref No. CC6/CTI19013105/Aha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIRCON FAN MOTOR	NOT NECESSARY	435.00	-
1	AIRCON FAN BLADE	CRACKED	179.00	179.00
1	AIRCON PIPE	NOT NECESSARY	387.00	-
1	RADIATOR	CRACKED	2,125.00	2,125.00
1	RADIATOR FAN COWLING	CRACKED	399.00	399.00
1	RADIATOR FAN MOTOR	NOT NECESSARY	457.00	-
1	RADIATOR FAN BLADE	CRACKED	169.00	169.00
2	RADIATOR SIDE GARNISH @\$160.00	N/S DEFORMED	320.00	160.00
1	BOOTLID	DISTORTED	910.00	910.00
1	BOOTLID DETECTOR	NOT NECESSARY	395.00	-
2	BOOTLID LAMP @\$420.00	NOT NECESSARY	840.00	-
1	BOOT LID EMBLEM "CAMRY"	NECESSARY	65.00	65.00
1	BOOT LID EMBLEM "2.4"	NECESSARY	60.00	60.00
1	BOOT LID LOGO	NECESSARY	80.00	80.00
2	BOOTLID HINGE @\$126.00	NOT NECESSARY	252.00	-
2	BOOTLID STOPPER @\$19.00	NOT NECESSARY	38.00	-
1	BOOTLID INSULATOR	NOT NECESSARY	265.00	-
1	BOOTLID LOCK	DAMAGED	395.00	395.00
1	BOOTLID CATCHER	NOT NECESSARY	25.00	-
1	BOOTLID WEATHERSTRIP	CUT	240.00	240.00
1	REAR NUMBER PLATE GARNISH WITH MOULDING	CRACKED	380.00	380.00
1	REAR BUMPER	DEFORMED	560.00	560.00
2	REAR BUMPER REFLECTOR @\$75.00	CRACKED	150.00	150.00
2	REAR BUMPER SIDE RETAINER (SIDE) @\$70.00	NECESSARY	140.00	140.00
2	REAR BUMPER SIDE RETAINER (CORNER) @\$80.00	NECESSARY	160.00	160.00
2	REAR BUMPER SCREW COVER GARNISH @\$28.00	NOT NECESSARY	56.00	-
1	REAR BUMPER REINFORCEMENT	BENT	405.00	405.00
2	REAR TOWING HOOK @\$28.00	NOT NECESSARY	56.00	-
2	TAILLAMP @\$535.00	CRACKED	1,070.00	1,070.00
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	230.00	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	995.90	-
2	REAR FENDER INNER COWLING @\$405.00	NOT NECESSARY	810.00	-

Report Ref No. CC6/CTI19013105/Aha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR FENDER INNER TRIM @\$675.00	NOT NECESSARY	1,350.00	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	240.00	-
1	REAR END PANEL	DISTORTED	620.00	620.00
1	REAR END PANEL TOP GARNISH	DEFORMED	420.00	420.00
1	REAR FLOOR PANEL TOP BOARD	TORN	280.00	280.00
1	REAR FLOOR PANEL	BUCKLED	1,140.00	1,140.00
1	REAR SPARE TYRE BOLT	NOT NECESSARY	32.00	-
1	REAR CHASSIS MEMBER RH	TO REPAIR SEE LABOUR	796.00	-
1	REAR EXHAUST PIPE	TO REPAIR SEE LABOUR	892.10	-
1	REAR EXHAUST INSULATOR	NOT NECESSARY	161.10	-
1	SET REAR EXHAUST GASKET	NOT NECESSARY	75.00	-
2	REAR EXHAUST MOUNTING @\$39.00	NOT NECESSARY	78.00	-
	LESS 25% DISCOUNT		-8,762.28	-5,528.50
			26,286.82	16,585.50
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	CRACKED	50.00	50.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	SET BONNET INSULATOR CLIP (SN)	NOT NECESSARY	50.00	-
1	SET FRONT FENDER COWLING CLIPS (SN)	NOT NECESSARY	60.00	-
1	RADIATOR SUPPORT PANEL SEALANT (SN)	NOT NECESSARY	80.00	-
1	RADIATOR COOLANT (SN)	NECESSARY	60.00	40.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	SET BOOTLID INSULATOR CLIP (SN)	NOT NECESSARY	50.00	-
1	SET TAILLAMP CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR FENDER SEALANT RH (SN)	NOT NECESSARY	150.00	-
1	SET REAR FENDER COWLING CLIPS (SN)	NOT NECESSARY	50.00	-
1	SET REAR FENDER INNER TRIM CLIPS (SN)	NOT NECESSARY	50.00	-
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR WINDSCREEN INNER SEAL (SN)	NOT NECESSARY	60.00	-
1	REAR END PANEL INSULATION SEAL (SN)	NECESSARY	150.00	60.00

Report Ref No. CC6/CTI19013105/Aha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FLOOR PANEL INSULATION SEAL (SN)	NECESSARY	350.00	200.00
1	REAR EXHAUST CHROME (SPECIAL TYPE)(SN)	NOT NECESSARY	350.00	-
1	REVERSE SENSOR (SN)	DAMAGED	220.00	200.00
			2,050.00	640.00
	LABOUR			
	PANEL BEATING,REMOVING AND REPLACING PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER.		1,600.00	800.00
	SPRAY PAINTING TO AFFECTED AREA.		1,600.00	800.00
	REFOCUS HEADLAMP BEAM.		60.00	30.00
	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS.		120.00	60.00
	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST.		80.00	60.00
	PANEL BEATING,REMOVAL AND REPLACING PARTS.INCLUSIVE OF THE REPAIR OF TAILLAMP PANEL RH,REAR FENDER RH,REAR CHASSIS MEMBER RH AND REAR EXHAUST PIPE.		2,400.00	1,400.00
	TO SPRAY PAINT AFFECTED AREA.		1,600.00	1,400.00
	TUFF COAT.		250.00	100.00
	WIRING CHECK.		160.00	30.00
	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR.		250.00	120.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		80.00	50.00
	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING.	NOT NECESSARY	80.00	-
	TRANSFER BOOTLID MECHANISM.		80.00	60.00
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	80.00	-
	REMOVE AND REFIX REAR WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
	REMOVE AND REFIX REAR EXHAUST.	NOT NECESSARY	180.00	-
	TRANSFER REAR DOOR MECHANISM.	NOT NECESSARY	80.00	-
	REMOVE & REINSTALL REAR WINDOW GLASS.	NOT NECESSARY	80.00	-
	REMOVE AND REFIX FUEL TANK TO FACILIATE FENDER REPLACEMENT.	NOT NECESSARY	80.00	-

Report Ref No. CC6/CTI19013105/Aha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	180.00	-
			9,160.00	4,910.00
GRAND TOTAL			37,496.82	22,135.50

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,000.00
---	--	--	--	----------

Report Ref No. CC6/CTI19013105/Aha3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

