

ASS. REC. BY:

REF: CS/FC119013111/T15f3ⁿ²

Special Instruction:

Surveyor: Tauhihi

ASSIGNMENT (Office)

CWS

From (Person): Sitharu

of

PEI

Date/Time: 9.47am 25/7/19

Estimated Cost:

Bill to:

OD TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJV 7183A

Insured:

SHC 0814H

at Workshop m/s

Gold Autoworks

Tel:

8199 9149

at

48 toh Anen Rd East #01-119

Policy No:

Claim No:

D19004819 MF5H

Sum Insured:

Excess:

Make of Veh:

D.O.A.

18/7/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10.40am 25/7/19

Person Contacted:

Simon

Vehicle IN OUT

Date/Time	Action/Instruction
	1. Initial <u>1</u>
	SJV 7183A NS/INC19006220/K1gd3n2 DOA = 5/4/19
	SHC 814H NS/INC16020726/H1gh3m2 DOA = 30/10/16
26/07/19	@ 4:43 pm revised PA to Sitharu via email



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19004819MFSH

Date: 26 July 2019

Our Ref: CS/FCI19013111/T1sf3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJV 7183A .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 25/07/2019 at the premises of M/s Gold Autoworks Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 8,412.75 .
Revised Estimate Amount	: S\$ 3,465.75 .
"Check" Items Amount	: S\$ 1,609.50 .
Total	: S\$.
Market Value	: S\$.
LTA Reimbursement Value	: S\$.
Nett Value	: S\$.

Description of Damage:

The vehicle sustained damages at the front o/s portion. The undercarriage affected due to collision.



Comments/ Present Status:

Damages Consistent.
Repair days: 5 days

Yours faithfully,
Mohamad Taufikh
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	24-07-2019	Our Ref No. D19004819MFSH
Accident Date	18-07-2019	Claim Type. Third Party
Insured Vehicle	SHC0814H	Third Party Vehicle. SJV7183A
Survey Location	48 TOH GUAN RD EAST ENTERPRISE HUB01-119, GOLD AUTO WORKS	
Contact Person.	SIMON TAN	
Contact No.	81999149/ 81999149	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	GOLD AUTO WORKS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

To: claims@goldautoworks.com.sg; Taufikh
Cc: survey
Subject: RE: Requesting for finalise amount : SJV7183A

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25
| S(408933)

-----Original Message-----

From: claims@goldautoworks.com.sg [mailto:claims@goldautoworks.com.sg]

Sent: Tuesday, 6 August 2019 3:51 PM

To: Taufikh <taufikh@lkkauto.com>

Cc: survey <sur@lkkauto.com>

Subject: Requesting for finalise amount : SJV7183A

Hi Taufikh, without prejudice

Please kindly advice us your finalise amount for our client veh no :
SJV7183A

THANKS & REGARDS,
SIMON TAN
GOLD AUTOWORKS PTE LTD
8199-9149

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 26 July 2019 2:43 PM
To: 'Sithara'; 'CWS Motor Claims'
Cc: assignments; SUR
Subject: RE: SURVEY ASSESSMENT - D19004819MFSH/1
Attachments: SJV 7183A - Preli Advise -.pdf

Dear Sithara,

Enclosed preliminary revised of vehicle SJV 7183A.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 25 July 2019 10:45 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19004819MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Thursday, 25 July 2019 9:47 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004819MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System


Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	832J
Vehicle Details	
Vehicle No.:	SJV7183A
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	3ZZ4964223
Chassis No.:	MR053ZEE106165178
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,853.00
Original Registration Date:	08 Feb 2010
First Registration Date:	08 Feb 2010
Transfer Count:	1
Actual ARF Paid:	\$17,853.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Feb 2020
PARF Rebate Amount:	\$8,926.00
Intended COE Rebate Details	
COE Expiry Date:	07 Feb 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$19,989.00
COE Rebate Amount:	\$1,066.00
Total Rebate Amount:	\$9,992.00

The information contained herein is correct as at 26 Jul 2019

OK

GOLD AUTOWORKS PTE LTD

48 Toh Guan Road East Enterprise Hub #01-119 Singapore 608586

Email : claims@goldautoworks.com.sg Company Reg no. 201716329M

CAR MODEL : TOYOTA ALTIS

VEH NO: SJV7183A

CHASSIS NO : MR053ZEE106165178

HP:8199-9149

Estimate Bill

	List Item	Qty	Unit Price	Amount
1	front bumper	1	\$ 463.00	\$ 463.00
2	front bumper retainer RH	1	\$ 122.00	\$ 122.00
3	front bumper weatherstrip	1	\$ 145.00	\$ 145.00
4	front bonnet	1	\$ 980.00	\$ 980.00
5	front wahser tank	1	\$ 285.00	\$ 285.00
6	front foglamp RH	1	\$ 220.00	\$ 220.00
7	foglamp garnishes RH	1	\$ 175.00	\$ 175.00
8	front fender RH	1	\$ 722.00	\$ 722.00
9	front headlamp RH	1	\$ 544.00	\$ 544.00
10	front support panel	1	\$ 736.00	\$ 736.00
11	front wheel garnishes RH	1	\$ 230.00	\$ 230.00
12	front lower arm RH	1	\$ 375.00	\$ 375.00
13	front suspension RH	1	\$ 664.00	\$ 664.00
14	front wheel knuckle RH	1	\$ 480.00	\$ 480.00
15	front wheel bearing	1	\$ 286.00	\$ 286.00
16	front stabilizer link RH	1	\$ 130.00	\$ 130.00
List Total				\$ 6,557.00
List 25% Discount				\$ 1,639.25
After Discount				\$ 4,917.75
Special Nett Item				
17	VVTi emblem	1	\$ 90.00	\$ 90.00
18	front TOYOTA logo	1	\$ 90.00	\$ 90.00
19	support panel sealant	1	\$ 100.00	\$ 100.00
20	wheel alignment	1	\$ 100.00	\$ 100.00
21	front tyre 195/65/r15 RH	1	\$ 280.00	\$ 120-150.00
22	bumper clip	10	\$ 4.00	\$ 40.00
23	wheel garnishes clip	15	\$ 3.00	\$ 45.00
Labour				
A	to check wiring system & repair wire harness, focus headlamp	-	\$ 100.00	\$ 100.00
B	to remove, check & replace front RH undercarriage parts	-	\$ 300.00	\$ 300.00
C	to apply anti-rust coating on new & affected panel	-	\$ 150.00	\$ 150.00
D	to straighten, repair, realign on damaged area	-	\$ 1,000.00	\$ 1,000.00
E	to spray painting, blending on damaged area	-	\$ 1,200.00	\$ 1,200.00
Total Labour & S/N				\$ 3,495.00
After Lump-sum 20%				\$ 6,730.20

de ✓
ne ✓
Bent ✓
RX ✓
ole ✓
X nn ✓
X ? de ✓
bt ✓
Gra ✓
Ry ✓
do ✓
X X nn ✓
X nn ✓
Pbt ✓
Pbt ✓
X nn ✓

3452
2589

Asi ✓
Asi ✓
X nn ✓
60 L ✓
cut ✓ 80%
30 ne ✓
10 ne ✓
400

30 ✓
150? plus ✓
30 ✓
500 ✓
600 ✓
1410
4399
4543500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97495744 5 days
"wp"
9 25/7/19 @ 1130
Lump sum
Resurvey after repair
5 days
sure lkkauto.com
taufik@lkkauto.com

Soon Huat Autoserv Pte Ltd

48 Tuh Guan Road East #01-136

Enterprise Hub

Singapore 668586

Phone Number 8002 5982, 9770 5782

After

Customer: GA GOLD AUTO WORKS Date: 7/26/2019 1:24 PM
Company: VIN
License No: SJV7183A Technician: AL HONG
Odometer: Order No.

VEHICLE ALIGNMENT REPORT

TOYOTA, COROLLA ALIIS E141(Custom), 07-12,

Primary Angles

Primary Angles			Initial	Specifications		Final
Front	Caster	Left	2°36'	Min 2°00'	Max 3°30'	2°35'
		Right	2°10'	2°00'	3°30'	2°11'
	Camber	Left	0°01'	-1°15'	0°15'	-0°44'
		Right	-1°17'	-1°15'	0°15'	-1°20'
	Toe	Left	1.2	-0.6mm	0.6mm	0.0
		Right	2.5	-0.6mm	0.6mm	0.0
		Total	3.7	-1.2	1.2	0.0
	Rear	Camber	Left	-1°23'	-2°00'	-1°00'
Right			-1°15'	-2°00'	-1°00'	-1°13'
Toe		Left	0.2	-0.2mm	1.3mm	0.3
		Right	0.1	-0.2mm	1.3mm	0.0
		Total	0.3	-0.3	2.6	0.3
Thrust Angle			0°00'	---	---	-0°01'

Secondary Angles

			Initial	Specifications		Final
				Min	Max	
SAI	Left		12°32'	11°15'	11°15'	12°32'
	Right		12°52'	11°15'	11°15'	12°52'
Included Angle	Left		12°33'	---	---	11°48'
	Right		11°35'	---	---	11°32'
Toe Out On Turns	Left		---	---	---	---
	Right		---	---	---	---
Maximum Turns	Left		---	---	---	---
	Right		---	---	---	---
Toe Curve Change	Left		---	---	---	---
	Right		---	---	---	---
Setback	Front		3mm	---	---	4mm
	Rear		-4mm	---	---	-4mm
Track Width Diff			3mm			2mm
Wheel Base Diff			7mm			8mm
Front Ride Height	Left		---	---	---	---
	Right		---	---	---	---
Rear Ride Height	Left		---	---	---	---
	Right		---	---	---	---
Frame Angle						

Thank You For Your Business



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19013111/T1sf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 04-09-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 814H	Veh. Inspected	SJV 7183A
Policy No.		Coverage (\$)	0.00
Claim No.	D19004819MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	25/07/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	MR053ZEE106165178	Colour	WHITE
Odometer	229347	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	RASSURER	6 mm
L/H Front Tyre	195/65 R15	RASSURER	6 mm
R/H Rear Tyre	195/65 R15	RASSURER	6 mm
L/H Rear Tyre	195/65 R15	RASSURER	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	18/07/2019	Inspection Date	25/07/2019
Survey held at	GOLD AUTOWORKS PTE LTD 48 TOH GUAN ROAD EAST #01-119 ENTERPRISE HUB SINGAPORE 608586		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 7183A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED	463.00	463.00
1	FRONT BUMPER RETAINER RH	NECESSARY	122.00	122.00
1	FRONT BUMPER WEATHERSTRIP	CUT	145.00	145.00
1	FRONT BONNET	TO REPAIR SEE LABOUR	980.00	-
1	FRONT WASHER TANK	DEFORMED	285.00	285.00
1	FRONT FOGLAMP RH	NOT NECESSARY	220.00	-
1	FOGLAMP GARNISHES RH	DEFORMED	175.00	175.00
1	FRONT FENDER RH	BENT	722.00	722.00
1	FRONT HEADLAMP RH	CRACKED	544.00	544.00
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	736.00	-
1	FRONT WHEEL GARNISHES RH	DEFORMED	230.00	230.00
1	FRONT LOWER ARM RH	NOT NECESSARY	375.00	-
1	FRONT SUSPENSION RH	NOT NECESSARY	664.00	-
1	FRONT WHEEL KNUCKLE RH	BENT	480.00	480.00
1	FRONT WHEEL BEARING	BENT	286.00	286.00
1	FRONT STABILIZER LINK RH	NOT NECESSARY	130.00	-
	LESS 25% DISCOUNT		-1,639.25	-863.00
			4,917.75	2,589.00
<u>SPECIAL NETT ITEMS</u>				
1	VVTI EMBLEM (SN)	NECESSARY	90.00	90.00
1	FRONT TOYOTA LOGO (SN)	NECESSARY	90.00	90.00
1	SUPPORT PANEL SEALANT (SN)	NOT NECESSARY	100.00	-
1	FRONT TYRE 195/65/R15 RH (\$150.00)(80%)(SN)	CUT	280.00	120.00
10	BUMPER CLIP @\$4.00 (SN)	NECESSARY	40.00	30.00
15	WHEEL GARNISHES CLIP @\$3.00 (SN)	NECESSARY	45.00	10.00
			645.00	340.00
<u>LABOUR</u>				
	WHEEL ALIGNMENT.		100.00	60.00

Report Ref No. CS/FCI19013111/T1sf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING SYSTEM & REPAIR WHERE HARNESS, FOCUS HEADLAMP.		100.00	30.00
	TO REMOVE, CHECK & REPLACE FRONT RH UNDERCARRIAGE PARTS.		300.00	150.00
	TO APPLY ANTI-RUST COATING ON NEW & AFFECTED PANEL.		150.00	30.00
	TO STRAIGHTEN, REPAIR, REALIGN ON DAMAGED AREA, INCLUSIVE OF THE REPAIR OF FRONT BONNET AND FRONT SUPPORT PANEL.		1,000.00	600.00
	TO SPRAY PAINTING, BLENDING ON DAMAGED AREA.		1,200.00	600.00
			2,850.00	1,470.00
GRAND TOTAL			8,412.75	4,399.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,500.00

Report Ref No. CS/FCI19013111/T1sf3n2

MARKET VALUE: \$18,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$9,992.00=NETT VALUE: \$8,008.00

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.