

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931 . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GY8464C190718

Estimate**Customer**

Name: AXA Insurance Singapore Pte Ltd

Date: 24-07-19

Address: Motor Claims Department

Vehicle No: GY8464C

8 Shenton Way #27-01

Model/Make: Toyota Hiace Manual

AXA Tower

Singapore 068811

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate <i>Body</i>	\$ 1,456.00	
2	Tailgate Weatherstrip <i>1m</i>	\$ 395.10	
3	Tailgate Inner Lock <i>20/3m</i>	\$ 359.00	
4	Tailgate Lock Striker <i>11</i>	\$ 20.50	X
5	Tailgate Inner Trim Board <i>11</i>	\$ 248.20	X
6	Tailgate Inner Trim Board Clips 16 pcs (@ S\$5.50) <i>11</i>	\$ 88.00	X
7	Tailgate Number Plate "Metal" <i>11</i>	\$ 35.00	SN X
8	Tailgate Number Plate Lamp Outer Garnish <i>11</i>	\$ 346.50	X
9	Tailgate "70 KM/H" Sticker <i>11</i>	\$ 15.00	SN 10 S-1
10	Tailgate "8 PAX" Sticker <i>11</i>	\$ 15.00	SN 10 S-2
11	Tailgate "Toyota Logo" Emblem <i>11</i>	\$ 70.50	X
12	Tailgate Windscreen Moulding <i>11</i>	\$ 219.00	X
13	Tailgate Windscreen Sealant <i>11</i>	\$ 50.00	SN 405.2
14	Tail Lamp 02 pcs (@ S\$303.10) <i>11</i>	\$ 606.20	X
15	Tailgate 3rd Brake Lamp <i>11</i>	\$ 234.20	X
16	Corner Panel 02 pcs (@ S\$169.30) <i>11</i>	\$ 338.60	12C
17	Corner Panel <i>garnish</i> : 02 pcs (@ S\$71.50) <i>11</i>	\$ 143.00	12C
18	"Corporate" Advertisement & Artwork Sticker <i>11</i>	\$ 400.00	SN X
19	Bumper <i>466.10</i> <i>Ref 10.1</i>	\$ 599.30	X
20	Bumper Side Retainer 02 pcs (@ S\$65.10) <i>11</i>	\$ 130.20	SN 12C
21	Bumper Clips 1 set <i>11</i>	\$ 65.00	X
22	Bumper Side Holder 02 pcs (@ S\$69.10) <i>11</i>	\$ 138.20	12C
23	Bumper Lower Bracket 04 pcs (@ S\$103.00) <i>11</i>	\$ 412.00	205 70
24	Bumper Reverse Sensor <i>11</i>	\$ 220.00	X
25	End Panel Outer <i>Body</i>	\$ 566.10	X
26	End Panel Inner <i>Body</i>	\$ 936.20	X
27	End Panel Top Plate <i>11</i>	\$ 299.50	X
28	End Panel Sealant <i>11</i>	\$ 80.00	SN 50 S-2
29	Spare Tyre Carrier <i>11</i>	\$ 265.60	X
30	Spare Tyre Carrier Holder <i>11</i>	\$ 345.10	X
33	Plywood <i>11</i>	\$ 250.00	SN X
31	Rear Lh Body Panel (Fender) <i>Body/34C</i>	\$ 1,308.10	X
32	Tail Lamp Panel <i>Ref 10.1</i>	\$ 936.20	X
	Remove and refix rear tailgate components & wiper mechanism	\$ 80.00	60
	To check all wiring & electrical component for proper function	\$ 60.00	20
	Remove & reinstall Windscreen Glass to facilitate repairs	\$ 120.00	60
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,200.00	1100
	To putty & spray painting & including touch up paint on accident affe	\$ 1,000.00	800
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 80.00	✓

Total Parts & Labour of estimate for damaged vehicle: \$ 14,131.30

Total amount in Lump Sum Basis for repaired vehicle: \$ 14,131.30

SDLS:


Liu's Brother Auto Engineering Workshop
the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



APR 5 2019

not added
25/7/19
L/S \$ 5200
by
Wahab Ali Hassan

P-6067-1
507
P-2023-55
S.W 110-00
100-1120