_	Chong Buon Sin of CT	1 Date/Time 25.1-19 1-3572-m			
Estimated Co	,	Bill to:			
To Inspect Ve	STTP RES / OD RES / EVA / INV / MV / chicle No: SFV 80864	CS			
	m/s Performana	Insured: GB J 18017 Tel: 6319 0174			
of 303	Alexandra Roud				
Policy No:		Claim No: SN M 1917203462			
Sum Insured:		Excess:			
Make of Veh:(Client's Record)		D.O.A. 23.7.19			
CA / REV	REP. / REV 24 HRS 26-1-19 2-09, m Person Contacted:	Carolina Vehicle IN OUT			
Date/Time	Action/Instruction (V) Estimat				
		119013089/24 DOA = 23/7/19			
	GBI 18014	11.			
18/9/19		infirmed by email (Red 19, 817.85)7			

(TP)

BMW 5401

228

WBHJB320709459799

per la America (A subset) front of the

245/35K20

INSTRUMENTATIONS CONTRACTOR PORTRACTOR

"lebrite \$ 104,601

RECEIVED 1 8 SEP 2019

001120

189- typist

PP\$52,992.45

16

Nivitha (LKK Auto)

From:

Chong Boon Sen <booksen.chong@sg.cntaiping.com>

Sent:

Thursday, 25 July 2019 1:35 PM

To:

PBSP

Cc:

assignments

Subject:

RE: OUR REF: SNM19D203462/CHONGBS - FW: CAR IN WORKSHOP. PLEASE ARRANGE SURVEY ASAP. REQUEST FOR DIRECT SETTLEMENT - SFV8088H &

GBJ1801Y ON 23/07/2019

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG 3 Anson

Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]

Sent: Thursday, 25 July, 2019 1:34 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: OUR REF: SNM19D203462/CHONGBS - FW: CAR IN WORKSHOP. PLEASE ARRANGE SURVEY ASAP.

REQUEST FOR DIRECT SETTLEMENT - SFV8088H & GBJ1801Y ON 23/07/2019

Dear Sirs

We are agreeable to use a common surveyor below as the SJE. Please inform surveyor that our vehicle is in the workshop and to survey ASAP.

XING QUO QIANG

KENNETH KONG

Thank you.

Regards.

Caroline

C/o Performance Motors Limited - Body and Paint 303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Sent: Thursday, 25 July 2019 1:32:42 PM

To: 'pml-pbsp@simedarby.com.sg' <'pml-pbsp@simedarby.com.sg'>

Subject: RE: OUR REF: SNM19D203462/CHONGBS - FW: CAR IN WORKSHOP. PLEASE ARRANGE SURVEY ASAP.

REQUEST FOR DIRECT SETTLEMENT - SFV8088H & GBJ1801Y ON 23/07/2019

Without Prejudice

Dear Sir,

Kindly note above reference is CORRECT reference.

Chong Boon Sen

Claims Executive Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sq.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG 3 Anson

Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Chong Boon Sen

Sent: Thursday, 25 July, 2019 1:31 PM To: 'pml-pbsp@simedarby.com.sg'

Subject: RE: OUR REF: SNM19D2O3462/CHONGBS - FW: CAR IN WORKSHOP. PLEASE ARRANGE SURVEY ASAP.

REQUEST FOR DIRECT SETTLEMENT - SFV8088H & GBJ1801Y ON 23/07/2019

WITHOUT PREJUDICE

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING	
Kelvin Ang	
SEE CHEW SENG	
MOHD FADHILAH BIN OSMA	V
XING QUO QIANG	
KENNETH KONG	
SIMON HO	
CHUA WEIJIE	
MARCUS CHUA	
HENRY NG	

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive .Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG 3 Anson

Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Lim Shu Min

Sent: Thursday, 25 July, 2019 1:20 PM

To: Chong Boon Sen

boonsen.chong@sg.cntaiping.com>; 'pml-pbsp@simedarby.com.sg'

Cc: Angle Foo <angle.foo@sg.cntaiping.com>

Subject: FW: OUR REF: SNM19D203461/CHONGBS - FW: CAR IN WORKSHOP. PLEASE ARRANGE SURVEY ASAP.

REQUEST FOR DIRECT SETTLEMENT - SFV8088H & GBJ1801Y ON 23/07/2019

Dear All,

Please note that claim no. should be SNM19D203461.

Thanks, shumin

From: Claims Dept of CTI

Sent: Thursday, July 25, 2019 1:16 PM

To: Chong Boon Sen; Alfred Toh; Chee So Chow; 'pml-pbsp@simedarby.com.sg'

Cc: Angie Foo

Subject: OUR REF: SNM19D203462/CHONGBS - FW: CAR IN WORKSHOP, PLEASE ARRANGE SURVEY ASAP, REQUEST

FOR DIRECT SETTLEMENT - SFV8088H & GBJ1801Y ON 23/07/2019

Dear Boon Sen,

Please conduct PRS for SFV8088H.

Note: officer in charge is Boon Sen, 63896171.

Thanks, shumin

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]

Sent: Wednesday, July 24, 2019 3:48 PM

To: Claims Dept of CTI

Subject: CAR IN WORKSHOP. PLEASE ARRANGE SURVEY ASAP. REQUEST FOR DIRECT SETTLEMENT - SFV8088H &

GBJ1801Y ON 23/07/2019

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct

Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards, Caroline C/o Performance Motors Limited - Body and Paint 303 Alexandra Road Singapore 159941 DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit http://www.symanteccloud.com

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

307H

Vehicle Details

Vehicle No.:

SFV8088H

Vehicle to be Exported:

No

Intended Deregistration

26 Jul 2019

Date:

Vehicle Make:

B.M.W.

Vehicle Model:

540I SR LED NAV HUD

RCP MSPORT

Primary Colour:

Blue

Manufacturing Year:

2017

Engine No.:

11769873B58B30A

Chassis No.:

WBAJB32070G459799

Maximum Power

250.0 kW (335 bhp)

Output:

Open Market Value:

\$64,240.00

Original Registration

31 Mar 2017

Date:

First Registration Date:

31 Mar 2017

Transfer Count:

0

Actual ARF Paid:

\$87,632.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry

30 Mar 2027

Dates

PARF Rebate Amount:

\$65,724.00

Intended COE Rebate Details

COE Expiry Date:

30 Mar 2027

COE Category:

E - Open Category

COE Period(Years):

10

QP Paid:

\$51,000.00

COE Rebate Amount:

\$38,863.00

Total Rebate Amount:

\$104,587.00

The information contained herein is correct as at 26 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1, Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

	ACCIDENT STATEMENT
Date Of Report	24/07/2019 10:01
Date Of Accident	23/07/2019 18:30
Exact Location Of Accident	NORTHBOUND CTE BEFORE MERCHANT RD EXIT
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SFV8088H
Insured/Policyholder	
Name Of Registered Owner	GOH PUI KIAT
NRIC No	S1749307H
Email Address	GOHSAN999@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97694582
Alternative Phone No	OTHERS-97694582
Vehicle Particulars	
Manufacturer	DMM/

Manufacturer BMW
Model 5401

Exact Purpose for which vehicle was being used at

time of accident

NORMAL USAGE

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number P1919115

Cover Note Number

Driver

 Name of Driver
 GOH PUI KIAT

 NRIC No
 \$1749307H

 Date Of Birth
 07/07/1966

 Occupation
 INDOOR

 Date Of Driving Pass
 11/12/1985

Driving Experience 33 YEARS AND 7 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-97694582

Fax Number

Contact Number OTHERS-97694582

EMail Address GOHSAN999@GMAIL.COM

Address

22 NEWTON ROAD #15-08

Postcode

307990

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

3

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBJ1801Y

Vehicle Make/Model/Colour

SILVER NISSAN NV350

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

PHILBERT KHOO YAO SHENG

NRIC/Passport Number

S8632658B

Contact Number

97843721

Address

Postcode

Insurance Company Name

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SBL6859M

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

HYUNDAI RED TUCSON

PRIVATE CAR KAMINI D/O KUNASEGARAN \$8535166D

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

GARY FOR CHAI HOON
Performance factors (Philed
303 Alexanora Road
Sime Darby Performance Sentre
Singapore (599)

24/7/1

Policyholder's Signature Date & Time:

Tam.

Oriver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

CH PLAN						
A B B SFUSOSPH	C 281	E859 M	→			
RIBE CIRCUMSTANCES OF THE ACCIDE	ENT					
	ddm stop me of 1.(23/7/1	North	vehicle bound 30pm)	C (SBL 68:	59 M) he	
I am our 8.	I Stoppe			behind bu	hick C	٤.
	n (vehic hit my uto C.			ed ship	e .	
There was no	injuries.					
my front d	back por	As were	danag	ed.		
we atchonged I had the c	pmA:cula ar tened		Performani	re Motors s	repsogna	11/4
ARATION declare the foregoing particulars are true in	every respect.		S	Performence Metacs L 303 Alexandra Ref Singapore 15994	e Centre	74
holder's Signature Driver's S Time: (If driver	gnature s not the policyhold	DOM:	Reporting (entre Personnel's Sig	gnature	

Date & Time:

NRIC/FIN No.:

bmw Dealer

Estimate No.

Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197481553W GDT Reg. No M2-8020881-8 TG11-Free Mumber (1800-2355269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax: 64347770

: b1

52098

280. Eampony Arany Boad East Coast Centre Singapore 438180 Fax: 63449773

315, Alexandra Road Sime Darby Business Centre Eingaphre 189944 Fax. 64796621 (AfterSal 64786624 (Notorrad



GST REG. NO : M2 - 0020081 - X

ESTIMATE

2 4 JUL 2019

Page No. : 1 of 7

Date Estimated : 24/07/2019 Prepared By : Gary Poh Chai Hoon	
- ESTIMATE REPAIR FOR - Goh Pui Kiat 22 Newton Road #15-08 Singapore 307990	- ACCOUNT - 40000 Cash Sales - Service Singapore
REGN. NO. CHASSIS NO. REGN.	DATE MODEL MILEAGE
SFV8088H G459799 31/03	/2017 540iA 0
DESCRIPTION To replace frt bumper boonet, inner suppor bumper , bootlid tail panel, trunk floor and a include knockinbg cause by the accident	
painting front bumper bonnet, rear bumper trunk floor .left rear fender ,right rear fende	
To tow accident vehicle to PML workshop.	195.00
To supply front and rear emboss number p	late. bt 165.00
To check electrical wiring system at the fro sections for proper function including adjus headlights.	tment of
To replace both left and right headlights.	816 711 837.00
To replace radiator assembly, fan housing to conduct pressure test, bleed bleed cooling for leak. (For all models except 7 series).	
To replace air con condenser and air con h vacuum system, top up freon gas and chec (For all models except for 7 series).	10-19-03-13-15-16-16-16-16-16-16-16-16-16-16-16-16-16-
To carry out body cavity preservation. (Per panel).	200 - 236.00
To carry out body cavity preservation. (For cut panel).	7 4 5 531.00
To remove and install boot compartment ca to facilitate repairs.	arpet and garnish 230 271.00
To replace bootlid smart opener control un bottom sensor lines including program and	it, top and Iss place 7. 5 (661.00

Estimate No.

Performance Motors Limited

A Sine Darby Motors Company Co. Reg. No. 1974015598 OST Reg. No M2-8020881-s Tull-Free Mumber (1800-2255269)

303, Alexandra Road Eime Darby Performance Centre Eingapore 139941 Fax. 66767270

: b1

52098

280, Kampong Arang Road East Coast Centre Singapore 438180 Fax. 63449773 315. Alexandra Road Sime Darby Business Destre Hingspore 159944 Fax 64796601 (AfterSales) 64796224 (Motorrad)



Page No. : 2 of 7

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Date Estim					rage no.	2 02 /
Prepared B	y : Gary Poh C	hai Hoon				
REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL			MILEAGE
SFV8088H	G459799	31/03/2017	540iA			0
	DESCRIPTION					VALUE
	proper function.					
	To transfer lock mechanism fr including conduct checks on r system for proper function.		g		ηŊ	45 / 531.00
	To replace both front seat bel reset and checks for proper fu		ng		X electo	4517 531.00
	To replace rear exhaust silence system and conduct checks for				/ punto	451 531.00
	To replace front exhaust silen exhaust system and conduct				~ photo.	?45) 531.00
	To replac front end wiring cab function	eles including perform			1	7 451 531.00
	Sundries.				V	150.00
				Tot	al Labour 1:	24,183.00
	DESCRIPTION			QTY	PRIC	VALUE
	RADIATOR			1	1.032.65	71,032.65
	COVERING LOWER			1	74.95	74.95
	Rock guard			1	97.40	97.40
	RADIATOR			1	1,147.40	7 1,147.40
	FAN HOUSING WITH FAN 40	WOO		1	1,377.10	? 1,377.10
	CLAMPING BUSH			1	66.80	ht 7 66.80
	LH TAILPIPE TRIM CHROME			1	185.45	bt 185.45
	RH TAILPIPE TRIM CHROME	Ē		1	185.45	× 185.45 XW
	SWING SUPPORT			1	42.90	42.90
	FRONT MUFFLE			1	1,568.90	1,568.90
	Intermediate			1	577.50	h 7 577.50
	REAR SILENCER W/EXHAU	ST FLAP		1	2,211.30	bt ? 2,211.30 V
	RR TRUNK FLOOR CROSS	MEMBER		1	120.75	7 120.75
	LH ENGINE HOOD HINGE			1	92.75	7 92.75
	RH ENGINE HOOD HINGE			1	92.75	92.75
	LH TRUNK FLOOR			1	139.80	(139.80
	COMPLETE TAIL TRIM			1	833.60	833.60
	REAR LUGGAGE COMPART	MENT FLOOR		1	279.55	279.55
	ALUMINIUM ENGINE HOOD			1	2,371.75	61-2,371.75
	TAILGATE ALUMINIUM			1	1,741.00	17,741.00
	LH TRUNK LID HINGE			1	118.80	£ 118.80 \ /
	RH TRUNK LID HINGE			1	118.80	7 118.80 4 "
	OUTER PANEL TAIL TRIM			1	583.55	7 583.55
	FRT BUMPER CARRIER			1	723.05	ht 17 723.05

BOOK Dowler:

Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-8028081-x Toll-Free Number (1808-2255269)

103, Alexandra Rund Sime Durby Performance Centre Singapore 189941 Pax. 66767770 280. Kampong Arang Road East Coast Centre Singapore 438180 Fas: 63449773 313, Alexandra Road Sime Darby Business Centre Singapara Fax. 64796621 (AfterSales) 64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 52098 Page No. : 3 of 7

Date Estimated : 24/07/2019

Prepared By : Gary Poh Chai Hoon

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SEVROBBH	G459799	31/03/2017	540iA	0

FV8088H	G459799	31/03/2017	540iA		0
	DESCRIPTION		QTY	PRIC	VALUE
	FRT BUMPER BOTTOM CA	ARRIER	1	397.70	? 397.70
	LH GUIDE TOP		1	34.55	? 34.55
	RH GUIDE TOP		1	34.55	7 34.55
	FRT BUMPER TOP IMPAC	T ABSORBER (M)	1	62.05	des 62.05
	GRILLE AIR INLET MIDDLE		1	95.70	7 95.70
	LH GRILLE AIR INLET OPE		4	85.00	× 85.00
	RH GRILLE AIR INLET OPE	7.107		85.00	¥ 85.00
	LH FOG LAMP SUPPORT			77.95	¥ 77.95
				77.95	Y 77.95
	RH FOG LAMP SUPPORT				
	LH FINISHER DECO HIGH			80.30	€ 80.30
	RH FINISHER DECO HIGH			80.30	¥ 80.30
	FRT BUMPER BOTTOM IM	The state of the s	1	33.50	A-33.50
	FRT BUMPER PANEL PRIM	MED (M)	1	1,618.50	1,618.50
	REAR BUMPER CARRIER			857.75	857.75 108.65
	EXHAUST SUPPORT		1	108.65	
	REAR BUMPER COVER (N	1)	1	268.30	268.30
	REAR BUMPER LH GUIDE	(M)	1	55.75	55.75
	REAR BUMPER RH GUIDE	(M)	1	55.75	7 55.75
	REAR BUMPER CENTRE (GUIDE (M)	9	61.55	61.55
	REAR BUMPER PANEL PR		- 1	1,542.05	4 1,542.05
	TRIM GRILLE FRT (I CAM)		- 1	28.45	di3/7 28.45
	FRAME BOTTOM			55.95	7 55.95
	FRT LH GRILLE (M/SPORT	n.		145.70	Cam 145.70
	FRT RH GRILLE (M/SPORT	(4)		145.70	145.70
				84.80	de 84.80
	LICENCE PLATE HOLDER	(IVI)			1.60
	EMBLEM GROMMET		2		1.00
	LETTERING 540I		13	64.10	64.10
	PLAQUE 82MM		3	71.25	71.25
	PLAQUE 74MM		1	71.25	71.25
	GROMMET		2		2 1.50
	GAS FILLED STRUT ENGI	NE COMPARTMENT	2		248.00
	LOCK LH		1	120.05	120.05
	LOCK RH		1	120.05	120.05
	STRIKER BOOT LID		1	57.40	7 57.40
	BOOT LID/TAILGATE PUSI	H BOTTON (RFK)	1	24.60	My × 24.60
	TRUNK LID POWER LOCK	PANEL	9	221.60	221.60
	COUNTER SUPPORT REA	R VIEW CAMERA (R	9	4.60	4.60
	LOCK TRUNK LID		9	228.00	228.00
	RH SPINDLE DRIVE		9	580.35	,7 580.35
	REAR SILENCER HEAT IN	SULATION FRT	9	114.30	114.30
	REAR SILENCER LH HEAT		8	165.70	1 165.70
	REAR SILENCER HEAT IN		15	286.20	H-7 286.20
	WARNING SIGNALLER		7.6	38.95	7 38.95
	CONNECTION FRT TOP			252.05	ht 5 252.05
					64/87.95
	FRT PANEL SUPPORT		3	87.95	The second secon
	FRONT CROSSLINK		33	167.40	100000
	LH HEADLIGHT MOUNTIN	773		140.20	140.20
	RH HEADLIGHT MOUNTIN		31	140.20	MS 140.20
	COVERING CROSS MEMB	BER (ECE)	- 11	33.65	11× 33.65

MMM Dealer-

Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-w Tull-Pree Number (1800-2255269)

301, Alexandru Road Sine Darby Performance Centre Singapore 199941 Fax. 64147770

200, Hamping Arang Boad Bast Chast Centre Singapore 638380 Fax. 63448772





73,193.24

:

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. Date Estimated Prepared By	: b1 5209 : 24/07/2019 : Gary Poh 0)		Page	e No. : 4	of 7
REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL			MILEAGE
SFV8088H	G459799	31/03/2017	540iA			0
Claims OD / 3nd Regulary Putting Regular	196 430 Eso Tough Wh say 27495749 Aun	ES GH (ICON LIG GH (ICON LIG R) (ICON LIG R) (ICON LIG R) (ICON LIG R) (ICON LID RUNK LID RUNK LID (ICON) (the R To ri To d Part Thir No ii Sup	Auto Consultants hepairer of the folio survey before/after spreplay damaged part(s) is prices are subject to diparty survey in on a "legal modification(s) is plementary (tem(s) must bject to final approval to suledged by Repairer ture:	50 50 45 30 95 15 85 25 25 90 90 10 10 45 45 60 60 85 65 05 exts: ence notify wing: ay painting during resurvey confirmation National Prejudice* allowed at the resurveyed at from Insurance Con	d
				abour 1	- 1	24,183.00 44,221.90
				arts abour 2	13	0.00
				abour 2 xcess		0.00
				xcess otal GST 0 7	7% :	4,788.34
			G	rand Total		73 193 24

^{**} THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

^{**} PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **



		FACSIMILE	MESSAGE	
DATE	8/8/2019 China Taiping	TIME FAX NO NO OF PAG	ES	-
SUV ATTN MCA	Taufikh LKK Auto Gary Poh	FAX NO FAX NO TEL NO	64743229	-
Dear S		red in order, please do	call CSA. Thank you	
Vehicl Vehicl	ementary repair for B e Registration No. e Chassis No.	M\540iA SFV8088H G459799 replaced YESX Re	efer to attachment	
Supp	iementary raits to	NO 🗌		

Parts Description QTY		Prices	
Rep. cable ITS head airbag & c - X (Kit set activated)	1	\$59.75	
Rear silencer RHS heat insulation - X (Deformed)	1	\$165.7	
	_		
	_		
	Total =>	\$225.4	

A member of the Sime Darby Group Co. Reg. No. 197401559W. QST Reg. No. M2-0020081+X



Final Report

Estimate No. :

b1 52098

Date Estimated :

24/07/2019

Prepared By :

Gary Poh Chai Hoon

- ESTIMATE REPAIR FOR -

Goh Pui Kiat 22 Newton Road

#15-08

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd

8,500.00

5,542.00

702.00

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

Singapore 307990

REGN, NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

SFV8088H

G459799

31/03/2017

540iA

0

0

DESCRIPTION

To replace front bumper and attachments, front bonnet and attachments, both grilles, front panel support, front crosslink, air flaps top, upper left eninge compartment cover, rear bumper and attachmens, rear boot lid and dattachments, tail end panel and left tail lamps etc including to make good trunk floor panel, both rear fenders and knock out dented area caused by the accident. To remove and install body parts in order to carry

both rear fenders and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job.

To respray front bumper, front bonnet, rear bumper, rear boot lid, tail end panel, trunk floor panel and both rear fenders etc.

To tow accident vehicle to PML workshop.

To supply front and rear emboss number plate.

To check electrical wiring system at the front and rear sections for proper function including adjustment of headlights.

To replace both LED AHL High headlights.

To replace radiator assembly including to conduct pressure test, bleed bleed cooling system and check for leak.

To remove and install air con condenser and air con hose including to vacuum system, top up freon gas and check for leak.

To carry out body cavity preservation.

To carry out body cavity preservation.

(For cut panel).

To remove and install boot compartment carpet and garnish to facilitate repairs.

To replace bootlid smart opener control unit bottom sensor line and external aerial comfort access etc including program and conduct checks for proper function. ACCOUNT: ORIGINAL PRICE DISC. % NETT

8,500.00

0 5,542.00

702.00

195.00 0 195.00

165.00 0 165.00

250.00 0 250.00

816.00 0 816.00

0

852.00 0 852.00

200.00 0 200.00

451.00 0 451.00

230.00 0 230.00

451.00 0 451.00

A member of the Sime Darby Group Co. Reg. No. 197401559W. OST Reg. No. M2-0020001-X



Final Report

451.00	0	451.00
451.00	0	451.00
451.00	0	451.00
451.00	0	451.00
150.00	0	150.00
451.00	0	451.00
425.00	0	425.00
752.00	0	752.00
100.00	0	100.00
	451.00 451.00 451.00 150.00 451.00 425.00 752.00	451.00 0 451.00 0 451.00 0 150.00 0 451.00 0 425.00 0

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT	
# # ADJUSTABLE BLIND RIVET	3.15	2	0	6.30	
	2.75	2	0	5.50	
# EXPANDING NUT	1.25	2		2.50	
# BLIND RIVET	1,25	2 2 2	0	2.50	
# BLIND RIVET	11.00	1	0	11.00	
# FASTENING ELEMENTS	1,032.65	1	0	1,032.65	
RADIATOR	66.80	1		66.80	
CLAMPING BUSH	66.80	1	0	66.80	2ht-
CLAMPING BUSH	185.45	1	0	185.45	
LH TAILPIPE TRIM CHROME	57.20	1	0	57.20	
# REAR SILENCER BRACKET FRT	42.90	1	0	42.90	
SWING SUPPORT	577.50	1	0	577.50	
INTERMEDIATE PIPE REAR SILENCER W/EXHAUST FLAP	2,211.30	1	0 0 0	2,211.30	
	833.60	1	0	833.60	
COMPLETE TAIL TRIM	2,371.75	1	0	2,371.75	
ALUMINIUM ENGINE HOOD	1,741.00	1	0	1,741.00	
TAILGATE ALUMINIUM # FRT LH SIDE PANEL ALUMINIUM	933.30	1	0	933.30	
	723.05	1	0	723.05	
FRT BUMPER CARRIER # LH BUMPER GUIDE	16.15	- 1	0	16.15	
FRT BUMPER TOP IMPACT ABSORBER (M)	62.05	1	0	62.05	
FRT BUMPER BOTTOM IMPACT ABSORBER (33.50	1	0 0 0	33.50	
FRT BUMPER PANEL PRIMED (M)	1,618.50	1	0	1,618.50	
	857.75	1	0	857.75	
REAR BUMPER CARRIER	108.65	1	0	108.65	
EXHAUST SUPPORT REAR BUMPER COVER (M)	268.30	1	0	268.30	

A member of the Sime Darby Group Co. Reg. No. 197401559W. CST Reg. No. M2-0020081-K



Final Report

A WINDS OF THE CHIPE IN	61.55	1	0	61.55
REAR BUMPER CENTRE GUIDE (M)	1,542.05	1	0	1,542.05
REAR BUMPER PANEL PRIMED (M)	28.45	1	0	28.45
TRIM GRILLE FRT (I CAM)		1	0	145.70
FRT LH GRILLE (M/SPORT)	145.70			145.70
FRT RH GRILLE (M/SPORT)	145.70	1	0	
# ADJUSTMENT ELEMENT	6.05	2	0	12.10
LICENCE PLATE HOLDER (M)	84.80	1	0	84.80
EMBLEM GROMMET	0.80	2	0	1.60
LETTERING 540I	64.10	1	0	64.10
# BREAKTHROUGH BUFFER	8.35	1	0	8.35
PLAQUE 82MM	71.25	1	0	71.25
PLAQUE 74MM	71.25	1	0	71.25
	0.75	2	0	1,50
GROMMET	0.45	6	Ö	2.70
# RIVET	120.05	1	ő	120.05
LOCK LH	120.05		Ö	120.05
LOCK RH		4	ő	72.05
# LOCK TOP PART	72.05		_	72.05
# LOCK TOP PART	72.05		0	
BOOT LID/TAILGATE PUSH BOTTON (RFK)	24.60	1	0	24.60
# EXPANDING RIVET D=8MM	1.05	5	0	5.25
REAR SILENCER LH HEAT INSULATION	165.70	1	0	165.70
# REAR SILENCER RH HEAT INSULATION	165.70	1	0	165.70
REAR SILENCER HEAT INSULATOR	286.20	1	0	286.20
# CLIP	0.80	5	0	4.00
# CONNECTION REAR TOP	147.55	1	0	147.55
CONNECTION FRT TOP	252.05	1	0	252.05
	87.95	1	0	87.95
FRT PANEL SUPPORT	167.40	1	0	167.40
FRONT CROSSLINK	140.20	4	0	140.20
LH HEADLIGHT MOUNTING	140.20	4	o	140.20
RH HEADLIGHT MOUNTING	1000000000	4	ő	61.50
AIR DUCT RADIATOR TOP	61.50		0	61.50
AIR DUCT RADIATOR BOTTOM	61.50	1		
AIR FLAPS TOP	280.45	3	0	280.45
UNDERBODY PANELLING REAR	41.30	3	0	41.30
# FRT ENGINE BONNET SEAL	33.70	1	0	33.70
# UPPER LH ENGINE COMPARTMENT COVER	35.80	1	0	35.80
# (DG) REPAIR KIT CRASH ACTIVE HEAD R	163.80	2	0	327.60
# PLUG BLACK D=5MM	0.90	10	0	9.00
CABLE SET FRONT END	677.15	1	0	677.15
# REP. CABLE ITS HEAD AIRBAG & CTRL U	59.75	1	0	59.75
# SENSOR WIRE FOR SMART OPENER BOTTOM	41.50	1	0	41.50
LH HEADLIGHT LED AHL HIGH (ICON LIG	4,855.25	1	0	4,855.25
	4,855.25	1	0	4,855.25
RH HEADLIGHT LED AHL HIGH (ICON LIG	622.10	4	o	622.10
REAR LH LIGHT IN THE SIDE PANEL	367.45	-	ő	367.45
REAR LH LIGHT IN TRUNK LID		4	o	20.00
# REGISTRATION PLATE LAMP	20.00	1	ő	96.35
# EXTERNAL AERIAL COMFORT ACCESS	96.35	40		
# BLIND RIVET AVIBVLB	0.55	40	0	22.00
# SCREW (SF PLUS M5X15)	0.55	5	0	2.75
# (DG/SL) BODY ADHESIVE K5B (195ML)	326.80	1	0	326.80
# PUNCH RIVET N4	0.55	20	0	11.00
# (DG) CLEANER R1 (100ML)	26.15	1	0	26.15
# (S/L) SEAM SEAL 300ML	33.80	1	0	33.80
# (S/L) ANTI FREEZE 1.5 LITRES	20.10	2	0	40.20

A member of the Sime Darby Group Co. Rep. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

SUPPLEMENTARY ITEMS

Total Labour : 22,036.00
Total Parts : 30,956.45
Total Repair Costs less Excess: 52,992.45
GST @7%: 3,709.47
Grand Total : 56,701.92

	00	אדהנים מהנ	DATE	0.573
FAY TO FAY NO		Toufirh.	अशिष	16
FAX TO FAX NO				
F=X TG F=NG		1		
CONFIRMED				
PLEASE FOLLAS	1117			

LOSS OF USE = \$100 X 16 DAYS GIA SEARCH FEE = \$2.00

A member of the Sime Durby Group Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. :

b1 52098

Date Estimated :

24/07/2019

Prepared By :

Gary Poh Chai Hoon

- ESTIMATE REPAIR FOR -

Goh Pui Kiat 22 Newton Road

#15-08

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

Singapore 307990

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

SFV8088H

G459799

31/03/2017

540iA

0

SFV8088H	G459799	31/03/2017	540IA		U	
DESCRIPTION				CCOUNT: AL PRICE	DISC. %	NETT
# To replace both from including to reset ar	nt seat crash-active nd conduct checks f	head restraint repair kit or proper function		451.00	0	451.00
# To replace front left	fender			425.00	0	425.00
# To respray front left	fender and left roof	frame		752.00	0	752.00
# To carry out body o	avity preservation.			100.00	0	100.00
DESCRIPTION			UNIT PRICE	QTY	DISC. %	NETT
# ADJUSTABLE BLII # EXPANDING NUT # BLIND RIVET # BLIND RIVET # FASTENING ELEN # REAR SILENCER E # FRT LH SIDE PANI # LH BUMPER GUID # ADJUSTMENT EL # BREAKTHROUGH # RIVET # LOCK TOP PART # LOCK TOP PART # LOCK TOP PART # EXPANDING RIVE # REAR SILENCER F # CLIP # CONNECTION RE # FRT ENGINE BON # UPPER LH ENGINI # (DG) REPAIR KIT O # PLUG BLACK D=5 # REP. CABLE ITS H # SENSOR WIRE FO	ENTS BRACKET FRT EL ALUMINIUM E EMENT BUFFER T D=BMM RH HEAT INSULAT AR TOP NET SEAL E COMPARTMENT CRASH ACTIVE HE MM HEAD AIRBAG & CT	COVER AD R	3.15 2.75 1.25 1.25 11.00 57.20 933.30 16.15 6.05 8.35 0.45 72.05 72.05 1.05 165.70 0.80 147.55 33.70 35.80 163.80 0.90 59.75 41.50 20.00	2 2 2 2 1 1 1 1 2 1 6 1 1 5 1 5 1 1 1 2 10 1 1 1	000000000000000000000000000000000000000	6.30 Mg 5.50 Mg 2.50 Mg 2.50 Mg 11.00 Mg 57.20 Mg 16.15 Mg 12.10 Mg 72.05 Mg 72.05 Mg 72.05 Mg 72.05 Mg 72.05 Mg 32.70 Mg 4.00 Mg 147.55 Mg 33.70 Mg 33.70 Mg 35.80 Mg 327.60 Mg 59.75 Mg 20.00 Mg 59.75 Mg 20.00 Mg
# REGISTRATION P # EXTERNAL AERIA # BLIND RIVET AVIE # SCREW (SF PLUS	L COMFORT ACC 3VLB	ESS	96.35 0.55 0.55	1 40 5	0	96.35 45 22.00 m 2.75 M

A member of the Sime Daity Group Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

# (DG/SL) BODY ADHESIVE K5B (195ML)	326.80	1	0	326.80 ML
	0.55	20	0	11.00 121
# PUNCH RIVET N4 # (DG) CLEANER R1 (100ML)	26.15	1	0	26.15
# (S/L) SEAM SEAL 300ML	33.80	1	0	33.80 W
# (S/L) ANTI FREEZE 1.5 LITRES	20.10	2	0	40.20 wer-
#				
#				

SUPPLEMENTARY ITEMS

 Total Labour :
 1,728.00

 Total Parts :
 2,610.60

 Total Repair Costs less Excess:
 4,338.60

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Wednesday, 18 September 2019 2:41 PM

To:

Sharon Heng L K; Taufikh (LKKAuto)

Cc:

Keith Leo Chi Yung; Teng Wai Khan; SUR

Subject:

RE: DIRECT SETTLEMENT FINAL REPORT - SFV8088H

Dear Sharon,

WITHOUT PREJUDICE

Confirmed amount \$52,992.45 before GST @ 16 working days.

Kindly send Final invoice and all supporting documents directly to CHINA TAIPING

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

----Original Message-----

From: Sharon Heng L K <sharon.heng.leekun@simedarby.com.sg>

Sent: Tuesday, 17 September 2019 3:54 PM To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>

Cc: Keith Leo Chi Yung <keith.leo.chiyung@simedarby.com.sg>; Teng Wai Khan <teng.wai.khan@simedarby.com.sg>

Subject: FW: DIRECT SETTLEMENT FINAL REPORT - SFV8088H

Dear Taufikh

The Final Report can confirm?

Best Regards

Sharon Heng

PML - Body and Paint

DID: 63190123 Fax: 64743229

----Original Message---From: Sharon Heng L K

Sent: Tuesday, 10 September, 2019 8:45 AM

To: Taufikh (LKKAuto)

Cc: Keith Leo Chi Yung; Teng Wai Khan

Subject: FW: DIRECT SETTLEMENT FINAL REPORT - SFV8088H

Dear Taufikh

The Final Report can confirm ?

Best Regards

Sharon Heng

PML - Body and Paint

DID: 63190123 Fax: 64743229

----Original Message-----From: Sharon Heng L K

Sent: Friday, 30 August, 2019 6:20 PM

To: Taufikh (LKKAuto)

Subject: DIRECT SETTLEMENT FINAL REPORT - SFV8088H

Dear Taufikh

For your perusal:

Labour

\$22036.00

Parts

\$30956.45

Total

\$52992.45

Owner is claiming

LOSS OF USE = \$100 X 16 DAYS.

GIA SEARCH FEE - \$2.00

Note: 16 working days.

Please reply me directly.

Best Regards

Sharon Heng

PML - Body and Paint

DID: 63190123 Fax: 64743229

----Original Message----

From: service.pml@simedarby.com.sg [mailto:service.pml@simedarby.com.sg]

Sent: Friday, 30 August, 2019 6:15 PM

To: Sharon Heng L K

Subject: Message from KM_C458

...CLAIM SUBFOLDER...(Pending for Survey Report)

	OLDER TRA		150.000	Take a			1	15	
Main .	Notified 26 Jul 2019	Est Submitted	Adj Assigned 26 Jul 2019 14:52 Edit Adj Rpt	Adj Rpt S\$52,992.4 Edit Estimat	5 5\$5	5ubmitted 2,992.45 ew Rpt	Ins Auth'ed	Pending for Survey Report Cancel Case	
51	Main	R	eference	Clair	n Details		Documen	ts	Show Alt
CLAIM SU	BFOLDER D					[Created	by insurer]		
Main Claimant:	GOH PUI	GOH PUI KIAT, ID: S1749307H							
Vehicle Reg No.:	SFV808	8H		Da	te of Lass:		19 18:00 - :59 is and 23 Days F	rom LTA Reg Dat	e (Man Yr)]
Claim Type:	TP / SN	TP / SNM19D203462C02				DMCVSN1	9063619000		
Vehicle Reg No. (Insured):	GBJ1801Y				licy No. laimant);	P1919115			
	Darforma	nce Motore I imi	ted (Alexandra) 3	200	cess:	S\$0.00 Darby Performance Centre, 159941 Alexandra - Tel:			
Repairer:		/63190174	teo (Alexandra)	S OF ARTHUR A	one, airre	Daniel Latino	manue cemue, s	22274 (11648114114	. 1 640
Handling Insurer:	China Ta	iping Insurance	(Singapore) Pte. I	Ltd. (HQ) - Tel:	6389 611	1 [Handle	ed by Chong Boo	n Sen]	
Claimant's Insurer:	AXA Insu	rance Pte Ltd (F	IQ) - Tel: 6338 728	8					
Adjuster:	06/08/2		Ltd (HQ) - Tel: 63	256-3561 [H	endled by P	HOHD TAUF	TKH BIN HAMII) [Final Rp	t due
ASSOCIAT	ED MAIL RE	CEIVED					v	iew All Comp	ose Case Mai
There are n	o mail for this	Case.							
ALL ASSO	CIATED TAS	544500 VI	Group Subje	ct Handler	Assign	View All	Search Tasks Completed Or	Create New Task	Complete On Done

Claim Documents

*SFV8088H (SNM19D203462C02)

[GBJ1801Y]

TP

GOH PUI KIAT

Jul 23 2019 6:00PM

[-]

Performance Motors Limited

Ass	essment Reports		1 per g	page 🔻	V
No.	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	24/07/19 10:10	Accident Statement	0	Load HTM	
Pho	otos/Images		3 per p	page 🔻	Ø
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	24/07/19 10:07	Accident Photo	0	Load JPG	2
2	24/07/19 10:07	[Linked Accident Report Documents] Accident Photo	0	Load JPG	E21
3	Dovernous Day	[Linked Accident Report Documents] Accident Photo	0	Load JPG	52
_	24/07/19 10:07	[Linked Accident Report Documents] Accident Photo		20072500031	
4	24/07/19 10:07	[Linked Accident Report Documents]	0	Load JPG	82
5	24/07/19 10:07	Accident Photo [Linked Accident Report Documents]	0	Load JPG	82
6	24/07/19 10:07	Accident Photo [Linked Accident Report Documents]	0	Load 3PG	₽.
7	24/07/19 10:07	Accident Photo [Linked Accident Report Documents]	0	Load 3PG	2
В	24/07/19 10:07	Accident Photo [Linked Accident Report Documents]	0	Load 3PG	2
9	24/07/19 10:07	Accident Photo [Linked Accident Report Documents]	0	Load JPG	Ø
10	24/07/19 10:07	Accident Photo [Linead Accident Report Documents]	0	Load JPG	Ø
11	24/07/19 10:07	Accident Photo [Linked Accident Report Documents]	0	Load JPG	Ø
12	24/07/19 10:07	Accident Photo	0	Load JPG	Ø
13	24/07/19 10:07	[Linkest Accident Report Documents] Accident Photo	0	Load IPG	Ø
14	24/07/19 10:07	[Linked Accident Report Documents] Accident Photo	0	Load IPG	Ø
15	24/07/19 10:07	[Linked Accident Report Documents] Accident Photo	0	Load JPG	V
16	24/07/19 10:07	[Linked Accident Report Documents] Accident Photo	0	Load JPG	Ø
17	24/07/19 10:07	[Linked Accident Report Documents] Accident Photo	0	Load JPG	2
18	24/07/19 10:07	(Linked Accident Report Documents) Accident Photo	0	Load JPG	M
	220	[Linked Accident Report Documents] Accident Photo	0	Load JPG	M
19	24/07/19 10:07	[Linked Accident Report Documents] Accident Photo			
20	24/07/19 10:07	[Linked Accident Report Documents]	0	Load JPG	M
21	24/07/19 10:07	Accident Photo [United Accident Report Documents]	0	Load JPG	82
22	24/07/19 10:07	Accident Photo [Linked Accident Report Documents]	0	Load JPG	Ø
Νa	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	18/09/19 14:36	General View	0	Load PDF	
2	18/09/19 14:36	Reinspection Photo	0	Load PDF	
Doc	cumentation		1 per p	page V	Ø
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnall	_
1	24/07/19 10:06	Sketch Plan [Unkell Accident Report Documents]	0	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
	The state of the s	Supplementary	0	Load PDF	

Linked Accident Report Documents

	View View		View in Brown	w in Browser	
Ass	essment Reports		1 per	page: 💟	M
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	24/07/19 10:10	Accident Statement	0	Load HTM	
Pho	otos/Images		3 per	page 🔽	Ø
Na	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	24/07/19 10:07	Accident Photo	0	Load JPG	V
2	24/07/19 10:07	Accident Photo	0	Load JPG	V
3	24/07/19 10:07	Accident Photo	0	Load JPG	2
4	24/07/19 10:07	Accident Photo	8	Load JPG	Z
5	24/07/19 10:07	Accident Photo	0	Load JPG	R.
6	24/07/19 10:07	Accident Photo	0	Load JPG	V
7	24/07/19 10:07	Accident Photo	0	Load JPG	V
8	24/07/19 10:07	Accident Photo	0	Load JPG	2
9	24/07/19 10:07	Accident Photo	0	Load JPG	82
10	24/07/19 10:07	Accident Photo	0	Load 3PG	Ø
11	24/07/19 10:07	Accident Photo	0	Load JPG	V
12	24/07/19 10:07	Accident Photo	0	Load JPG	2
13	24/07/19 10:07	Accident Photo	0	Load JPG	2
14	24/07/19 10:07	Accident Photo	0	Load JPG	Ø
15	24/07/19 10:07	Accident Photo	0	Load 3PG	M
16	24/07/19 10:07	Accident Photo	0	Load JPG	1
17	24/07/19 10:07	Accident Photo	0	Load JPG	2
18	24/07/19 10:07	Accident Photo	0	Load JPG	2
19	24/07/19 10:07	Accident Photo	0	Load JPG	M
20	24/07/19 10:07	Accident Photo	0	Load JPG	80
21	24/07/19 10:07	Accident Photo	0	Load JPG	Ø
22	24/07/19 10:07	Accident Photo	0	Load JPG	2 1
Do	cumentation		1 per	page 💟	W
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	24/07/19 10:06	Sketch Plan	0	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Ramarks are private unless you show it to other perties.	

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6258-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19013123/T1VF3E2

Date:

20/09/2019

REFERENCE

Handling Insurer:

China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

DMCVSN19063619000

Claimant Vehicle No:

SFV8088H

Insured Vehicle No:

GBJ1801Y

Date of Loss:

23/07/2019

Nature of Claim: TP

Claim No:

SNM19D203462C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SFV8088H

Make & Model:

BMW 540I, 3.0 SR LED NAV HUD RCP MSPORT

Engine No:

11769873B58B30A

Reg. Date:

31/03/2017 (Man. Year: 2017)

Chassis No:

WBAJB32070G459799

Colour:

Grey 2998 cc Odometer:

20123 km

Engine Capacity: Market Value/New Car

Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable): Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

245/35 R20

Rear Tyre Size:

245/35 R20

Front Left Side: Front Right Side: Goodyear 6 mm Goodyear 6 mm Rear Left Side: Rear Right Side: Goodyear 6 mm Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIM	S	Repairer's	Adjuster's	Difference	Diff %
Parts		47,214.30	31,271,45	15,942.85	33.77
Miscellaneous Item	s	0.00	0.00	0.00	
Labour		25,596.00	21,721.00	3.875.00	15.14
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	72,810.30	52,992.45	19,817.85	27.22
	+ GST 7.00/7.00% (S\$)	5,096.72	3,709.47	1,387.25	27.22
	Nett Amount (S\$)	77,907.02	56,701.92	21,205.10	27.22

INSPECTION

Date of Assignment:

26/07/2019

Date Inspected:

25/07/2019 Inspected At:

Performance Motors Limited

(Alexandra)

303 Alexandra Road, Sime Darby

Performance Centre Singapore 159941

Estimated Period of Repair:

16.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Referen	ce				
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Sep 2019)			
Parts:	143	BMW 540I 3.0 SR LED NAV HUD RCP MSPORT (A) (Catalogue:Merimen Singapore 1.0)			
Labour:	Repairer's	(Price-denominated Standard List)			
Print Code:	A STATE OF THE RESERVE AND ADDRESS OF THE PARTY OF THE PA	, no print-code for SFV8088H)			
Validity:		These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info:	Items/values	not in reference catalogue are prefixed with an asterisk *.			

_				_	
О.	ecom		dod	Doct	~
H 6	7(2())	11111111	$\alpha = \alpha$	Pall	-

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT AND REAR EMBOSS NUMBER PLATE	Bent	165.00 FS	*165.00 FS
2	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
3	1		*RADIATOR	Bent	1,032.65 FS	*1,032.65 FS
4	1		*COVERING LOWER	Not Necessary	74.95 FS	*-FS
5	1		*ROCK GUARD	Not Necessary	97.40 FS	*- FS
6	1		*RADIATOR	Not Necessary	1,147.40 FS	*-FS
7	1		*FAN HOUSING WITH FAN 400W	Not Necessary	1,377.10FS	*-FS
В	1		*CLAMPING BUSH	Bent	66.80 FS	*66.80 FS
9	1		*LH TAILPIPE TRIM CHROME	Bent	185.45 FS	*185.45 FS
10	1		*RH TAILPIPE TRIM CHROME	Not Necessary	185.45 FS	*-FS
11	1		*SWING SUPPORT	Bent	42.90 FS	*42.90 FS
12	1		*FRONT MUFFLE	Not Necessary	1,568.90 FS	*-FS
13	1		INTERMEDIATE	Bent	577.50 FS	*577.50 FS
14	1		*REAR SILENCER W/EXHAUST FLAP	Bent	2,211.30 FS	*2,211.30 FS
15	1		*RR TRUNK FLOOR CROSS MEMBER	Not Necessary	120.75 FS	*- FS
16	1		*LH ENGINE HOOD HINGE	Not Necessary	92,75FS	*-FS
17	1		*RH ENGINE HOOD HINGE	Not Necessary	92.75FS	*- FS
18	1		*LH TRUNK FLOOR	Not Necessary	139.80 FS	*-FS
19	1		*COMPLETE TAIL TRIM	Distorted	833.60 FS	*833.60 FS
20	1		*REAR LUGGAGE COMPARTMENT FLOOR	Not Necessary	279.55 FS	*-FS
21	1		*ALUMINIUM ENGINE HOOD	Bent	2,371.75FS	*2,371.75 FS
22	1		*TAILGATE ALUMINIUM	Bent	1,741.00 FS	*1,741.00 FS
23	1		*LH TRUNK LID HINGE	Not Necessary	118.80 FS	*-FS
24	1		*RH TRUNK LID HINGE	Not Necessary	118.80FS	*- FS
25	1		*OUTER PANEL TAIL TRIM	Not Necessary	583.55 FS	*-FS
26	1		*FRT BUMPER CARRIER	Bent	723.05 FS	*723.05 FS
27	1		*FRT BUMPER BOTTOM CARRIER	Not Necessary	397.70 FS	*-FS
28	1		*LH GUIDE TOP	Not Necessary	34.55 FS	*-FS
29	1		*RH GUIDE TOP	Not Necessary	34.55 FS	*-FS
30	1		*FRT BUMPER TOP IMPACT ABSORBER (M)	Distorted	62.05 FS	*62.05 FS
31	1		*GRILLE AIR INLET MIDDLE	Not Necessary	95.70 FS	*-FS
32	1		*LH GRILLE AIR INLET OPEN	Not Necessary	85.00 FS	*-FS
33	1		*RH GRILLE AIR INLET OPEN	Not Necessary	85.00 FS	*-FS
34	1		*LH FOG LAMP SUPPORT (M)	Not Necessary	77.95 FS	*-FS
35	1		*RH FOG LAMP SUPPORT (M)	Not Necessary	77.95 FS	*-FS
36	1		*LH FINISHER DECO HIGH-GLOSS BLACK	Not Necessary	80.30 FS	*-FS
37	1		*RH FINISHER DECO HIGH-GLOSS BLACK	Not Necessary	80.30 FS	*-FS
38	1		*FRT BUMPER BOTTOM IMPACT ABSORBER (Deformed	33.50 FS	*33.50 FS
39	1		*FRT BUMPER PANEL PRIMED (M)	Deformed	1,618.50 FS	*1,618.50FS
40	1		*REAR BUMPER CARRIER	Bent	857.75 FS	*857.75 FS
41	1		*EXHAUST SUPPORT	Bent	108.65 FS	*108.65 FS
42	1		*REAR BUMPER COVER (M)	Deformed	268.30 FS	*268.30 FS
43	1		*REAR BUMPER LH GUIDE (M)	Not Necessary	55.75 FS	*- FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*REAR BUMPER RH GUIDE (M)	Not Necessary	55.75 FS	*-FS
45	1		*REAR BUMPER CENTRE GUIDE (M)	Deformed	61.55 FS	*61.55 FS
46	1		*REAR BUMPER PANEL PRIMED (M)	Deformed	1,542.05 FS	*1,542.05 FS
47	1		*TRIM GRILLE FRT (I CAM)	Distorted	28.45 FS	*28.45 FS
48	1		*FRAME BOTTOM	Not Necessary	55.95 FS	*-FS
49	1		*FRT LH GRILLE (M/SPORT)	Cracked	145.70 FS	*145.70 FS
50	1		*FRT RH GRILLE (M/SPORT)	Cracked	145.70 FS	*145.70 FS
51	1		*LICENSE PLATE HOLDER (M)	Deformed	84.80 FS	*84.80 FS
52	2		*EMBLEM GROMMET	Necessary	1.60 FS	*1.60FS
53	1		*LETTERING 540I	Necessary	64.10 FS	*64.10FS
54	1		*PLAQUE 82MM	Necessary	71.25 FS	*71.25 FS
55	1		*PLAQUE 74MM	Necessary	71.25 FS	*71.25 FS
56	2		*GROMMET	Necessary	1.50 FS	*1.50 FS
			*GAS FILLED STRUT ENGINE COMPARTMENT	Not Necessary	248.00 FS	*-FS
57	2			Bent	120.05 FS	*120.05FS
58			*LOCK LH			*120.05 FS
59	1		*LOCK RH	Bent	120.05 FS	*-FS
60	1		*STRIKER BOOT LID	Not Necessary	57.40 FS	
61	1		*BOOT LID / TAILGATE PUSH BOTTON (RFK)	Distorted	24.60 FS	*24.60 FS
62	1		*TRUNK LID POWER LOCK PANEL	Not Necessary	221.60 FS	*-FS
63	1		*COUNTER SUPPORT REAR VIEW CAMERA (R	Not Necessary	4.60 FS	*-FS
64	1		*LOCK TRUNK LID	Not Necessary	228.00 FS	*-FS
65	1		*RH SPINDLE DRIVE	Not Necessary	580.35 FS	*- FS
66	1		*REAR SILENCER HEAT INSULATION FRT	Not Necessary	114.30 FS	*- FS
67	1		*REAR SILENCER LH HEAT INSULATION	Bent	165.70 FS	*165.70 FS
68	1		*REAR SILENCER HEAT INSULATOR	Bent	286.20 FS	*286.20 FS
69	1		*WARNING SIGNALLER	Not Necessary	38.95 FS	*-FS
70	1		*CONNECTION FRT TOP	Bent	252.05 FS	*252.05 FS
71	1		*FRT PANEL SUPPORT	Bent	87.95 FS	*87.95 FS
72	1		*FRONT CROSSLINK	Bent	167.40 FS	*167.40 FS
73	1		*LH HEADLIGHT MOUNTING	Distorted	140.20 FS	*140.20 FS
74	1		*RH HEADLIGHT MOUNTING	Distorted	140.20 FS	*140.20FS
75	1			Not Necessary	33.65 FS	*-FS
	1		*COVERING CROSS MEMBER (ECE)	Cracked	61.50 FS	*61.50 FS
76	1		*AIR DUCT RADIATOR TOP			
77			*AIR DUCT RADIATOR BOTTOM	Deformed	61.50 FS	*61.50 FS
78	1		*AIR FLAPS TOP	Deformed	280.45 FS	
79	1		*UNDERBODY PANELLING REAR	Distorted	41.30 FS	*41.30 FS
80	1		*TRUNK LID GASKET	Not Necessary	127,95 FS	*-F8
81	1		*CABLE SET FRONT END	Distorted	677.15 FS	
82	1		*FRT BUMPER SET OF CABLES	Not Necessary	232.85 FS	*-FS
83	1		*LH HEADLIGHT LED AHL HIGH (ICON LIG	Cracked	4,855.25 FS	*4,855.25 FS
84	1		*RH HEADLIGHT LED AHL HIGH (ICON LIG	Cracked	4,855.25 FS	*4,855.25 FS
85	1		*REAR LH REAR REFLECTOR	Not Necessary	37.90 FS	*-FS
86	1		*REAR RH REAR REFLECTOR	Not Necessary	37.90 FS	*-FS
87	1		'REAR LH LIGHT IN THE SIDE PANEL	Cracked	622.10 FS	*622.10FS
88	1		*REAR RH LIGHT IN THE SIDE PANEL	Not Necessary	622.10FS	*- FS
89	1		*REAR LH LIGHT IN TRUNK LID	Cracked	367.45 FS	The second second second
90	1		*REAR RH LIGHT IN TRUNK LID	Not Necessary	367.45 FS	
91	1		*LH TAIL LIGHT FINISHER TRUNK LID	Not Necessary	33.60 FS	*-F8
92	1		*RH TAIL LIGHT FINISHER TRUNK LID	Not Necessary		
93	1		*CONDENSER AIR CONDITIONING W/DRIER	Not Necessary		
94	12			Not Necessary		
	- 11/11		*ULTRASONIC SENSOR BLUESTONE (C2Y)	and the second of the second o		
95	12		*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	60.60 FS	
96	1		*CLAMPING BUSH	Bent	66.80 FS	
97	2		*ADJUSTABLE BLIND RIVET	Necessary	6.30 FS	
98	2		*EXPANDING NUT	Necessary	5.50 FS	
99	2		*BLIND RIVET	Necessary	2.50 FS	
100	2		*BLIND RIVET	Necessary	2.50 FS	*2.50 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
101	1	322.33	*FASTENING ELEMENTS	Necessary	11.00 FS	*11.00 FS
102	1		*REAR SILENCER BRACKET FRT	Bent	57.20 FS	*57.20 FS
103	1		*FRT LH SIDE PANEL ALUMINIUM	Bent	933.30 FS	*933.30 FS
104	1		*LH BUMPER GUIDE	Deformed	16.15 FS	*16.15FS
105	2		*ADJUSTMENT ELEMENT	Distorted	12.10FS	*12.10FS
106	1		*BREAKTHROUGH BUFFER	Deformed	8.35 FS	*8.35FS
107	6		*RIVET	Necessary	2.70 FS	*2.70FS
108	1		*LOCK TOP PART	Bent	72.05 FS	*72.05FS
109	1		*LCOK TOP PART	Bent	72.05 FS	*72.05 FS
110	5		*EXPANDING RIVET D=8MM	Necessary	5.25 FS	*5.25 FS
111	1		*REAR SILENCER RH HEAT INSULATION	Bent	165.70 FS	*165,70 FS
112	5		*CLIP	Necessary	4.00 FS	*4.00 FS
113	1		*CONNECTION REAR TOP	Bent	147.55 FS	*147.55 FS
114	1		*UPPER LH ENGINE COMPARTMENT COVER	Deformed	35.80 FS	*35.80 FS
115	2		*(DG) REPAIR KIT CRASH ACTIVE HEAD R	Activated	327.60 FS	*327.60 FS
116	10		*PLUG BLACK D=5MM	Necessary	9.00 FS	*9.00 FS
117	1		*REP. CABLE ITS HEAD AIRBAG & CTRL U	Distorted	59.75 FS	*59.75 FS
118	1		*SENSOR WIRE FOR SMART OPENER BOTTOM	Distorted	41.50 FS	*41.50 FS
119	1		*REGISTRATION PLATE LAMP	Cracked	20.00 FS	*20.00 FS
120	1		*EXTERNAL AERIAL COMFORT ACCESS	Distorted	96.35 FS	*96.35 FS
121	1		*BLIND RIVET AVIBVLB (40PCS)	Necessary	22.00 FS	*22.00 FS
122	5		*SCREW (SF PLUS M5X15)	Necessary	2.75FS	*2.75FS
123	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Necessary	326.80 FS	*326.80 FS
124	20		*PUNCH RIVET N4	Necessary	11.00 FS	*11.00 FS
125	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26,15 FS
126	1		*(S/L) SEAM SEAL 300ML	Necessary	33.80 FS	*33.80 FS
127	2		*(S/L) ANTI FREEZE 1.5 LITRES	Necessary	40.20 FS	*40.20FS
128	1		*FRT ENGINE BONNET SEAL	Necessary	33.70 FS	*33.70 FS
F=Fn	enchise	part. S=Spo	Nett.	Total Parts (S\$)	47,214.30	31,271.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Pa	com	mer	hahr	1 2	bour
170	СОП	HILL	IUEU		DOUL

Particulars	Lab.Type	Repairer's	Amount
pur Items			
TO REPLACE FRT BUMPER, BONNET, INNER SUPPORT PANEL, REAR BUMPER, BOOTLID, TAIL PANEL, TRUNK FLOOR AND ATTACHMENT INCLUDE KNOCKING CAUSE BY THE ACCIDENT	New	10,200.00	8,500.00
PAINTING FRONT BUMPER, BONNET, REAR BUMPER, BOOTLID, TAIL PANEL, TRUNK FLOOR, LEFT REAR FENDER, RIGHT REAR FENDER	New	6,158.00	5,542.00
TO TOW ACCIDENT VEHICLE TO PML WORKSHOP	New	195.00	195.00
TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT AND REAR SECTIONS FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS	New	295.00	250.00
TO REPLACE BOTH LEFT AND RIGHT HEADLIGHTS	New	837.00	816.00
TO REPLACE RADIATOR ASSEMBLY, FAN HOUSING WITH FAN INCLUDING TO CONDUCT PRESSURE TEST, BLEED COOLING SYSTEM AND CHECK FOR LEAK. (FOR ALL MODELS EXCEPT 7 SERIES)	New	826.00	702.00
INCLUDING TO VACUUM SYSTEM, TOP UP FREON GAS		1,003.00	852.00
TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL)	New	236.00	200.00
TO CARRY OUT BODY CAVITY PRESERVATION. (FOR CUT PANEL)	New	531.00	451.00
TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	230.00
TO REPLACE BOOTLID SMART OPENER CONTROL UNIT, TOP AND BOTTOM SENSOR LINES INCLUDING PROGRAM AND CONDUCT CHECKS FOR PROPER FUNCTION	New	661.00	451.00
TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	531.00	451.00
TO REPLACE BOTH FRONT SEAT BELTS AND TENSIONERS INCLUDING RESET AND CHECKS FOR PROPER FUNCTION	New	531.00	0.00
TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK	New	531.00	451.00
TO REPLACE FRONT EXHAUST SILENCER INCLUDING ALIGN EXHAUST SYSTEM AND CONDUCT CHECKS FOR LEAK	New	531.00	451,00
TO REPLACE FRONT END WIRING CABLES INCLUDING PERFORM FUNCTION	New	531.00	451.00
TO REPLACE BOTH FRONT SEAT CRASH-ACTIVE HEAD RESTRAINT REPAIR KIT INCLUDING TO RESET AND CONDUCT CHECKS FOR PROPER FUNCTION	New	451.00	451.00
TO REPLACE FRONT LEFT FENDER	New	425.00	425.00
TO RESPRAY FRONT LEFT FENDER AND LEFT ROOF FRAME	New	752.00	752.00
TO CARRY OUT BODY CAVITY PRESERVATION	New	100.00	100.00
Gross Labou	r Cost (S\$)	25,596.00	21,721.00
	TO REPLACE FRT BUMPER, BONNET, INNER SUPPORT PANEL, REAR BUMPER, BOOTLID, TAIL PANEL, TRUNK FLOOR AND ATTACHMENT INCLUDE KNOCKING CAUSE BY THE ACCIDENT PAINTING FRONT BUMPER, BONNET, REAR BUMPER, BOOTLID, TAIL PANEL, TRUNK FLOOR, LEFT REAR FENDER RIGHT REAR FENDER TO TOW ACCIDENT VEHICLE TO PML WORKSHOP TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT AND REAR SECTIONS FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS TO REPLACE BOTH LEFT AND RIGHT HEADLIGHTS TO REPLACE BOTH LEFT AND RIGHT HEADLIGHTS TO REPLACE RADIATOR ASSEMBLY, FAN HOUSING WITH FAN INCLUDING TO CONDUCT PRESSURE TEST, BLEED COOLING SYSTEM AND CHECK FOR LEAK. (FOR ALL MODELS EXCEPT 7 SERIES) TO REPLACE AIR CON CONDENSER AND AIR CON HOSE INCLUDING TO VACUUM SYSTEM, TOP UP FREON GAS AND CHECK FOR LEAK. (FOR ALL MODELS EXCEPT FOR 7 SERIES) TO CARRY OUT BODY CAVITY PRESERVATION. (FOR CUT PANEL) TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS TO REPLACE BOOTLID SMART OPENER CONTROL UNIT, TOP AND BOTTOM SENSOR LINES INCLUDING PROGRAM AND CONDUCT CHECKS FOR PROPER FUNCTION TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION TO REPLACE BOTH FRONT SEAT BELTS AND TENSIONERS INCLUDING RESET AND CHECKS FOR PROPER FUNCTION TO REPLACE FRONT EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK TO REPLACE FRONT EXHAUST SILENCER INCLUDING ALIGN EXHAUST SYSTEM AND CONDUCT CHECKS FOR LEAK TO REPLACE FRONT END WIRING CABLES INCLUDING PERFORM FUNCTION TO REPLACE FRONT END WIRING CABLES INCLUDING PERFORM FUNCTION TO REPLACE FRONT END WIRING CABLES INCLUDING PERFORM FUNCTION TO REPLACE FRONT END WIRING CABLES INCLUDING PERFORM FUNCTION TO REPLACE FRONT END WIRING CABLES INCLUDING PERFORM FUNCTION TO REPLACE FRONT END WIRING CABLES INCLUDING PERFORM FUNCTION TO REPLACE FRONT LEFT FENDER TO CARRY OUT BODY CAVITY PRESERVATION	TO REPLACE FRT BUMPER, BONNET, INNER SUPPORT PANEL, REAR BUMPER, BOOTLID, TAIL PANEL, TRUNK FLOOR AND ATTACHMENT INCLUDE KNOCKING CAUSE BY THE ACCIDENT PAINTING FRONT BUMPER, BONNET, REAR BUMPER, BOOTLID, TAIL PANEL, TRUNK FLOOR, LEFT REAR FENDER, RIGHT REAR FENDER TO TOW ACCIDENT VEHICLE TO PML WORKSHOP TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT NEW NEW AND REAR SECTIONS FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS TO REPLACE BOTH LEFT AND RIGHT HEADLIGHTS TO REPLACE RADIATOR ASSEMBLY, FAN HOUSING WITH FAN INCLUDING TO CONDUCT PRESSURE TEST, BLEED COOLING SYSTEM AND CHECK FOR LEAK. (FOR ALL MODELS EXCEPT 7 SERIES) TO REPLACE AIR CON CONDENSER AND AIR CON HOSE INCLUDING TO VACUUM SYSTEM, TOP UP FREON GAS AND CHECK FOR LEAK. (FOR ALL MODELS EXCEPT FOR 7 SERIES) TO CARRY OUT BODY CAVITY PRESERVATION. (PER New PANEL) TO CARRY OUT BODY CAVITY PRESERVATION. (FOR CUT PANEL) TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS TO REPLACE BOOTLID SMART OPENER CONTROL UNIT, TOP AND BOTTOM SENSOR LINES INCLUDING PROGRAM AND CONDUCT CHECKS FOR PROPER FUNCTION TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION TO REPLACE BOTH FRONT SEAT BELTS AND TENSIONERS INCLUDING RESET AND CHECKS FOR PROPER FUNCTION TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR PROPER FUNCTION TO REPLACE FRONT EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK TO REPLACE FRONT EXHAUST SILENCER INCLUDING NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION TO REPLACE FRONT EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK TO REPLACE FRONT EXHAUST SILENCER INCLUDING NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION TO REPLACE FRONT EXHAUST SILENCER INCLUDING NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION TO REPLACE FRONT EXHAUST SILENCER INCLUDING NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION TO REPLACE FRONT EXHAUST SILENCER INCLUDING NEW BOOTLID CENTRAL KIT INCLUD	TO REPLACE FRT BUMPER, BONNET, INNER SUPPORT PANEL, REAR BUMPER, BOOTLID, TAIL PANEL, TRUNK FLOOR AND ATTACHMENT INCLUDE KNOCKING CAUSE BY THE ACCIDENT PANEL, REAR BUMPER, BONNET, REAR BUMPER, BOOTLID, TAIL PANEL, TRUNK FLOOR, LEFT REAR POURTING RENT BUMPER, BONNET, REAR BUMPER, BOOTLID, TAIL PANEL, TRUNK FLOOR, LEFT REAR FENDER, RIGHT REAR FENDER TO TOW ACCIDENT VEHICLE TO PML WORKSHOP TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT AND REAR SECTIONS FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS TO REPLACE BOTH LEFT AND RIGHT HEADLIGHTS TO REPLACE RADIATOR ASSEMBLY, FAN HOUSING WITH FAN INCLUDING TO CONDUCT PRESSURE TEST, BLEED COOLING SYSTEM AND CHECK FOR LEAK. (FOR ALL MODELS EXCEPT 7 SERIES) TO REPLACE RON CONDENSER AND AIR CON HOSE INCLUDING TO VACUUM SYSTEM, TOP UP FREON GAS AND CHECK FOR LEAK. (FOR ALL MODELS EXCEPT FOR 7 SERIES) TO CARRY OUT BODY CAVITY PRESERVATION. (FOR CUT PANEL) TO CARRY OUT BODY CAVITY PRESERVATION. (FOR CUT PANEL) TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS TO REPLACE BOOTLID SMART OPENER CONTROL UNIT, TOP AND BOTTOM SENSOR LINES INCLUDING PROGRAM AND CONDUCT CHECKS FOR PROPER FUNCTION TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION TO REPLACE BOTH FRONT SEAT BELTS AND TENSIONERS INCLUDING RESET AND CHECKS FOR PROPER FUNCTION TO REPLACE BOTH FRONT SEAT BELTS AND TENSIONERS INCLUDING RESET AND CHECKS FOR PROPER FUNCTION TO REPLACE BOTH FRONT SEAT BELTS AND TENSIONERS INCLUDING RESET AND CHECKS FOR PROPER FUNCTION TO REPLACE BOTH FRONT SEAT BELTS AND TENSIONERS INCLUDING RESET AND CHECKS FOR PROPER FUNCTION TO REPLACE BOTH FRONT SEAT BELTS AND TENSIONERS INCLUDING RESET AND CHECKS FOR PROPER FUNCTION TO REPLACE FRONT EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK TO REPLACE FRONT END WIRING CABLES INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK TO REPLACE FRONT END WIRING CABLES INCLUDING TO REPLACE FRONT END WIRING CABLES INCLUDING TO REPLACE FRONT END WIRING

Adjuster Report Page 7 of 7

No Particulars Lab.Type Repairer's Amount

Report was unsubmitted during this print-out.

< END OF ESTIMATES >