

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
NG KAI LI (HUANG KAILI) BLK 421 JURONG WEST STREET 42 #07-1043 SINGAPORE 640421 Contact No Mobile: 91124673	Cust No/Name	LCV08863/NG KAI LI (HUANG KAILI)
	Reg No/Reg Date	SMJ6014P / 13/03/201
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5031135
	Engine No	G4FGJH722210
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	24/07/2019/ 15:47		247 / DonBong	54736		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							1650.00
RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER FACE, REPAIR REAR END PANEL							SSU 1650.00
E PNT88000							80.00
REMOVE AND INSTALL PARKING ASSIST							X 275.00
E PNT88000							1200.00
REMOVE AND INSTALL REAR CABIN, SIDE TRIM TO FACILITATE REPAIR WORK							420 1200.00
E PNT98000							80.00
PAINT WORK RESPRAY ON REAR END PANEL, REAR BUMPER AND AFFECTED PORTION							X 80.00
M SUNDRY							? 220.00
PERFORM RUST PREVENTION							40.00
M SUNDRY							200.00
SUPPLY PARKING SENSOR							50.00
A 54900099							20 50.00
CHECK ELECTRICAL AND CHASSIS ELECTRICAL SYSTEM							
A 10028901							
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							
M SUNDRY							
SUNDRIES							
M	BRACKET ASSY-RR BPR SIDE UPR,L			1.00	25.00	00.00	25.00
M	BRACKET-ASSY RR BPR SIDE UPR,R			1.00	31.00	00.00	31.00
M	COVER-RR BUMPER UNDER,RH			1.00	33.00	00.00	33.00
M	STAY-RR BUMPER LH			1.00	65.00	00.00	65.00
M	STAY-RR BUMPER RH			1.00	65.00	00.00	65.00
M	ANTENNA ASSY-SMARTKEY			1.00	46.00	00.00	46.00
M	BEAM-RR BUMPER			1.00	318.00	00.00	318.00
M	BRACKET-RR BEAM UPR MTG,LH			1.00	9.00	00.00	9.00
M	BRACKET-RR BEAM UPR MTG,RH			1.00	9.00	00.00	9.00
M	BRACKET-RR BEAM LWR,CTR			1.00	6.00	00.00	6.00
M	BRACKET-RR BEAM LWR MTG			2.00	6.00	00.00	12.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
NG KAI LI (HUANG KAILI) BLK 421 JURONG WEST STREET 42 #07-1043 SINGAPORE 640421 Contact No Mobile: 91124673	Cust No/Name	LCV08863/NG KAI LI (HUANG KAILI)
	Reg No/Reg Date	SMJ6014P / 13/03/201
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5031135
	Engine No	G4FGJH722210
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	24/07/2019/ 15:47		247 / DonBong	54736

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M EXTN WIRING ASSY-BWS X	1.00	207.00	00.00	207.00
M LAMP ASSY-SIDE T/SIGNAL,LH X	1.00	181.00	00.00	181.00
M LAMP ASSY-SIDE T/SIGNAL,RH X	1.00	181.00	00.00	181.00
M COVER-RR BUMPER FOG LAMP,LH X	1.00	19.00	00.00	19.00
M COVER-RR BUMPER FOG LAMP,RH X	1.00	19.00	00.00	19.00
M CLIP X	10.00	1.00	00.00	10.00
M GROMMET ASSY-SCREW X	2.00	2.00	00.00	4.00
M COVER-RR BUMPER repair	1.00	688.00	00.00	688.00
M COVER-RR BUMPER LWR cut ✓	1.00	197.00	00.00	197.00
M COVER-RR BUMPER UNDER,LH X	1.00	33.00	00.00	33.00

Estimate

SURVEYOR NAME: Rashid - 4p 90010068

SURVEYOR SIGNATURE: [Signature]

DATE: 13/08/19 @ 1400

REMARKS: 3 days

Repy before repur

Confirm & accepted by

7% GST on	Nett 6013.00	6,013.00
		420.91
Total Payable		6,433.91

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.