

SGIC B17L / LANCER GLX / CS3ASTJEQP

TPQBE.

Jiale.

RR RH Tail Lamp	\$480	x	new
RR LH Tail Lamp	\$480	✓	344 cruld
RR Boot	\$620	✓	Dented
RR bumper	\$740	✓	del
Reverse Sensor	\$160	✓	Damaged
RR LH bumper bracket	\$78	44 ✓	new
RR RH bumper bracket	\$78	44 ✓	new
RR boot lock	\$98	✓	del
RR boot stricker	\$48	x	new
RR boot weatherstrip	\$210	✓	lt
RR end panel	\$580	✓	Dented.
RR bumper clip	\$4 x 10 = \$40	✓	new
RR bumper skirt	\$420	x	Repair
RR boot no: plate garnish	\$220	✓	cracked.
RR no: plate with housing	\$60	x	new
RR LH wheel ^{Inner Shield}	del \$80	✓	turn.
Emblem 'GLX'	\$42	✓	} new.
Emblem 'GLX'	\$68	✓	
Emblem 'laner'	\$75	✓	
RR reinforcement	\$260	✓	But.

Nett: 3625

un 10%: 3262.50

Labour: 1600

total: 4862.50

4/5: 3.9K

06days.

Panel beat and Labour charge to transfer and do wiring ~~\$1200~~ 800.
spray works ~~\$1200~~ 800.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

H/s Admin Lj
29/07/19.

06days.

9021 7013