

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG17010253/SEB3S2-1**Date:** 13/09/2019REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SLK6993U**Insured Vehicle No :** SLN1966R

Date of Loss: 22/05/2017

Nature of Claim:

TP

Claim No: 0169130903SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLK6993U**

Make & Model: HONDA VEZEL, 1.5 X CVT (A)

Engine No: L15B4406524

Reg. Date: 24/01/2017 (Man. Year: 2016)

Chassis No: RU11206525

Colour: White

Odometer: 5806 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16

Rear Tyre Size:

215/60R16

Front Left Side: Dunlop 7 mm

Rear Left Side:

Dunlop 7 mm

Front Right Side: Dunlop 7 mm

Rear Right Side:

Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,182.47	7,025.70	6,156.77	46.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,260.00	2,390.00	1,870.00	43.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,442.47	9,415.70	8,026.77	46.02
+ GST 7.00/7.00% (S\$)	1,220.97	659.10	561.87	46.02
Nett Amount (S\$)	18,663.44	10,074.80	8,588.64	46.02
+ Car Rental (8.0 x S\$100.00/day) (S\$)		800.00		
+ Other Costs (S\$)		60.00		
Nett Liability (S\$)		10,934.80		

INSPECTION

Date of Assignment: 25/05/2017

Date Inspected:

25/05/2017

Inspected At:

Goldbell Engineering Pte Ltd ((Tuas))
No. 10 Tuas Avenue 18
Singapore 638894

Estimated Period of Repair: 8.0 days

Adjuster: Sebastian Yeang Wai Keen**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,399.57 FL	*1,100.90 FL
2	1		*TAILGATE GLASS MOULDING	Necessary	150.70 FL	*150.70 FL
3	1		*TAILGATE LOGO	Necessary	43.80 FL	*43.80 FL
4	1		*TAILGATE EMBLEM - VEZEL	Necessary	110.20 FL	*110.20 FL
5	2		*TAILGATE LAMP	Cracked	1,280.40 FL	*760.00 FL
6	1		*TAILGATE OUTER GARNISH	Not Necessary	680.90 FL	*- FL
7	1		*TAILGATE LOCK	Jammed	413.90 FL	*190.00 FL
8	1		*TAILGATE LOCK STRIKER	Bent	55.79 FL	*55.79 FL
9	1		*TAILGATE WEATHERSTRIP	Deformed	215.90 FL	*145.00 FL
10	2		*TAILGATE INNER HINGE	Not Necessary	190.30 FL	*- FL
11	2		*TAILGATE ABSORBER	Not Necessary	380.90 FL	*- FL
12	1		*TAILGATE INNER PULL COVER	Deformed	81.90 FL	*20.70 FL
13	1		*TAILGATE INNER TRIM	Cracked	814.90 FL	*325.00 FL
14	1		*TAILGATE WIPER MOTOR	Not Necessary	540.80 FL	*- FL
15	1		*REAR BUMPER	Cut	890.32 FL	*890.32 FL
16	2		*REAR BUMPER SIDE RETAINER	Necessary	140.90 FL	*50.00 FL
17	2		*REAR BUMPER REFLECTOR	Cracked	180.00 FL	*78.30 FL
18	1		*REAR EXHAUST SILENCER	Bent	930.22 FL	*930.22 FL
19	2		*REAR EXHAUST MOUNTING	Necessary	80.00 FL	*80.00 FL
20	1		*REAR EXHAUST HEAT SHIELD	Deformed	198.00 FL	*198.00 FL
21	2		*REAR OUTER TAILLAMP	Cracked	960.30 FL	*960.30 FL
22	2		*REAR FENDER INNER TRIM	Not Necessary	1,120.80 FL	*- FL
23	1		*END PANEL	Dented	890.30 FL	*514.00 FL
24	1		*END PANEL GARNISH	Deformed	367.30 FL	*182.00 FL
25	1		*SPARE TYRE TOP BOARD	Not Necessary	491.30 FL	*- FL
26	1		*SPARE TYRE TOOL COVER	Cracked	375.50 FL	*268.00 FL
27	1		*FLOOR COMPARTMENT	Dented	1,020.39 FL	*1,020.39 FL
28	1		*SPARE TYRE UNDER COVER	Deformed	370.00 FL	*296.00 FL
29	2		*REAR CORNER BUMPER	Not Necessary	190.30 FL	*- FL
30	1		*SET REAR BUMPER CLIP	Necessary	70.00 FS	*30.00 FS
31	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	60.00 FS	*50.00 FS
32	1		*WINDSCREEN SEALANT	Necessary	150.00 FS	*40.00 FS
33	1		*JOINT SEALANT	Necessary	150.00 FS	*40.00 FS
34	1		*FLOOR INSULATOR	Necessary	150.00 FS	*40.00 FS
35	1		*REAR REVERSE SENSOR	Damaged	150.00 FS	*130.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	16,295.59	8,699.62
- List Item Discount on L Items 20.00/20.00% (S\$)	3,113.12	1,673.92
Total Parts (S\$)	13,182.47	7,025.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK FRONT WIRING AND LIGHTING SYSTEM.	New	60.00	30.00
2	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH.	New	200.00	80.00
3	REMOVE AND RENEW REAR REVERSE SENSOR.	New	150.00	50.00
4	REMOVE AND REFIT FUEL TANK.	New	150.00	100.00
5	REMOVE AND RENEW REAR EXHAUST ASSY.	New	150.00	80.00
6	REMOVE AND REFIT WINDSCREEN.	New	150.00	100.00
7	REMOVE AND REAR FLOOR INSULATOR.	New	150.00	50.00
8	TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW.	New	200.00	60.00
9	PANEL BEATING ON AFFECTED AREAS.	New	1,500.00	1,000.00
10	SPRAY PAINTING ON AFFECTED AREAS.	New	1,400.00	800.00
11	APPLY ANTI RUST ON AFFECTED AREAS.	New	150.00	40.00
Gross Labour Cost (\$\$)			4,260.00	2,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >