



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Repair Estimates

SMC 4115 G

*Not Authorized  
Repair by Repairer*

|                                |    |          |
|--------------------------------|----|----------|
| ts (a) Cost / List Price Items | \$ | 6,242.66 |
| Plus/Less 25%                  | \$ | 1,560.67 |
| Total of Cost / List           | \$ | 4,682.00 |
| (b) Nett Price Items           |    |          |
| Less                           |    |          |
| Total of Nett Item             |    |          |
| (c) Special Nett Items         | \$ | 295.00   |
| al Parts Cost                  | \$ | 4,977.00 |
| our                            | \$ | 3,230.00 |
| al                             | \$ | 8,207.00 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary repair(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

above total will be subjected to 7% G.S.T.

Name of Surveyor : Hennerh  
Company : LKK  
Survey conducted on : 26/7/19 at 11.10am

## Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 06 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$                     

(e) Signature of surveyor : Le Date: 26/7/19



## ESTEEM PERFORMANCE PTE I

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com

### are Parts

Vehicle No. : **SMC 4115 G**  
Year & Model : **TOYOTA PRIUS ALPHA**  
Chassis No : **ZVW400029727**

Submit By : \_\_\_\_\_  
Year Manufacture : \_\_\_\_\_  
Engine No. : \_\_\_\_\_  
**Cost / List**

| No. | Part Description                   | Qty | Unit Price | Price    |
|-----|------------------------------------|-----|------------|----------|
| 1   | Rear windscreen moulding <i>nc</i> | 1   | \$70.20    | ✓        |
| 2   | Rear windscreen sealant <i>nc</i>  | 1   | \$50.00    | S.N 4052 |
| 3   | Reverse sensor <i>nc</i>           | 1   | \$200.00   | S,N ✓    |
| 4   | Rear number plate <i>nc</i>        | 1   | \$45.00    | S.N ✓    |
| 5   | Rear bumper <i>Bu</i>              | 1   | \$459.20   | ✓        |
| 6   | Rear bumper clip <i>nc</i>         | 10  | \$38.90    | ✓        |
| 7   | Rear bumper side retainer LH       | 1   | \$121.70   | ?        |
| 8   | Rear bumper side retainer RH       | 1   | \$121.70   | ?        |
| 9   | Rear bumper reinforcement          | 1   | N/A        |          |
| 10  | Rear bumper reflector LH <i>sn</i> | 1   | \$58.70    | X        |
| 11  | Rear bumper reflector RH <i>sn</i> | 1   | \$58.70    | X        |
| 12  | Tail door <i>Bu</i>                | 1   | \$1,022.50 | ✓        |
| 13  | Tail door lock <i>Is</i>           | 1   | \$391.60   | ✓        |
| 14  | Tail door plate garnish            | 1   | \$498.30   | ?        |
| 15  | Tail door emblem                   | 1   | \$67.10    | ?        |
| 16  | Wording "PRIUSCX" <i>nc</i>        | 1   | \$72.66    | ✓        |
| 17  | Tail end panel <i>Bu</i>           | 1   | \$678.10   | ✓        |
| 18  | Tail end panel garnish             | 1   | \$154.60   | ?        |
| 19  | Tail end panel garnish clip        | 10  | \$39.20    | ?        |
| 20  | Boot weatherstrip                  | 1   | \$342.70   | ?        |
| 21  | Spare tyre board                   | 1   | \$698.30   | ?        |
| 22  | Tail lamp LH <i>cm</i>             | 1   | \$653.20   | ✓        |
| 23  | Tail lamp RH <i>cm</i>             | 1   | \$653.20   | ✓        |

3: If any of the quoted parts are recommended to be repaired, then an additional labour charge  
be charged accordingly under supplementary.

**are Parts**

icle No. : **SMC 4115 G**  
 e & Model : **TOYOTA PRIUS ALPHA**  
 issis No : **ZVW400029727**

Submit By : \_\_\_\_\_  
 Year Manufacture : \_\_\_\_\_  
 Engine No. : \_\_\_\_\_

**Cost / List**

| o. | Part Description         |  |  | Qty | Unit Price | Price    |
|----|--------------------------|--|--|-----|------------|----------|
| 24 | Tail lamp clip <i>me</i> |  |  | 10  | \$42.10    | <i>✓</i> |
| 25 |                          |  |  |     |            |          |
| 26 |                          |  |  |     |            |          |
| 27 |                          |  |  |     |            |          |
| 28 |                          |  |  |     |            |          |
| 29 |                          |  |  |     |            |          |
| 30 |                          |  |  |     |            |          |
| 31 |                          |  |  |     |            |          |
| 32 |                          |  |  |     |            |          |
| 33 |                          |  |  |     |            |          |
| 34 |                          |  |  |     |            |          |
| 35 |                          |  |  |     |            |          |
| 36 |                          |  |  |     |            |          |
| 37 |                          |  |  |     |            |          |
| 38 |                          |  |  |     |            |          |
| 39 |                          |  |  |     |            |          |
| 40 |                          |  |  |     |            |          |
| 41 |                          |  |  |     |            |          |
| 42 |                          |  |  |     |            |          |
| 43 |                          |  |  |     |            |          |
| 44 |                          |  |  |     |            |          |



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Labour

Vehicle No. : **SMC 4115 G** Submit By : **Carmen Lim**  
Make & Model : **TOYOTA PRIUS ALPHA** Year of Manufacture : **2018**

| S/No | Labour Description                                                                                                    | Estimated Price | Adjusted Price |
|------|-----------------------------------------------------------------------------------------------------------------------|-----------------|----------------|
| 1    | TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (TAIL DOOR, REAR BUMPER, END PANEL, SPARE TYRE WELL PANEL)   | \$1,200.00      | 600            |
| 2    | TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (TAIL DOOR, REAR BUMPER, END PANEL, SPARE TYRE WELL PANEL) | \$1,200.00      | 600            |
| 3    | To check wiring                                                                                                       | \$50.00         | 20             |
| 4    | To remove & refit reverse sensor                                                                                      | \$120.00        | 50             |
| 5    | To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.                                      | \$150.00        | 60             |
| 6    | To remove & refit rear windscreen                                                                                     | \$120.00        | ✓              |
| 7    | To tuff coat                                                                                                          | \$150.00        | 60             |
| 8    | To transfer boot mechanism to new boot                                                                                | \$120.00        | 60             |
| 9    | To conduct water leakage tests to ensure proper air and sealing                                                       | \$120.00        | 20             |
|      |                                                                                                                       |                 |                |
|      |                                                                                                                       |                 |                |
|      |                                                                                                                       |                 |                |

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.