

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #08-16  
Singapore 079120

**Our File No:** CC3/AIG19013196/AQF3E2**Date:** 02/01/2020**REFERENCE**

Insured/Claimant: CHEW CHAN FEI Policy No: 1800154437  
Date of Loss: 24/07/2019 Nature of Claim: OD Claim No: 1548334104SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMG6334G**  
Make & Model: AUDI A4, 2.0 (A) Engine No: CVK071511  
Reg. Date: 27/12/2018 (Man. Year: 2018) Chassis No: WAUZZZF48KN000715  
Colour: Blue Odometer: 14240 km  
Engine Capacity: 1984 cc  
Market Value/New Car Price: S\$160,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18  
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm  
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	16,331.00	3,096.32	13,234.68	81.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,102.00	3,822.00	3,280.00	46.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>23,433.00</b>	<b>6,918.32</b>	<b>16,514.68</b>	<b>70.48</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,640.31</b>	<b>484.28</b>	<b>1,156.03</b>	<b>70.48</b>
<b>Nett Amount (S\$)</b>	<b>25,073.31</b>	<b>7,402.60</b>	<b>17,670.71</b>	<b>70.48</b>

**INSPECTION**

Date of Assignment: 26/07/2019

Date Inspected: 26/07/2019 Inspected At:

Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699

Estimated Period of Repair: 5.0 days

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,999.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	531.00 FS	*- FS
3	1		*AIR GUIDE-RH	Not Necessary	56.00 FS	*- FS
4	1		*FOAM FILLER PIECE	Not Necessary	113.00 FS	*- FS
5	1		*FRONT BUMPER CARRIER	Not Necessary	733.00 FS	*- FS
6	1		*FRONT BUMPER GUIDE SECTION-RH	Not Necessary	34.00 FS	*- FS
7	1		*FRONT BUMPER BRACKET	Not Necessary	125.00 FS	*- FS
8	2		*FRONT BUMPER SUPPORT-LH/RH	Not Necessary	52.00 FS	*- FS
9	2		*PARKING AID SENSOR-FRONT INNER/OUTER	Not Necessary	462.00 FS	*- FS
10	4		*SEAL RING	Not Necessary	12.00 FS	*- FS
11	1		*HORN-LOW TONE RH	Not Necessary	262.00 FS	*- FS
12	1		*SPRING SHACKLE-RH	Not Necessary	26.00 FS	*- FS
13	1		*FENDER-RH	Distorted	700.00 FS	*559.60 FS
14	1		*FENDER ATTACHMENT PARTS	Not Necessary	183.00 FS	*- FS
15	1		*CLOSING ELEMENT-RH	Not Necessary	45.00 FS	*- FS
16	1		*FENDER BRACKET-RH	Bent	32.00 FS	*25.20 FS
17	1		*DEFORMATION ELEMENT BRACKET-RH	Damaged	45.00 FS	*35.60 FS
18	6		*POP RIVET	Necessary	18.00 FS	*14.40 FS
19	1		*FENDER BRACKET-RH	Bent	29.00 FS	*22.64 FS
20	1		*BRACE-RH FRONT	Bent	107.00 FS	*85.60 FS
21	1		*WHEEL HOUSING LINER-RH	Deformed	220.00 FS	*175.60 FS
22	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	211.00 FS	*- FS
23	1		*WHEEL SPOILER (NPA)	Not Necessary	0.00 FS	*- FS
24	1		*END PLATE-RH	Not Necessary	33.00 FS	*- FS
25	1		*STONE CHIP GUARD-RH	Necessary	46.00 FS	*36.64 FS
26	1		*FENDER TOP LEDGE COVER-RH UPPER	Necessary	28.00 FS	*22.24 FS
27	1		*FENDER TOP LEDGE COVER-RH LOWER	Necessary	21.00 FS	*16.16 FS
28	1		*BONNET	Dented	2,554.00 FS	*2,043.20 FS
29	1		*IMPACT PROTECTION-CENTRE	Necessary	25.00 FS	*19.92 FS
30	2		*IMPACT PROTECTION-LH/RH	Necessary	50.00 FS	*39.52 FS
31	1		*LED HEADLIGHT	Not Necessary	7,087.00 FS	*- FS
32	1		*LIFT CYLINDER-RH	Not Necessary	192.00 FS	*- FS
33	1		*AIR GUIDE GRILLE-RH (NPA)	Not Necessary	0.00 FS	*- FS
34	1		*FRONT RIM-RH (NPA)	Not Necessary	0.00 FS	*- FS
35	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)** **16,331.00** **3,096.32**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,150.00	1,500.00
3	TO RESPRAY FRONT BUMPER, BONNET AND RHS FRONT FENDER	New	3,000.00	1,650.00
4	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>7,102.00</b>	<b>3,822.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >