Claim Reference: TP 0719 - 5615 Assessment number: 011604

Version: 1810

Date calculated: 25/07/2019 4:07 PM

**Full Report** Registration: SGL2174Y Printed: 25/07/2019 4:07 PM

### **Summary Information**

Claim

Location:

Printed by:

Claim Reference:

Estimated Repair Time: Actual Repair Days:

Singapore (SG)

Ray Lin

TP 0719 - 5615

Work Provider:

Currency: Date of Incident:

Hire Car Start: Hire Car End:

AXA Insurance Pte Ltd

SGD 24/07/19

### **Vehicle Details**

Vehicle

Manufacturer:

**DAEWOO** 

Model:

OPTRA (KLAN/J200)

Sub Model:

BASE MODEL 14 09 31

Model Sheet Number: Registration:

SGL2174Y

VIN number:

110951

Odometer: **Model Specs** 

4-DOOR

REAR PARKING SYSTEM

TWO COAT METALLIC

PAINTING OFF VEHICLE

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claim Reference: TP 0719 - 5615 Assessment number: 011604

Version: 1810

Date calculated: 25/07/2019 4:07 PM

Full Report Registration: SGL2174Y Printed: 25/07/2019 4:07 PM


### **Vehicle Condition**

#### **Vehicle Status**

Pre-Accident Damage: Date of Inspection:

#### **Damage Areas**

All Underbody



#### Labour

	Time Base 10 WU/h	Price = 45.00 SGD/h	
Code	Description	WU	Price SGD
NO NUMBER	R + R L/R OUTER PARKING AID SENSOR	1.0	4.50
NO NUMBER	R + R R/R OUTER PARKING AID SENSOR	1.0	4.50
95 711 00)	R + R REAR BUMPER CPL	3.0	13.50
95 711 00)	RENEW REAR BUMPER (REMOVED)	3.0	13.50
91 802 00)	R + R L/TAILLAMP	2.0	9.00
91 801 00)	R + R R/TAILLAMP	1.0	4.50
91 803 00)	R + R TAILLAMPS	1.0	4.50
93 818 00)	R + R L/R WING COVERING	1.0	4.50
93 818 00)	R + R R/R WING COVERING	1.0	4.50
93 814 00	R + R REAR PANEL TRIM	2.0	9.00
2711	REAR PANEL CPL REPAIR	10 Wy 20.0*	90.00

Claim Reference: TP 0719 - 5615 Assessment number: 011604

Version: 1810

Date calculated: 25/07/2019 4:07 PM

Full Report Registration: SGL2174Y Printed: 25/07/2019 4:07 PM

Labour Cost Panel / Mechanical Labour		Hrs 3.60	WU 36.0	162.00
Total of Labour				162.00
SYSTEM	1 AZT	Tii	ne Basi	s 10WU/h
<b>Description - TWO COAT METALLIC</b>			WU	Price SGD
REAR PANEL CPL REPAIR PAINTING <50	0%		12.0 11.0 6.0	
al Per Part				
REAR PANEL CPL REPAIR PAINTING <50	0%			Price SGD 61.01 11.95 14.19
Labour Cost - Paint	45.00 SGD/h	Hrs	WU	Price SGD
Time Paint Preparation Main Work Metal		2.10 0.50	29.0 21.0 5.0	94.50 22.50
Total	10 WU/h	5.50	55.0	247.50
Material Cost - Paint New Part Painting - Plastic K1R Repair Painting Surface-/Blend Paint Material-constant Metal Material-constant Plastic Total				Price SGD 61.01 11.95 14.19 18.10 9.00 114.25
	Total of Labour  SYSTEM  Description - TWO COAT METALLIC  REAR BUMPER CPL NEW PART PAINT KI REAR PANEL CPL REPAIR PAINTING <5 L/OUTER WHEELHOUSE SURFACE PAIN  al Per Part  Description  REAR BUMPER CPL NEW PART PAINT KI REAR PANEL CPL REPAIR PAINTING <5 L/OUTER WHEELHOUSE SURFACE PAIN  Labour Cost - Paint Factor Time Paint Preparation Main Work Metal Preparation Comp. Work Plastic  Total  Material Cost - Paint New Part Painting - Plastic K1R Repair Painting Surface-/Blend Paint Material-constant Metal Material-constant Metal Material-constant Plastic	SYSTEM AZT  Description - TWO COAT METALLIC  REAR BUMPER CPL NEW PART PAINT K1R REAR PANEL CPL REPAIR PAINTING <50% L/OUTER WHEELHOUSE SURFACE PAINT  al Per Part  Description REAR BUMPER CPL NEW PART PAINT K1R REAR PANEL CPL REPAIR PAINTING <50% L/OUTER WHEELHOUSE SURFACE PAINT  Labour Cost - Paint Factor Time Paint Preparation Main Work Metal Preparation Main Work Plastic Total  Material Cost - Paint New Part Painting - Plastic K1R Repair Painting Surface-/Blend Paint Material-constant Metal Material-constant Metal Material-constant Plastic	Panel / Mechanical Labour  Total of Labour  SYSTEM AZT  Description - TWO COAT METALLIC  REAR BUMPER CPL NEW PART PAINT K1R REAR PANEL CPL REPAIR PAINTING <50% L/OUTER WHEELHOUSE SURFACE PAINT  Tal Per Part  Description REAR BUMPER CPL NEW PART PAINT K1R REAR PANEL CPL REPAIR PAINTING <50% L/OUTER WHEELHOUSE SURFACE PAINT  Labour Cost - Paint Factor Time Paint Preparation Main Work Metal Preparation Comp. Work Plastic Total  Material Cost - Paint New Part Painting - Plastic K1R Repair Painting Surface-/Blend Paint Material-constant Metal Material-constant Metal Material-constant Plastic	Panel / Mechanical Labour  Total of Labour  SYSTEM AZT  Description - TWO COAT METALLIC  REAR BUMPER CPL NEW PART PAINT K1R REAR PANEL CPL REPAIR PAINTING < 50% L/OUTER WHEELHOUSE SURFACE PAINT  Description REAR BUMPER CPL NEW PART PAINT K1R REAR PANEL CPL REPAIR PAINTING < 50% L/OUTER WHEELHOUSE SURFACE PAINT  Description REAR BUMPER CPL NEW PART PAINT K1R REAR PANEL CPL REPAIR PAINTING < 50% L/OUTER WHEELHOUSE SURFACE PAINT  Labour Cost - Paint Factor Time Paint Preparation Main Work Metal Preparation Comp. Work Plastic Total  10 WU/h 5.50  Material Cost - Paint New Part Painting Surface-/Blend Paint Material-constant Metal Material-constant Metal Material-constant Plastic

Spare Parts

Code	Description	Part Number	prices as at 2015-06-01/01 Supplier Price SGD
		, 10	
2581	REAR BUMPER CPL	96960349	1,052.00
3281	L/R OUTER LAMP	96551225 🗶	328.00

Claim Reference: TP 0719 - 5615 Assessment number: 011604

Version: 1810

Date calculated: 25/07/2019 4:07 PM

Full Report Registration: SGL2174Y Printed: 25/07/2019 4:07 PM

Code	Description Part Number	Supplier	Price SGD
9619	L/R OUT PARKING SENS 96945980 X		0.00
9620	R/R OUT PARKING SENS 96945980 🗴		0.00
f: OEM Parts	Savings		0.00
n: Non-OEM Parts	Subtotal		1,380.00
u: Used parts	Addition(+15.00%)		207.00
	Total		1,587.0
Extras			
Code	Description		Price SGI
1000	RR PARKING SENSOR X		220.00
	Total Extras		220.00
Parts Addition(+15.00%)		1,380.00 207.00	
<b>Total Parts</b>			1,587.00
Labour Time B			
Total 36.0 WU X 45.00 SGD/h  Total of Labour		162.00	162.00
Total Of Extras			220.00
Paint Work Ti	mo Paco 10 WII /h		
Paint Work Time Base 10 WU/h Labour Cost 55.0 WU X 45.00 SGD/h		247.50	
Material Cost		114.25	
Total Paint Incl	luding Material		361.7
Repair Cost Exc			2,330.75
GST (+7.00%			163.1
Repair Cost Inc	luded GST		2,493.90

Claim Reference: TP 0719 - 5615 Assessment number: 011604

Version: 1810

Date calculated: 25/07/2019 4:07 PM

Full Report Registration: SGL2174Y Printed: 25/07/2019 4:07 PM

#### Comments

\* - USER SUPPLIED DATA NN - NO MANUFACTURERS CODE EXISTS ) - WU PARTIAL INCL IN OTHER POSITIONS