

CC 6, ABE 190 13223, Ada3

Surveyor:

LMP

DGI:

ASSIGNMENT

26/1/2019

Date / Time:

26/1/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : SLN8568K

Name of Insured : Choo Kok Wee

Insured Tel No. : HP:

Excess Sec II : SS D.O.A: 25/1/19

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

Claim No. : Gx

Policy No. :

Make / Model :

Place of Accident :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SLW 69080

INSRS: my solution
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time		STAGE	DATE / PIC
		Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	> 6/8/19
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	☐
		After call ltr to OI:	☐
		Authorisation To Act:	☐
		Release Voucher:	☐
		Final Repair Bill:	☐
		Car Rental Invoice:	☐
		Towing Invoice	☐
		LTA / GIA :	☐
		Medical Bill:	☐
		PIR:	☐
		Mandate/Reject Instruction:	☐
		LOD	☐
		Payment Breakdown Form:	☐
		Post-Repair Photos:	☐
		Others:	☐

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	SS	(days) Reduction:	%
FINAL SETTLEMENT		Date/Time: 3/3/2020	Confirm with: Ms Wong
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	27
Repair Cost: (n/631)	SS 16371.00		
Loss of Rental (LOR):	SS -	(days)	
Loss of Use (LOU):	SS 1200.00	(\$ 60 x 20 days)	
Loss of Income (LOI):	SS -	(\$ x days)	
LOR only ☐	LOU only ☐	LOR + LOU ☐	LOR + LOI ☐ [Tick only one]
GIA/LTA Search	SS 7.45		
Medical:	SS -		
Disbursement:	SS 50.00	(e.g. Tow/ Independent)	
Legal Cost	SS -		
Total:	SS 17628.45	Global Sum SS:	
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	SS 17628.45	Name 1:	MG Solution Pte Ltd
Payee 2:	SS	Name 2:	
Payee 3:	SS	Name 3:	

COPY SENT 12/3/2020

- 1) Claim status: Normal/Reject/Private Settle
 2) Report Format: TP
 3) Survey fee: \$400

Accident

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 14 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SUW6908D Yr Regn: 2018 / Feb.

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Shuttle C.C. 1456

Colour: Silver AC: Insured / Std / NI / NA

Sp. Reading: 141983 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GP 71202405

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 195/55R15

R: 195/55R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Doublstar

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 26/07/19

Survey held at M6 Solution

Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPQBE

45 - \$15300 (Red \$ 11937.60 / 442)

MV :

PV :

Nett:

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Prel. Report

Final Report

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

___ S + RS, ___ SI

Photos

Others

TOTAL

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: QBE	DATE	: 26-Jul-19
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SLW6908D		
MODEL	: HONDA SHUTTLE 1.5G		
CHASSIS NO	:		
<u>ACCIDENT DETAILS</u>		DATE	: 25-Jul-19
		TIME	: 08:40HR
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/ N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Distorted</i>	1	\$ 1,250.00	\$ 1,250.00
2	TAILGATE LOGO	1	\$ 55.60	\$ 55.60
3	TAILGATE EMBLEM "SHUTTLE" <i>for</i>	1	\$ 85.20	\$ 85.20
4	TAILGATE EMBLEM "HYBRID"	1	\$ 85.20	\$ 85.20
5	TAILGATE HINGE <i>new Best</i>	2	\$ 50.00	\$ 100.00
6	TAILGATE DAMPER <i>new</i>	2	\$ 180.00	\$ 360.00
7	TAILGATE REFLECTOR <i>could</i>	2	\$ 420.00	\$ 840.00
8	TAILGATE INNER LOCK <i>new</i>	1	\$ 130.00	\$ 130.00
9	TAILGATE INNER HANDLE <i>could</i>	1	\$ 55.00	\$ 55.00
10	TAILGATE CATCH <i>Best</i>	1	\$ 65.30	\$ 65.30
11	TAILGATE WEATHER STRIP <i>lt</i>	1	\$ 235.00	\$ 235.00
12	TAILGATE INNER TRIM BOARD <i>could</i>	1	\$ 385.00	\$ 385.00
13	TAILGATE STOPPER <i>new</i>	2	\$ 22.00	\$ 44.00
14	TAILGATE NUMBER PLATE GARNISH <i>could</i>	1	\$ 405.00	\$ 405.00
15	TAILGATE NUMBER PLATE CHROME <i>could</i>	1	\$ 410.00	\$ 410.00
16	TAILGATE WIPER BLADE <i>lt</i>	1	\$ 80.00	\$ 80.00
17	TAILGATE WIPER BLADE MOTOR <i>new</i>	1	\$ 530.00	\$ 530.00
18	TAILGATE WINDSCREEN <i>shattered</i>	1	\$ 1,155.90	\$ 1,155.90
19	TAILGATE WINDSCREEN MOULDING(TOP) <i>for</i>	1	\$ 150.00	\$ 150.00
20	TAILGATE WINDSCREEN MOULDING(LOW)	1	\$ 180.00	\$ 180.00

Tailgate detector *could*
Tailgate buzzer *could*

110 ✓
91 ✓

21	REAR BUMPER	Distorted	1	\$	1,250.00	\$	1,250.00	✓
22	REAR BUMPER SIDE RETAINER	new	2	\$	64.50	\$	129.00	✓
23	REAR BUMPER REFLECTOR	new	2	\$	113.20	\$	226.40	x
24	REAR BUMPER REFLECTOR GARNISH	new	2	\$	113.20	\$	226.40	✓
25	REAR BUMPER TOWING COVER	new	1	\$	45.20	\$	45.20	✓
26	REAR BUMPER AIR VENT	LH could.	2	\$	64.50	\$	129.00	64.50
27	REAR BUMPER SIDE SPONGE	could	2	\$	75.20	\$	150.40	✓
28	TAILLAMP	could	2	\$	580.00	\$	1,160.00	✓
29	TAILLAMP PANEL	LH Distorted	2	\$	320.00	\$	640.00	320
30	REAR FENDER	LH Buckled	2	\$	1,120.00	\$	2,240.00	1120.
31	REAR FENDER INNER COWLING(FRONT)	new	2	\$	93.00	\$	186.00	x
32	REAR FENDER INNER COWLING(REAR)	LH torn	2	\$	150.00	\$	300.00	150
33	REAR FENDER INNER TRIM(TOP)	LH could	2	\$	550.00	\$	1,100.00	550 285
34	REAR FENDER INNER TRIM(LOW)	Distorted	2	\$	630.00	\$	1,260.00	850.
35	REAR FENDER INNER TRIM SIDE CARRIER COVER	LH could	2	\$	89.00	\$	178.00	89.
36	REAR QUARTER GLASS MOULDING	new LH.	2	\$	101.00	\$	202.00	101.
37	SPARE TYRE TOOL BOX CARRIER	could	1	\$	360.00	\$	360.00	✓
38	SPARE TYRE TOOL BOX CARRIER BELOW	could	1	\$	180.00	\$	180.00	✓
39	SPARE TYRE TOOL BOX CARRIER SIDE	could	1	\$	180.00	\$	180.00	✓
40	SPARE TYRE TOOL BOX SPONGE	could	1	\$	250.00	\$	250.00	✓
41	SPARE TYRE BOLT	new	1	\$	75.20	\$	75.20	x
42	REAR END PANEL	Distorted	1	\$	655.00	\$	655.00	560.00
43	REAR END PANEL TOP GARNISH	could	1	\$	180.00	\$	180.00	✓
44	REAR FLOOR PANEL	Distorted	1	\$	1,150.00	\$	1,150.00	✓
45	REAR FLOOR PANEL TOP BOARD	Deformed	1	\$	410.00	\$	410.00	280
46	AIR DUCT ASSY	could	1	\$	180.00	\$	180.00	✓
47	IPU INLET SUB	could	1	\$	266.50	\$	266.50	✓
48	HYBRID BATTERY COVER	Bent	1	\$	455.90	\$	455.90	✓
49	HYBRID BATTERY TRAY	new	1	\$	680.80	\$	680.80	x

Rear side panel LH Distorted

Rear end panel cover 2nd

TOTAL PRICE \$ 21,047.00
 LESS 20% 10 ✓ \$ 4,209.40
 SUB TOTAL PRICE \$16,837.60

16796.90
 13437.52

S/ N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE Bent	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIPS new	1	\$ 40.00	\$ 40.00
3	TAILGATE INNER TRIM CLIP (SET) new	1	\$ 40.00	\$ 40.00
4	TAILGATE WINDSCREEN SEALANT new	1	\$ 80.00	\$ 80.00
5	TAILGATE WINDSCREEN INNER SEAL	1	\$ 80.00	\$ 80.00
6	TAILGATE WINDSCREEN SOLAR FILM new	1	\$ 250.00	\$ 250.00

7	REAR FENDER INNER COWLING CLIPS (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	+
8	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	✓
9	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	10. ✓
10	REAR END PANEL INSULATOR SEAL <i>new</i>	1	\$ 60.00	\$ 60.00	✓
11	REAR FLOOR PANEL SEALANT <i>new</i>	1	\$ 40.00	\$ 40.00	✓
12	REVERSE CAMERA <i>David</i>	1	\$ 350.00	\$ 350.00	✓
13	ROAD CAMERA <i>new</i>	1	\$ 550.00	\$ 550.00	+
14	REVERSE SENSOR <i>David</i>	1	\$ 220.00	\$ 220.00	200. ✓

1090.

TOTAL

\$1,880.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 2,400.00	1800	
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,400.00	1400	
3	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 150.00	50	
4	REMOVE AND REFIX REVERSE CAMERA	\$ 220.00	50	
5	REMOVE AND REFIX FUEL TANK	\$ 100.00	80	
6	TO REMOVE AND REFIX QUARTER GLASS	\$ 100.00	60	
7	TRANSFER TAILGATE MECHANISM	\$ 120.00	80	
8	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 150.00	120	
9	WIRING CHECK	\$ 150.00	30	
10	CONDUCT WATER LEAKAGE TEST	\$ 250.00	x	
11	TO REMOVE AND REFIX REAR SAFETY BELT	\$ 380.00	240	
12	TO REMOVE AND REFIX HYBRID BATTERY	\$ 850.00	400	
13	TO APPLY PHV	\$ 50.00	30 ✓	
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO	\$ 1,200.00	280.	

TOTAL

\$8,520.00

4640

ESTIMATE REPORT

TOTAL PARTS COST : \$18,717.60
TOTAL LABOUR COST : \$8,520.00

27277.60

TOTAL REPAIR COST : \$27,237.60

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

Adrian Lij

4/s 26/07/19.

14 Days.

total 19167.52

4/s 15.3K ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CC6/QBE19013223/Ada3q2		
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 17-03-2020		
		Code : QBE		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLN 8568K	Veh. Inspected	SLW 6908D	
Policy No.	8-V0017899-MVA-R001	Coverage (\$)	0.00	
Claim No.	VC012816	Excess (\$)	0.00	
Assign From		Assign Date	26/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	GP71202405	Colour	SILVER	
Odometer	141983	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55 R15	DOUBLESTAR	6 mm	
L/H Front Tyre	195/55 R15	DOUBLESTAR	6 mm	
R/H Rear Tyre	195/55 R15	DOUBLESTAR	6 mm	
L/H Rear Tyre	195/55 R15	DOUBLESTAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/07/2019	Inspection Date	26/07/2019	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 6908D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	DISTORTED	1,250.00	1,250.00
1	TAILGATE LOGO	NECESSARY	55.60	55.60
1	TAILGATE EMBLEM 'SHUTTLE'	NECESSARY	85.20	85.20
1	TAILGATE EMBLEM 'HYBRID'	NECESSARY	85.20	85.20
2	TAILGATE HINGE @\$50.00	BENT	100.00	100.00
2	TAILGATE DAMPER @\$180.00	NOT NECESSARY	360.00	-
2	TAILGATE REFLECTOR @\$420.00	CRACKED	840.00	840.00
1	TAILGATE INNER LOCK	DAMAGED	130.00	130.00
1	TAILGATE INNER HANDLE	DEFORMED	55.00	55.00
1	TAILGATE CATCH	BENT	65.30	65.30
1	TAILGATE WEATHERSTRIP	CUT	235.00	235.00
1	TAILGATE INNER TRIM BOARD	DEFORMED	385.00	385.00
2	TAILGATE STOPPER @\$22.00	NOT NECESSARY	44.00	-
1	TAILGATE NUMBER PLATE GARNISH	CRACKED	405.00	405.00
1	TAILGATE NUMBER PLATE CHROME	CRACKED	410.00	410.00
1	TAILGATE WIPER BLADE	CUT	80.00	80.00
1	TAILGATE WIPER BLADE MOTOR	DAMAGED	530.00	530.00
1	TAILGATE WINDSCREEN	SHATTERED	1,155.90	1,155.90
1	TAILGATE WINDSCREEN MOULDING (TOP)	NECESSARY	150.00	150.00
1	TAILGATE WINDSCREEN MOULDING (LOW)	NECESSARY	180.00	180.00
1	TAILGATE REFLECTOR	CRACKED	110.00	110.00
1	TAILGATE BUZZLE	CRACKED	91.00	91.00
1	REAR BUMPER	DISTORTED	1,250.00	1,250.00
2	REAR BUMPER SIDE RETAINER @\$64.50	NECESSARY	129.00	129.00
2	REAR BUMPER REFLECTOR @\$113.20	NOT NECESSARY	226.40	-
2	REAR BUMPER REFLECTOR GARNISH @\$113.20	DEFORMED	226.40	226.40
1	REAR BUMPER TOWING COVER	DEFORMED	45.20	45.20
2	REAR BUMPER AIR VENT @\$64.50	N/S CRACKED	129.00	64.50
2	REAR BUMPER SIDE SPONGE @\$75.20	CRACKED	150.40	150.40
2	TAILLAMP @\$580.00	CRACKED	1,160.00	1,160.00
2	TAILLAMP PANEL @\$320.00	N/S DISTORTED	640.00	320.00

Report Ref No. CC6/QBE19013223/Ada3q2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR FENDER @\$1120.00	N/S BUCKLED	2,240.00	1,120.00
2	REAR FENDER INNER COWLING (FRONT) @\$93.00	NOT NECESSARY	186.00	-
2	REAR FENDER INNER COWLING (REAR) @\$150.00	N/S TORN	300.00	150.00
2	REAR FENDER INNER TRIM (TOP) @\$550.00	N/S CRACKED	1,100.00	285.00
2	REAR FENDER INNER TRIM (LOW) @\$630.00	DISTORTED	1,260.00	850.00
2	REAR FENDER INNER TRIM SIDE CARRIER COVER @\$89.00	N/S DEFORMED	178.00	89.00
2	REAR QUARTER GLASS MOULDING @\$101.00	N/S NECESSARY	202.00	101.00
1	SPARE TYRE TOOL BOX CARRIER	CRACKED	360.00	360.00
1	SPARE TYRE TOOL BOX CARRIER BELOW	DEFORMED	180.00	180.00
1	SPARE TYRE TOOL BOX CARRIER SIDE	DEFORMED	180.00	180.00
1	SPARE TYRE TOOL BOX SPONGE	CRACKED	250.00	250.00
1	SPARE TYRE BOLT	NOT NECESSARY	75.20	-
1	REAR END PANEL	DISTORTED	655.00	560.80
1	REAR END PANEL TOP GARNISH	CRACKED	180.00	180.00
1	REAR FLOOR PANEL	DISTORTED	1,150.00	1,150.00
1	REAR FLOOR PANEL TOP BOARD	DEFORMED	410.00	380.00
1	AIR DUCT ASSY	DEFORMED	180.00	180.00
1	IPU INLET SUB	DEFORMED	266.50	266.50
1	HYBRID BATTERY COVER	BENT	455.90	455.90
1	HYBRID BATTERY TRAY	NOT NECESSARY	680.80	-
2	REAR SIDE PANEL @\$305.00	N/S DENTED	610.00	305.00
2	REAR END PANEL COVER @\$5.00	DAMAGED	10.00	10.00
	LESS 20% DISCOUNT		-4,373.60	-3,359.38
			17,494.40	13,437.52
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN)	BENT	50.00	50.00
1	REAR BUMPER CLIPS (SN)	NECESSARY	40.00	30.00
1	SET TAILGATE INNER TRIM CLIP (SN)	NECESSARY	40.00	30.00
1	TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	TAILGATE WINDSCREEN INNER SEAL (SN)	NECESSARY	80.00	40.00
1	TAILGATE WINDSCREEN SOLAR FILM (SN)	NECESSARY	250.00	200.00
1	SET REAR FENDER INNER COWLING CLIPS (SN)	NOT NECESSARY	40.00	-

Report Ref No. CC6/QBE19013223/Ada3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR FENDER INNER TRIM CLIPS (SN)	NECESSARY	40.00	40.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	40.00	10.00
1	REAR END PANEL INSULATOR SEAL (SN)	NECESSARY	60.00	60.00
1	REAR FLOOR PANEL SEALANT (SN)	NECESSARY	40.00	40.00
1	REVERSE CAMERA (SN)	DAMAGED	350.00	350.00
1	IROAD CAMERA (SN)	NOT NECESSARY	550.00	-
1	REVERSE SENSOR (SN)	DAMAGED	220.00	200.00
			1,880.00	1,090.00
	LABOUR			
	TO PANEL BEAT ,REMOVE AND REPLACE PARTS.		2,400.00	1,800.00
	TO SPRAY PAINT AFFECTED AREA.		2,400.00	1,400.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		150.00	50.00
	REMOVE AND REFIX REVERSE CAMERA.		220.00	50.00
	REMOVE AND REFIX FUEL TANK.		100.00	80.00
	TO REMOVE AND REFIX QUARTER GLASS.		100.00	60.00
	TRANSFER TAILGATE MECHANISM.		120.00	80.00
	REMOVE AND REFIX TAILGATE WINDSCREEN.		150.00	120.00
	WIRING CHECK.		150.00	30.00
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	250.00	-
	TO REMOVE AND REFIX REAR SAFTLY BELT.		380.00	240.00
	TO REMOVE AND REFIX HYBRID BATTERY .		850.00	400.00
	TO APPLY PHV.		50.00	50.00
	TO CHECK DIAGNOSTIC OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO.		1,200.00	280.00
			8,520.00	4,640.00
	GRAND TOTAL		27,894.40	19,167.52
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			15,300.00

Report Ref No. CC6/QBE19013223/Ada3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.