

ASS. REC. BY:

REF: CS/FCI19013255/KgA3^{N2} Special Instruction:Supervisor: Kenneth

ASSIGNMENT (Office)

From (Person): Henry Kao of FCI Date/Time: 26/7/19 @ 5:34pm

Estimated Cost: _____ Bill to: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SHC 5634C Insured: SHA 9180Dat Workshop m/s Transcab Tel: 6287 6666of NO. 2 Amic St - 63Policy No: _____ Claim No: D19004877 MFSTH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 25/7/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 9:43am 26/7/19 Person Contacted: Candy Vehicle IN / OUT

Date/Time	Action/Instruction
	<u>Shanghai ✓</u>
	<u>SHC 5634C CS3/ASM19002655/Gtd 3e2-1 DOA = 7/2/19</u>
	<u>SHA 9180D CC4/11119006506/DA3 DOA = 9/4/19</u>
<u>26/7/19 @</u>	<u>US\$2k returned to Henry Kao by email.</u>
	<u>V2 to 900, 2 days CRD to 40231.04, 98%.</u>

REF: FCI

ASS. REC. BY:

ASSIGNMENT

From: _____ Date: 29/7/19

Estimated Cost: _____

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No: SHC 5634C

at Workshop m/s Transcab

of No. 2 Amk st. 63

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

(DS)

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHC 5634C Yr Regn: 11 / 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Perant Lotitude C.C. 1995

Colour: m. white / Red A/C: Insured / Std / NI / NA

Sp. Reading: 655300 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VI-1 ABL 15 AUG 27 9629

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 25/7/19

Rear

R/Bal. 8 mm

L/Bal. 8 mm

D.O.I. 29/7/19

'Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S 19

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

/ RECEIVED 02 AUG 2019

Date/Time, File Pass to?

☐

Preli. Report

1) 01/8/19

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Report Format: 7P

Lump Sum / L.P.R. \$

900

350



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19004877MFSH

Date: 30 July 2019

Our Ref: CS/FCI19013255/Kqf3

The Motor Claims Department
MS First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 5634C .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 29/07/2019 at the premises of M/s TRANS-CAB, and have the following to report:-

Workshop Estimate Amount	: S\$ 41,131.04 .
Revised Estimate Amount	: S\$ 1,155.45 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at the n/s front portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	26-07-2019	Our Ref No. D19004877MFSH
Accident Date	25-07-2019	Claim Type. Third Party
Insured Vehicle	SHA9180D	Third Party Vehicle. SHC5634C
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	CANDY KONG	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Friday, 2 August 2019 10:40 AM
To: Shiau Chan (LKKAUTO)
Subject: RE: TP VEHICLE SHC 5634C (DOA: 25/07/2019) -- AAD1907-234
Attachments: image001.wmz

Hi Shiau Chan

Amount confirmed \$ 900 (b4 GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Tuesday, 30 July, 2019 11:57 AM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Subject: TP VEHICLE SHC 5634C (DOA: 25/07/2019)

Dear Wai Yin,

Based on our surveyor's estimate marking, the calculation of repair cost will be at Lump Sum \$900 and 2 repair days.

Kindly check.

Best Regards,

Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 30 July 2019 11:55 AM
To: 'CWS Motor Claims'; assignments
Cc: 'Henry Kao'; SUR
Subject: RE: SURVEY ASSESSMENT - D19004877MFSH/1
Attachments: CSFCI19013255Kqf3.pdf

Dear Henry,

Enclosed herewith preliminary advice of SHC 5634C.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Monday, 29 July 2019 9:11 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19004877MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 26 July 2019 5:39 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004877MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHC5634C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	25 Jul 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C002006
Chassis No.:	VF1ABL15AUC279629
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	04 Nov 2014
First Registration Date:	04 Nov 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Nov 2022
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	
COE Expiry Date:	03 Nov 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$51,337.00
COE Rebate Amount:	\$21,012.00
Total Rebate Amount:	\$30,385.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 25 Jul 2019

OK

Trans-cab Auto Services Pte Ltd

AAD1907-234

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5634C

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC 5634C

VF1ABL15AUC279629

RENAULT

LATITUDE

25.7.19

FIRST CAPITAL

4/11/2014

Not Authorised
11 Sep @ 900h

PART		LIST	
1	BUMPER COVER FRT	\$	1,259.42
1	BUMPER SPOILER FRT	\$	181.75
1	BUMPER ABSORBER FRT	\$	394.68
1	BUMPER RETAINER FRT LH	\$	151.41
1	BUMPER SUPPORT FRT	\$	123.88
1	BUMPER UNDERTRAY FRT	\$	472.83
1	BUMPER GRILLE LOWER FRT	\$	266.80
1	BUMPER FOG LAMP GRILLE LH	\$	207.21
1	BUMPER BEAM FRT	\$	914.08
1	HEADLAMP LH	\$	1,184.43
1	HEADLAMP PANEL FRT LH	\$	152.15
1	FENDER PANEL FRT LH	\$	783.83
1	WHEELARCH FRT LH	\$	278.84
1	FENDER BRACKET LOWER LH	\$	15.79
1	FENDER INSULATOR LH	\$	130.84
1	FRONT BRACE PANEL	\$	177.22
1	RADIATOR GRILLE	\$	1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	225.36
1	RADIATOR GRILLE FRAME	\$	1,353.75
1	FRAME FULL SUPPORT PANEL	\$	615.90
1	FRAME FULL SUPPORT BRACKET	\$	89.79
1	BONNET	\$	1,941.63
1	BONNET INSULATOR	\$	405.73
1	BONNET STRUT LH	\$	88.61
1	BONNET STRUT RH	\$	88.61
1	BONNET HINGE LH	\$	348.31
1	BONNET HINGE RH	\$	348.31
1	BONNET LOCK	\$	305.48
1	BONNET CABLE	\$	119.19

Trans-cab Auto Services Pte Ltd

AAD1907-234

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5634C

1	BONNET CABLE COVER	\$	SL	161.03	}
1	BONNET SEAL OUTER	\$	SL	92.36	
1	BONNET SEAL INNER	\$	SL	157.28	
1	AIR CLEANER BOX	\$	SL	464.20	
1	AIR CLEANER HOSE	\$	SL	175.85	
1	AIR CLEANER LOWER	\$	SL	271.26	
1	DOOR PANEL FRT LH	\$	N	2,844.66	
1	DOOR MIRROR ASSY LH	\$	SL	1,483.40	
1	DOOR HARNESS WIRE LH	\$	SL	2,670.00	
1	ROCKER PANEL INNER GARNISH LH	\$	SL	466.51	
1	ROCKER PANEL INNER LH	\$	N	1,024.79	
1	ROCKER PANEL OUTER LH	\$	N	1,184.99	
1	ROCKER PANEL CENTER LH	\$	N	990.25	
TOTAL		\$		26,320.18	
10%		\$		2,632.02	
		\$		23,688.16	

Special Nett

1	BUMPER CLIP FRT	\$	~	66.00	}	X
1	BUMPER BRACKET CLIP FRT LH	\$	~	12.00		
1	BUMPER SUPPORT CLIP FRT LH	\$	~	10.50		
1	BUMPER GRILLE LOWER CLIP	\$	~	69.00		
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	~	70.00		
2	FRAME FULL SUPPORT PANEL NUT	\$	~	20.00		
2	FRAME FULL SUPPORT PANEL STUD	\$	~	30.00		
1	WHEELARCH CLIP FRT LH	\$	~	30.50		
1	FRONT LEFT TYRE	\$	S _L	300.00		
1	FRONT LEFT TYRE RIM	\$	S _L	380.00		
1SET	Front licence plate with holder	\$	S _L	80.00		
1	WINDSCREEN SEALANT	\$	~	253.80		
1	FRONT WINDSCREEN MOULDING	\$	S _L	120.00		
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	~	100.00		
6	BONNET INSULATOR CLIP L70Y	\$	~	7.30		
2	BONNET STRUT L70Y	\$	S _L	88.61		
2	BONNET CABLE CLIP L70Y	\$	~	6.31		
2	BONNET CABLE COVER SCREW L70Y	\$	S _L	10.85		
1SET	RADIATOR GRILLE FRAME CLIP	\$	~	52.00		
1SET	RADIATOR GRILLE SCREW	\$	~	16.00		

Trans-cab Auto Services Pte Ltd**AAD1907-234**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5634C

1	FRONT DOOR STICKER 'Trans-Cab'	\$	<i>nn</i> 80.00 X
1	FRONT DOOR STICKER 'Classic'	\$	<i>nn</i> 80.00 X

TOTAL	\$	1,882.88
--------------	-----------	-----------------

TOTAL PARTS	\$	25,571.04
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	<i>2ccf</i> 6,000.00
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>h</i> 380.00 X
To transfer of front windscreen fittings and conduct water seepage test.	\$	<i>h</i> 170.00 X
To check steering geometry and computer wheel alignment	\$	<i>h</i> 220.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>h</i> 380.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>h</i> 170.00 X
Putty and spray painting of the affected portion.	\$	6,000.00 <i>22cf</i>
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>h</i> 380.00 X

Trans-cab Auto Services Pte Ltd**AAD1907-234**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5634CTo transfer of front door fittings, attachment and
perform water seepage test.\$ *nn* 380.00 *X*To apply paint protection system (PPS) maintain
and enhancement\$ *nn* 380.00 *✓*

To Check Electrical Lighting Concerned.

\$ *nn* 170.00 *X*

To rust-proofing of the affected areas.

\$ 170.00 *301***TOTAL \$ 15,560.00****Over All Total \$ 41,131.04****LUMP SUM (REPAIR DAY)***20 days**2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19013255/Kqf3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 02-08-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9180D	Veh. Inspected	SHC 5634C	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004877MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	26/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC279629	Colour	METALLIC WHITE / RED	
Odometer	655300	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	8 mm	
L/H Front Tyre	215/60 R16	GITI	8 mm	
R/H Rear Tyre	215/60 R16	GITI	8 mm	
L/H Rear Tyre	215/60 R16	GITI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/07/2019	Inspection Date	29/07/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5634C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER FRT	SERVICEABLE	1,259.42	-
1	BUMPER SPOILER FRT	SERVICEABLE	181.75	-
1	BUMPER ABSORBER FRT	SERVICEABLE	394.68	-
1	BUMPER RETAINER FRT LH	SERVICEABLE	151.41	-
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE LH	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	914.08	-
1	HEADLAMP LH	SERVICEABLE	1,184.43	-
1	HEADLAMP PANEL FRT LH	TO REPAIR SEE LABOUR	152.15	-
1	FENDER PANEL FRT LH	BENT	783.83	783.83
1	WHEELARCH FRT LH	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER LH	SERVICEABLE	15.79	-
1	FENDER INSULATOR LH	SERVICEABLE	130.84	-
1	FRONT BRACE PANEL	TO REPAIR SEE LABOUR	177.22	-
1	RADIATOR GRILLE	SERVICEABLE	1,707.78	-
1	RADIATOR GRILLE BADGE "RENAULT"	SERVICEABLE	225.36	-
1	RADIATOR GRILLE FRAME	SERVICEABLE	1,353.75	-
1	FRAME FULL SUPPORT PANEL	TO REPAIR SEE LABOUR	615.90	-
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	89.79	-
1	BONNET	TO REPAIR SEE LABOUR	1,941.63	-
1	BONNET INSULATOR	SERVICEABLE	405.73	-
1	BONNET STRUT LH	SERVICEABLE	88.61	-
1	BONNET STRUT RH	SERVICEABLE	88.61	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	348.31	-

Report Ref No. CS/FCI19013255/Kqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET LOCK	TO REPAIR SEE LABOUR	305.48	-
1	BONNET CABLE	SERVICEABLE	119.19	-
1	BONNET CABLE COVER	SERVICEABLE	161.03	-
1	BONNET SEAL OUTER	SERVICEABLE	92.36	-
1	BONNET SEAL INNER	SERVICEABLE	157.28	-
1	AIR CLEANER BOX	SERVICEABLE	464.20	-
1	AIR CLEANER HOSE	SERVICEABLE	175.85	-
1	AIR CLEANER LOWER	SERVICEABLE	271.26	-
1	DOOR PANEL FRT LH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR MIRROR ASSY LH	SERVICEABLE	1,483.40	-
1	DOOR HARNESS WIRE LH	SERVICEABLE	2,670.00	-
1	ROCKER PANEL INNER GARNISH LH	SERVICEABLE	466.51	-
1	ROCKER PANEL INNER LH	TO REPAIR SEE LABOUR	1,024.79	-
1	ROCKER PANEL OUTER LH	TO REPAIR SEE LABOUR	1,184.99	-
1	ROCKER PANEL CENTER LH	TO REPAIR SEE LABOUR	990.25	-
	LESS 10% DISCOUNT		-2,632.02	-78.38
			23,688.17	705.45
	SPECIAL NETT ITEMS			
1	BUMPER CLIP FRT (SN)	NOT NECESSARY	66.00	-
1	BUMPER BRACKET CLIP FRT LH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN)	NOT NECESSARY	10.50	-
1	BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	WHEELARCH CLIP FRT LH (SN)	NOT NECESSARY	30.50	-
1	FRONT LEFT TYRE (SN)	SERVICEABLE	300.00	-
1	FRONT LEFT TYRE RIM (SN)	SERVICEABLE	380.00	-

Report Ref No. CS/FC119013255/Kqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	80.00	-
1	WINDSCREEN SEALANT (SN)	NOT NECESSARY	253.80	-
1	FRONT WINDSCREEN MOULDING (SN)	SERVICEABLE	120.00	-
1	FRONT WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
6	BONNET INSULATOR CLIP L70Y (SN)	NOT NECESSARY	7.30	-
2	BONNET STRUT L70Y (SN)	SERVICEABLE	88.61	-
2	BONNET CABLE CLIP L70Y (SN)	NOT NECESSARY	6.31	-
2	BONNET CABLE COVER SCREW L70Y (SN)	SERVICEABLE	10.85	-
1	SET RADIATOR GRILLE FRAME CLIP (SN)	NOT NECESSARY	52.00	-
1	SET RADIATOR GRILLE SCREW (SN)	NOT NECESSARY	16.00	-
1	FRONT DOOR STICKER "TRANS-CAB" (SN)	NOT NECESSARY	80.00	-
1	FRONT DOOR STICKER "CLASSIC" (SN)	NOT NECESSARY	80.00	-
			1,882.87	-
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM FRT,HEADLAMP PANEL FRT LH,FRONT BRACE PANEL,FRAME FULL SUPPORT PANEL,FRAME FULL SUPPORT BRACKET,BONNET,BONNET HINGE LH,BONNET HINGE RH,BONNET LOCK,DOOR PANEL FRT LH,ROCKER PANEL INNER LH,ROCKER PANEL OUTER LH AND ROCKER PANEL CENTER LH.		6,000.00	200.00
	TO TRANSFER OF FRONT BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-

Report Ref No. CS/FCI19013255/Kqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	220.00
	TO TRANSFER OF BONNET FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	170.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
			15,560.00	450.00
GRAND TOTAL			41,131.04	1,155.45

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				900.00
--	--	--	--	--------

Report Ref No. CS/FC119013255/Kqf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.