

22/01/2001

ASS. REC. BY:

REF:

CS/FCI 19013257/BAF3ⁿ²

Special Instruction:

Surveyor: SherylASSIGNMENT (Office)From (Person): CWS Henry Kao

of

FCI

Date/Time: 26/7/19 @ 5.46pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PA 5721A

Insured:

SHC 0446L

at Workshop in/s

Yew Tee Automobile

Tel:

67653373

of

Blk 6 woodlands Rd 319F Yew Tee Ind. Est.

Policy No:

Claim No: D19004828MF54

Sum Insured:

Excess:

Make of Vch:

(Client's Record)

D.O.A. 23/7/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9.17am @ 29/7/19

Person Contacted:

Shu Yi

Vehicle IN (OUT)

Date/Time

Action/Instruction

Telephone

PA 5721A X

SHC 0446L CC3/TM117004549/H1rbn2-1 DOA= 4/3/17

30/7 @ 2:08pm - Sent revised preli advise email

WV/ALB

Stone

REF:

FCI

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR. Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lump Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

MV- 23,000
LTA 14,253
NV- 8,747

21/8/19 Finalize Conf- \$1900, 3 days (Vianje)
Red: 2437.41; 56%

RECEIVED 21 AUG 2019

Veh No.

PA5721A

Yr Regn

21/10/05

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Hiace

C.S. 2494

Colour

Silver

A/C Insured / Std / NI / NA

Sp. Reading

288508

T/Radio: Insured / Std / NI / NA

Eng/No:

Ct/No:

JTFJ S92 P800004328

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

195R15C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Gilen - max

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

23/7/19

D.O.A.

29/7/19

Survey held at

New Tec

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report

1) 21/8 Typist

☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation

) S + RS CI

) Photos

) Other

TOTAL

Add Fee:

☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech Invs (\$

☐ : Weekend (\$

Report Format :

Lump Sum / I.B.F. (\$

TP
1900/-

135
50
50
44

279



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19004828MFSH

Date: 30/7/2019

Our Ref: CS/FCI19013257/Etf3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. PA 5721A

Please be informed that we had conducted the inspection of the abovementioned vehicle 29/7/2019 at the premises of M/s Yew Tee Automotive have the following to report: -

Workshop Estimate Amount	: S\$ <u>4,337.40</u>
Revised Estimate Amount	: S\$ <u>2,359.83</u>
"Check" Items Amount	: S\$ <u>0.00</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the front portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Steve

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	24-07-2019	Our Ref No. D19004828MFSH
Accident Date	23-07-2019	Claim Type. Third Party
Insured Vehicle	SHC0446L	Third Party Vehicle. PA5721A
Survey Location	BLK 6 WOODLANDS ROAD 399F YEW TEE INDUSTRIAL ESTATE	
Contact Person.	SHUYI	
Contact No.	67653373/ 0	Fax No. 67604895
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	YEW TEE AUTOMOBILE TECH PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 30 July 2019 2:08 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Henry Kao'; SUR
Subject: RE: SURVEY ASSESSMENT - D19004828MFSH/1
Attachments: PRELI ADVISED OF PA 5721A.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **PA 5721A**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Monday, 29 July 2019 8:51 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19004828MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 26 July 2019 5:46 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004828MFSH/1

Steve Chen (LKK Auto)

From: YT(HQ) <info@yewteegroup.com>
Sent: Wednesday, August 21, 2019 9:40 AM
To: Steve Chen (LKK Auto)
Cc: 'Yew Tee (HQ)'
Subject: RE: PA5721A FINALIZE

Hi Steve,

Ok we are confirmed COR \$1900.

Thank you

Best Regards

Vinnie Lim



Yew Tee Automobile Tech Pte Ltd

HQ:
Blk 6 Woodlands Road 399F
Yew Tee Ind. Est
Singapore 678006
DID: 6765 3373 /6764 9042 Fax: 6760 4895
Email: utauto@singnet.com.sg

Branch Office:
Synergy@KB, 25 Kaki Bukit Road
Unit No #01-60/61
Singapore 417800
DID: 6702 3113
Email: utauto2@singnet.com.sg

Branch Office:
39 Woodlands Close,
#01-12 Mega@Woodlands
Singapore 737856
DID:62562081
Email: info@yewteegroup.com

 please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business
Owner ID: 377A

Vehicle Details

Vehicle No.: PA5721A
Vehicle to be Exported: No
Intended Deregistration Date: 29 Jul 2019
Vehicle Make: TOYOTA
Vehicle Model: HIACE MANUAL
Primary Colour: Silver
Manufacturing Year: 2005
Engine No.: 2KD1333322
Chassis No.: JTFJS02P800004328
Maximum Power Output: -
Open Market Value: \$26,622.00
Original Registration Date: 21 Oct 2005
First Registration Date: 21 Oct 2005
Transfer Count: 2
Actual ARF Paid: \$1,332.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 20 Oct 2020
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 5
PQP Paid: \$23,992.00
COE Rebate Amount: \$14,253.00
Total Rebate Amount: \$14,253.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 29 Jul 2019

OK

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Block 6 Woodlands Road 399F, Yew Tee Industrial Estate
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : FIRST CAPITAL INSURANCE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTHQ/TP/1907/021
Policy No:	D18MTSCBU000500	Date of Loss:	23/07/2019
Vehicle Reg. No.:	PA5721A	Driveable?	no
Driver Age:		Third Party Vehicle No.:	SHC446L
Any Injuries?	yes	Contact No:	98341104
Insured/Claimant:	SAN TRANSPORT SERVICES	Driver:	KUMARI D/O CHANDRASIGARAN

Make/Model:	Toyota, Hiace	Vehicle Reg. Date:	21 Oct 2005
Vehicle Colour:	SILVER	Engine Number:	2KD1333322
Chassis No:	JTFJS02P800004328	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

Description of Accident/loss COLLISION - CROSS JUNCTION
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

COST OF CLAIMS

	Amount
Parts	3,057.41
Miscellaneous Items	60.00
Labour	530.00
Paintwork Labour	690.00
Towing	0.00
Gross Total(S\$):	4,337.40
GST 7.00%(S\$):	303.62
Nett Amount(S\$):	4,641.02

This claim is handled by: SHUYI

P- 1376-52
N- 30
L- 960
2366.52
C/S- 1893-21
= 1900

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT BUMPER <i>BR</i>	568.95	-25.00	426.71
2	1	FRONT BUMPER SIDE RETAINER LH <i>BR</i>	206.37	-25.00	154.78
3	1	FRONT GRILLE <i>X NAI</i>	539.75	-25.00	404.81
4	1	FRONT GRILLE BASE <i>X NAI</i>	358.45	-25.00	268.84
5	1	FRONT HEADLAMP LH <i>BR</i>	798.75	-25.00	599.06
6	1	FRONT CORNER PANEL LH <i>DD</i>	292.37	-25.00	219.28
7	1	FRONT BONNET <i>X R</i>	1,055.62	-25.00	791.72
8	1	FRONT BONNET HINGE LH <i>X NAI</i>	90.50	-25.00	67.88
9	1	FRONT DOOR LH <i>X R</i>	0.00	0.00	0.00
10	1	FRONT DOOR STEP GARNISH LH <i>X NAI</i>	165.78	-25.00	124.34

1835.37
- 25%
1376.52

Total Parts (\$\$) 3,057.41

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT BUMPER CLIPS <i>MC</i>	30.00	0.00	30.00
2	1	FRONT HEADLAMP CLIPS <i>X N</i>	30.00	0.00	30.00

Sub Total (\$\$) 60.00

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	500.00	0.00	500.00
2	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	0.00	30.00

Gross Labour Cost (\$\$) 530.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	650.00	0.00	650.00
2		To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	40.00	0.00	40.00

Gross Labour Cost (\$\$) 690.00

< END OF ESTIMATES >

29/7/19, 3.00pm

L/S, Reg AR Spy

4337.41



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19013257/Eff3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 26-08-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 446L	Veh. Inspected	PA 5721A
	Policy No.		Coverage (\$)	0.00
	Claim No.	D19004828MFSH	Excess (\$)	0.00
	Assign From	HENRY KAO	Assign Date	26/07/2019
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE	c.c	2494
	Engine No.	HIDDEN	Year of Reg.	2005
	Chassis No.	JTFJS02P800004328	Colour	SILVER
	Odometer	288508	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	GREEN MAX	5 mm
	L/H Front Tyre	195 R15C	GREEN MAX	5 mm
	R/H Rear Tyre	195 R15C	GREEN MAX	5 mm
	L/H Rear Tyre	195 R15C	GREEN MAX	5 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	23/07/2019	Inspection Date	29/07/2019
	Survey held at	YEW TEE AUTOMOBILE TECH PL (HQ) BLK 6 WOODLANDS ROAD 399F YEW TEE IND. ESTATE SINGAPORE 678006		
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PA 5721A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	BROKEN	568.95	568.95
1	FRONT BUMPER SIDE RETAINER LH	BROKEN	206.37	175.30
1	FRONT GRILLE	NOT NECESSARY	539.75	-
1	FRONT GRILLE BASE	NOT NECESSARY	358.45	-
1	FRONT HEADLAMP LH	BROKEN	798.75	798.75
1	FRONT CORNER PANEL LH	DENTED	292.37	292.37
1	FRONT BONNET	TO REPAIR SEE LABOUR	1,055.62	-
1	FRONT BONNET HINGE LH	NOT NECESSARY	90.50	-
1	FRONT DOOR LH (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT DOOR STEP GARNISH LH	NOT NECESSARY	165.78	-
	LESS 25% DISCOUNT		-1,019.14	-458.84
			3,057.40	1,376.53
SPECIAL NETT ITEMS				
1	FRONT BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	FRONT HEADLAMP CLIPS (SN)	NOT NECESSARY	30.00	-
			60.00	30.00
LABOUR				
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.INCLUSIVE OF THE REPAIR OF FRONT BONNET AND FRONT DOOR LH.		500.00	400.00
	TO DISCONNECT AND RECONNECT,CHECK ELECTRICAL WIRING HARNESS WIRE,SOCKETS,REPLACE DAMAGED PARTS.		30.00	30.00
	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER,CLEANING AND SANDING OF SURFACES,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		650.00	500.00

Report Ref No. CS/FCI19013257/Etf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		40.00	30.00
			1,220.00	960.00
GRAND TOTAL			4,337.40	2,366.53

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,900.00
---	--	--	----------

Report Ref No. CS/FCI19013257/Etf3n2

MARKET VALUE: \$23,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$14,253.00=NETT VALUE: \$8,747.00

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.