

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19013286/KRS3Q2

Date: 10/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900105863

Claimant
Vehicle No : SLK7407P **Insured Vehicle No :** SLP3091R

Date of Loss: 25/07/2019 Nature of Claim: TP Claim No: 5798622656SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK7407P	Engine No:	2ZRR980243
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Chassis No:	JTDKB3FU903540525
Reg. Date:	25/01/2017 (Man. Year: 2016)	Odometer:	220475 km
Colour:	Metallic Silver		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,786.88	1,219.78	1,567.10	56.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,140.00	580.00	2,560.00	81.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	5,926.88	1,799.78	4,127.10	69.63
+ GST 7.00/7.00% (\$\$)	414.88	125.98	288.90	69.63
Nett Amount (\$\$)	6,341.76	1,925.76	4,416.00	69.63
+ Car Rental (5.0 x S\$75.00/day) (\$\$)		375.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		2,308.21		

INSPECTION

Date of Assignment: 26/07/2019

Date Inspected: 30/07/2019 Inspected At: Esteem Performance Pte Ltd - Sin Ming (HQ)
385 Sin Ming Drive
Singapore 575718

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	497.50 FL	*497.50 FL
2	10		*REAR BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
3	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	112.70 FL	*- FL
4	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	112.70 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Bent	398.90 FL	*398.90 FL
6	1		*REAR BUMPER LOWER CENTRE GARNISH	Dented/Cut	582.60 FL	*582.60 FL
7	1		*REAR BUMPER TOW COVER	Serviceable	31.70 FL	*- FL
8	1		*WORDING PRIUS	Necessary	51.90 FL	*51.90 FL
9	1		*WORDING HYBRID	Necessary	55.47 FL	*55.47 FL
10	1		*TAIL DOOR PLATE GARNISH	Serviceable	782.50 FL	*- FL
11	1		*TAIL END PANEL	Repair	596.60 FL	*- FL
12	1		*TAIL END PANEL GARNISH	Serviceable	151.60 FL	*- FL
13	10		*TAIL END PANEL GARNISH CLIP	Not Necessary	35.00 FL	*- FL
14	1		*REVERSE SENSOR	Serviceable	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,649.17	1,626.37
- List Item Discount on L Items 25.00/25.00% (\$\$)	862.29	406.59
Total Parts (\$\$)	2,786.88	1,219.78

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(REAR BUMPER,TAIL DOOR,TAIL DOOR PLATE GARNISH,END PANEL,SPARE TYRE COMPARTMENT)	New	1,200.00	200.00
2	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(REAR BUMPER,TAIL DOOR,TAIL DOOR PLATE GARNISH,END PANEL,SPARE TYRE COMPARTMENT)	New	1,200.00	320.00
3	TO CHECK WIRING	New	50.00	10.00
4	TO REMOVE & REFIT SPARE TYRE,SPARE TYRE BOARD,CARPET TRIM TO ASSIST WORK LOAD	New	150.00	0.00
5	TO TUFF COAT	New	150.00	0.00
6	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING	New	120.00	0.00
7	TO TRANSFER BOOT MECHANISM TO NEW BOOT	New	120.00	0.00
8	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	50.00
Gross Labour Cost (\$\$)			3,140.00	580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >