Ala: LKK



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates	SI	LK 7407 P	Nor Notharke Menony Bypains
rts (a) Cost / List Price Items	\$	3,449.17	
Plus/Less25%	\$	862.29	
Total of Cost / List	\$	2,586.88	
(b) Nett Price Items  Less  Total of Nett Item			LKK Auto Consultants hence notify the Repairer of the following:  To resurvey before/after spray painting  To display damaged part(s) during resurvey  Parts prices are subject to confirmation  Third party survey is on a "Without Prejudice" be  No illegal modification (a) Without Prejudice" be
(c) Special Nett Items	\$	200.00	<ul> <li>No illegal modification(s) is allowed</li> <li>Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Comp</li> </ul>
tal Parts Cost	\$	2,786.88	Acknowledged by Repairer
bour	\$	3,140.00	Signature: Date:
tal	\$	5,926.88	Date.
e above total will be subjected to			
e above total will be subjected to  Name of Surveyor			
e above total will be subjected to			Kennery UCIC 0/1/18 at
e above total will be subjected to  Name of Surveyor  Company			
e above total will be subjected to  Name of Surveyor  Company  Survey conducted on	7% G.S.T. : :	30	Kennerh UKIC 0/1/18 at
e above total will be subjected to  Name of Surveyor  Company  Survey conducted on  Remarks By Surveyor	7% G.S.T.	30	Kennerh UKIC olJIIP at
e above total will be subjected to  Name of Surveyor  Company  Survey conducted on  Remarks By Surveyor  (a) The repair of this vehicle is	7% G.S.T.	is not authorized until furth	Kennery  UKIC  oly118 at  her notice.
e above total will be subjected to  Name of Surveyor  Company  Survey conducted on  Remarks By Surveyor  (a) The repair of this vehicle is a subjected to	7% G.S.T.	is not authorized until furth  O2  Required / Not Required	Kennery  UKIC  oly118 at  her notice.



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

S	pa	re	Pa	irts

Vehicle No. :	SLK 7407 P	Submit By	:	JENNY
Make & Model:	TOYOTA PRIUS	Year Manufacture	:	2016
Chassis No :	JTDKB3FU903540525	Engine No.	:	
		Cost / List		

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	Sh	1	\$200.00	S.N	X
2	Rear bumper	Bu	1	\$497.50		_
3	Rear bumper clip	M	10	\$40.00		_
4	Rear bumper side retainer LH	Sa	1	\$112.70		×
5	Rear bumper side retainer RH	5~	1	\$112.70		×
6	Rear bumper reinforcement		1	\$398.90		?
7	Rear bumper lower centre garnish	nella.	1	\$582.60		
8	Rear bumper tow cover	Sm	1	\$31.70		×
9	Wording "PRIUS"	1c	1	\$51.90		_
10	Wording "HYBRID"	M	1	\$55.47		
11	Tail door plate garnish		1	\$782.50		7
12	Tail end panel	n	1	\$596.60		×
13	Tail end panel garnish	52	1	\$151.60		~
14	Tail end panel garnish clip	nn	10	\$35.00		X
15						
16						
17						
18						
19						
20						
21						
22						
23						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



## **ESTEEM PERFORMANCE PTE LTD**

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Labour

Vehicle No.	:	SLK 7407 P	Submit By :	Carmen Lim
Make & Model	: _	TOYOTA PRIUS	Year of Manufacture:	2016

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
	REPAIR AREA. (REAR BUMPER, TAIL DOOR, TAIL DOOR	\$1,200.00	2001
	PLATE GARNISH,END PANEL,SPARE TYRE COMPARTMENT)		
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		2.2
	REPAIR AREA. (REAR BUMPER, TAIL DOOR, TAIL DOOR	\$1,200.00	3201
	PLATE GARNISH,END PANEL,SPARE TYRE COMPARTMENT)		
3	To check Wiring	\$50.00	101
4	To remove & refit spare tyre, spare tyre board, carpet trim 🛮 🗸	\$150.00	X
	to assist work load.		
5	To tuff coat	\$150.00	X
6	To conduct water leakage tests to ensure proper air and	\$120.00	Х
	sealing		
7	To transfer boot mechanism to new boot	\$120.00	X
8	To remove & refit reverse sensor	\$150.00	501

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.