

ASS. REC. BY:

REF: CS/MSG 19013335/KVJ312 Special Instruction:

Surveyor: Kenneth ASSIGNMENT (Office)

From (Person): Jowyn Tay ni ling of MSG Date/Time: 29.7.19 16.47p.m

Estimated Cost: Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SFC 59U Insured: SLC 551T

at Workshop m/s (Long Hoe motor Tel: 67556142

of Blk 1019 # 01-374/382

Policy No: 29077929amy Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A 28.7.19 (Client's Record)

CA / REV / REP. / REV 24 HRS vmp H.O.D. Endorsement:

Date/Time: 30.7.2019 9.31 Person Contacted: June Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SFC 59U - X
	SLC 551T - X
31/7/19	Send preli revised via merimen
26/8	5504.25 Confirm Efrdg (Red 2283.37, 2990 (NO LS)

Merimen

REF: MS19

ASSIGNMENT

From: _____ Date: 30.1.2019

Estimated Cost: _____

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFC 59 U

at Workshop m/s Chong Hap motor

of BK 1019 # 01-374 / 382

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: SFC 59 U Yr Regn: 03 16

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: Toy Axiom G c.c. 1496

Colour: M. D. Blue A/C: Insured / Std / NI / NA

Sp. Reading: 98666 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NR E 161 000 9537

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: Delium 195/65R15

R: L490



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front	Rear
R/Bal. <u>8</u> mm	R/Bal. <u>9</u> mm
L/Bal. <u>8</u> mm	L/Bal. <u>9</u> mm
D.O.A. <u>28/7/19</u>	D.O.I. <u>30/7/19</u>

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS rup

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
RECEIVED 26 AUG 2019	
	<i>[Signature]</i>
	26/8/2019

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to? 26/8-typist

Report Format: Merimen

Lump Sum / I.B.I. (\$) 5504.25

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee: _____

Transportation: 150

5 + RS: 11

Photos: _____

Others: _____

Add Fee: : Site Insp (\$) _____

: Interview (\$) _____

: Tech. Invs (\$) _____

: Weekend (\$) _____

TOTAL: 161

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
--	---

Attn: Jowyn Tay Mei Ling

Date: 31 Jul 2019

Preliminary Advice

Insured Vehicle No	: SLC551T	Accident Date	: 28/07/2019
TP Vehicle No	: SFC59U	Assignment Date	: 29/07/2019
Make	: TOYOTA COROLLA AXIO	Est. Duration of Repair	: 6.00
Date of Inspection	: 30/07/2019		
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:SS	7,787.62
Revised Amount	:SS	5,695.87
Check Items (Estimated)	:SS	808.30
Total	:SS	6,504.17

Lump Sum Repair	:SS	
-----------------	-----	--

Total Loss Consideration

New for Old Value	:SS	
Pre-Accident Value	:SS	
COE / PARF Rebate	:SS	
Salvage Value	:SS	
Margin for Repair	:SS	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Jul 2019 10:34		29 Jul 2019 16:47 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	FONG CHON KIAT, ID: S8086599F		
Main Claimant:	TAN LAI SOON, ID: S1133004E		
Vehicle Reg. No.:	SFC59U	Date of Loss:	28/07/2019 00:00 - :59 [40 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	29077929QMY (Comprehensive) Coverage: 29/04/2019 - 28/04/2020
Vehicle Reg. No. (Insured):	SLC551T	Policy No. (Claimant):	
		Excess:	
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/07/2019]		
Adj Asg. Remarks:	on WP. Liab: Dispute (NR) TP Agree on SJE - assign Kenneth Kong from LKK Auto Consultants. Contact: June @ 6755 6142		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			
ALL ASSOCIATED TASKS		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	004E
Vehicle Details	
Vehicle No.:	SFC59U
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5G A
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	2NR8498242
Chassis No.:	NRE1610009537
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,173.00
Original Registration Date:	03 Mar 2016
First Registration Date:	03 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$7,173.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Mar 2026
PARF Rebate Amount:	\$5,379.00
Intended COE Rebate Details	
COE Expiry Date:	02 Mar 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$43,000.00
COE Rebate Amount:	\$28,331.00
Total Rebate Amount:	\$33,710.00

The information contained herein is correct as at 29 Jul 2019

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SFC59U
 TP/MSIG

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
 16 RAFFLES QUAY
 #24-01 HONG LEONG BUILDING
 SINGAPORE 048581

TEL: 68277660
 ATTN: Motor Claim Department

WS Ref: TP/MSIG
 Claim Type: Third Party
 Accident Date: 28/07/2019
 TP Veh Reg No: SLC551T

FAX: 62257402
Not with claim
Resurvey by paint
6 days

Estimate No: ES1991805/YISHUN
 Date: 29 Jul 2019
 Policy No: 5078044117-03
 Veh Reg No: SFC59U
 Make/Model: TOYOTA VIOS E MANUAL
 Chassis No: MR053HY9305079471
 Engine No: 1NZX795771
 Reg. Date: 08/09/2008

Estimate Repair Cost to Vehicle No :SFC59U

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	530.50	1 PC	B ₁ 530.50	✓
2 REAR BUMPER LH REFLECTOR	56.90	1 PC	Sm 56.90	X
3 REAR BUMPER CLIPS	3.50	6 PCS	me 21.00	✓
4 REAR BUMPER SIDE RETAINER	92.33	1 PC	Diy 92.33	✓
5 REAR LH FENDER	1,026.80	1 PC	R 1,026.80	X
6 REAR LH FENDER INNER GARNISH CLIPS	3.50	6 PCS	me 21.00	✓
7 REAR BOOT	880.10	1 PC	B ₁ 880.10	✓
8 REAR BOOT INNER LOCK	360.24	1 PC	me 360.24	✓
9 REAR BOOT INNER RUBBER	185.20	1 PC	Diy 185.20	✓
10 REAR BOOT EMBLEM (COROLLA)	39.29	1 PC	me 39.29	✓
11 REAR BOOT EMBLEM (AXIO)	44.17	1 PC	me 44.17	✓
12 REAR BOOT EMBLEM (G)	34.10	1 PC	me 34.10	✓
13 REAR BOOT OUTER MOULDING	301.00	1 PC	Sm 301.00	X
14 REAR LH FENDER INNER GARNISH	325.50	1 PC	Return 325.50	✓
15 TAILLAMPS	426.00	2 PCS	me 852.00	✓
16 REAR PANEL	602.00	1 PC	R B ₁ 602.00	X
17 REAR PANEL INNER TOP GARNISH	218.00	1 PC	Diy 218.00	✓
18 TAILLAMP CLIPS	4.50	4 PCS	me 18.00	✓
19 REAR SPARE TYRE TOP BOARD	392.70	1 PC	Return 392.70	✓
20 REAR WINDSCREEN GLASS MOULDING	97.80	1 PC	me 97.80	X
21 REAR SMART KEY SENSOR	138.20	1 PC	CM 138.20	✓
			6,236.83	
		Less 25%	1,559.21	4,677.62
Special Net				
22 REVERSE SENSOR	200.00	1 SET	CM 200.00	✓
23 REVERSE CAMERA	280.00	1 PC	Sm 280.00	X
24 REAR SPARE TYRE PANEL TOP COAT	80.00	1 PC	me 80.00	60.00
			560.00	560.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be removed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Cheng Hoe Motor Pte Ltd

Bik 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
 16 RAFFLES QUAY
 #24-01 HONG LEONG BUILDING
 SINGAPORE 048581

TEL: 68277660 FAX: 62257402
 ATTN: Motor Claim Department

WS Ref: TP/MSIG
 Claim Type: Third Party
 Accident Date: 28/07/2019
 TP Veh Reg No: SLC551T

Estimate No: ES1991805/YISHUN
Date: 29 Jul 2019
Policy No: 5078044117-03
Veh Reg No: SFC59U
Make/Model: TOYOTA VIOS E
 MANUAL
Chassis No: MR053HY9305079471
Engine No: 1NZX795771
Reg. Date: 08/09/2008

Estimate Repair Cost to Vehicle No :SFC59U

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
Labour				
25 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	X
26 REMOVE & REFIX REAR SEAT,CARPET,GARNISH, TOP ROOF LINING,ETC	120.00	1 LA	120.00	✓
27 REMOVE & REFIX REAR BUMPER ASSY,REFLECTORS,TAILLAMPS,REAR BOOT,KNOCK & REPAIR TAILLAMP PANELS,REAR SPARE TYRE COMPARTMENT,CUT,WELD & RENEW REAR PANEL,REAR LH FENDER & REALIGN THE SAME	1,200.00	1 LA	1,200.00	1000
28 PUTTY & RESPRAY ON REAR SPARE TYRE COMPARTMENT,REAR BOTH FENDERS,REAR BOOT,HINGES,REAR PANEL,TAILLAMP PANELS & REAR AFFECTED AREAS	1,000.00	1 LA	1,000.00	900
29 REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	50.00	1 LA	50.00	✓
30 RUSTPROOFING	60.00	1 LA	60.00	✓
			2,550.00	2,550.00
			Total	S\$ 7,787.62
			Add GST @ 7%	545.13
			Total Amount Payable	S\$ 8,332.75

For Cheng Hoe Motor Pte Ltd



 AUTHORIZED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19013335/KVF3N2
Date: 28/08/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29077929QMY
Claimant Vehicle No :	SFC59U	Insured Vehicle No :	SLC551T
Date of Loss:	28/07/2019	Nature of Claim:	TP
			Claim No: 601237

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFC59U	Engine No:	2NR8498242
Make & Model:	TOYOTA COROLLA AXIO, 1.5 G (A)	Chassis No:	NRE1610009537
Reg. Date:	03/03/2016 (Man. Year: 2015)	Odometer:	98666 km
Colour:	Metallic Dark Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Delium 8 mm	Rear Left Side:	LEAO 9 mm
Front Right Side:	Delium 8 mm	Rear Right Side:	LEAO 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,237.62	3,374.25	1,863.37	35.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,550.00	2,130.00	420.00	16.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,787.62	5,504.25	2,283.37	29.32
+ GST 7.00/7.00% (S\$)	545.13	385.30	159.83	29.32
Nett Amount (S\$)	8,332.75	5,889.55	2,443.20	29.32

INSPECTION

Date of Assignment:	29/07/2019	
Date Inspected:	30/07/2019	Inspected At:
		Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Aug 2019)
Parts: 143	TOYOTA COROLLA AXIO 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SFC59U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Bent	530.50 FL	*530.50 FL
2	1	*REAR BUMPER LH REFLECTOR	Serviceable	56.90 FL	*- FL
3	6	*REAR BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
4	1	*REAR BUMPER SIDE RETAINER	Distorted	92.33 FL	*92.33 FL
5	1	*REAR LH FENDER	Repair	1,026.80 FL	*- FL
6	6	*REAR LH FENDER INNER GARNISH CLIPS	Necessary	21.00 FL	*21.00 FL
7	1	*REAR BOOT	Bent	880.10 FL	*880.10 FL
8	1	*REAR BOOT INNER LOCK	Dented	360.24 FL	*360.24 FL
9	1	*REAR BOOT INNER RUBBER	Distorted/Dented	185.20 FL	*185.20 FL
10	1	*REAR BOOT EMBLEM (COROLLA)	Necessary	39.29 FL	*39.29 FL
11	1	*REAR BOOT EMBLEM (AXIO)	Necessary	44.17 FL	*44.17 FL
12	1	*REAR BOOT EMBLEM (G)	Necessary	34.10 FL	*34.10 FL
13	1	*REAR BOOT OUTER MOULDING	Serviceable	301.00 FL	*- FL
14	1	*REAR LH FENDER INNER GARNISH	Deformed	325.50 FL	*325.50 FL
15	2	*TAILLAMPS	N/s Cracked/O/s Dented	852.00 FL	*852.00 FL
16	1	*REAR PANEL	Repair	602.00 FL	*- FL
17	1	*REAR PANEL INNER TOP GARNISH	Distorted	218.00 FL	*218.00 FL
18	4	*TAILLAMP CLIPS	Necessary	18.00 FL	*18.00 FL
19	1	*REAR SPARE TYRE TOP BOARD	Deformed	392.70 FL	*392.70 FL
20	1	*REAR WINDSCREEN GLASS MOULDING	Not Necessary	97.80 FL	*- FL
21	1	*REAR SMART KEY SENSOR	Cracked	138.20 FL	*138.20 FL
22	1	*SET REVERSE SENSOR	Cracked	200.00 FS	*200.00 FS
23	1	*REVERSE CAMERA	Serviceable	280.00 FS	*- FS
24	1	*REAR SPARE TYRE PANEL TOP COAT	Necessary	80.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,796.83	4,412.33
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,559.21	1,038.08
Total Parts (\$\$)	5,237.62	3,374.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	0.00
2	REMOVE & REFIX REAR SEAT,CARPET,GARNISH, TOP ROOF LINING,ETC	New	120.00	120.00
3	REMOVE & REFIX REAR BUMPER ASSY,REFLECTORS,TAILLAMPS,REAR BOOT,KNOCK & REPAIR TAILLAMP PANELS,REAR SPARE TYRE COMPARTMENT,CUT,WELD & RENEW REAR PANEL,REAR LH FENDER & REALIGN THE SAME	New	1,200.00	1,000.00
4	PUTTY & RESPRAY ON REAR SPARE TYRE COMPARTMENT,REAR BOTH FENDERS,REAR BOOT,HINGES,REAR PANEL,TAILLAMP PANELS & REAR AFFECTED AREAS	New	1,000.00	900.00
5	REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	New	50.00	50.00
6	RUSTPROOFING	New	60.00	60.00
Gross Labour Cost (\$\$)			2,550.00	2,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >