

ASS. REC. BY:

REF: CS/PCJ 19013361 / kvf3

Special Instruction: n2

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Sithara

of PCJ

Date/Time: 30.7.2019 2.57p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SL2 9418R

Insured: SHA 9172C

at Workshop m/s Esteem Performance

Tel: 87990066 / 6753 2112

of 385 Sn my have (s)

Jenny 65662112

Policy No:

Claim No: D19004901MFSH

Sum Insured:

Excess:

Make of Veh: (Client's Record)

D.O.A. 27.7.2019

CA / REV / REP. / REV 24 HRS

sup

Date/Time: 30.7.19 3.13p.m

Person Contacted: Carmen / Jenny

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SL2 9418R -
	SHA 9172C - CC3/CTJ 17001782 / 410A 312 DOA - 24/01/2017
13/8/19	Email preli revised to FCJ
12/9	88516.48 Confirm (Real 9728.20, 53%)

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s Estuam

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 875k

IDAC Accident Report: _____ Consistent? : Yes or No


GIA / PR Soon: _____ Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: 1-B-1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT



Veh No: SL79418R Yr Regn: 05,18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or Wagon

Make: Honda Shuttle c.c. 1496

Colour: M. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 151884 T/Radio: Insured / Std / NI / NA

Eng/No: _____ C/No: GPF 1207470

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoper / Jammed / Leaked / Burnt or

Brake: Inoper / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Falken 185/60R15 R: Nexen

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 27/7/19 D.O.I. 30/7/19

Survey held at _____ Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Rear O/S & PA

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 13 SEP 2019

Date / Time	Action / Instruction
<u>1</u>	<u>File pass to</u>

Date/Time, File Pass to? : Prell. Report : Final Report

1) _____
2) 13/9 - typist

Report Format: aws
Lump Sum / I.B.I.: (\$) 8516.48

Days Of Repair: 12

Resurvey No. of Trip: 2

- Add Fee: : Site Insp (\$)
- : Interview (\$)
- : Tech Invs (\$)
- : Weekend (\$)

Survey Fee:

Transportation: _____

S - RS. \$ _____

Fees: BSP

Others: Blalk

TOTAL

<u>170+195</u>
<u>50</u>
<u>50+50</u>
<u>66</u>
<u>581</u>

13x15 = 195



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19004907MFSH

Our ref: CS/FCI19013361/Kvf3

Date : 13/8/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLZ 9418R


We thank for your instruction on 30/7/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 30/7/2019 at the premises of M/s ESTEEM PERFORMANCE and have the following to report:-

Workshop Estimate Amount	: S\$21,822.58
Revised Estimate Amount	: S\$8,169.35
"Check" Items Amount	: S\$5,361.90
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear o/s portion and front portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	29-07-2019	Our Ref No. D19004907MFSH
Accident Date	27-07-2019	Claim Type. Third Party
Insured Vehicle	SHA9172C	Third Party Vehicle. SLZ9418R
Survey Location	385 SIN MING DRIVE (S) 575718 (INSIDE VICOM)	
Contact Person.	CARMEN LIM	
Contact No.	0/ 87990066	Fax No. 62593326
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ESTEEM PERFORMANCE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 13 August 2019 11:05 AM
To: 'CWS Motor Claims'; SUR
Cc: 'Sithara'
Subject: RE: SURVEY ASSESSMENT - D19004907MFSH/1-SLZ 9418R
Attachments: SLZ 9418R PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLZ 9418R
Date of survey: 30/7/2019
Number of days : 14 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Tuesday, 30 July 2019 3:13 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19004907MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 30 July, 2019 2:57 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004907MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	651D
Vehicle Details	
Vehicle No.:	SLZ9418R
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Jul 2019
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE HYBRID 1.5 AUTO
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	LEB6549193
Chassis No.:	GP71207470
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$22,935.00
Original Registration Date:	23 May 2018
First Registration Date:	23 May 2018
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 May 2028
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	22 May 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$37,010.00
COE Rebate Amount:	\$32,602.00
Total Rebate Amount:	\$36,352.00

The information contained herein is correct as at 31 Jul 2019

OK

MS First
Cap
LKK



ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Not Authorized
Repair By paint

Repair Estimates

SLZ 9418 R

Parts	(a) Cost / List Price Items	\$	21,850.10	22,805.85
	Plus/Less 25%	\$	5,462.53	
	Total of Cost / List	\$	<u>16,387.58</u>	18,244.68
	(b) Nett Price Items			
	Less			
	Total of Nett Item			
	(c) Special Nett Items	\$	145.00	
Total Parts Cost		\$	<u>16,532.58</u>	
Labour		\$	<u>5,290.00</u>	
Total		\$	<u>21,822.58</u>	23,674.68

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplemental parts must be insured and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 30/7/19 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 14 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Ke Date: 30/7/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLZ 9418 R
 Make & Model : HONDA SHUTTLE
 Chassis No : GP71207470

Submit By : Carmen Lim
 Year Manufacture : 2017
 Engine No. : _____
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen moulding	1	\$120.00		✓
2	Rear windscreen sealant	1	\$50.00	S.N	4012
3	Rear bumper	1	\$1,150.60		✓
4	Rear bumper clip	10	\$35.00		✓
5	Rear bumper side retainer LH	1	\$26.50		X
6	Rear bumper side retainer RH	1	\$26.50		✓
7	Rear bumper bracket LH	1	\$48.70		? ✓
8	Rear bumper bracket RH	1	\$48.70		? X
9	Rear bumper sponge	2	\$179.00		? X
10	Rear bumper reflector LH	1	\$45.00		X
11	Rear bumper reflector RH	1	\$45.00		? ✓
12	Rear bumper reflector garnish LH	1	\$45.00		X
13	Rear bumper reflector garnish RH	1	\$45.00		✓
14	Tail door	1	\$1,193.00		✓
15	Tail door lock	1	\$157.10		X
16	Tail door emblem	1	\$38.00		✓
17	Wording "SHUTTLE"	1	\$55.00		✓
18	Wording "HYBRID"	1	\$80.10		✓
19	Tail door chrome	1	\$383.10		X
20	Tail door trim	1	\$320.00		X
21	Tail door trim clip	10	\$35.00		X
22	Taildoor reflector RH	1	\$395.00		X
23	Tail end panel	1	\$560.80		? X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : SLZ 9418 R
 Make & Model : HONDA SHUTTLE
 Chassis No : GP71207470

Submit By : Carmen Lim
 Year Manufacture : 2017
 Engine No. : _____

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Tail end panel garnish <i>Pr</i>	1	\$155.50		X
25	Tail end panel garnish clip <i>rr</i>	10	\$35.00		X
26	Boot weatherstrip	1	\$168.50		? X
27	Tail lamp RH <i>Pr</i>	1	\$520.50		X
28	Spare tyre well panel	1	\$956.00		? X
29	Spare tyre board <i>Pr</i>	1	\$655.00		X
30	Gargo Box	1	\$295.00		? X
31	Tail door inner pocket <i>Pr</i>	1	\$19.50		X
32	RH rear fender <i>Pr</i>	1	\$1,010.90		✓ X
33	RH rear fender glass sealant <i>Pr</i>	1	\$50.00	S.N	Pr
34	Bonnet <i>Pr</i>	1	\$920.80		✓
35	Bonnet lock	1	\$135.00		? X
36	Bonnet hinge LH <i>R</i>	1	\$45.00		X
37	Bonnet hinge RH <i>R</i>	1	\$45.00		X
38	Headlamp LH <i>Pr</i>	1	\$2,250.00		X
39	Headlamp RH	1	\$2,250.00		? X
40	Headlamp lower panel LH <i>R</i>	1	\$48.00		X
41	Headlamp lower panel RH <i>R</i>	1	\$48.00		X
42	Front grille <i>C</i>	1	\$395.00		? X
43	Front grille chrome <i>CM</i>	1	\$362.50		✓
44	Front grille emblem <i>Pr</i>	1	\$23.40		✓
45	Front grille chrome - lower	1	\$250.70		? X
46	Front support panel (complete) <i>R</i>	1	\$785.00		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : SLZ 9418 R
 Make & Model : HONDA SHUTTLE
 Chassis No : GP71207470

Submit By : Carmen Lim
 Year Manufacture : 2017
 Engine No. : _____

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	Front support panel top garnish <i>Sn</i>	1	\$58.20		X
48	Front support panel top garnish clip <i>nn</i>	10	\$35.00		X
49	Condenser	1	\$985.00		? X
50	Condenser fan motor	1	\$330.00		? X
51	Condenser fan blade	1	\$78.00		? X
52	Condenser fan cowling <i>Sn</i>	1	\$121.90		X
53	Radiator <i>Sn</i>	1	\$1,540.40		X
54	Radiator fan motor <i>Sn</i>	1	\$329.80		X
55	Radiator fan blade <i>Sn</i>	1	\$78.00		X
56	Radiator fan cowling <i>Sn</i>	1	\$115.00		X
57	Coolant <i>nn</i>	1	\$48.60		X
58	Front bumper <i>Bu</i>	1	\$1,050.00		✓
59	Front bumper clip <i>nn</i>	1	\$35.00		✓
60	Front bumper reinforcement	1	\$297.00		? X
61	Front bumper side retainer LH	1	\$25.40		? X
62	Front bumper side retainer RH	1	\$25.40		? X
63	Front bumper bracket LH	1	\$38.00		? X
64	Front bumper bracket RH	1	\$38.00		? X
65	Front bumper tow cover <i>Sn</i>	1	\$35.00		X
66	Front bumper lower grille <i>nd</i>	1	\$180.00		✓
67	Front number plate <i>nd</i>	1	\$45.00	S.N	✓
68					
69					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : SLZ 9418 R Submit By : Carmen Lim
Make & Model : HONDA SHUTTLE Year of Manufacture : 2017

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (TAILDOOR,REAR BUMPER,END PANEL,SPARE TYRE WELL PANEL,RHR FENDER,FRONT BUMPER,BONNET, SUPPORT PANEL)	\$2,200.00	1500
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (TAILDOOR,REAR BUMPER,END PANEL,SPARE TYRE WELL PANEL,RHR FENDER,FRONT BUMPER,BONNET, SUPPORT PANEL)	\$1,800.00	1200
3	To check wiring & focus headlamp	\$50.00	40
4	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	100
5	To remove & refit rear windscreen.	\$120.00	✓
6	To tuff coat.	\$150.00	120
7	To transfer boot mechanism to new boot	\$150.00	60
8	To conduct water leakage tests to ensure proper air and sealing	\$120.00	20
9	To remove & refit radiator, condenser to assist work load, to top up A/C gas.	~ \$150.00	✓

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

MS First
Cap.
LKK



ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Not authorized
Achieve B4 paint

Supplementary:-

- RHR fuder inner trim board.
- RHR fuder inner trim clip.

Repair Estimates

SLZ 9418 R

Parts	(a) Cost / List Price Items	\$ <u>6364.35</u>	21,850.10
	Plus/Less ²⁰ 25%	\$ <u>1272.87</u>	5,462.53
	Total of Cost / List	\$ <u>5091.48</u>	16,387.58
	(b) Nett Price Items	_____	_____
	Less	_____	_____
	Total of Nett Item	_____	_____
	(c) Special Nett Items	\$ <u>125.00</u>	145.00
	Total Parts Cost	\$ <u>5216.48</u>	16,532.58
	Labour	\$ <u>3300.00</u>	5,290.00
	Total	\$ <u>8516.48</u>	21,822.58

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 30/7/19 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 14 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Se Date: 30/7/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : _____
Make & Model : SLZ 9418 R
 : HONDA SHUTTLE
Chassis No : GP71207470

Submit By : _____
Year Manufacture : _____
Engine No. : _____
Cost / List

Carmen Lim
2017

i/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen moulding	1	\$120.00		✓
2	Rear windscreen sealant	1	\$50.00	S.N	4052
3	Rear bumper	1	\$1,150.60		✓
4	Rear bumper clip	10	\$35.00		✓
5	Rear bumper side retainer LH	1	\$26.50		X
6	Rear bumper side retainer RH	1	\$26.50		✓
7	Rear bumper bracket LH	1	\$48.70		X
8	Rear bumper bracket RH	1	\$48.70		X
9	Rear bumper sponge	2	\$179.00		X
10	Rear bumper reflector LH	1	\$45.00		X
11	Rear bumper reflector RH	1	\$45.00		X
12	Rear bumper reflector garnish LH	1	\$45.00		X
13	Rear bumper reflector garnish RH	1	\$45.00		✓
14	Tail door	1	\$1,193.00		X
15	Tail door lock	1	\$157.10		X
16	Tail door emblem	1	\$38.00		✓
17	Wording "SHUTTLE"	1	\$55.00		✓
18	Wording "HYBRID"	1	\$80.10		✓
19	Tail door chrome	1	\$383.10		X
20	Tail door trim	1	\$320.00		X
21	Tail door trim clip	10	\$35.00		X
22	Taildoor reflector RH	1	\$395.00		X
23	Tail end panel	1	\$560.80		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

2856.90
40 SN

Spare Parts

Vehicle No. : _____
 Make & Model : HONDA SHUTTLE
 Chassis No : GP71207470

SLZ 9418 R

Submit By : _____
 Year Manufacture : 2017
 Engine No. : _____

Carmen Lim

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Tail end panel garnish	1	\$155.50		X
25	Tail end panel garnish clip	10	\$35.00		X
26	Boot weatherstrip	1	\$168.50		X
27	Tail lamp RH	1	\$520.50		X
28	Spare tyre well panel	1	\$956.00		X
29	Spare tyre board	1	\$655.00		X
30	Gargo Box	1	\$295.00		X
31	Tail door inner pocket	1	\$19.50		X
32	RH rear fender	1	\$1,010.90		X
33	RH rear fender glass sealant	1	\$50.00	S.N	X
34	Bonnet	1	\$920.80		X
35	Bonnet lock	1	\$135.00		X
36	Bonnet hinge LH	1	\$45.00		X
37	Bonnet hinge RH	1	\$45.00		X
38	Headlamp LH	1	\$2,250.00		X
39	Headlamp RH	1	\$2,250.00		X
40	Headlamp lower panel LH	1	\$48.00		X
41	Headlamp lower panel RH	1	\$48.00		X
42	Front grille	1	\$395.00		X
43	Front grille chrome	1	\$362.50		X
44	Front grille emblem	1	\$23.40		X
45	Front grille chrome - lower	1	\$250.70		X
46	Front support panel (complete)	1	\$785.00		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

1306-70
 405-N

Spare Parts

Vehicle No. : SLZ 9418 R
 Make & Model : HONDA SHUTTLE
 Chassis No : GP71207470

Submit By : Carmen Lim
 Year Manufacture : 2017
 Engine No. : _____
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	Front support panel top garnish	1	\$58.20		X
48	Front support panel top garnish clip	10	\$35.00		X
49	Condenser	1	\$985.00		X
50	Condenser fan motor	1	\$330.00		X
51	Condenser fan blade	1	\$78.00		X
52	Condenser fan cowling	1	\$121.90		X
53	Radiator	1	\$1,540.40		X
54	Radiator fan motor	1	\$329.80		X
55	Radiator fan blade	1	\$78.00		X
56	Radiator fan cowling	1	\$115.00		X
57	Coolant	1	\$48.60		X
58	Front bumper	1	\$1,050.00		✓
59	Front bumper clip	1	\$35.00		✓
60	Front bumper reinforcement	1	\$297.00		X
61	Front bumper side retainer LH	1	\$25.40		X
62	Front bumper side retainer RH	1	\$25.40		X
63	Front bumper bracket LH	1	\$38.00		X
64	Front bumper bracket RH	1	\$38.00		X
65	Front bumper tow cover	1	\$35.00		X
66	Front bumper lower grille	1	\$180.00		✓
67	Front number plate	1	\$45.00	S.N	✓
68					
69					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

1265

455N



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : SLZ 9418 R Submit By : Carmen Lim
Make & Model : HONDA SHUTTLE Year of Manufacture : 2017

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (TAILDOOR,REAR BUMPER,END PANEL,SPARE TYRE WELL PANEL,RHR FENDER,FRONT BUMPER,BONNET, SUPPORT PANEL)	\$2,200.00	1500
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (TAILDOOR,REAR BUMPER,END PANEL,SPARE TYRE WELL PANEL,RHR FENDER,FRONT BUMPER,BONNET, SUPPORT PANEL)	\$1,800.00	1200
3	To check wiring & focus headlamp	\$50.00	40
4	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	100
5	To remove & refit rear windscreen.	\$120.00	✓
6	To tuff coat.	\$150.00	120
7	To transfer boot mechanism to new boot	\$150.00	60
8	To conduct water leakage tests to ensure proper air and sealing	\$120.00	20
9	To remove & refit radiator, condenser to assist work load, to top up A/C gas.	\$150.00	100

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

ESTEEM PERFORMANCE PTE LTD

BLK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-259 SINGAPORE 569536

Tel:64841221 Fax:64847829

Spare Parts

Vehicle No. :
Make & Model :
Chassis No :

SLZ 9418 R

HONDA SHUTTLE

GP71207470

Submit By :
Year Manufacture :
Engine No. :
Cost / List

CARMEN LIM

2017

Supplementary

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear fender inner trim board RH <i>Return</i>	1	\$706.20	✓	✓
2	Rear fender inner trim board cover RH <i>Dis</i>	1	\$176.55	✓	✓
3	Rear fender inner trim board clip RH <i>na</i>	10	\$35.00		✓
4	Air Duct <i>na</i>	1	\$38.00	✓	✓
5		1			
6		1			
7		1			
8		1			
9		1			
10		1			
11		1			
12		1			
13		1			
14		1			
15		1			
16		1			
17		1			
18		1			
19		1			
20		4			
21		1			
22		1			
23		1			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

955.75



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19013361/Kvf3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 17-09-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 9172C	Veh. Inspected	SLZ 9418R
Policy No.		Coverage (\$)	0.00
Claim No.	D19004907MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	30/07/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GP71207470	Colour	METALLIC GREY
Odometer	151884	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	FALKEN	6 mm
L/H Front Tyre	185/60 R15	FALKEN	6 mm
R/H Rear Tyre	185/60 R15	NEXEN	6 mm
L/H Rear Tyre	185/60 R15	NEXEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S AND FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/07/2019	Inspection Date	30/07/2019
Survey held at	385 SIN MING DRIVE SINGAPORE 575718		
Repairer	ESTEEM PERFORMANCE PTE LTD		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 9418R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR WINDSCREEN MOULDING	NECESSARY	120.00	120.00
1	REAR BUMPER	BENT	1,150.60	1,150.60
10	REAR BUMPER CLIP	NECESSARY	35.00	35.00
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	26.50	-
1	REAR BUMPER SIDE RETAINER RH	DISTORTED	26.50	26.50
1	REAR BUMPER BRACKET LH	TO REPAIR SEE LABOUR	48.70	-
1	REAR BUMPER BRACKET RH	DISTORTED	48.70	48.70
2	REAR BUMPER SPONGE	SERVICEABLE	179.00	-
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	45.00	-
1	REAR BUMPER REFLECTOR RH	CRACKED	45.00	45.00
1	REAR BUMPER REFLECTOR GARNISH LH	SERVICEABLE	45.00	-
1	REAR BUMPER REFLECTOR GARNISH RH	DENTED	45.00	45.00
1	TAIL DOOR	BENT	1,193.00	1,193.00
1	TAIL DOOR LOCK	TO REPAIR SEE LABOUR	157.10	-
1	TAIL DOOR EMBLEM	NECESSARY	38.00	38.00
1	WORDING "SHUTTLE"	NECESSARY	55.00	55.00
1	WORDING "HYBRID"	NECESSARY	80.10	80.10
1	TAIL DOOR CHROME	SERVICEABLE	383.10	-
1	TAIL DOOR TRIM	SERVICEABLE	320.00	-
10	TAIL DOOR TRIM CLIP	NOT NECESSARY	35.00	-
1	TAILDOOR REFLECTOR RH	SERVICEABLE	395.00	-
1	TAIL END PANEL	TO REPAIR SEE LABOUR	560.80	-
1	TAIL END PANEL GARNISH	SERVICEABLE	155.50	-
10	TAIL END PANEL GARNISH CLIP	NOT NECESSARY	35.00	-
1	BOOT WEATHERSTRIP	SERVICEABLE	168.50	-
1	TAIL LAMP RH	SERVICEABLE	520.50	-
1	SPARE TRYE WELL PANEL	TO REPAIR SEE LABOUR	956.00	-
1	SPARE TRYE BOARD	SERVICEABLE	655.00	-

Report Ref No. CS/FCI19013361/Kvf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	GARGO BOX	SERVICEABLE	295.00	-
1	TAIL DOOR INNER POCKET	SERVICEABLE	19.50	-
1	RH REAR FENDER	TO REPAIR SEE LABOUR	1,010.90	-
1	BONNET	BENT	920.80	920.80
1	BONNET LOCK	TO REPAIR SEE LABOUR	135.00	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	45.00	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	45.00	-
1	HEADLAMP LH	SERVICEABLE	2,250.00	-
1	HEADLAMP RH	SERVICEABLE	2,250.00	-
1	HEADLAMP LOWER PANEL LH	TO REPAIR SEE LABOUR	48.00	-
1	HEADLAMP LOWER PANEL RH	TO REPAIR SEE LABOUR	48.00	-
1	FRONT GRILLE	SERVICEABLE	395.00	-
1	FRONT GRILLE CHROME	CRACKED	362.50	362.50
1	FRONT GRILLE EMBLEM	NECESSARY	23.40	23.40
1	FRONT GRILLE CHROME-LOWER	SERVICEABLE	250.70	-
1	FRONT SUPPORT PANEL (COMPLETE)	TO REPAIR SEE LABOUR	785.00	-
1	FRONT SUPPORT PANEL TOP GARNISH	SERVICEABLE	58.20	-
10	FRONT SUPPORT PANEL TOP GARNISH CLIP	NOT NECESSARY	35.00	-
1	CONDENSER	SERVICEABLE	985.00	-
1	CONDENSER FAN MOTOR	SERVICEABLE	330.00	-
1	CONDENSER FAN BLADE	SERVICEABLE	78.00	-
1	CONDENSER FAN COWLING	SERVICEABLE	121.90	-
1	RADIATOR	SERVICEABLE	1,540.40	-
1	RADIATOR FAN MOTOR	SERVICEABLE	329.80	-
1	RADIATOR FAN BLADE	SERVICEABLE	78.00	-
1	RADIATOR FAN COWLING	SERVICEABLE	115.00	-
1	COOLANT	NOT NECESSARY	48.60	-
1	FRONT BUMPER	BUCKLED	1,050.00	1,050.00

Report Ref No. CS/FC119013361/Kvf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER CLIP	NECESSARY	35.00	35.00
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	297.00	-
1	FRONT BUMPER SIDE RETAINER LH	SERVICEABLE	25.40	-
1	FRONT BUMPER SIDE RETAINER RH	SERVICEABLE	25.40	-
1	FRONT BUMPER BRACKET LH	TO REPAIR SEE LABOUR	38.00	-
1	FRONT BUMPER BRACKET RH	TO REPAIR SEE LABOUR	38.00	-
1	FRONT BUMPER TOW COVER	SERVICEABLE	35.00	-
1	FRONT BUMPER LOWER GRILLE	DISTORTED	180.00	180.00
1	REAR FENDER INNER TRIM BOARD RH (ADDITIONAL)	DEFORMED	706.20	706.20
1	REAR FENDER INNER TRIM BOARD COVER RH (ADDITIONAL)	DISTORTED	176.55	176.55
10	REAR FENDER INNER TRIM BOARD CLIP RH (ADDITIONAL)	NECESSARY	35.00	35.00
1	AIR DUCT (ADDITIONAL)	DENTED	38.00	38.00
	LESS 20% DISCOUNT		-4,561.17	-1,272.87
			18,244.68	5,091.48
	SPECIAL NETT ITEMS			
1	RH REAR FENDER GLASS SEALANT (SN)	NECESSARY	50.00	40.00
1	FRONT NUMBER PLATE (SN)	DENTED	45.00	45.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
			145.00	125.00
	LABOUR			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (TAILDOOR, REAR BUMPER, END PANEL, SPARE TYRE WELL PANEL, RHR FENDER, FRONT BUMPER, BONNET, SUPPORT PANEL). INCLUSIVE OF THE REPAIR OF REAR BUMPER BRACKET LH, TAIL DOOR LOCK, TAIL END PANEL, SPARE TYRE WELL PANEL, RH REAR FENDER, BONNET LOCK, BONNET HINGE LH, BONNET HINGE RH, HEADLAMP LOWER PANEL LH, HEADLAMP LOWER PANEL RH, FRONT SUPPORT PANEL (COMPLETE), FRONT BUMPER REINFORCEMENT, FRONT BUMPER BRACKET LH AND FRONT BUMPER BRACKET RH.		2,200.00	1,500.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (TAILDOOR, REAR BUMPER, END PANEL, SPARE TYRE WELL PANEL, RHR FENDER, FRONT BUMPER, BONNET, SUPPORT PANEL).		1,800.00	1,200.00
	TO CHECK WIRING & FOCUS HEADLAMP.		50.00	40.00
	TO REMOVE & REFIT SPARE TYRE, SPARE TYRE BOARD, CARPET TRIM TO ASSIST WORK LOAD.		150.00	100.00
	TO REMOVE & REFIT REAR WINDSCREEN.		120.00	120.00
	TO TUFF COAT.		150.00	120.00
	TO TRANSFER BOOT MECHANISM TO NEW BOOT.		150.00	60.00
	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.		120.00	20.00
	TO REMOVE & REFIT RADIATOR, CONDENSER TO ASSIST WORK LOAD, TO TOP UP A/C GAS.	NOT NECESSARY	150.00	-
	TO REMOVE & REFIT INNER SEAT & UPHOLSTERY TO ASSIST WORK LOAD.		250.00	80.00
	TO REMOVE & REFIT RH REAR FENDER FLASS TO ASSIST WORK LOAD.		150.00	60.00
			5,290.00	3,300.00
GRAND TOTAL			23,679.68	8,516.48
RECOMMENDED COST OF REPAIRS				8,516.48

Report Ref No. CS/FCI19013361/Kvf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.