

20/07/2017

ASS. REC. BY:

REF: 083 / 17014601 / 61037

Special Instruction:

Survivor:

From Person: Melimen Norsiah

ASSIGNMENT (Office)

Estimated Cost:

of

All

Date/Time: 30/7/2019

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLJ 4898 X

Insured:

G8D 8006L

at Workshop m/s

Twinclur Automotive

Tel:

6842 0051

of

2 Kaki Bukit Ave 2 # 01-17

Policy No:

Sum Insured:

Claim No:

808/919326SG

Make of Veh:

Excess:

(Client's Record)

D.O.A.

26072017

CA / REV / REP. / REV 24 HRS Wp

Date/Time: 280720171005am

Person Contacted:

Hui Xin

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SLJ 4898 X - NA / 17014601 / 13</u>
	<u>G8D 8006L - X</u>
	<u>Dismantle Part: 31072017</u>
	<u>After repair 04082017</u>

31/19 Submit LS \$ 6650, 7 Days.
(Red 14,350, 6870)

31/9/2019

RECEIVED 05 SEP 2019

Richard

REF: CS3/AIG/17014601/36

DAR

ASSIGNMENT

From _____ Date _____
 Estimated Cost _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No _____
 at Workshop mis _____
 of _____
 Insured _____
 Policy No _____
 Claims No _____
 Sum Insured _____ Excess _____
 (Client's Record)
 Make of Veh _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal or Market Value _____

IDAC Accident Report: Consistent? Yes or No
 G/A PR Seen: Consistent? Yes or No
 Est. Repairs: 8 days Res. Yes or No
 Lump Sum: % 3 Val. Yes or No

CA / REV / REP. / 24 HRS

Date _____ Person Contacted _____

Vehicle: IN / OUT

Veh No **SLJ 4598X** Yr Page **13/12 2016**
 Type M.Car / M.Cycle / Bus ☒ Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make **TOYOTA VELLFIRE** C/C **2494**
 Colour **WHITE** A/C Insured / Std / NI / NA
 Sp Reading **8653** T-Ratio Insured / Std / NI / NA
 Eng No _____
 C/No **JTNGF3DH 708007166**
 Gen Cond ☒ Good / Fair / Poor / Burnt
 Steering ☒ Good / Jammed / Leaked / Burnt or
 Brake ☒ Good / Jammed / Leaked / Burnt or
 Modi Nil ☒ S/Rim / STD A/Rim or
 Tyre Size F: **235/50R18**
 R: " " "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
☒ TOYO / YOKO or

Front		Rear	
R/Bal	6 mm	R/Bal	6 mm
L/Bal	6 mm	L/Bal	6 mm
D.O.A	26/7 17:55	D.O.A	28/7 12:50pm
Survey held at N51			
Des. of Damages Frt <input checked="" type="checkbox"/> Rear <input checked="" type="checkbox"/> O/S / N/S / U/C / Rooftop or			

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Date/Time File Pass to?

13/12/2017

Date/Time File Return to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

3 - 3 - 3 - 3

1 - 1 - 1 - 1

1 - 1 - 1 - 1

1 - 1 - 1 - 1

Report Format: **PRS**

Lump Sum / I.B.I: (\$)

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Insp (\$)
☐ Weekend (\$)

[Signature]

13/12/2017

Nivitha (LKK Auto)

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Tuesday, 30 July 2019 10:41 AM
To: assignments
Subject: FW: Claim No: 8081919326SG-Paper Survey
Attachments: 8081919326SG_28_08_2018_RULINGS_JUDGMENTS_SENTENCES_B37934 -001.pdf

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Md Noor, Norsiah <Norsiah.MdNoor@aig.com>
Sent: Tuesday, 30 July 2019 10:29 AM
To: SUR <sur@lkkauto.com>
Subject: Claim No: 8081919326SG-Paper Survey

Dear Team,

Refer to the above.

Kindly assist to conduct paper adjustment as attached.

Thank you

Kind regards
Norsiah

Norsiah Md Noor
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419-1606
Norsiah.MdNoor@aig.com | www.aig.com.sg



Follow us:



IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	436Z
Vehicle Details	
Vehicle No.:	SLJ4598X
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VELLFIRE 2.5 CVT S/R
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	2ARH792943
Chassis No.:	JTNGF3DH708007166
Maximum Power Output:	134.0 kW (179 bhp)
Open Market Value:	\$45,431.00
Original Registration Date:	13 Dec 2016
First Registration Date:	13 Dec 2016
Transfer Count:	0
Actual ARF Paid:	\$55,604.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Dec 2026
PARF Rebate Amount:	\$41,703.00
Intended COE Rebate Details	
COE Expiry Date:	12 Dec 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$54,901.00
COE Rebate Amount:	\$39,038.00
Total Rebate Amount:	\$80,741.00

The information contained herein is correct as at 30 Jul 2019

OK

Report No: 0211-18-TCA

23 April 2018

ACCIDENT VEHICLE SURVEY REPORT

Singapore Yongan Pharmaceutical Factory Pte Ltd
c/o Twincar Automotive Pte Ltd
2 Kaki Bukit Ave 2 #01-17
Kaki Bukit Auto Hub
Singapore 417921

VEHICLE INFORMATION:

Vehicle Reg No.:	SLJ4598X	Odometer:	8653km
Make & Model:	Toyota Wellfire 2.5 CVT	Colour:	White
Chassis number:	JTNGF3DH708007166	Date of accident:	26/07/2017
Year of Regn.:	13/12/2016	Date inspected:	28/07/2017
Repairer at:	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921	Date inspected (After Repair):	04/08/2017

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	5mm/Toyo	5mm/Toyo	235/50R18
Rear:	5mm/Toyo	5mm/Toyo	235/50R18

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
REAR BUMPER	1	squashed	1,776.30	1,776.30 / 691.3
REAR BUMPER BRACKET L/R	2	bent	220.80	220.80 X
REAR BUMPER CENTRE REVERSE SENSOR COVER L/R	2	necessary	36.20	36.20 X SVC
REAR BUMPER CENTRE REVERSE SENSOR HOLDER L/R	2	necessary	38.50	38.50 X
REAR BUMPER CENTRE REVERSE SENSOR L/R	2	shorted	1,018.30	1,018.30 / 100(SN)
REAR BUMPER CORNER BRACKET L/R	2	bent	206.40	206.40 X
REAR BUMPER CORNER REVERSE SENSOR COVER L/R	2	necessary	36.20	36.20 X SVC
REAR BUMPER CORNER REVERSE SENSOR HOLDER L/R	2	necessary	38.50	38.50 X
REAR BUMPER CORNER REVERSE SENSOR L/R	2	shorted	1,018.20	1,018.20 / 100(SN)
REAR BUMPER LH LOWER COVER	1	reuse	145.10	0.00 SVC
REAR BUMPER REFLECTOR L/R LH / OPA RH X NN	1	fractured	196.20	196.20 67.6
REAR BUMPER REVERSE SENSOR WIRE HARNESS	1	snapped	110.35	110.35 X SVC
REAR BUMPER RH LOWER COVER	1	reuse	145.10	0.00 SVC
REAR BUMPER SIDE RETAINER L/R LH - Cut RH X NN	2	necessary	220.70	220.70 74.43
REAR BUMPER TOW HOOK COVER L/R	2	warped	78.90	78.90 35.9
REAR END PANEL	1	buckled	780.20	780.20 /
REAR END PANEL ANTENNA SENSOR	1	shorted	124.10	124.10 X SVC
REAR END PANEL BUZZLE SENSOR	1	shorted	509.10	509.10 X
REAR END PANEL INNER TOP GARNISH	1	fractured	212.10	212.10 /
REAR END PANEL SIDE RUBBER STOPPER L/R	2	deformed	132.20	132.20 X SVC
REAR FENDER INNER UPHOLSTERY TRIM GARNISH L/R LH - DE RH X NN	2	deformed	1,658.40	1,658.40 / 829.2
REAR FLOOR PANEL	1	repair	978.40	0.00
REAR FLOOR PANEL TRIM CARPET	1	deformed	890.10	890.10 / 220
REAR LH FENDER	1	repair	806.00	0.00
REAR LH FENDER AIR VENT	1	warped	100.40	100.40 X SVC
REAR LH FENDER GLASS INNER TRIM GARNISH	1	reuse	399.10	0.00 SVC
REAR LH FENDER GLASS MOULDING	1	reuse	408.10	0.00
REAR LH SAFETY BELT	1	jammed	780.10	780.10 X
REAR NUMBER PLATE LAMP L/R	2	fractured	808.70	808.70 X
REAR SPARE TYRE RETAINER LOCK	1	bent	45.90	45.90 X SVC
REAR SPARE TYRE TOP SPONGE L/R	2	deformed	220.70	220.70 X
REAR SPARE TYRE TRAY GARNISH	1	deformed	109.10	109.10 X
REAR TAILGATE	1	buckled	1,956.30	1,956.30 /
REAR TAILGATE 'VELLFIRE' EMBLEM	1	necessary	110.35	110.35 / 82.5
REAR TAILGATE AUTO CLOSE MOTOR UNIT	1	shorted	1,089.10	1,089.10 X SVC
REAR TAILGATE AUTO CLOSE MOTOR UNIT ROD	1	repair	236.95	0.00
REAR TAILGATE AUTO CLOSE MOTOR UNIT ROD BRACKET	1	repair	124.10	0.00
REAR TAILGATE CHROME MOULDING	1	necessary	210.35	210.35 X SVC
REAR TAILGATE CHROME MOULDING 'LOGO' EMBLEM	1	necessary	65.10	65.10 X SVC
REAR TAILGATE CHROME MOULDING GARNISH	1	fractured	1,089.45	1,089.45 / 725.7
REAR TAILGATE CLOSE BUTTON SWITCH	1	shorted	202.10	202.10 X
REAR TAILGATE DAMPER L/R	2	bent	562.80	562.80 X SVC

REAR TAILGATE HINGES L/R	2	bent	138.40	138.40	X SVC
REAR TAILGATE INNER DAMPER MOUNTING	1	reuse	45.90	0.00	SVC
REAR TAILGATE INNER PULL GARNISH	1	reuse	110.35	0.00	
REAR TAILGATE MECHANISM LOCK	1	bent	509.10	509.10	
REAR TAILGATE MECHANISM LOCK MOTOR	1	shorted	550.45	550.45	X
REAR TAILGATE MECHANISM LOCK STRIKER	1	bent	45.10	45.10	X SVC
REAR TAILGATE OPENER BUTTON SENSOR	1	shorted	509.40	509.40	X SVC
REAR TAILGATE REFLECTOR LAMP BACK RUBBER L/R	2	necessary	80.20	80.20	X
REAR TAILGATE REFLECTOR LAMP L/R <i>LH - CRA RH X NN</i>	2	fractured	808.20	808.20	X 4.1
REAR TAILGATE RUBBER GUIDE STOPPER 'LOWER' L/R	2	deformed	266.20	266.20	X
REAR TAILGATE RUBBER GUIDE STOPPER 'TOP' L/R	2	deformed	220.50	220.50	X SVC
REAR TAILGATE SIDE RUBBER STOPPER L/R	2	deformed	220.50	220.50	X
REAR TAILGATE SIDE SENSOR L/R	2	shorted	1,198.20	1,198.20	X
REAR TAILGATE UPHOLSTERY SIDE TRIM GARNISH L/R	2	fractured	450.40	450.40	X
REAR TAILGATE UPHOLSTERY TOP TRIM GARNISH	1	fractured	303.10	303.10	X
REAR TAILGATE UPHOLSTERY TRIM GARNISH	1	fractured	404.10	404.10	X
REAR TAILGATE WEATHERSTRIP	1	deformed	395.45	395.45	X 357
REAR TAILGATE WINDSCREEN MOULDING	1	necessary	210.10	210.10	X 156.6
REAR TAILLAMP BACK RUBBER GASKET L/R	2	necessary	90.20	90.20	X SVC
REAR TAILLAMP L/R <i>LH - CRA RH X NN</i>	2	fractured	870.20	870.20	X 35.1
REAR TAILLAMP LH INNER PANEL	1	buckled	110.10	110.10	X SVC
REAR TAILLAMP LH OUTER PANEL	1	buckled	405.10	405.10	X SVC
REAR TAILLAMP LOWER GARNISH L/R	2	L-deformed	420.70	210.35	
REAR THIRD SEAT RAIL BRACKET CENTRE GARNISH	1	deformed	123.95	123.95	X SVC
REAR THIRD SEAT RAIL BRACKET GARNISH L/R	2	deformed	220.30	220.30	X SVC
REAR THIRD SEAT RAIL BRACKET L/R	2	repair	246.20	0.00	
Subtotal before discount			S\$ 28,847.45	S\$ 24,991.80	7747.48
Percentage discount 25% and 25%			S\$ 7,211.86	S\$ 6,247.95	5810.61
Sub-total 1			S\$ 21,635.59	S\$ 18,743.85	
REAR BUMPER CLIPS - SET	1	necessary	50.00	50.00	30
REAR BUMPER LOWER COVER CLIPS - SET	1	necessary	50.00	50.00	X NN
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	necessary	40.00	40.00	20
REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R - SET	2	necessary	100.00	100.00	60
REAR FLOOR PANEL INSULATOR MAT	1	necessary	500.00	350.00	X SVC
REAR FLOOR PANEL TRIM CARPET CLIPS - SET	1	necessary	50.00	50.00	20
REAR LH FENDER GLASS INNER TRIM GARNISH CLIPS - SET	1	necessary	30.00	30.00	X NN
REAR LH FENDER GLASS SEALANT	1	reuse	80.00	0.00	NN
REAR NUMBER PLATE	1	reuse	25.00	0.00	
REAR NUMBER PLATE HOLDER	1	reuse	50.00	0.00	SVC
REAR TAILGATE CHROME MOULDING CLIPS - SET	1	necessary	30.00	30.00	20
REAR TAILGATE REVERSE CAMERA	1	shorted	800.00	800.00	X SVC
REAR TAILGATE WINDSCREEN SEALANT	1	necessary	100.00	100.00	50
REAR TAILLAMP CLIPS L/R - SET	1	necessary	60.00	60.00	20
REAR TAILLAMP LOWER GARNISH CLIPS L/R - SET	1	necessary	60.00	60.00	20

REAR THIRD SEAT RAIL BRACKET GARNISH CLIPS - SET

1 necessary	50.00	50.00 XNN
Subtotal before discount	S\$ 2,075.00	S\$ 1,770.00
Sub-total 2	S\$ 2,075.00	S\$ 1,770.00 440
Parts-total	S\$ 23,710.59	S\$ 20,513.85

LABOUR

To reset system after repair works	500.00	400.00 XNN
To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	100.00	60.00 /
To remove, reinstall tailgate windscreen	300.00	150.00 100
To remove, reinstall fender glass	150.00	0.00
To remove, reinstall petrol tank. (to FR)	80.00	0.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	200.00	100.00 60
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	2,200.00	1,500.00 1000
To remove and reinstall exhaust pipe.	150.00	0.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	3,800.00	1,540.00 800
To mount vehicle on to Car 'O' Liner.	400.00	400.00 XNN
To apply anti-rust chemical on repaired and replaced panel.	120.00	90.00 60
Labour Total	S\$ 8,000.00	S\$ 4,240.00 2080
Parts & Labour Total	S\$ 31,710.59	S\$ 24,753.85

Results of inspection of the accident vehicle are as shown above.


8330.61

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : S\$ 21,000.00
and the recommended number of working days for the repairs is within 9 day(s).

20% 6650

7 Days.


B J Loi (I Eng., MIML, AIRTE)
Automotive Appraiser

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/07/2017 15:00
Date Of Accident	26/07/2017 17:55
Exact Location Of Accident	PIE TWDS CHANGI B4 BKE EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ4598X
Insured/Policyholder	
Name Of Registered Owner	SINGAPORE YONGAN PHARMACEUTICAL FACTORY PTE LTD
Co Reg No	201617436Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91887608

Vehicle Particulars

Manufacturer	TOYOTA
Model	VELLFIRE
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100492905-00000
Cover Note Number	

Driver

Name of Driver	SHEN GUO BIAO JACK
Work Permit No	F2194145W
Date Of Birth	03/11/1977
Occupation	INDOOR
Date Of Driving Pass	20/06/2017
Driving Experience	0 YEAR AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91887608
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	29 LILY AVENUE
Postcode	277789
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - CO-OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH WORKSHOP
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD8006L
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available if so said.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"); the Insurers, lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



10/10/2017
10/10/2017

Sketch Plan #2

Describe Circumstances of the Accident

Blank lined paper with horizontal ruling lines.

Declaration

We declare the foregoing particulars are true in every respect.


 Policyholder's Signature: _____ Date: _____
 Time: _____

Driver's Signature (if driver is not the policyholder) : Date & Time

Witnessed by Reporting Centre
Date: 27/07/20

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/07/2017 14:33
Date Of Accident	26/07/2017 17:55
Exact Location Of Accident	PIE TOWARDS CHANGI BEFORE BKE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD8006L
Insured/Policyholder	
Name Of Registered Owner	BLOSSOM PAPER PRODUCTS PTE LTD
Co Reg No	198703709M
Email Address	SALES@BLOSSOM.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62805055

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	COMPANY USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100412833-02000
Cover Note Number	

Driver

Name of Driver	TEO KEN HOW
NRIC No	S1334612G
Date Of Birth	22/11/1958
Occupation	OUTDOOR
Date Of Driving Pass	30/11/1976
Driving Experience	40 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98229063
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 171 YISHUN AVENUE 7 #05-779
Postcode	760171
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLJ4598X
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time
27 JUL 2017

Driver's Signature (If driver is not the policyholder) / Date & Time
27 JUL 2017

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

The incident happened on Wednesday (26/07/17) at 5.55pm.
 I was driving my lorry along PIE towards Changi before BKE.
 There was an accident happened in front, vehicle SLJ 4598X
 quickly jammed brakes, I could not stopped in time and
 collided onto the rear of SLJ 4598X.

[Signature]

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &
 Time 27 JUL 2017


[Signature]

Driver's Signature (If driver is not the policyholder) / Date
 & Time 27 JUL 2017

[Signature]

Witnessed by Reporting Centre
 Personnel

Sketch Plan #2 Pg. 1



CERTIFICATE OF INSURANCE

M.Z.300

Padmya

En. Reg. No. 201000040441

Accident Photo



Accident Photo



Accident Photo



TOYOTA MOTOR CORPORATION JAPAN
MODEL KDY231R-TLMKY
ENGINE 1KD-FTV 2982 cc
FRAME No. JTFAT35Y30K204444
COLOR 199 TRIM EA12 PLANT P11
TRANS./AXLE R451 A06B 524




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS3/AIG17014601/Gvd3e2-1		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 06-09-2019		
ATTN : NORSIAH		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 8006L	Veh. Inspected	SLJ 4598X	
Policy No.	2100412833-02000	Coverage (\$)	0.00	
Claim No.	8081919326SG	Excess (\$)	0.00	
Assign From	NORSIAH	Assign Date	30/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VELLFIRE	c.c	2494	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTNGF3DH708007166	Colour	WHITE	
Odometer	8653	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/50 R18	TOYO	6 mm	
L/H Front Tyre	235/50 R18	TOYO	6 mm	
R/H Rear Tyre	235/50 R18	TOYO	6 mm	
L/H Rear Tyre	235/50 R18	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/07/2017	Inspection Date	28/07/2017	
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 4598X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	SQUASHED	1,776.30	691.30
2	REAR BUMPER BRACKET L/R	SERVICEABLE	220.80	-
2	REAR BUMPER CENTRE REVERSE SENSOR COVER L/R	SERVICEABLE	36.20	-
2	REAR BUMPER CENTRE REVERSE SENSOR HOLDER L/R	SERVICEABLE	38.50	-
2	REAR BUMPER CORNER BRACKET L/R	SERVICEABLE	206.40	-
2	REAR BUMPER CORNER REVERSE SENSOR COVER L/R	SERVICEABLE	36.20	-
2	REAR BUMPER CORNER REVERSE SENSOR HOLDER L/R	SERVICEABLE	38.50	-
1	REAR BUMPER LH LOWER COVER	SERVICEABLE	145.10	-
2	REAR BUMPER REFLECTOR L/R	N/S CRACKED / O/S NOT NECESSARY	196.20	67.60
1	REAR BUMPER REVERSE SENSOR WIRE HARNESS	SERVICEABLE	110.35	-
1	REAR BUMPER RH LOWER COVER	SERVICEABLE	145.10	-
2	REAR BUMPER SIDE RETAINER L/R	N/S CUT / O/S NOT NECESSARY	220.70	74.43
2	REAR BUMPER TOW HOOK COVER L/R	N/S CUT / O/S NOT NECESSARY	78.90	35.90
1	REAR END PANEL	BUCKLED	780.20	780.20
1	REAR END PANEL ANTENNA SENSOR	SERVICEABLE	124.10	-
1	REAR END PANEL BUZZLE SENSOR	SERVICEABLE	509.10	-
1	REAR END PANEL INNER TOP GARNISH	FRACTURED	212.10	212.10
2	REAR END PANEL SIDE RUBBER STOPPER L/R	SERVICEABLE	132.20	-
2	REAR FENDER INNER UPHOLSTERY TRIM GARNISH L/R	N/S DEFORMED / O/S NOT NECESSARY	1,658.40	829.20
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	978.40	-
1	REAR FLOOR PANEL TRIM CARPET	DEFORMED	890.10	220.00
1	REAR LH FENDER	TO REPAIR SEE LABOUR	806.00	-
1	REAR LH FENDER AIR VENT	SERVICEABLE	100.40	-
1	REAR LH FENDER GLASS INNER TRIM GARNISH	SERVICEABLE	399.10	-
1	REAR LH FENDER GLASS MOULDING	SERVICEABLE	408.10	-

Report Ref No. CS3/AIG17014601/Gvd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR LH SAFETY BELT	SERVICEABLE	780.10	-
2	REAR NUMBER PLATE LAMP L/R	SERVICEABLE	808.70	-
1	REAR SPARE TYRE RETAINER LOCK	SERVICEABLE	45.90	-
2	REAR SPARE TYRE TOP SPONGE L/R	SERVICEABLE	220.70	-
1	REAR SPARE TYRE TRAY GARNISH	SERVICEABLE	109.10	-
1	REAR TAILGATE	BUCKLED	1,956.30	1,956.30
1	REAR TAILGATE 'VELLFIRE' EMBLEM	NECESSARY	110.35	82.50
1	REAR TAILGATE AUTO CLOSE MOTOR UNIT	SERVICEABLE	1,089.10	-
1	REAR TAILGATE AUTO CLOSE MOTOR UNIT ROD	TO REPAIR SEE LABOUR	236.95	-
1	REAR TAILGATE AUTO CLOSE MOTOR UNIT ROD BRACKET	TO REPAIR SEE LABOUR	124.10	-
1	REAR TAILGATE CHROME MOULDING	SERVICEABLE	210.35	-
1	REAR TAILGATE CHROME MOULDING 'LOGO' EMBLEM	SERVICEABLE	65.10	-
1	REAR TAILGATE CHROME MOULDING GARNISH	FRACTURED	1,089.45	725.70
1	REAR TAILGATE CLOSE BUTTON SWITCH	SERVICEABLE	202.10	-
2	REAR TAILGATE DAMPER L/R	SERVICEABLE	562.80	-
2	REAR TAILGATE HINGES L/R	SERVICEABLE	138.40	-
1	REAR TAILGATE INNER DAMPER MOUNTING	SERVICEABLE	45.90	-
1	REAR TAILGATE INNER PULL GARNISH	SERVICEABLE	110.35	-
1	REAR TAILGATE MECHANISM LOCK	BENT	509.10	509.10
1	REAR TAILGATE MECHANISM LOCK MOTOR	SERVICEABLE	550.45	-
1	REAR TAILGATE MECHANISM LOCK STRIKER	SERVICEABLE	45.10	-
1	REAR TAILGATE OPENER BUTTON SENSOR	SERVICEABLE	509.40	-
2	REAR TAILGATE REFLECTOR LAMP BACK RUBBER L/R	SERVICEABLE	80.20	-
2	REAR TAILGATE REFLECTOR LAMP L/R	N/S CRACKED / O/S NOT NECESSARY	808.20	404.10
2	REAR TAILGATE RUBBER GUIDE STOPPER 'LOWER' L/R	SERVICEABLE	266.20	-
2	REAR TAILGATE RUBBER GUIDE STOPPER 'TOP' L/R	SERVICEABLE	220.50	-
2	REAR TAILGATE SIDE RUBBER STOPPER L/R	SERVICEABLE	220.50	-
2	REAR TAILGATE SIDE SENSOR L/R	SERVICEABLE	1,198.20	-
2	REAR TAILGATE UPHOLSTERY SIDE TRIM GARNISH L/R	SERVICEABLE	450.40	-
1	REAR TAILGATE UPHOLSTERY TOP TRIM GARNISH	SERVICEABLE	303.10	-
1	REAR TAILGATE UPHOLSTERY TRIM GARNISH	SERVICEABLE	404.10	-

Report Ref No. CS3/AIG17014601/Gvd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TAILGATE WEATHERSTRIP	DEFORMED	395.45	357.00
1	REAR TAILGATE WINDSCREEN MOULDING	NECESSARY	210.10	156.60
2	REAR TAILLAMP BACK RUBBER GASKET L/R	SERVICEABLE	90.20	-
2	REAR TAILLAMP L/R	N/S CRACKED / O/S NOT NECESSARY	870.20	435.10
1	REAR TAILLAMP LH INNER PANEL	SERVICEABLE	110.10	-
1	REAR TAILLAMP LH OUTER PANEL	SERVICEABLE	405.10	-
2	REAR TAILLAMP LOWER GARNISH L/R	N/S DEFORMED	420.70	210.35
1	REAR THIRD SEAT RAIL BRACKET CENTRE GARNISH	SERVICEABLE	123.95	-
2	REAR THIRD SEAT RAIL BRACKET GARNISH L/R	SERVICEABLE	220.30	-
2	REAR THIRD SEAT RAIL BRACKET L/R	TO REPAIR SEE LABOUR	246.20	-
	LESS 25% DISCOUNT		-6,702.74	-1,936.87
			20,108.21	5,810.61
2	REAR BUMPER CENTRE REVERSE SENSOR L/R (SN)	SHORTED	1,018.30	100.00
2	REAR BUMPER CORNER REVERSE SENSOR L/R (SN)	SHORTED	1,018.20	100.00
	LESS 25% DISCOUNT		-509.13	-
			1,527.37	200.00
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	SET REAR BUMPER LOWER COVER CLIPS (SN)	NOT NECESSARY	50.00	-
1	REAR END PANEL INNER TOP GARNISH CLIPS (SN)	NECESSARY	40.00	20.00
2	SET REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R (SN)	NECESSARY	100.00	60.00
1	REAR FLOOR PANEL INSULATOR MAT (SN)	SERVICEABLE	500.00	-
1	SET REAR FLOOR PANEL TRIM CARPET CLIPS (SN)	NECESSARY	50.00	20.00
1	SET REAR LH FENDER GLASS INNER TRIM GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-
1	REAR LH FENDER GLASS SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR NUMBER PLATE (SN)	SERVICEABLE	25.00	-
1	REAR NUMBER PLATE HOLDER (SN)	SERVICEABLE	50.00	-
1	SET REAR TAILGATE CHROME MOULDING CLIPS (SN)	NECESSARY	30.00	20.00
1	REAR TAILGATE REVERSE CAMERA (SN)	SERVICEABLE	800.00	-

Report Ref No. CS3/AIG17014601/Gvd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	100.00	50.00
2	SET REAR TAILLAMP CLIPS L/R (SN)	NECESSARY(1 SET ONLY)	60.00	20.00
2	SET REAR TAILLAMP LOWER GARNISH CLIPS L/R (SN)	NECESSARY(1 SET ONLY)	60.00	20.00
1	SET REAR THIRD SEAT RAIL BRACKET GARNISH CLIPS (SN)	NOT NECESSARY	50.00	-
			2,075.00	240.00
	LABOUR			
	TO RESET SYSTEM AFTER REPAIR WORKS.	NOT NECESSARY	500.00	-
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR.		100.00	60.00
	TO REMOVE, REINSTALL TAILGATE WINDSCREEN.		300.00	100.00
	TO REMOVE, REINSTALL FENDER GLASS.	NOT NECESSARY	150.00	-
	TO REMOVE, REINSTALL PETROL TANK. (TO FR)	NOT NECESSARY	80.00	-
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)		200.00	60.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		2,200.00	1,000.00
	TO REMOVE AND REINSTALL EXHAUST PIPE.	NOT NECESSARY	150.00	-
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL, REAR LH FENDER, REAR TAILGATE AUTO CLOSE MOTOR UNIT ROD, REAR TAILGATE AUTO CLOSE MOTOR UNIT ROD BRACKET AND REAR THIRD SEAT RAIL BRACKET L/R.		3,800.00	800.00
	TO MOUNT VEHICLE ON TO CAR 'O' LINER.	NOT NECESSARY	400.00	-
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	60.00
			8,000.00	2,080.00
GRAND TOTAL			31,710.58	8,330.61

Report Ref No. CS3/AIG17014601/Gvd3e2-1



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,650.00
---	--	--	----------

Report Ref No. CS3/AIG17014601/Gvd3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.