

# ECLIPSE AUTO PTE LTD

155 KAKI BUKIT AVENUE 1, SHUN LI INDUSTRIAL PARK LEVEL 1 & 2, SINGAPORE 416012

TEL : (65) 6844 2814 FAX : (65) 6748 3762

Co. Reg. No.: 201221209k

Vehicle No: SLG 4889 Y

Made / Model: MERCEDES BENZ C200 AMG

Name: DREAM CAR LEASING PTE LTD

Address: C/o: 155 Kaki Bukit Avenue 1, Shun Li Industrial Park  
#01-00 Singapore 416012

Accident Date: 6/11/18

RE: FINAL BILL FOR VEHICLE NO. SLG 4889 Y

(LUMP SUM REPAIR)

\$ 11,200.00

Singapore Dollars: Eleven Thousand and Two Hundred Only.



PHOTOCOPY

## INVOICE

TO : DREAM CAR LEASING PTE LTD  
C/O: ECLIPSE AUTO PTE LTD  
155 KAKI BUKIT AVE 1 #01-00,  
SHUNLI INDUSTRIAL PARK  
SINGAPORE 416012

Invoice No.: 1118/EA871  
Date: 30-Nov-2018

### PARTICULARS

Vehicle Registration No.: SLG 4889 Y  
Date of Loss: 06-Nov-2018  
Date of Assessment: 09-Nov-2018

### SERVICES

### FEES

1. Assessment with report Photographs -  
Including films, developing, storage and Transport. \$500.00

TOTAL \$500.00

SINGAPORE DOLLARS FIVE HUNDRED ONLY

We would appreciate your cheque crossed and made payable to:  
"AEON AUTO CONSULTANTS LLP" with our invoice no. written on the back of the cheque.

AEON AUTO CONSULTANTS LLP



### AEON AUTO CONSULTANTS LLP

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874  
Telephone +65 97687958 Facsimile +65 68264112 Email amas@aeonac.com  
Reg. No. LL0701273L (registered with limited liability)

## AUTOMOBILE ASSESSMENT REPORT

TO: DREAM CAR LEASING PTE LTD  
C/O: ECLIPSE AUTO PTE LTD  
155 KAKI BUKIT AVE 1 #01-00,  
SHUNLI INDUSTRIAL PARK  
SINGAPORE 416012

Our Reference: 1118/EA871  
Date: 30-Nov-2018

### ASSESSMENT OF VEHICLE NO. SLG 4889 Y

DATE OF LOSS: 06-Nov-2018

We have carried out a physical assessment at **ECLIPSE AUTO PTE LTD**,  
155 Kaki Bukit Ave 1 #01-00 Shunli Industrial Park, Singapore 416012, according to your instruction  
on **09-Nov-2018** and are pleased to submit our report herewith.

### 1. VEHICLE PARTICULARS

Registration No.:	SLG 4889 Y
Make & Model:	MERCEDES BENZ C200 AMG
Year of Registration:	2016
Engine Capacity:	1991
Chassis No.:	WDD2053422F338693
Engine No.:	27492030514463
Colour:	GREEN
Mileage (km):	26353

### 2. VEHICLE CONDITION

Body Paint:	GOOD
Steering:	SERVICEABLE
Foot Brake:	SERVICEABLE
Parking Brake:	SERVICEABLE
Modification:	NIL

### 3. TYRE PARTICULARS & CONDITION

Front			
RH Make/Size/Thread:	PIRELLI	245/35	R19 – 80%
LH Make/Size/Thread:	PIRELLI	245/35	R19 – 80%
Rear			
RH Make/Size/Thread:	PIRELLI	275/30	R19 – 80%
LH Make/Size/Thread:	PIRELLI	275/30	R19 – 80%


#### 4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the FRONT portion.

#### 5. REMARKS

Market Value: Na  
Salvage Value: Na  
Repair Limit: Na

Estimated Amount: \$16,171.20  
Adjusted Amount: \$14,016.20  
Lump Sum: **\$11,200.00**  
Estimated Repair Days: 8 days



Pursuant to your instruction, we have **NOT AUTHORISED** repair.

The assessment was conducted on a **"Without Prejudice"** basis.

If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

#### Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.

### ASSESSMENT REPORT FOR VEHICLE NO. SLG 4889 Y

#### PARTS (LIST ITEMS)

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	FRONT BONNET	Repair	1,850.00	-
2	FRONT BONNET LOCK STRIKER L/R	Bent	60.00	60.00
2	FRONT BONNET MECHANISM LOCK L/R	Bent	390.00	390.00
2	FRONT BONNET RUBBER GUIDE STOPPER L/R	Bent	18.00	18.00
1	FRONT BONNET WEATHER STRIP	Cut	135.00	135.00
2	FRONT HEADLAMP L/R	Cracked	2,420.00	2,420.00
1	FRONT GRILLE	Cracked	125.00	125.00
1	FRONT GRILLE 'LOGO' EMBLEM	Cracked	123.00	123.00
1	FRONT GRILLE 'LOGO' EMBLEM BASE	Cracked	45.00	45.00
1	FRONT GRILLE CHROME GARNISH ASSY	Cracked	297.00	297.00
1	FRONT BUMPER	Cracked	1,580.00	1,580.00
1	FRONT BUMPER INNER FRAME	Cracked	368.00	368.00
6	FRONT BUMPER PARKING SENSOR (ORIGINAL)	Cracked	1,650.00	1,650.00
6	FRONT BUMPER PARKING SENSOR HOLDER	Cracked	111.00	111.00
6	FRONT BUMPER PARKING SENSOR RUBBER SEAL	Necessary	33.00	33.00
1	FRONT BUMPER PARKING SENSOR WIRE HARNESS - SET	Cut	218.00	218.00
2	FRONT BUMPER FOGLAMP GARNISH L/R	Cracked	178.00	178.00
1	FRONT BUMPER SPONGE	Cracked	295.00	295.00
1	FRONT BUMPER LOWER CENTER GRILLE	Cracked	225.00	225.00
1	FRONT BUMPER DIFFUSER CHROME MOULDING	Cracked	650.00	650.00
2	FRONT BUMPER SIDE BRACKET L/R	Bent	114.00	114.00
2	FRONT BUMPER SIDE RETAINER L/R	Bent	70.00	70.00
1	FRONT BUMPER TOW HOOK COVER	Necessary	72.00	72.00
1	FRONT BUMPER REINFORCEMENT	Bent	368.00	368.00
2	FRONT BUMPER REINFORCEMENT BRACKET L/R	Bent	226.00	226.00
1	DRUMPET HORN L/R - SET	Cracked	162.00	162.00
1	FRONT BRACE PANEL	Bent	235.00	235.00
1	FRONT BUMPER LOWER UNDER COVER	Cracked	325.00	325.00
1	FRONT BUMPER NUMBER PLATE GARNISH	Cracked	115.00	115.00
1	FRONT SUPPORT PANEL	Cracked	1,110.00	1,110.00
1	FRONT SUPPORT PANEL TOP GARNISH	Cracked	58.00	58.00
1	FRONT SUPPORT PANEL TOP GARNISH BRACKET	Bent	16.00	16.00
4	FRONT SUPPORT PANEL TOP GARNISH CLIPS	Necessary	26.00	26.00
			<b>13,668.00</b>	<b>11,818.00</b>
Less 10% discount			<b>1,366.80</b>	<b>1,181.80</b>
Parts Total:			<b>12,301.20</b>	<b>10,636.20</b>

### ASSESSMENT REPORT FOR VEHICLE NO. SLG 4889 Y

#### SPECIAL NETT ITEMS

1	FRONT BUMPER NUMBER PLATE	Cracked	120.00	120.00
1	FRONT BUMPER NUMBER PLATE HOLDER	Cracked	50.00	50.00
1	FRONT BUMPER CLIPS - SET	Necessary	100.00	100.00
Special Nett Total :			<u>270.00</u>	<u>270.00</u>

#### LABOUR

S/N	Description	Workshop's Estimate	Our Assessment
1	To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.	180.00	160.00
2	To reset system after repair works.	500.00	450.00
3	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,300.00	1,100.00
4	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,500.00	1,300.00
5	To apply anti-rust chemical on repaired and replaced panel.	120.00	100.00
Labour Total :		<u>3,600.00</u>	<u>3,110.00</u>
TOTAL (PARTS & LABOUR) \$		<u>16,171.20</u>	<u>14,016.20</u>

The workshop has agreed to undertake the repair on a Lump Sum basis.

The final adjusted Lump Sum contract amount is

**\$11,200.00** (SINGAPORE DOLLARS ELEVEN THOUSAND TWO HUNDRED ONLY)



Amas Ong  
Automobile Assessor