



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2003569
INV Date 29/04/2020
Reference CC6/CTI19013426/Aea3n2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SLF 5944U
Insured Veh. PC 7304Y
Claim No. SNM19D203415
Policy No. DMB1SN1825471800
Accident Date 20/07/2019
Inspection Date 30/07/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI19013426/Aea3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 29-04-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PC 7304Y	Veh. Inspected	SLF 5944U
Policy No.	DMB1SN1825471800	Coverage (\$)	0.00
Claim No.	SNM19D203415	Excess (\$)	0.00
Assign From		Assign Date	30/07/2019

2. Vehicle Particulars & Condition

Make & Model	BMW X1	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WBAHS120405F01962	Colour	WHITE
Odometer	31814	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R18	PIRELLI	6 mm
L/H Front Tyre	225/50 R18	PIRELLI	6 mm
R/H Rear Tyre	225/50 R18	PIRELLI	6 mm
L/H Rear Tyre	225/50 R18	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/07/2019	Inspection Date	30/07/2019
Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 5944U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BONNET	DISTORTED	1,980.00	1,980.00
2	FRONT BONNET HINGES @\$121.00	BENT	242.00	242.00
1	FRONT BONNET BMW LOGO	NECESSARY	91.30	91.30
1	FRONT BONNET INSULATION	NOT NECESSARY	225.50	-
2	FRONT BONNET LOCK @\$115.50	DAMAGED	231.00	231.00
2	FRONT BONNET SHOCK ABSORBER @\$154.00	NOT NECESSARY	308.00	-
1	FRONT SUPPORT PANEL	BENT	324.50	324.50
1	FRONT SUPPORT PANEL TOP RUBBER	NOT NECESSARY	71.50	-
1	FRONT SUPPORT PANEL TOP COVER	CRACKED	528.00	528.00
2	FRONT GRILLE @\$148.50	NOT NECESSARY	297.00	-
2	FRONT HEADLAMP @\$3,190.00	N/S SMASHED / O/S CRACKED	6,380.00	5,734.00
2	FRONT HEADLAMP HID UNIT @\$1,078.00	N/S DAMAGED	2,156.00	455.00
1	FRONT BUMPER	DISTORTED	1,050.00	1,050.00
2	FRONT BUMPER SIDE HOLDER @\$29.70	NECESSARY	59.40	59.40
1	FRONT BUMPER LOWER CENTRE GRILLE	DEFORMED	137.50	137.50
1	FRONT BUMPER LOWER LIP	DEFORMED	247.50	247.50
1	FRONT BUMPER LOWER CENTRE GARNISH	CUT	264.00	264.00
1	FRONT BUMPER LH FOG LAMP	CRACKED	330.00	330.00
1	FRONT BUMPER LH FOG LAMP LOWER GRILLE	DEFORMED	115.50	115.50
1	FRONT BUMPER REINFORCEMENT	BENT	451.00	451.00
2	FRONT BUMPER BRACKET @\$165.00	N/S BENT	330.00	165.00
1	SET FRONT BUMPER CLIPS	NECESSARY	77.00	30.00
2	FRONT FENDER @\$803.00	N/S DENTED	1,606.00	803.00
2	FRONT FENDER SIDE GARNISH @\$181.50	NOT NECESSARY	363.00	-
2	FRONT FENDER INNER SHIELD @\$170.50	N/S TORN	341.00	170.50
1	SET FRONT FENDER INNER SHIELD CLIPS	NECESSARY	60.50	30.00
1	AIRCON CONDENSER	BENT	1,177.00	1,177.00
1	RADIATOR	CRACKED	990.00	990.00
1	RADIATOR TOP NOSE	NOT NECESSARY	132.00	-
1	RADIATOR BOTTOM NOSE	NOT NECESSARY	99.00	-

Report Ref No. CC6/CTI19013426/Aea3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIR DUCT	CRACKED	286.00	286.00
1	AIR CLEANER ASSY	NOT NECESSARY	550.00	-
1	RADIATOR FAN ASSY	NOT NECESSARY	1,138.50	-
1	FRONT LH SPORT RIM	NOT NECESSARY	968.00	-
1	FRONT LH TYRE	NOT NECESSARY	418.00	-
1	FRONT LH LOWER ARM	NOT NECESSARY	352.00	-
1	FRONT LH KNUCKLE ARM	NOT NECESSARY	583.00	-
1	FRONT LH KNUCKLE ARM BEARING	NOT NECESSARY	616.00	-
1	FRONT RADIATOR OIL COOLER	CRACKED	704.00	704.00
1	FRONT BUMPER SPONGE	CRACKED	175.00	175.00
1	FRONT GRILLE INNER FRAME	CRACKED	352.00	352.00
1	HORN	DAMAGED	68.00	68.00
1	FRONT BUMPER LOWER BEAM	BENT	286.00	286.00
	LESS 5% DISCOUNT		-1,358.09	-873.86
			25,803.61	16,603.34
	LABOUR			
	TO CHECK WIRING.		50.00	30.00
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	REMOVE & REINSTALL AIR CON FILL IN GAS.		200.00	120.00
	REMOVE & REINSTALL FRONT LH SUSPENSION.	NOT NECESSARY	400.00	-
	REMOVE, REPLACE & REPAIR CONSISTENT TO THE ACCIDENT.		2,500.00	1,000.00
	RESPRAY PAINTING.		1,800.00	1,000.00
	TUFF KOTE.		150.00	50.00
			5,200.00	2,200.00
GRAND TOTAL			31,003.61	18,803.34
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				15,000.00

Report Ref No. CC6/CTI19013426/Aea3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.